



CUT MARK NEEDS TO PRINT

CUT MARK NEEDS TO PRINT

CUT MARK NEEDS TO PRINT

CUT MARK NEEDS TO PRINT

CUT MARK NEEDS TO PRINT

CUT MARK NEEDS TO PRINT

CUT MARK NEEDS TO PRINT

CUT MARK NEEDS TO PRINT

PLEASE PRINT ALL CUT MARKS



ENVELOPE DELINE

- ✓ Please follow the exact die line. It is important to keep the scale at 200%
- ✓ It is essential that the grain run in the direction specified by Cutting Edge Envelopes
- ✓ The position of the envelope is critical to ensure proper breakdown in the die cutting process
- ✓ Envelope machines cannot fold perfect borders or bleeds. Designs with bleeds must allow 1/8" around to bleed.
- ✓ Mark your goods and papers. Make sure stock is tagged. Print die marks.
- ✓ Unfinished edges must be free of dirt and wrinkles, otherwise gear or gum may fail.
- ✓ We cannot guarantee envelopes if our die line is not followed.
- ✓ Cut marks must be printed on sheet.
- ✓ There may be a variance of 2-3" in any direction. This is industry standard.
- ✓ Please provide 20% or minimum of 5000 orders

PLEASE PRINT ALL CUT MARKS