




# Electronic Pumps and Injectors



| Make                    | Model  | Year        | Engine         | High Pressure Reman Pump | Injector Reman Assembly | Notes      |  |
|-------------------------|--|-------------|----------------|--------------------------|-------------------------|------------|--|
| Chevrolet<br>GMC Trucks | 2500HD / 3500<br>Hummer H1<br>Kodiak<br>Top Kick | 2001-2004½  | 6.6L (LB7)     | 0986437303               | 0986435502              |            |  |
|                         |  | 2004½-2005  | 6.6L (LLY)     | 0986437308               | 0986435504              |            |  |
|                         |  | 2006        | 6.6L (LBZ)     | 0986437332               | 0986435521              |            |  |
|                         |  | 2007-2010   | 6.6L (LLM/LBZ) | 0986437332               | 0986435520              |            |  |
| Dodge Trucks            | Cab Chassis                                      | 2007-2008   | 6.7L (All)     | 0986437334               | 0986435519              |            |  |
|                         |  | Ram         | 2003-2004½     | 5.9L (All)               | 0986437304              | 0986435503 |  |
|                         |  | Ram         | 2004½-2007     | 5.9L (All)               | 0986437304              | 0986435505 |  |
|                         |  | Ram Pick-up | 2007-2010      | 6.7L (All)               | 0986437334              | 0986435518 |  |



All manufacturer names, model and part numbers used for reference purposes only.



## MILLER DIESEL, INC.

*Diesel Fuel Injection & Turbo Specialist*

717.545.5931 • Fax: 717.545.3467 • 800.296.5931 • millerdiesel@comcast.net

6030 Jonestown Road, Harrisburg, Pa 17112




**BOSCH**

# Dodge 5.9L Fuel Injection Pump

**Dodge Cummins 5.9L &  
Cummins Mid-range  
1998.5 - 2002**

**VP44 Fuel Injection Pumps,  
Injectors, Turbos & More**



**Contact Miller Diesel With Engine S/N  
For Your Application**

**Dodge/Cummins  
Fuel Transfer Pump Kit**



**Warning:** Failure to replace feed pump (fuel transfer pump) along with the injection pump may cause damage that could void warranty. It is highly recommended that the feed pump be changed along with the injection pump.



All manufacturer names, model and part numbers used for reference purposes only.



## MILLER DIESEL, INC.

*Diesel Fuel Injection & Turbo Specialist*

717.545.5931 • Fax: 717.545.3467 • 800.296.5931 • millerdiesel@comcast.net

6030 Jonestown Road, Harrisburg, Pa 17112