

Adhesives for Display Assembly

- ❖ **Optically Clear Adhesives – OCA**
 - Liquid adhesives for bonding display elements in the optical path.

- ❖ **UV PSAs for perimeter bonding, tape replacement.**

- ❖ **Opaque UV cure adhesives and sealants for edge bonding and bezel replacement.**

- ❖ **PSA OCA Assembly Process – Patent pending assembly process for displays of any size**
 - **Contact CTECH!**