



# Tokyo Keiso/Malema 8000/8100 Slurry Controllers Refurbishment

## **REFURBISHMENT SERVICE:**

Tokyo Keiso/Malema 8000/8100

### **Services Performed:**

- Incoming inspection & Failure Determination
- Complete Tear-Down
- Motor Driven pinch valve tubing replaced (OEM recommendation 1 yr PM cycle)
- ISO Valve Rebuild
- Range Changes Available on 8100 within device capabilities
- Ultrasonic Flow Meter Tested
- Flow Controller Tested
- Unit Tested for repeatability at "like process" flow rates
- Leak Tested and Purged
- Packaged in Cleanroom environment
- Includes accompanying Test Report
- Tool Ready Quality Assurance



Our team of industry professionals are considered leaders in precision pressure and flow devices within the semiconductor industry. Our services are performed in clean environment with procedures that meet or exceed the most stringent OEM and industry specifications. We provide exceptional value, quick turn around times, and customizable testing procedures.

Phone: 208-794-8666

Fax: 208-968-9662

Email: [service@mbartechlogies.com](mailto:service@mbartechlogies.com)

