

### PICMG 2.11 R1.0 P47 Power Connector Pin Assignments

Description	Pin	Pin	Description
AC Line/-DC_IN	47	31	GA2
AC Neutral/DC_RTN	46	30	+5V Sense
Chassis GND	45	29	+5V Adjust
+12V Current Share	44	28	GA1
IPMB PWR	43	27	Enable
FAIL	42	26	RSVD
+3.3V Current Share	41	25	GA0
IPMB SDA	40	24	GND
Inhibit	39	23	RSVD
Degrade	38	22	RTN
IPMB SCL	37	21	-12V
+12V Sense	36	20	+12V
+5V Current Share	35	19	GND
GND Sense	34	13-18	+3.3V
+3.3V Sense	33	5-12	GND
3.3V Adjust	32	1-4	+5V

