



- NOTES:
- 1) *Denotes Silver Mica
 - 2) S4 and S5 are mechanically ganged and shown in 80M position
 - 3) M1 is 50µA movement, 3000 VDC FS
 - 4) M2 is 1mA movement, 1000 mA FS
 - 5) M3 is 1mA movement, 100 ma FS