


10 Motor, 20 Amp Power Distribution Panel



The Following is also included with your Power Panel:

1. Qty 1 110 V AC Power Cord
2. Qty 1 Strain-Relief for 110 V AC Power Cord
3. Qty 1 Grommet for Knock Out
4. Qty 1 Panel lock with Qty 2 Keys

Note: See further Instructions on Reverse

email us at customerservice@porterpreston.com

www.porterpreston.com • Tel: (866) 753-1113 • Fax: (203) 597-8828

10 Motor, 20 Amp Power Distribution Panel

Step 1: Power Cord to be attached as follows:

Black wire attache to L
White wire attache to N
Green wire attach to Ground



Step 2: Motors to be attached as follows:

24 V Motor Wire
+24 Positive
-24 Neutral
Note: These wires are polarity sensitive

email us at customerservice@porterpreston.com

www.porterpreston.com • Tel: (866) 753-1113 • Fax: (203) 597-8828