

The Rxg Doctor's

Joan and Fred McAninch
1412 South County Road 1050-E
Indianapolis, Indiana 46231-1866
317-839-7534

Equipment Available For Immediate Delivery

Failing Model G-250-HT High Torque PTO, 28" shaft centers, 10,000 lbs., net ft lbs on truck drive lines. 5000 ft lbs on drill rig output shaft. All shafts splined for common spicer flanges. 1-to-1 chain drive ratio. Net weight: 700 lbs. Failing part #156F090 pictures and dimension specs available. Possible delivery. Possible parting out.....**\$7000**

4X5 Gardner Denver mud pump, model FF-FXF-B, rebuilt to new condition on gear and fluid end. Pictures available. Possible delivery.....**\$7500**

12" I.D. Failing rotary table, Failing part number 101F670 brand new, never used, for Failing drill unit WW-1 only.....**\$8000**

Failing 5-5/16" I.D. rotary table, built up to brand new. Failing part number 152F091 (PB-1250-101-GA) New quill, new mud rejector, new bearings, new pinion flange, new seals for Failing model drills 1250/CF-15. Price includes freight to U.S. destination.....**\$13,000**