


AN IMPORTANT PART FOR PROPER OPERATION



Too many people omit installing this very important part, the Hot Air Pipe, Part No. 4582. The carburetor cannot be adjusted properly without this part. We have witnessed occasions where people have removed the cylinder head to check the valves, changed timers, coils, and carburetors and really all that caused the irregular misfire was that this part was not installed.

DRAWN BY: K.O. SCHROETER