



UPDATE

Lake Fork Reservoir – Soil Cement Repairs
SABINE RIVER AUTHORITY OF TEXAS
LAKE FORK
353 PR 5183, QUITMAN, TX 75783

April 1, 2022

Earlier this year the water level at Lake Fork Reservoir was lowered to an elevation of approximately 397-ft to make repairs and further assess soil cement along the upstream side of the Lake Fork Dam. Further inspections were conducted by divers and revealed submerged areas below elevation 397 that were also in need of repair. A two phased approach was conducted to repair the above water and below water repairs.

All above water repair work has been completed and as of this press release the SRA will no longer hold the reservoir at elevation 397. The rate of rise of the lake will depend on rainfall and inflow from upstream tributaries. Underwater repair work will continue for the foreseeable future but can be conducted as the reservoir is allowed to fill.

Lake side property owners should continue to inspect and make necessary repairs to boathouses, piers, retaining walls and related structures. Construction approval applications for this type of activity may be obtained from the Lake Fork Division Office (903-878-2262).

For more information contact the Lake Fork Division Office (903-878-2262).