

Audi as of 09/23/2019

Audi does not have a position statement regarding pre- and post-scanning, but they do, however, state when a scan tool is needed. For example, the Cautions and Warnings sectioning at the beginning of the body repair manual states “Any time the battery has been disconnected on an automatic transmission vehicle, it will be necessary to re-establish Transmission Control Module (TCM) basic settings using the VAG 1551 Scan Tool (ST).” Audi also specifies when a scan tool is needed within the procedures of the body repair manual.