

124 Kings Road • Chelsea • London SW3 4TP

Email: management@mitrehouse.org  $\bullet$  www.mitrehouse.org Telephone +44 (0)207 589 7502 Mbl: +44 (0)798 33 33 543

# 2014 Works' Invoices £105,877 AND Lessees' Windows Repair Accounts

(ORIGINALS & COPIES)





# MITRE HOUSE MANAGEMENT LIMITED

SUITE 7 MITRE HOUSE • 124 KINGS ROAD • CHELSEA • LONDON SW3 4TP
EMAIL: MANAGEMENT@MITREHOUSE.COM • WWW.MITREHOUSE.COM
TELEPHONE +44 20 7589 7502 • MBL: +44 (0)798 33 33 543

3 April 2016

P.F.C. Begg Esq., Solicitor, 9th Floor, Metro Building, 1 Butterwick, Hammersmith, London W6 8DL

DEAR MR. BEGG

Your Ref: Mrs Michele Hillgarth

Re: Requested documentation from our year ended 2014 Accounts

Further to your letters of 23 March and 31 March 2016 I have pleasure in supplying the various original invoices you have demanded with copies (save for the ring binder containing the costs & suppliers' accounts). I have supplied both paid and unpaid and renegotiated and the lessee Window Repair invoices as Mrs Hillgarth has accused ourselves of misappropriating those funds despite all cheques written directly to our contractor as evidenced by her own cheque made payable to AR Lawrence dated 17 Oct 2014?

You will note that savings were made and credited to Reserves of £2153 regarding the Water Tank & TV/Sky installations (due to scaffolding remaining in place) and £3185 off the Surveyor's final fees due to a substantial reduction in the overall total AR Lawrence budget on which the fees were based.

I am hopeful that these documents will answer your totally refuted accusations of fraud as stated in your letter of 23 March 2016 as our year ended accounts dated 30 May 2015 well evidence indicating Reserves of £16,201 carried forward to 2015 as opposed to what lessees had been advised of only £11,243.

I can also confirm categorically that not one single request was received from any lessee to view documents from our 2014 Accounts within the statutory six months from publication despite our insistence that they were very welcome to do so in various emails during the works' schedule.

As regards the multitude of other accusations and innuendos as stated at length in your thirteen page 23 March 2016 letter, we will respond in due course with hard copy evidence to thoroughly refute each and every one as they are mostly childish bleatings of your client, evidencing her jealous, vindictive and malicious attitude towards Mitre House Management Limited and most notably myself.

Please return the originals after use. Thank you.

Yours sincerely,

Paul Brown-Constable cc Segar Karupiah, Dima International Ltd

AML BROWN-CONSTABLE



MAINTAINING MITRE HOUSE

## **Chartered Surveyors**

Established 1847 10 Genotin Terrace, Enfield,

Middlesex, EN1 2AF

Tel: 020 8367 5100

Fax: 020 8366 3056

Your Ref: VAT Reg No 467 6205 30

Our Ref: D3827

Account No. 7787 Date: 13<sup>th</sup> February 2014

Mitre House Management Limited, 7 Mitre House, 124 Kings Road, LONDON, SW3 4TP

Mitre House, 124 Kings Road, London SW3		
To receiving your instructions to prepare a scheme for external repair/redecoration and redecoration of the internal common parts at the above property, including provision of CDM Co-ordinator services under the CDM Regulations 2007.		
Attending a preliminary meeting with you to discuss the proposed scope of works, carrying out further detailed inspections, taking details and photographs, preparing a draft Specification and submitting this to you, for comment/approval.		
First interim fee for professional services to draft Specification stage, say;	£2,250.00	
VAT @ 20%		£450.00
Travelling, copying, binding and other disbursements to date.	£70.40	
VAT @ 20%		£14.08
Sub Totals	£2,320.40	£464.08
Total VAT	£464.08	
TOTAL	£2,784.48	

## **Chartered Surveyors**

Established 1847 10 Genotin Terrace,

Enfield,

Middlesex, EN1 2AF

Tel: 020 8367 5100

Fax: 020 8366 3056

Your Ref: VAT Reg No 467 6205 30

Our Ref: D3827

Account No. 7810 Date: 24<sup>th</sup> March 2014

Mitre House Management Limited, 7 Mitre House, 124 Kings Road, LONDON, SW3 4TP

Mitre House, 124 Kings Road, London SW3		
To continuing professional services in connection with the scheme for external repair/redecoration and redecoration of the internal common parts at the above property, including provision of CDM Co-ordinator services under the CDM Regulations 2007.		
Receiving your instructions to invite tenders for the work following receipt of the draft Specification, preparing and issuing tender documents to five building contractors, checking/reviewing the tenders on receipt and preparing and issuing our tender report.		
Second interim fee for professional services to receipt of tender stage, based on agreed scale and calculated against lowest tender received;		
50% of 11% (10% + 1% CDM) of £76,101.00 <u>Less</u> : Previous account dated 13/02/14	£4,185.56 £2,250.00 £1,935.56	
VAT @ 20%		£387.11
Further copying, binding and other disbursements to date.	£108.50	
VAT @ 20%		£21.70
Sub Totals	£2,044.06	£408.81
Total VAT	£408.81	
TOTAL	£2,452.87	

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: <a href="mailto:arlawrencemail@aol.com">arlawrencemail@aol.com</a>

MITRE HOUSE MANAGEMENT LTD C/O
BOYCE EVENS & CARPENTER
10 GENOTIN TERRACE
ENFIELD
MIDDLESEX
EN1 2AF

INVOICE F/9/14

DATE	16 SEPTEMBER 2014	YOUR REF	DEREK ISAACS	OUR REF: AI	DW/4474/	<u>LW</u>
REQUEST FOR PAYMENT  APPLICATION FOR PAYMENT ON ACCOUNT NO. 1						
MITR	E HOUSE, 124 KINGS RO	AD, LONDON	SW3			
То	Works carried out to date, s	scaffold and ma	iterials on site		11102	50
Less	Retention @ 5%				<u>555</u>	13
					10547	37
	Value Added Tax @ 20%				2109	48
				£	12656	85
For BAC	CS payment our details are as follow	vs:-				
A/C Nan	ne: A R LAWRENCE & SO	NS LTD				
Sort Cod	le: 40 45 17					
Account	No.: 31260391					
Payment	required within 30 days of invoice pl	ease				
A VAT r	eceipt will be issued upon receipt of p	payment				

## **Chartered Surveyors**

Established 1847

10 Genotin Terrace,

Enfield,

Middlesex, EN1 2AF

Tel: 020 8367 5100

Fax: 020 8366 3056

Your Ref:

VAT Reg No 467 6205 30

Our Ref: D3827

Account No. 7880

Date: 22<sup>nd</sup> September 2014

Mitre House Management Limited, 7 Mitre House, 124 Kings Road, LONDON, SW3 4TP

## Mitre House, 124 Kings Road, London SW3

To continuing professional services in connection with the scheme for external repair/redecoration and redecoration of the internal common parts at the above property, including provision of CDM Co-ordinator services under the CDM Regulations 2007.

Discussing certain reductions to the proposed scope of works following receipt of tender and receiving your instructions to place a contract for the works with A.R. Lawrence & Sons Ltd on the basis of a reduced contract sum in the amount of £63,828.00 plus VAT.

Receiving and checking the contractor's insurance details, Construction Phase Plan and proposed programme, submitting an F10 Notification to the HSE, preparing and issuing the formal contract documents for signing and attending and minuting a precontact meeting.

Carrying out inspections of the work in progress, issuing Surveyors Instructions for certain variations to date and issuing the first payment certificate.

Third interim fee, based on 67½% of agreed scale fee and calculated against original lowest tender received;

67½% of 11% (10% + 1% CDM) of £76,101.00 Less: Previous accounts up to and including account dated

24/03/14

£5,650.50

£4,185.56

£1,464.94

VAT @ 20%

£292.99

Contract documents and further travelling, copying, binding and other disbursements to date.

£173.20

VAT @ 20%		£34.64
Sub Totals	£1,638.14	£327.63
Total VAT	£327.63	
TOTAL	£1,965.77	

















6 Blackthorn Close, West kingsdown, Kent TN15 6UF Tel: 01474 853335 Fax: 01474 852083 sales@aerialtec.co.uk www.aerialtec.co.uk

Customer Details		1-0
MITTE Mouse	monagnest	LIL
7 mitre Mou	Se	
124 Kings R	20	
larder SW3	HTP	
Tel No: 0207 589	2764	
Invoice Details (if different from		THE PERSON

Invoice No. 06402

VAT No. 885 7378 57

Sales & definition.couk www.definition.couk	
Installation Details	E : p
It installation of a command IIs	:
Schellife System to 9 Plats and	:
9 bedroun's within the flats	
It sent sistem interpreted with	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TO THE PERSON NAMED IN COLUMN T
Salellate Siglem	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	rem :
	Sarajin ratii it
It corretion of tries dish to rem Sixter	h :
and Ix buch hotbyd dish	A The Company of
	:
	The State of the S
Product Guarantee Period (yrs)	1212:
Perial: 1 0 2 0 3 0 5 0 Amplifier: 1 0 SKY/DTT Equipment: 1 0	4310.
SKY/DTT - STB Serial No.	862:
TOTAL	5172: -
Paid by: Cash Cheque Credit Card To be Invoiced C	The market on
full invoice amount and VAT must be paid to the installation Engineer for the equipment installed and work completed, Unless an alternative payment me he Company. AerialTec ltd or its subsidiaries reserve the right to remove any equipment not paid for. This agreement does not apply to storm or malicio	
Engineer's Observations & Recommendation	CAST SANGER
2 years Gurantee Payment within	28 days
Place	
Declaration	
259	P0.00

Declaration: Please read this invoice carefully before paying for work done and signing to your complete satisfaction.

The above work has been carried out to my complete satisfaction. The installation engineer has explained the alternative aerials available, the prices and signal defects if any. I understand payment is due on completion and consent to the removal of the aerial at any time during working hours in default of payment. I further agree to indemnify the installer against any losses incurred by default of payment. The signing of the receipt in no way invalidates your rights of common law.

Engineer Signature	Cus	tomer Signature		
Print Name Jewy	Date 13 10 14	Date 3	10/14	-

















6 Blackthorn Close, West kingsdown, Kent TN15 6UF Tel: 01474 853335 Fax: 01474 852083 sales@aerialtec.co.uk www.aerialtec.co.uk

Custo	omer Details
M	is M Millgarth
fl.	of 5 Mitte house
1<1	mss Rid
	5W3
Tel No:	
Invoid	ce Details (if different from above)
Mr	S M Hillgarth
66	Bedford Gardens
long	der W8 7FM

Invoice No. 06401

VAT No. 885 7378 57

Installation Details	£ : p
Ref.	Artical Learning
Re colling of existing convertions without to	:
She but	:
re installing sky signed to flat and	and in the second
renord of cases and dish	menin extract ext
a cost con	To the second second
the section of the se	Life paragraphing (A
	The same of the sa
	- <del></del>
	•
	0
Product Guarantee Period (yrs)	1195:
erial: 1 2 2 3 3 5 Amplifier: 1 SKY/DTT Equipment: 1 VAT %)	639:
KY/DTT - STB Serial No. TOTAL	1221
aid by : Cash Cheque Credit Card To be Invoiced	1234:
all invoice amount and VAT must be paid to the installation Engineer for the equipment installed and work completed, Unless an alternative payme Company. AerialTec Itd or its subsidiaries reserve the right to remove any equipment not paid for. This agreement does not apply to storm or	nent method has been agreed in writing malicious damage.
Engineer's Observations & Recommendation	TO SERVICE OF SERVICE
Parment within	28 das
Payment within	
( Yha	

Declaration: Please read this invoice carefully before paying for work done and signing to your complete satisfaction.

The above work has been carried out to my complete satisfaction. The installation engineer has explained the alternative aerials available, the prices and signal defects if any. I understand payment is due on completion and consent to the removal of the aerial at any time during working hours in default of payment. I further agree to indemnify the installer against any losses incurred by default of payment. The signing of the receipt in no way invalidates your rights of common law.

Engineer Signature	Cust	tomer Signature	
Print Name	Date   3   0   14	Date 13 10 14	

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: <a href="mailto:arlawrencemail@aol.com">arlawrencemail@aol.com</a>

### MITRE HOUSE MANAGEMENT LTD

7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

INVOICE F/10/14

DATE	24 OC	CTOBER 2014	YOUR REF	DEREK ISAACS	OUR REF: AD	<u>W/4474/LV</u>	<u>V</u>
				PAUL BROWN-CONS	STABLE		
REC	QUES	ST FOR PA	AYMENT				
APPL	ICATIO	N FOR PAYME	ENT ON ACCOU	INT NO. 2			
MITR	E HOU	SE, 124 KINGS	ROAD, LONDO	ON SW3			
To	Works	carried out to da	te, scaffold and r	naterials on site		32577	95
Less	Retenti	on @ 5%				1628	90
						30940	05
Less	Previou	us Application				10547	37
						20401	68
	Value A	Added Tax @ 2	20%			4080	34
					£	24482	02
For BA	CS payme	nt our details are as i	follows:-				
A/C Naı	me:	A R LAWRENCE &	& SONS LTD				
Sort Co	de:	40 45 17					
Account	t No.:	31260391					
Payment	t required in	n accordance with pay	ment certificate please				
A VAT 1	receipt will	be issued upon receip	ot of payment				

## **Chartered Surveyors**

**Established 1847** 10 Genotin Terrace, Enfield,

Middlesex, EN1 2AF

Tel: 020 8367 5100

Fax: 020 8366 3056

Your Ref: VAT Reg No 467 6205 30

D3827 Our Ref:

Date: 31<sup>st</sup> October 2014 Account No. 7905

Mitre House Management Limited, 7 Mitre House, 124 Kings Road, LONDON, SW3 4TP

Mitre House, 124 Kings Road, London SW3		
To continuing professional services in connection with the scheme for external repair/redecoration and redecoration of the internal common parts at the above property, including provision of CDM Co-ordinator services under the CDM Regulations 2007.		
Carrying out further inspections of the work in progress, issuing further Surveyors Instructions for certain variations to date and reporting to you.		
Fourth interim fee, based on 80% of agreed scale fee and calculated against original lowest tender received;		
80% of 11% (10% + 1% CDM) of £76,101.00 Less: Previous accounts up to and including account dated	£6,696.89	
22/09/14	£5,650.50	
	£1,046.39	
VAT @ 20%		£209.28
Further travelling and other disbursements to date.	£94.70	
VAT @ 20%		£18.94
Sub Totals	£1,141.09	£228.22
Total VAT	£228.22	
TOTAL	£1,369.31	



## Houseman Water Hygiene Specialists Ltd

19 Clifftown Road INVOICE NO JO2020

 Southend on Sea
 DATE
 6th November 2014

 Essex
 VAT- NO 912 1556 51

 SS1 1AB
 Co. Reg: 5539899

Tel: 0845 272 0881 Email: service@housemanwatertreatment.com

TO PAUL BROWN

MITRE HOUSE MANAGEMENT LTD

7 MITRE HOUSE 124 KINGS ROAD CHELSEA, LONDON

SW3 4TP

P.O. NUMBER	TERMS
0013/Ref email 6 October 2014	30 days

QUANTITY	DESCRIPTION	UNIT PRICE	LINE TOTAL
1.00	Tank Removal and Replacement	£4,875.00	4,875.00
INV. CODE			
WH/LW			
	_	SUBTOTAL	4,875.00
		VAT TOTAL	975.00
		TOTAL	£5,850.00

BACS DETAILS: SORT CODE 30-15-99 ACCT NO. 0506205

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: <u>arlawrencemail@aol.com</u>

### MITRE HOUSE MANAGEMENT LTD

7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

INVOICE B/12/14

DATE	2 DECEMBER 2014	YOUR REF	DEREK ISAACS	OUR REF: AD	W/4474/L	W	
			PAUL BROWN-CON	STABLE			
REQUEST FOR PAYMENT							
APPLICATION FOR PAYMENT ON ACCOUNT NO. 3							
MITR	E HOUSE, 124 KINGS I	ROAD, LONDO	N SW3				
То	Works carried out to date	e, scaffold and n	naterials on site		47887	10	
Less	Retention @ 5%				2394	35	
					45492	75	
Less	Previous Application				30949	05	
					14543	70	
	Value Added Tax @ 20	)%			2908	74	
				£	17452	44	
For BAC	CS payment our details are as fo	llows:-					
A/C Naı	me: A R LAWRENCE &	SONS LTD					
Sort Co	de: 40 45 17						
Account	Account No.: 31260391						
Payment required in accordance with payment certificate please							
A VAT 1	A VAT receipt will be issued upon receipt of payment						

## **Chartered Surveyors**

**Established 1847** 

10 Genotin Terrace, Enfield,

Middlesex, EN1 2AF

Tel: 020 8367 5100

Fax: 020 8366 3056

Your Ref: VAT Reg No 467 6205 30

D3827 Our Ref:

Date: 9<sup>th</sup> December 2014 7938 Account No.

Mitre House Management Ltd., 7 Mitre House, 124 Kings Road, LONDON, SW3 4TP

Mitre House, 124 Kings Road, London SW3		
To continuing professional services in connection with the scheme for external repair/redecoration and redecoration of the internal common parts at the above property, including provision of CDM Co-ordinator services under the CDM Regulations 2007.		
Carrying out further inspections of the work in progress, issuing further Surveyors Instructions for certain variations to date and issuing further payment certificates.		
Fifth interim fee, based on 90% of agreed scale fee and calculated against original lowest tender received;		
90% of 11% (10% + 1% CDM) of £76,101.00	£7,533.99	
<u>Less</u> : Previous accounts up to and including account dated 31/10/14	£6,696.89	
	£837.10	
VAT @ 20%		£167.42
To also organising joinery repairs to the various flat windows, inspecting the windows in detail, preparing and costing separate window repair schedules for the windows at the front and rear of each flat as applicable and reporting to you.		
Fee, based on agreed scale and calculated against net cost of window repairs;		
10% of £6,770.00	£677.00	
VAT @ 20%		£135.40
Further travelling and other disbursements to date.	£103.50	

VAT @ 20%		£20.70
Sub Totals	£1,617.60	£323.52
Total VAT	£323.52	
TOTAL	£1,941.12	

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

### MITRE HOUSE MANAGEMENT LTD

7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

INVOICE D/12/14

DATE	17 DECEMBER 2014	YOUR REF	DEREK ISAACS	OUR REF: AD	)W/4474/I	<u>.W</u>		
			PAUL BROWN-CONST	TABLE .				
REQUEST FOR PAYMENT								
FINAL ACCOUNT								
MITR	E HOUSE, 124 KINGS RO	OAD, LONDO	N SW3					
То	Final Contract Sum				54528	40		
Less	Retention @ 2.5%				1363	21		
					53165	19		
Less	Previous Application				45492	75		
					7672	44		
	Value Added Tax @ 20%	o O			1534	49		
				4	0206			
				£	9206	93		
For BA	CS payment our details are as follo	ws:-						
A/C Nai		ONS LTD						
Sort Co	de: 40 45 17							
Account	No.: 31260391							
Payment	required in accordance with paymer	nt certificate please						
A VAT	A VAT receipt will be issued upon receipt of payment							

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482 E-mail: arlawrencemail@aol.com

MITRE HOUSE MANAGEMENT LTD 7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

INVOICE D/12/14

**RECEIPT 4067**VAT REG NO. 652 8482 15

DATE	30 JANUARY 2015	YOUR REF	DEREK ISAACS PAUL BROWN-CONS		W/4474/LV 	<u>Y</u>
	CEIPT & TAX I	<u>NVOICE</u>				
MITR	RE HOUSE, 124 KINGS R	ROAD, LONDO	N SW3			
То	Final Contract Sum				53000	00
Less	Retention @ 2.5%				1325	00
					51675	00
Less	Previous Application				45492	75
					6182	25
	Value Added Tax @ 20	%			1236	45
				£	7418	70
	YMENT RECEI WRENCE & SONS LTD	VED WIT	THANKS			

## **Chartered Surveyors**

**Established 1847** 

10 Genotin Terrace,

Enfield,

Middlesex, EN1 2AF

Tel: 020 8367 5100

Fax: 020 8366 3056

VAT Reg No 467 6205 30

Date: 29<sup>th</sup> January 2015

Your Ref:

D3827 Our Ref: Account No. 7957

Mitre House Management Ltd., 7 Mitre House, 124 Kings Road, LONDON, SW3 4TP

Mitre House, 124 Kings Road, London SW3		
To continuing professional services in connection with the scheme for external repair/redecoration and redecoration of the internal common parts at the above property, including provision of CDM Co-ordinator services under the CDM Regulations 2007.		
Carrying out further inspections of the work in progress, snagging the works towards completion, issuing Snagging Lists to the contractor and issuing the Certificate of Practical Completion. To also agreeing the contractor's final account in the sum of £53,000.00 plus VAT and issuing a further payment certificate.		
Sixth interim fee, based on 97½% of agreed scale fee and calculated against original lowest tender received;		
97½% of 11% (10% + 1% CDM) of £76,101.00 Less: previous accounts up to and including account dated	£8,161.83	
09/12/14	£7,533.99	
	£627.84	
VAT @ 20%		£125.57
Further travelling and other disbursements to date.	£34.20	
VAT @ 20%		£6.84
Sub Totals	£662.04	£132.41
Total VAT	£132.41	
TOTAL	£794.45	



# MITRE HOUSE MANAGEMENT LIMITED

(Representing The Nine Leasehold Owners Of Mitre House)

124 Kings Road • Chelsea • London SW3 4TP Email: management@mitrehouse.com • www.mitrehouse.com Telephone +44 (0)20 7589 7502 or Mbl +44 (0)798 33 33 543

31 December 2014

Service Charge Account c/o Flat 7 Mitre House 124 Kings Road London SW3 4TP

INVOICE/00014 0007

#### **Mitre House**

Additional Works included in the £31,756.21 savings made from the 22 June 2014 s.20 approved budget of £105,019

**RE:** Additional workings, costs and fees from July 2011 to 31st Dec 2014 by Mitre House Management Limited in the execution of the 2014 Internals & Externals programme.

(1) Source various competitive quotations (approx three per item) and estimates for all intended works. Serve and issue relevant notices, notifications to all lessees, supplying all references required and posting all on Mitrehouse.com website. Make required specifications and brief and liase with Surveyor and arrange all required section notice tenders and advise and inform all lessees in correspondence and post all on website. Supplying full colour design proposals (4 drafts) full colour voting preferences, full colour analyses of all quotes and tenders received, all of which sent direct to all lessees with instructions on how to compute and posted on the website.

All for £1,500. 00

(2) Full supervision and project managing the full works' programme including managing both the new Water Tank and TV/Sky installations, insisting on required 100% agreements in place of usual notices and collection of funds to progress including renegotiating a discount, and making required savings of £31,756.21 to progress "additional works" not specified or included in the initial tender quotations sourced by our Surveyor

All for £1,500. 00

### (3) Major and Minor workings executed by MHML:

(3a) Total and complete renovation and refurbishment of the Lift car, the interior and exterior structure, doors, architrave and netting surrounds - to include full and comprehensive rub down, wash down and preparation for correct and professional metallic spray paint. Fitting of bronze acrylic mirrors to lift car interior and tiling interior with lightweight cork tiles and affixing all required safety signage and light fitments including sand blasted trellis decals.

All for £2,500. 00



(3b) Design, build and install three unique removable Meter Cupboards with circular meter windows ribbed in coloured beeding and with soft health and safety "baby proof" surrounds due to height limitations. To also include full boxing in and stapling of frontage on three floors of "untidy" stray cabling. To also include Shop Signage (4) design art and installation plus (2) additions.

All for £1,051.79

(3c) Arranging, measuring, installing wooden handrails on all floors including ground floor "foyer" entrance hall - adding brass end pieces to all units.

All for £1,500. 00

(3d) Design, build and install 12 piece mail pigeon box table with veneer top cork surrounds and brass furniture to suit re: x 9 flats and misc.

All for £572.85

(3e) From hired equipment, make good and repair and chemically clean, including power stripping in places of terrazzo flooring on all landings, stairs, and hall ways to the best condition possible.

All for £2,250.00

(3f) Various misc workings throughout: steam cleaning, sanding and polishing all bronze window partitions on three floors, brass buttoning all box panels throughout, repairing, renovating, and re-varnishing all doors and partition double doors, re-invigorating all brass self closers, removing and reinstalling after renovating and re-enameling all brassworks throughout, designing and installing new "Mitre House" signage at front entrance, designing and installing all required signage throughout Mitre House including fire safety and Health & Safety signage (No Smoking, CCTV etc), stripping and easing all Crittall Windows to have them ruined by sloppy workmanship and painting (to be re-done), total clearout and disposal of rubbish from roof, lift rooms and basement area, arranging and helping install all new Light Fitments, additional mains plug points and auto sensors on all lights throughout Mitre House to include Emergency Lighting on all floors including exterior fire escape and escape exits, installing brass door "hold backs" on all doors throughout Mitre House, new locks on rear Fire Escape doors (4), new brass bolts and signage and furniture on all doors throughout Mitre House including roof doors for Lift access rooms, painting & decorating third colour Metallic Gold on all exposed pipeworks throughout Mitre House and of the entire green dado rail, organising new matting throughout Mitre House including complimentary mats for all 9 lessees, sourcing and installing "special" silver Chubb Fire Extinguishers on all floors including lift access room and basement area, installing mail table mirror.

All for £2,500. 00

(3h) Costs incurred & paid by MHML/PBC on all above

£2,198.21

(3i) Various legacy items from 2011 - 2014 throughout Mitre House. No charge to date for legacy items such as Christmas tree and decorations, plants, artworks, misc artifacts, clocks, mirrors etc - and most especially the gardening efforts for the benefit of all lessees to include numerous window boxes on fire escape and potted plants in rear yard including interior stands and plants.

#### **GRAND TOTAL** Due to MHML for the works performed,

£15,572.85

Due to MHML for works performed £15,572.85 Supplies costs for MHML additional works

paid from Service Charge £16,183.36

Total Spent/Savings made £31,756.21

## Schedule of Works, Workings and Administration:

Nov/Dec 2011 - arranging quotations

2012 - arranging, discussing, preparation of Interior Decor Presentations, emails, correspondence etc 2012 (6 July) Issuing and overseeing s.20 Notices - withdrawn

2013 - arranging, discussing, preparation of Interior Decor Presentations, emails, correspondence etc 2013 (7 January) Issuing and overseeing s.20 Notices -

2013 (21 June) Issuing and overseeing s.20 Notices 2 - withdrawn

2013 (13 December) Issuing and overseeing s.20 Notices -

2013 - arranging, discussing, preparation of Schedule of Works with Surveyor

2014 - arranging, discussing, preparation of Interior Decor Presentations, emails, correspondence etc

2014 - arranging, discussing, preparation of Tenders of Schedule of Works with Surveyor

2014 (25 March) Issuing and overseeing s.20 Notices 2

2014 (22 June) Issuing and overseeing s.20 Notices 3 - approved

2014 - Project Management of £105,019 Budget for Internals/Externals

2014 - Project Management raising required funding for Internals/Externals

2014 - Project Management for replacement Water Tank and arranging funding

2014 - Project Management for Communal TV Sky install and arranging funding

2014 - Project Management on negotiating funding for additional works all done within £105,877 cost:

- a) installing and arranging and planning Emergency Lighting throughout incl. fire escape (ext)
- b) installing and arranging and planning new light fitments throughout communal areas
- c) installing and arranging and planning new light switches throughout building
- d) installing and arranging and planning new auto sensors on all floors and exterior fire escape
- e) installing planning and arranging new mains wiring throughout building for (a) and (b) above
- f) arranging all H&S inspections, Fire, Asbestos, Water, Electrics plus full reports/certificates
- f) arranging all H&S inspections, Fire, Asbestos, Water, Electrics plus full reports/certificates
- g) arranging and overseeing TV Sky installation, clearing rooftop, and preparing wiring plans
- h) arranging and overseeing replacement Water Tank installation and misc workings
- i) arranging and overseeing full decor renovation of lift exterior, doors, car decor and cage spraying
- j) arranging and overseeing main front door (interior architrave) removal and install
- k) arranging and installing and designing main entrance new Mitre House brass signage
- I) arranging and installing new Entryphone Brass Bell Push unit with required re-wirings
- m) arranging and installing all required (best quality/brass) signages throughout Mitre House
- n) arranging and installing replacement locks to all rear doors on each floor
- o) arranging planning, designing and installing Meter Boxes on each floor
- p) arranging planning, designing and installing wiring box enclosures on each floor
- q) arranging planning designing and installing required shop signages
- r) arranging planning and assisting (on a Sunday) BT wiring tidy up and sorting wiring (6 hours)
- s) removing as required all old redundant BT, TV, cable on exterior and roof
- t) removing and cleaning (properly professionally) all brass fitments throughout building

- u) removing and replacing any old brass furniture, incl. to main front door exterior/interior mailbox
- v) arranging planning and building hall mail pigeon box table and artifacts (brass number plates)
- w) arranging planning and fitting all artifacts, mirrors, plants etc throughout building
- x) dismantling old unit and fitting new teak handrail and fitting brass end pieces throughout building
- y) removing and replacing all every old screws throughout building and replacing with new
- z) removing old nuts from panelling on each floor and replacing with new fitments
- aa) stripping back all old varnish dirt on all window panelling and bringing back to original bronze
- bb) throughly cleaning and restoring all window twin door panelling on each floor
- cc) stripping all door edgings on each floor throughout to remove all burrs and wear markings
- dd) removing and installing new matting to main front entrance and lift
- ee) arranging cleaning and restoring full terrazzo floor clean to very acceptable level and also
- ff) arranging and installing special Chub Silver Fire Extinguishers throughout building
- gg) cleaning, decorating and renovating ground floor cleaner's cupboard incl water heater install
- hh) arranging, and overseeing full cleanup after Thames Water flooding of basement and shops
- ii) sorting and overseeing full Asbestos review after flooding of basement area
- jj) project managing entire works from Sunday 31st August (Scaffolding up) to Christmas Eve 24 December 2014



(REPRESENTING THE NINE LEASEHOLD OWNERS OF MITTE HOUSE)

124 Kings Road • Chelsea • London SW3 4TP Email: management@mitrehouse.com • www.mitrehouse.com Telephone +44 (0)20 7589 7502 or Mbl +44 (0)798 33 33 543

30 December 2014

Mitre House Service Charge a/c Mitre House 124 Kings Road London SW3 4TP

#### STATEMENT OF ADDITIONAL WORKS' COST PAID FROM RESERVES/CURRENT ACCOUNT

RE: Works' Supplier Costs over and above paid to AR Lawrence (ref Schedule of Works) were as follows:

#### Direct Fitment Purchases:

St_01_TLC Ltd (Electrics)	£24.36
St_01_Wood Finishes Direct (Supplies)	£53.50
St_01_Sandblasting (cash)	£350.00
St_04_Universal Lighting (Light units)	£382.23
St_04_Heart Of England (Brasses)	£24.00
St_04_Universal Lighting (Light units)	£1369.89
St_04_National Lighting (Light units)	£282.00
St_04_BES Electrics (Internal Electricals)	£1200.00
St_05_Handrail Direct (Handrails)	£40.00
St_05_Universal Lighting (Light units)	£65.10
St_05_Leylands (Supplies)	£113.65
St_05_Peter Jones (Lampshades)	£76.00
St_05_YMCA (Lampshades)	£12.96
St_06_Sign Builder (Shop Signage)	£47.28
St_06_Sign Builder (Shop Signage)	£47.28
St_06_Sign Builder (Shop Signage) credit	(£8.28)
St_06_Sign Builder (Shop Signage)	£45.48
St_06_Peter Jones (Lampshades) credit	(£28.00)
St_07_LED Hut (Bulbs)	£7.82
St_07_Sign Builder (Shop Signage) credit	(£8.28)
St_07_Sign Builder (Shop Signage)	£80.04
St_07_BES Electrics (Internal Electricals)	£1200.00
St_07_Sign Builder (Shop Signage) credit	(£8.28)
St_07_Brunei Engraving (Front Signage)	£148.02
ST_07_LED Hut (Bulbs)	£311.04



Main Supplier Purchases' Total	£10,089.43
Misc Amazon & others as per Analysis 2014	£6,093.93
TOTAL COSTS	<b>£16,183.36</b>
(plus MHML workings & fees)	£15,572.85
TOTAL BUDGET (Saved) SPENT	£31,756.21

	В	С	D	Е	F	G
2						
3	2	014 Additiona	Works	Costs		
4						
5 6						
7						
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS	SERVICE	
9				BUDGET	CHARGE	
11						
12						
13 14						
15						
16						
17						
18 19						
20	, , , , , , , , , , , , , , , , , , , ,					
21						
22						
24						
25						
26 27						
28						
29						
30 31						
32						
33						
34 35						
36						
37						
38 39						
40						
	pbc/cash	That's Andy misc	3.50		2.17	
42						
44	st 01	TLC Southern Electrics	24.36	24.36		
45						
46 47						
48						
49						
50 51						
52						
53						
54 55						
56						
57						
58						
59 60						
61						
62						
63 64						
65						
66						
67						
68	l					

	В	С	D	E	F	G
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS	SERVICE	
9				BUDGET	CHARGE	
10						
69 70						
71						
72						
73						
74						
75						
76 77						
78						
79						
80						
81	st 01	Woodfinishes	53.50	53.50		
82 83						
84						
85						
86						
87						
88 89						
90						
91						
92						
93						
94	PC_25	SANDBLASTING	350.00	350.00		
96	PC_25	SANDBLASTING	350.00	350.00		
97						
98						
99						
100						
101 102						
103						
104						
105						
106						
107 108						
109						
110						
111						
112						
113 114			-			-
115						
116						
117						
118						
119						
120 121						
122						
123						
124						
125						
126						
127 128						
129			-			
130						
131						
132						
133						

	В	С	D	Е	F	G
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS	SERVICE	
9				BUDGET	CHARGE	
10						
134 135						
136						
137						
138						
139						
140						
141 142						
143						
144						<u> </u>
145						
146						
147 148						
149				<del> </del>		
150						
151						
152						
153 154			_			ļ
155						
156						
157						
158						ļ
159 160						
161						
162						
163						
164						
165						
166 167				-		
168						
169						
170						
171						
172 173						
174						
175						
176						
177						
178 179						
180						-
181				-		<u> </u>
182						
183						
184						
185 186						
187						<del> </del>
188			1			
189						
190						
191						
192 193						-
193			-			
195				-		<del> </del>
196						
197					-	
198						

	В	С	D	E	F	G
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS BUDGET	SERVICE CHARGE	
10				BUDGET	CHARGE	
199						
200						
201						
202 203						
203						
205						
206						
207						
208						
209 210						
211						
212						
213 214						
214						
216						
217						
218						
219 220						
221						
222 223						
223						
224 225						
226						
227						
228 229 230						
229						
230						
232						
233						
234						
235	pbc/© EE	Amazon Colour Guide	5.58	5.58		
236 237						
238						
239						
240						
241 242						
242						
244						
245						
246	pbc/FF	Amazon Dulux ben	11.48	11 40		
247	hnr/ LL	אווומבטוז טעועג טפוז	11.48	11.48		
249						
250						
251						
252 253						
254						
255						
256						
257	st_04	Universal Lighting x 2	202.00	202.00		
259	JL_U <del>1</del>	oniversal Lighting X Z	382.00	382.00		
260						
261						
262						
263		1				

	В	С	D	E I	F	G
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS	SERVICE	
9				BUDGET	CHARGE	
10						
264						
265						
	segar/pbc	Waitrose Mop & Cleaner	12.14		12.14	
	pbc/in	Sainsbury	4.40		4.40	
268						
269 270						
	st 04	Heart Of England	24.00	24.00		
	st_04	Universal Lighting x8	1,369.89	1,369.89		
273	30_01	Oniversal Lighting XO	1,505.05	1,505.05		
274						
275						
	st 04_12	Amazon 60w bulbs	17.85	17.85		
277	st 04_13	Amazon 40w bulbs	17.97	17.97		
278						
	st_04	National Lighting	282.00	282.00		
280		DEC EL	1 205 55	1 202 25		
	st_04	BES Electrics	1,200.00	1,200.00		
282						
283	st 05_14	Amazon White Spirit (lift)	29.90	29.90		
285	31 03_14	Amazon write Spirit (iiit)	23.30	23.30	-	
	st_05	Handrails samples	40.00	40.00		
	st 05_15	Amazon Sprays x 20 (lift)	165.58	165.58		
	st 05_16	Amazon Voltage	20.99	20.99		
289						
290	st 05_17	Amazon protectors	35.90	35.90		
291						
292						
	st 05_19	Amazon (Hammerriteetc)	47.51	47.51		
	st 05_18	Amazon (filler cement)	17.28	17.28		
	st 05_20	Amazon (Damp Sealer)	56.55	56.55 165.58		
	st 06_24 st 05_21	RUSTOLEUM x 20 again Amazon (Hammerite x 2)	165.58 46.95	46.95		
	st_05_21	Universal lighting	65.10	65.10		
299		Oniversal lighting	05.10	05.10		
	pbc/cash-X	Homebase (Filler)	7.99	7.99		
301						
302						
	pbc/inv	Andys (Various Cleans)	18.98		18.98	
	pbc/cas_G	Goulds (Bonding)	5.50	5.50		
	st_05	Leylands	113.65	113.65		
306		Deter lenes (10 shedes)	76.00	76.00		
	st_05 pbc/TT	Peter Jones (10 shades) Newframes	76.00 14.35	76.00 14.35		
	st_05	YMCA (Shades x 4)	12.96	12.96		
	st 05_22	Amazon LED Bulbs x 8	67.92	67.92		
311			07.52	37.32		
312						
313	st 05_23	Amazon (Strip It x 4)	39.88	39.88		
	st 06_30	Amazon (Strip Polycel x 4)	27.28	27.28		
	st 06_25	Amazon (Strip Pads)	4.25	4.25		
316		ļ				
	st 06_27	Amazon (Abrasive Pads)	10.60	10.60		
318		Amazon (Hammorita Cra-	15.27	1		
319	st 06_28	Amazon (Hammerite Cream	15.37	15.37		
	st 06_26	Amazon (tools)	9.90	9.90		
	st 00_20 st 07_29	Amazon Oxide+brushes	27.08	27.08		
323		azon oxide i bidolico	27.00	27.00		
	st_06	Sign Builder Sassoon	47.28	47.28		
	st_06	Sign Builder Scribbler	47.28	47.28		
326	st_06_31	Amazon	35.70	35.70		
327						
328	st_06	Sign Builder Credit above2	(8.28)	(8.28)		

	В	C	D	E	F	G
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS	SERVICE	
9	710 1101		7	BUDGET	CHARGE	
10						
329	st_06_32	Amazon	1.75	1.75		
	st_06	Sign Builder Neal's Yard	45.48	45.48		
331	st 06_36	Amazon (10 x tin mugs)	49.90	49.90		
332	st_06	Peter Jones CREDIT shades	(28.00)	(28.00)		
333						
	st 06 34	Amazon (Karcher)	14.06	14.06		
-	st 08_38	Amazon (Karcher)	10.99	10.99		
	st 06_35	Amazon (Karcher etc0	349.99	349.99		
	st 06_37	Amazon (Karcher)	9.81	9.81		
	st 07 41	Amazon (Karcher misc)	41.78	41.78		
	st_06_33	Amazon	124.25	124.25		
	st_06	LEDHUT 1 x golfs bulbs)	7.82	7.82		
	st 06_40	Amazon (3 x golfs bulbs)	20.94	20.94		
	st 06_39	Amazon (tracing paper)	18.55	18.55		
	st_07	Signbuilder credit	(8.28)	(8.28)		
	st_07	SignBuilder (MHML&ARL)	80.04	80.04		
	st 07_42	Amazon (Protectors x 3)	47.97	47.97		
	st 07 44	Amazon (Karcher Water)	235.00	235.00		
	st 07_43	Amazon (Karcher Cleaner)	17.99		17.99	
	st 09_61	Amazon (Protectors)	80.16	80.16		
	pbc/cab_E	Wood Floor Protectors	15.00	15.00		
	st_07	BES Electrics (Pt2)	1,200.00	1,200.00		
	st_07	Signbuilder (credit)	(8.28)	(8.28)		
	st 07_45	Amazon (Brass)	3.75	3.75		
353		B	140.00	140.00		
354	st_07	Brunel Engraving	148.02	148.02		
	st 08_46	Amazon (2/2222)	F 00	F 00		
	st 08_46 st 08_47	Amazon (s/paper) Amazon (Course S/paperx2)	5.99 13.68	5.99 13.68		
358	St 08_47	Amazon (Course S/paperxz	13.08	13.08		
	st 07 50	Amazon (3 mats)	27.15	27.15		
	st 07_50 st 07_51	Amazon (4 mats)	39.80	39.80		
	st 07_51 st 07_52	Amazon (5Mats)	39.95	39.95		
	st 07_52 st 07_53	Amazon (6 mats)	54.30	54.30		
363	507_33	Amazon (o mats)	34.30	34.30		
	st_07	LED HUT (60 bulbs)	311.04	311.04		
	st 07 54	Amazon (blades)	6.98	6.98		
	st 07_51	Amazon (Glue)	7.90	7.90		
	st 07_56	Amazon (Bits)	10.00	10.00		
	st 07_57	Amazon (tool)	4.99	4.99		
	st 08_58	Amazon (Glue)	14.85	14.85		
	st 08_60	Amazon (Spray/Meters)	65.40	65.40		
	st_08	Brunel additional logo	36.00	36.00		
372	st_07_48	Amazon Crimpers	16.95	16.95		
	st 07_49	Amazon (Iron Mat)	21.98	21.98		
374						
375						
376						
377						
378						
	st_08	LED hut cr	(12.98)	(12.98)		
	st_08	LED hut cr	(12.98)	(12.98)		
	st 08_62	Amazon (Glue)	14.85	14.85		
	st 09_59	Amazon (Brass)	33.50	33.50		
	st 08_65	Amazon (Brass Knob)	20.99	20.99		
	st 09_63	Amazon (rubber surround)	15.99	15.99		
385						
	st 09_64	Amazon (stone spray x 3)	20.97	20.97		
	st 08_66	Amazon (Brass)	33.50	33.50		
388						
389						
	st_08	Allbert Construction	648.00	648.00		
391						
392						
393						

	В	С	D	E	F	G
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS	SERVICE	
9				BUDGET	CHARGE	
10						
394						
395						
396						
397	st 09_68	Amazon (drill bits)	26.54	26.54		
	st 09_67	Amazon (drill bits)	4.99	4.99		
	st_09	Newframes (glazing)	14.35	14.35		
	PC_26(pt)	Tony (Pip Lifts)	200.00	200.00		
401						
	st_09	Handrails Direct	754.00	754.00		
	st 09_69	Amazon (letterbox)	31.75	31.75		
	st 09_71	Amazon (Medusa)	11.95	11.95		
	st 10 _72	Amazon (2 x knobs)	39.48	39.48		
	st 9_73	Amazon (brass ends)	87.10	87.10		
	st_09	Door Handle Co	156.30	156.30		
	st_09	Carpettime Coir Matting	86.00	86.00		
	st 09_70	Amazon (No.2)	2.18	2.18		
	st_09	Ironmongery Direct	153.72	153.72		
	pbc/KK	Amazon (Brass)	18.75	18.75		
412	st_09	Heart Of England Brass	38.28	38.28		
413						
415						
415						
417						
418						
419						
420						
	st 11_74	Amazon (TV aerial)	21.40	21.40		
	st 11_75	Amazon (9 x tv cable)	24.75	24.75		
423	00 22_/ 0	/a_a (5 // cv aaa)				
424						
425						
	st 11_76	Amazon (Books)	23.94	23.94		
	st 11_77	Amazon (Drill)	99.95	99.95		
428	pbc/SS	Heart of England	82.80	82.80		
429	st 10_78	Amazon (chuck)	17.71	17.71		
430						
	pbc/NN	Amazon	39.28	39.28		
432	pbc/MM	Amazon9cement)	14.66	14.66		
	pbc/LL	Amazon (cement)	8.78	8.78		
	pbc/OO	Amazon (cement)	11.66	11.66		
	st_10	Eclipse (Ross BT)	75.00	75.00		
436						
437						
438						
	st 11_81	Amazon (tidy)	26.85	26.85		
	st 11_80	Amazon (tidy)	8.95	8.95		
	st 10_86	Amazon (Spray x 20)	165.58	165.58		
	PC_26(pt)	Tony (Lift cage spray)	100.00	100.00		
	st 10_82	Amazon (blades)	4.49	4.49		
	st 10_83	Amazon (cable ties)	5.28	5.28		
445	st 11_84	Amazon (Tidy)	21 25	21.25		
		Amazon (Tidy)	31.35	31.35		
	st 11_85 st 10_79	Amazon (conduit & clips)	2.49 2.09	2.49 2.09		
	st 10_/9 st 10_88	Amazon (blades)	9.95	9.95		
449		Amazon (tools)	9.95	9.95		
450						
	st 11_90	Amazon (Cording)	1.46	1.46		
	st 11_90 st 11_91	Amazon (Cording)	2.99	2.99		
	st 11_91 st 11_92	Amazon (w/plugs)	4.12	4.12		
	st 11_92 st 11_93	Amazon (Filler)	4.12	4.41		
	st 11_94	Amazon (tape)	4.50	4.50		
	st 11_95	Amazon (bits)	5.24	5.24		
	st 11_96	Amazon (cordings)	5.72	5.72		
	<u> </u>		J., _	J., _		L

	В	C	D	E	F	G
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS	SERVICE	
9				BUDGET	CHARGE	
10						
	st 11_97	Amazon (Cordings)	6.19	6.19		
	st 11_98	Amazon (bits)	6.40	6.40		
	st 11_99	Amazon (arrowheads)	7.50	7.50		
	st 11_100	Amazon n(bits)	9.00	9.00		
	st 11_101 st 11_102	Amazon (bits) Amazon (bits)	13.33 15.39	13.33 15.39		
	st 11_102	Amazon (cordings)	21.78	21.78		
466	30 11_103	/mazon (cordings)	21.70	21.70		
467						
	st 11 106	Amazon (tv)	1.57	1.57		
	st_10_89	Amazon Workbench	101.49	101.49		
	st_10	Acrylics R us	11.40	11.40		
	st 11_107	Amazon (graphite)	5.00	5.00		
	st 13_108	Amazon (s/paper0	7.64	7.64		
	st 13_109	Amazon (Silicone)	12.86	12.86		
	st 13_110	Amazon )s/paper)	27.96	27.96		
	st 11_111	Amazon (s/paper)	3.58	3.58		
	st 12_113 st 13_114	Amazon (tools)	5.77 19.50	5.77 19.50		
	st 13_114 st 11_112	Amazon (tools) Amazon (Sand/p etc)	5.95	5.95		
	st 11_112 st 11_104	Amazon (level)	25.57	25.57		
	st_11_104 st_11_105	Amazon	33.00	33.00		
	st 11	DoorHandleCo	49.87	49.87		
482	<del></del>					
483						
484						
485						
	st 12_119	Amazon (screws)	5.35	5.35		
	st 12_120	Amazon (Screws)	7.27	7.27		
488	-+ 12 122	A	22.50	22.50		
	st 12_122 st 13_123	AmazonSilvertrade Amazon (screws)	22.50 47.73	22.50 47.73		
	st 12_124	Amazon (screws)	6.90	6.90		
	PC_27	Mike Water Tank etc clean	50.00	50.00		
	st_12	Acrylics Rus (Trellis Mirrors)	385.98	385.98		
	pbc/QQ	Amazon (scratch repair)	45.06	45.06		
	st 13_125	Amazon (polish)	11.49	11.49		
496	st 14_126	Amazon (Glass Polish)	43.44	43.44		
	st 12_130	Amazon ( Polish)	15.30	15.30		
	st 12_127	Amazon (polish)	6.76	6.76		
	st 12_128	Amazon (cleaners)	7.30		7.30	
	st 14_129	Amazon (Barkeeper etc)	14.04		14.04	
501	st 14_132	Amazon (cloths)	3.84		3.84	
	st 13 133	Amazon (screws)	15.68	15.68	5.04	
$\overline{}$	st 13_133	Amazon (restorer)	16.96	16.96		
505	<u></u> -			20.50		
	st 14_135	Amazon	22.97	22.97		
507	st 13_136	Amazon (paint)	26.28	26.28		
	st 14_139	Amazon (mirror screws)	17.26	17.26		
	st 13_140	Amazon (screws)	56.58	56.58		
	st_12	Akzonobel Dulux	97.15	97.15		
511	st_13	Acrylics Rus (Lift Mirrors)	241.20	241.20		
	st 13_137	Amazon (solder)	13.47	13.47		
	st 14_138	Amazon (laquer)	14.40	14.40		
	st_13	Dulux Testers	36.15	36.15		
	st_13	Dukux Testers	79.15	79.15		
	st_13	Pegasus Delivery	19.74	19.74		
518						
	st 14_141	Amazon (bags)	16.22		16.22	
	st 14_142	Amazon (tools)	34.33	34.33		
	st 14_143	Amazon (tools)	39.50	39.50		
	st 35_144	Amazon (blades)	3.64	3.64	2.01	
523	st 13_145	Amazon (cleaners)	3.81		3.81	

	В	C	D	E	F	G
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS	SERVICE	<u> </u>
9	AC ICI	DESCRIPTION	AMOUNT	BUDGET	CHARGE	
10				DODGET	CHARGE	
	st 13 146	Amazon (Blades)	6.00	6.00		
	st 13_147	Amazon (tape)	7.49	7.49		
526		(60)				
	st 15_148	Amazon (Cork/Lift)	100.32	100.32		
	st 15 149	Amazon (glue)	6.95	6.95		
	st 13 141	Amazon bags	16.22	16.22		
	st 14 150	Amazon (cordings)	1.46	1.46		
531	st 14_151	Amazon (cordings)	2.44	2.44		
	st 14_152	Amazon (angles)	4.00	4.00		
533	st 15_153	Amazon (tape)	15.00	15.00		
	st 14_154	Amazon (soldering)	34.60	34.60		
	st 15_155	Amazon (tape)	17.50	17.50		
	st_14	Azkonobel (Dulux testers)	19.15	19.15		
	st 14_156	Amazon Prime	79.00	79.00		
	st_14	Leyland (Paints0	136.30	136.30		
539						
540						
541						
542						
543						
544						
	st_14	Leylands Paints Misc	138.08	138.08		
546						
547						
548						
549						
550 551						
552 553						
	st 14_157	Amazon (cleaners)	18.37		18.37	
	st 14_158	Amazon (tools)	11.54	11.54	10.57	
	st 15_159	Amazon (paint)	25.44	25.44		
	st 14 160	Amazon (tools)	34.16	34.16		
	st 14_161	Amazon (Dusters)	33.98	34.10	33.98	
559	50 1 1_101	/ Indzon (Busters)	33.30		33.30	
	st 14 162	Amazon (elec plates)	16.17	16.17		
561	50 11_102	/ indeen (elec places)	20117	10117		
562						
563						
564						
	inv/pbc_R	Leyland (tool/handrail)	13.98	13.98		
	PC_31	Workers/roof clean	10.00	10.00		
	st_14	Universal lighting x 3	345.60	345.60		
568						
569						
570						
	st 16_163	Amazon (misc)	33.77	33.77		
	st 16_164	Amazon (Misc)	136.06	136.06		
	st 15_165	Amazon (varnish)	43.49	43.49		
	st 16_166	Amazon (stripper)	16.14	16.14		
	st 15_167	Amazon (polisher brush)	48.48		48.48	
	st 15_168	Amazon (Floor Cleanse)	128.94	128.94		
	inv/pbc_S	Boots (Bicarb x 2)	2.58	2.58		
	inv/pbc_TT	Best One (Lighter Fuel x 3)	5.77	5.77		
	st_15	Senator Tools (misc)	45.13	45.13		
580						
581						
582						
583	ct 1E 1CO	Amazon (floor slasss)	26.70		26.70	
	st 15_169	Amazon (floor cleans)	26.79	150.00	26.79	
	st 15_170 st 15_171	Amazon (tools) Amazon (led bulbs x 15)	158.08 86.25	158.08 86.25		
	st 15_171 st 15_172	·	23.30	23.30		
		Amazon (s/paper0				
שמכן	st 15_174	Amazon (loops)	25.18	25.18		

### 2014 Additional Costs Analysis

	В	С	D	Е	F	G
8	Ac Ref	DESCRIPTION	AMOUNT	INTERNALS	SERVICE	
9				BUDGET	CHARGE	
10						
589						
590	pbc_18	Ian Cosmo (Electrician)	160.00	160.00		
591						
	st 16_175	Amazon (blades)	9.98	9.98		
593	st 15_176	Amazon (sanding sheets)	49.99	49.99		
594	st 17_177	Amazon (locks etc)	165.90	165.90		
595	st 16_178	Amazon (brummer)	7.40	7.40		
	st 16_179	Amazon (Brummer)	11.70	11.70		
597	st 16_180	Amazon (battery)	65.98	65.98		
598	st 17_181	Amazon (battery)	88.90	88.90		
599	st 67_182	Amazon (brummer)	6.92	6.92		
600	st 16_183	Amazon (cleaner)	1.98		1.98	
601	st 16_184	Amazon (brummer)	6.26	6.26		
602	st 16_185	Amazon (Brass)	17.45	17.45		
	st_15	HSS Hire	250.00	250.00		
	st 17_186	Amazon (end caps)	113.80	113.80		
	st 16_187	Amazon (duster)	6.63		6.63	
	st 17_188	Amazon (bulbs)	245.00	245.00		
607	st_16_189	Amazon	14.70	14.70		
608	st_16	Entryphone	209.88	209.88		
609	st_16	HSS Hire	(74.55)	(74.55)		
610						
611						
612						
613						
614						
615						
616						
617		Description	Amount	internals bdgt	service chg	
618			16,421.81	16,183.36	237.12	-
619						
620						

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

MITRE HOUSE MANAGEMENT LTD 7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

INVOICE D/6/15

DATE	17 JUNE 2015	YOUR REF	DEREK ISAACS PAUL BROWN-CONS	OUR REF: ADW/447. TABLE	4/LW 		
REQUEST FOR PAYMENT  MITTE HOUSE, 124 KINGS ROAD, LONDON SW3							
То	Retention Release				1325	00	
	Value Added Tax @	20%			265	00	
				£	1590	00	
	S payment our details are						
A/C Nam		E & SONS LTD					
Sort Code Account 1							
Account	No.: 31200391						
Payment r	required in accordance with	payment certificate	please				
A VAT re	ceipt will be issued upon rec	ceipt of payment					
					1	I	

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Mrs Michelle Hillgarth c/o Paul Brown-Constable MITRE HOUSE MANAGEMENT LTD 7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

RECEIPT / INVOICE 4036

VAT REG NO. 652 8482 15

DATE	E 8 OCTOBER 2014	YOUR REF	DEREK ISAACS	OUR REI	F: ADW/	4474/LW	
RE	CEIPT & TAX	INVOICE	7.				
KE	CEII I & IIIIX	mvolet	2				
MIT	RE HOUSE, 124 KINGS	S ROAD, LOND	OON SW3	4			
					10		
To	Front Elevation Windo	w Repairs to FI	LAT 5			445	00
	Value Added Tax @	20%				89	00
	· didd i idda i dii	_ 0 / 0					
					0	<b>504</b>	0.0
					£	534	vo

## PAYMENT RECEIVED WITH THANKS

A.R. LAWRENCE & SONS LTD

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Diego Fortunati c/o Paul Brown-Constable MITRE HOUSE MANAGEMENT LTD 7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

RECEIPT / INVOICE 4035

VAT REG NO. 652 8482 15

DATE	8 OCTOBER 2014	YOUR REF	DEREK ISAACS	OUR REF: AI	<u>) W/4474/LW</u>	
REC	CEIPT & TAX I	NVOICE	4			
MITRI	E HOUSE, 124 KINGS	ROAD, LOND	ON SW3			
То	Front Elevation Windov	v Repairs to FL	AT 9		365	00
	Value Added Tax @ 2	0%			73	00
				;	E 438	00
	MENT RECEI	VED WI	TH THANKS			
A.R. LAW	VRENCE & SONS LTD				74	

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Chelsea & Belgravia Investments Ltd c/o
Paul Brown-Constable
MITRE HOUSE MANAGEMENT LTD
7 MITRE HOUSE
124 KINGS ROAD
LONDON
SW3 4TP

RECEIPT / INVOICE 4034

VAT REG NO. 652 8482 15

DATE	8 OCTOBER 2014	YOUR REF	DEREK ISAACS	OUR REF: A	<u>ADW/44</u>	474/LW	
	E HOUSE, 124 KINGS						
То	Front Elevation Window	w Repairs to FL	AT 8			195	00
	Value Added Tax @ 2	0%				39	00
					£	234	00
	MENT RECEI	IVED WI	TH THANKS		ער.'		

**BUILDERS & DECORATORS** 

72 PINE WALK **CARSHALTON BEECHES SURREY** SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com Dr S F Riad EL Gharb Paul Brown-Constable

MITRE HOUSE MANAGEMENT LTD 7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

c/o

RECEIPT / INVOICE 4033

VAT REG NO. 652 8482 15

DATE	8 OCTOBER 2014	YOUR REF	DEREK ISAACS	OUR REF: ADW/-	4474/LW	
RE(	CEIPT & TAX	INVOICE	2			
			and the second			
MITR	E HOUSE, 124 KINGS	ROAD, LOND	ON SW3			
То	Front Elevation Windo	w Repairs to FL	LAT 4		595	00
	Value Added Tax @	20%			_119	00
				£	714	00

#### PAYMENT RECEIVED WITH THANKS

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Mr & Mrs E Leoni-Sceti c/o Paul Brown-Constable MITRE HOUSE MANAGEMENT LTD 7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

RECEIPT / INVOICE 4032

VAT REG NO. 652 8482 15

DATE	8 OCTOBER 2014	YOUR REF	DEREK ISAACS	OUR REF: ADW	/ <u>4474/LW</u>	
	E HOUSE, 124 KINGS					
То	Front Elevation Window	w Repairs to FL	AT 3		90	00
	Value Added Tax @ 2	0%			18_	00
				£	108	00
	MENT RECEI	VED WI	TH THANKS	" com		

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Mr Segar Karupiah c/o Paul Brown-Constable MITRE HOUSE MANAGEMENT LTD 7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

RECEIPT / INVOICE 4031

VAT REG NO. 652 8482 15

DATE	8 OCTOBER 2014	YOUR REF	DEREK ISAACS	OUR REF: ADW/4	1474/LW	
RE	CEIPT & TAX	INVOICE	$\Sigma$			
	RE HOUSE, 124 KING					
	Proceedings of the control of the co	aw Roungs to 13	AYT			0
То	Front Elevation Wind	ow Repairs to FI	LAT 2		345	0
	Value Added Tax @	20%			69	0
				£	414	00

## PAYMENT RECEIVED WITH THANKS

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Paul Brown-Constable MITRE HOUSE MANAGEMENT LTD 7 MITRE HOUSE 124 KINGS ROAD LONDON SW3 4TP

RECEIPT / INVOICE 4030

VAT REG NO. 652 8482 15

DATE	8 OCTOBER 2014	YOUR REF	DEREK ISAACS	OUR REF: ADW	<u>//4474/LW</u> 	
REC	CEIPT & TAX	INVOICE	2			
MITR	E HOUSE, 124 KINGS	ROAD, LOND	ON SW3			
То	Front Elevation Window	v Repairs to FL	AT 1		625	00
	Value Added Tax @ 2	0%			125	00
				£	750	00
PAY	MENT RECEI	VED WI	TH THANKS			

Boyce Evens & Carpenter, Chartered Surveyors,		
10 Genotin Terrace,	Date	15 <sup>th</sup> September 2014
Enfield,	LIN	D2027
Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

#### FLAT 1 – SCHEDULE OF WINDOW REPAIRS

1.	To Window 21, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 850mm.	£95.00
2.	To Window 21, carry out 150mm length splice repair to base of right hand pulley stile using Repair Care repair method C4.	£45.00
3.	To Window 21, remove decayed timber from base of external lining to right hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
4.	To Window 22, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 850mm approx.	£95.00
5.	To Window 22, remove decayed timber from base of right hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.	£25.00
6.	To Window 22, remove decayed timber from base of external lining to right hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
7.	To Window 23, carry out conservation joint repair to left hand end of bottom rail to top sash using Repair Care repair method P2.	£25.00
8.	To Window 23, remove decayed timber from right hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
9.	To Window 23, remove decayed timber from base of external lining to right hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
10.	To Window 24, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 850mm approx.	£95.00

11.	To Window 24, remove decayed timber from base of right hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
12.	To Window 25, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 850mm approx.	£95.00
13.	To Window 25, remove decayed timber from base of right hand perimeter architrave and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
	Sub Total	£625.00
	VAT @ 20%	£125.00
	TOTAL	£750.00

Boyce Evens & Carpenter,		
Chartered Surveyors,		
10 Genotin Terrace,	Date	15 <sup>th</sup> September 2014
Enfield,		
Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

#### FLAT 2 – SCHEDULE OF WINDOW REPAIRS

1.	To Window 26, remove decayed timber from both ends of bottom rail to bottom sash and carry out two pack filler repairs using Repair Care repair method C1, each repair size < 50 cm <sup>3</sup> in volume.	£50.00
2.	To Window 26, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 850mm approx.	£95.00
3.	To Window 26, carry out 200mm length splice repair to base of external lining to right hand box frame jamb using Repair Care repair method C4.	£65.00
4.	To Window 26, remove decayed timber from base of external lining to left hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
5.	To Window 77, replace 1 No. cracked pane glass to top sash with clear sheet glass, size 260 x 330mm approx.	£55.00
6.	To Window 77, refix/re-pin the loose right hand architrave.	£5.00
7.	To Window 77, remove decayed timber from right hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 m <sup>3</sup> in volume.	£25.00
8.	To Window 77, remove decayed timber from base of external lining to left hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 m³ in volume.	£25.00
	Sub Total	£345.00
	VAT @ 20%	£69.00
	TOTAL	£414.00

Boyce Evens & Carpenter, Chartered Surveyors, 10 Genotin Terrace, Enfield,	Date	15 <sup>th</sup> September 2014
Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

#### FLAT 3 – SCHEDULE OF WINDOW REPAIRS

1.	To Window 19, insert timber filler piece/splice to cut out in head around base of keystone using Repair Care repair method C4, length 150mm approx.	£45.00
2.	To Window 20, insert timber filler piece/splice to cut out in head around base of keystone using Repair Care repair method C4, length 150mm approx.	£45.00
	Sub Total	£90.00
	VAT @ 20%	£18.00
	TOTAL	£108.00

Boyce Evens & Carpenter, Chartered Surveyors,		
10 Genotin Terrace,	Date	15 <sup>th</sup> September 2014
Enfield,	* 1 3 *	D. 0.0.5
Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

#### FLAT 4 – SCHEDULE OF WINDOW REPAIRS

1.	To Window 12, remove decayed timber from right hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
2.	To Window 12, remove decayed timber from base of external lining to left hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
3.	To Window 13, remove decayed timber from right hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
4.	To Window 14, remove decayed timber from both ends of cill and carry out two pack filler repairs using Repair Care repair method C1, each repair size < 50 cm <sup>3</sup> in volume.	£50.00
5.	To Window 14, carry out 150mm length splice repair to base of external lining to right hand box frame jamb using Repair Care repair method C4.	£45.00
6.	To Window 15, carry out conservation joint repair to right hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
7.	To Window 15, renew the timber cill with new hardwood cill to match using Repair Care repair method C2, length 850mm.	£95.00
8.	To Window 15, remove decayed timber from retained back part of cill and carry out two pack filler repair using Repair Care repair method C1, repair size 50-100 cm <sup>3</sup> in volume.	£45.00
9.	To Window 15, carry out 200mm length splice repair to base of left hand pulley stile using Repair Care repair method C4.	£65.00
10.	To Window 15, carry out 200mm length splice repair to base of right hand pulley stile using Repair Care repair method C4.	£65.00
11.	To Window 15, carry out 200mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C1.	£65.00

12.	To Window 15, carry out 200mm length splice repair to base of external lining to right hand box frame jamb using Repair Care repair method C1.	£65.00
	Sub Total	£595.00
	VAT @ 20%	£119.00
	TOTAL	£714.00

Boyce Evens & Carpenter,		
Chartered Surveyors,		
10 Genotin Terrace,	Date	15 <sup>th</sup> September 2014
Enfield,		
Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

#### FLAT 5 – SCHEDULE OF WINDOW REPAIRS

1.	To Window 10, carry out conservation joint repair to left hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
2.	To Window 10, renew the timber cill with new hardwood cill to match using Repair Care repair method C2, length 850mm.	£95.00
3.	To Window 10, carry out 200mm length splice repair to base of right hand pulley stile using Repair Care repair method C4.	£65.00
4.	To Window 10, carry out 3000mm length splice repair to base of external lining to right hand box frame jamb using Repair Care repair method C4.	£75.00
5.	To Window 10, carry out 200mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.	£65.00
6.	To Window 11, renew the timber cill with new hardwood cill to match using Repair Care repair method C2, length 850mm.	£95.00
7.	To Window 11, remove decayed timber from base of right hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
	Sub Total	£445.00
	VAT @ 20%	£89.00
	TOTAL	£534.00

Boyce Evens & Carpenter, Chartered Surveyors,		
10 Genotin Terrace,	Date	15 <sup>th</sup> September 2014
Enfield,	LIN	D2027
Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

#### FLAT 8 – SCHEDULE OF WINDOW REPAIRS

1.	To Window 1, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.	£50.00
2.	To Window 1, remove decayed timber from left hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
3.	To Window 1, remove decayed timber from right hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size 50-100 cm³ in volume.	£25.00
4.	To Window 2, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.	£50.00
5.	To Window 2, remove decayed timber from both ends of cill and carry out two pack filler repairs using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
	Sub Total	£195.00
		£39.00
	VAT @ 20%	
	TOTAL	£234.00

Boyce Evens & Carpenter,		
Chartered Surveyors,		_
10 Genotin Terrace,	Date	15 <sup>th</sup> September 2014
Enfield,		
Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

#### FLAT 9 – SCHEDULE OF WINDOW REPAIRS

1.	To Window 8, carry out conservation joint type repair to split right hand end of bottom rail to top sash using Repair Care repair method P2.	£25.00
2.	To Window 8, remove decayed timber from both ends of cill and carry out two pack filler repairs using Repair Care repair method C1, each repair size < 50 cm <sup>3</sup> in volume.	£50.00
3.	To Window 9, renew the timber cill with new hardwood cill to match using Repair Care repair method C2, length 850mm.	£95.00
4.	To Window 9, carry out conservation joint repairs to both ends of bottom rail to top sash using Repair Care repair method P2.	£50.00
5.	To Window 9, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.	£50.00
6.	To Window 9, remove decayed timber from retained rear part of cill at right hand end and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
7.	To Window 9, carry out 150mm length splice repair to base of right hand pulley stile using Repair Care repair method C4.	£45.00
8.	To Window 9, remove decayed timber from base of external lining to right hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
	Sub Total	£365.00
	VAT @ 20%	£73.00
	TOTAL	£438.00

## Boyce, Evens & Carpenter

#### **Chartered Surveyors**

Established 1847

Kevin J. Savage BSc MRICS Derek M. Isaacs MRICS MCABE 10 Genotin Terrace, Enfield, Middlesex, EN1 2AF

Tel: 020 8367 5100

Fax: 020 8366 3056

Your Ref:

Our Ref: D3827

Date: 6<sup>th</sup> October 2014

A. R. Lawrence & Sons Ltd., 72 Pine Walk, Carshalton Beeches, SURREY, SM5 4HD

For the attention of Richard Cue Esq.

Dear Sirs,

<u>Mitre House, 124 Kings Road, London SW3 – External Repairs/Redecoration & Redecoration of Internal Common Parts</u>


Further to my letter of 2<sup>nd</sup> October 2014, I now enclose the final payment cheque in respect of the front elevation window repairs to Flat 5, in the total sum of £534.00 (£445.00 plus £89.00 VAT). I would ask that you now send a receipted VAT invoice for this amount to Mrs. Michelle Hillgarth c/o Paul Brown-Constable, Mitre House Management Limited, 7 Mitre House, 124 Kings Road, London, SW3 4TP.

Yours faithfully,

Derek Isaacs, Chartered Building Surveyor

c.c. Paul Brown-Constable Esq., Mitre House Management Ltd

#\*OOO854# 54#3060# 72902833#



50 ··· 1005 !: 83768033 !!



BLOOMSBURY & TOTTENHAM COURT ROAD BRANCH

20-10-53

50014885

Date 17 October 2014

MISS M SIGG-HILLGARTH PROPERTY ACCOUNT 28/10/2013 Cheque No. Sort Code Account No.

11º 10 248411 20-1053: 50014885:02

## Boyce, Evens & Carpenter

#### **Chartered Surveyors**

**Established 1847** 

Kevin J. Savage BSc MRICS Derek M. Isaacs MRICS MCABE 10 Genotin Terrace, Enfield, Middlesex, EN1 2AF

Tel: 020 8367 5100 Fax: 020 8366 3056

Your Ref:

Our Ref: D3827 Date: 12<sup>th</sup> November 2014

A. R. Lawrence & Sons Ltd., 72 Pine Walk, Carshalton Beeches, SURREY, SM5 4HD

For the attention of Richard Cue Esq.

Dear Sirs,

Mitre House, 124 Kings Road, London SW3 – External Repairs/Redecoration & Redecoration of Internal Common Parts

Following my site visit on 6<sup>th</sup> November 2014, I confirm that the rear elevation flat window repairs have now been satisfactorily completed. Accordingly, I enclose the payment cheques covering the agreed cost of repairs to Flats 2, 5, 6, 8 & 9. As previously, I would now ask that you provide receipted invoices in respect of the above, all of which should be sent c/o Paul Brown-Constable, Mitre House Management Ltd, 7 Mitre House, 124 Kings Road, London SW3 4TP, as follows:-

Flat 2 – Mr. Segar Karupiah - £585.00 + £117.00 VAT = £702.00

Flat 5 – Mrs. Michelle Hillgarth - £640.00 + £128.00 VAT = £768.00

Flat 6 – Jamil Raja/Dima International - £655.00 + £131.00 VAT = £786.00

Flat 8 – Christopher Leigh Pemberton Chelsea & Belgravia Investments Ltd - £745.00 + £149.00 VAT = £894.00

Flat 9 – Diago Fortunati - £800.00 + £160.00 VAT = £960.00

If you have any queries regarding the above, please let me know.

Yours faithfully,

Derek Isaacs, Chartered Building Surveyor

c.c. Paul Brown-Constable Esq., Mitre House Management Ltd (by e-mail)

Boyce Evens & Carpenter, Chartered Surveyors, 10 Genotin Terrace,	Date	15 <sup>th</sup> October 2014
Enfield, Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

## FLAT 2 – SCHEDULE OF WINDOW REPAIRS (REAR ELEVATION)

1.	To Window 50, carry out conservation joint repairs to both ends of bottom rail to top sash using Repair Care repair method P2.	£50.00
2.	To Window 50, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.	£95.00
3.	To Window 50, carry out conservation joint repair to right hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
4.	To Window 50, carry out 100mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.	£45.00
5.	To Window 51, remove decayed timber from left hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
6.	To Window 51, remove decayed timber from left hand end of bottom rail to bottom sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
7.	To Window 52, carry out conservation joint repair to right hand end of bottom rail to top sash using Repair Care repair method P2.	£25.00
8.	To Window 52, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.	£50.00
9.	To Window 52, remove decayed timber from both ends of cill and and carry out two pack filler repairs using Repair Care repair method C1, each repair size < 50 cm <sup>3</sup> in volume.	£50.00
10.	To Window 52, remove decayed timber along bottom edge of cill and carry out two pack filler repair using Repair Care repair method C1, repair size 50-100 cm³ in volume.	£45.00
11.	To Window 53, carry out conservation joint repairs to both top corners of box frame using Repair Care repair method P2.	£50.00

12.	To Window 53, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.	£50.00
13.	To Window 53, remove decayed timber from base of external lining to left hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.	£25.00
14.	To Window 53, remove decayed timber from right hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
	Sub Total	£585.00
	VAT @ 20%	£117.00
	TOTAL	£702.00

Boyce Evens & Carpenter, Chartered Surveyors, 10 Genotin Terrace,	Date	15 <sup>th</sup> October 2014
Enfield, Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

#### FLAT 5 – SCHEDULE OF WINDOW REPAIRS (REAR ELEVATION)

1.	To Window 46, carry out 100mm length splice repair to base of external lining to right hand box frame jamb using Repair Care repair method C4.	£45.00
2.	To Window 46, carry out conservation joint repair to right hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
3.	To Window 47, renew the existing cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.	£95.00
4.	To Window 47, carry out 150mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.	£45.00
5.	To Window 47, carry out 150mm length splice repair to base of left hand pulley stile using Repair Care repair method C4.	£45.00
6.	To Window 47, remove decayed timber from base of left hand stile to bottom sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume. Include for inserting fixing across existing split.	£25.00
7.	To Window 47, carry out conservation joint repair to right hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
8.	To Window 48, remove decayed timber from left hand end of bottom rail to top sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
9.	To Window 48, remove decayed timber from base of left hand stile to bottom sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
10.	To Window 48, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.	£95.00
11.	To Window 48, remove decayed timber from base of external linings to left hand and right hand box frame jambs and carry out two pack filler repairs using Repair Care repair method C1, each repair size < 50 cm <sup>3</sup> in volume.	£50.00

12.	To Window 49, carry out conservation joint repair to right hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
13.	To Window 49, carry out 150mm length splice repair to right hand end of cill using Repair Care repair method C4.	£45.00
14.	To Window 49, carry out 100mm length splice repair to base of external lining to right hand box frame jamb using Repair Care repair method C4.	£45.00
15.	To Window 49, remove decayed timber from front edge of cill at left hand end and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
	Sub Total	£640.00
	VAT @ 20%	£128.00
	TOTAL	£768.00

Boyce Evens & Carpenter, Chartered Surveyors, 10 Genotin Terrace, Enfield,	Date	15 <sup>th</sup> October 2014
Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

## FLAT 6 – SCHEDULE OF WINDOW REPAIRS (REAR ELEVATION)

1.	To Window 39, carry out 150mm length splice repair to base of external linings to left hand and right hand box frame jambs using Repair Care repair method C4.	£90.00
2.	To Window 39, remove decayed timber from left hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
3.	To Window 39, remove decayed timber from base of right hand stile to bottom sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
4.	To Window 40, carry out conservation joint repairs to both top corners of box frame using Repair Care repair method P2.	£50.00
5.	To Window 40, carry out conservation joint repairs to both ends of bottom rail to top sash using Repair Care repair method P2.	£50.00
6.	To Window 40, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.	£50.00
7.	To Window 40, carry out 250mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.	£65.00
8.	To Window 40, remove decayed timber from left hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
9.	To Window 41, carry out conservation joint repair to top left hand corner of box frame using Repair Care repair method P2.	£25.00
10.	To Window 41, carry out conservation joint repair to left hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
11.	To Window 41, remove decayed timber from base of external lining to right hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00

12.	To Window 41, carry out conservation joint repair to left hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
13.	To Window 41, remove decayed timber from left hand end of bottom rail to bottom sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
14.	To Window 41, remove decayed timber from base of left hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
15.	To Window 41, remove decayed timber from left hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
16.	To Window 42, remove decayed timber from base of left hand stile to bottom sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
17.	To Window 42, carry out conservation joint repair to left hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
18.	To Window 42, carry out conservation joint repair to right hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
19.	To Window 42, remove decayed timber from left hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
	Sub Total	£655.00
	VAT @ 20%	£131.00
	TOTAL	£786.00

Boyce Evens & Carpenter, Chartered Surveyors,		]
10 Genotin Terrace,	Date	15 <sup>th</sup> October 2014
Enfield, Middx EN1 2AF.	Job No.	D3827
WIIGUA EIVI ZAI .	<b>300</b> 110.	D3027
Tel: 020 8367 5100		

#### FLAT 8 – SCHEDULE OF WINDOW REPAIRS (REAR ELEVATION)

1.	To Window 35, carry out conservation joint repair to right hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
2.	To Window 35, remove decayed timber from left hand end of bottom rail to bottom sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
3.	To Window 35, carry out 100mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.	£45.00
4.	To Window 35, remove decayed timber from left hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
5.	To Window 36, carry out conservation joint repairs to both ends of bottom rail to top sash using Repair Care repair method P2.	£50.00
6.	To Window 36, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.	£50.00
7.	To Window 36, remove decayed timber from base of external lining to left hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
8.	To Window 36, carry out 100mm length splice repair to base of external lining to right hand box frame jamb using Repair Care repair method C4.	£45.00
9.	To Window 36, renew the timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.	£95.00
10.	To Window 37, remove decayed timber from top left hand joint to box frame and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
11.	To Window 37, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.	£50.00

To Window 37, carry out 100mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.	£45.00
To Window 37, renew the timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.	£95.00
To Window 38, carry out conservation joint repair to right hand end of bottom rail to bottom sash using Repair Care repair method P2.	£25.00
To Window 38, remove decayed timber from left hand end of bottom rail to bottom sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
To Window 38, remove decayed timber from base of external linings to left hand and right hand box frame jambs and carry out two pack filler repairs using Repair Care repair method C1, each repair size < 50 cm <sup>3</sup> in volume.	£50.00
To Window 38, remove decayed timber from left hand end and bottom edge of cill and carry out two pack filler repairs using Repair Care repair method C1, total repair size 50-100 cm <sup>3</sup> in volume.	£45.00
Sub Total	£745.00
VAT @ 20%	£149.00
TOTAL	£894.00
	to left hand box frame jamb using Repair Care repair method C4.  To Window 37, renew the timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.  To Window 38, carry out conservation joint repair to right hand end of bottom rail to bottom sash using Repair Care repair method P2.  To Window 38, remove decayed timber from left hand end of bottom rail to bottom sash and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.  To Window 38, remove decayed timber from base of external linings to left hand and right hand box frame jambs and carry out two pack filler repairs using Repair Care repair method C1, each repair size < 50 cm³ in volume.  To Window 38, remove decayed timber from left hand end and bottom edge of cill and carry out two pack filler repairs using Repair Care repair method C1, total repair size 50-100 cm³ in volume.  Sub Total  VAT @ 20%

Boyce Evens & Carpenter, Chartered Surveyors, 10 Genotin Terrace,	Date	15 <sup>th</sup> October 2014
Enfield, Middx EN1 2AF.	Job No.	D3827
Tel: 020 8367 5100		

#### FLAT 9 – SCHEDULE OF WINDOW REPAIRS (REAR ELEVATION)

in volume.  2. To Window 30, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  3. To Window 30, carry out conservation joint repair to left hand end of bottom rail to top sash using Repair Care repair method P2.  4. To Window 31 carry out 200mm length splice repair to base of right hand stile to top sash using Repair Care repair method C4.  5. To Window 31, carry out 100mm length splice repair to right hand end of bottom rail to top sash using Repair Care repair method C4.  6. To Window 31, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.  7. To Window 31, carry out conservation joint repair to left hand end of bottom rail to top sash using Repair Care repair method P2.  8. To Window 31, carry out 150mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.  9. To Window 31, remove decayed timber from base of left hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.  250.0  10. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  250.0  11. To Window 31, remove decayed timber from base of right hand pulley stile and carry out two pack filler repair using Repair Care repair method P2.	1.	To Window 30, remove decayed timber from left hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup>	
to bottom sash using Repair Care repair method P2.  250.0  To Window 30, carry out conservation joint repair to left hand end of bottom rail to top sash using Repair Care repair method P2.  To Window 31 carry out 200mm length splice repair to base of right hand stile to top sash using Repair Care repair method C4.  5. To Window 31, carry out 100mm length splice repair to right hand end of bottom rail to top sash using Repair Care repair method C4.  6. To Window 31, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.  7. To Window 31, carry out conservation joint repair to left hand end of bottom rail to top sash using Repair Care repair method P2.  8. To Window 31, carry out 150mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.  9. To Window 31, remove decayed timber from base of left hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.  £25.0  10. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  £50.0  11. To Window 31, remove decayed timber from base of right hand pulley stile and			£25.00
rail to top sash using Repair Care repair method P2.  4. To Window 31 carry out 200mm length splice repair to base of right hand stile to top sash using Repair Care repair method C4.  5. To Window 31, carry out 100mm length splice repair to right hand end of bottom rail to top sash using Repair Care repair method C4.  6. To Window 31, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.  7. To Window 31, carry out conservation joint repair to left hand end of bottom rail to top sash using Repair Care repair method P2.  8. To Window 31, carry out 150mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.  9. To Window 31, remove decayed timber from base of left hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.  £25.0  10. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  £25.0  11. To Window 31, remove decayed timber from base of right hand pulley stile and	2.	· · · · · · · · · · · · · · · · · · ·	£50.00
to top sash using Repair Care repair method C4.  5. To Window 31, carry out 100mm length splice repair to right hand end of bottom rail to top sash using Repair Care repair method C4.  6. To Window 31, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.  7. To Window 31, carry out conservation joint repair to left hand end of bottom rail to top sash using Repair Care repair method P2.  8. To Window 31, carry out 150mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.  9. To Window 31, remove decayed timber from base of left hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.  10. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  11. To Window 31, remove decayed timber from base of right hand pulley stile and	3.	, ,	£25.00
bottom rail to top sash using Repair Care repair method C4.  1. To Window 31, renew the existing timber cill with new hardwood cill to match using Repair Care repair method C2, length 870mm approx.  1. To Window 31, carry out conservation joint repair to left hand end of bottom rail to top sash using Repair Care repair method P2.  2. E25.0  2. To Window 31, carry out 150mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.  3. To Window 31, remove decayed timber from base of left hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.  1. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  2. £25.0  2. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  2. £50.0  3. To Window 31, remove decayed timber from base of right hand pulley stile and	4.		£65.00
using Repair Care repair method C2, length 870mm approx.  1. To Window 31, carry out conservation joint repair to left hand end of bottom rail to top sash using Repair Care repair method P2.  1. To Window 31, carry out 150mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.  2. To Window 31, remove decayed timber from base of left hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.  1. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  1. To Window 31, remove decayed timber from base of right hand pulley stile and	5.		£45.00
rail to top sash using Repair Care repair method P2.  8. To Window 31, carry out 150mm length splice repair to base of external lining to left hand box frame jamb using Repair Care repair method C4.  9. To Window 31, remove decayed timber from base of left hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.  10. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  11. To Window 31, remove decayed timber from base of right hand pulley stile and	6.		£95.00
to left hand box frame jamb using Repair Care repair method C4. £45.0  9. To Window 31, remove decayed timber from base of left hand pulley stile and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume. £25.0  10. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2. £50.0  11. To Window 31, remove decayed timber from base of right hand pulley stile and	7.	, ,	£25.00
carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm³ in volume.  £25.0  10. To Window 31, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.  £50.0  11. To Window 31, remove decayed timber from base of right hand pulley stile and	8.	, ,	£45.00
to bottom sash using Repair Care repair method P2. £50.0  11. To Window 31, remove decayed timber from base of right hand pulley stile and	9.	carry out two pack filler repair using Repair Care repair method C1, repair size	£25.00
	10.	, ,	£50.00
carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume. £25.0	11.	carry out two pack filler repair using Repair Care repair method C1, repair size	£25.00

12.	To Window 31, remove decayed timber from base of external lining to right hand box frame jamb and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
13.	To Window 32, remove 1 No. cracked pane glass to top sash and re-glaze in clear sheet glass, size 260 x 320mm approx.	£55.00
14.	To Window 32, carry out conservation joint repairs to both ends of bottom rail to top sash using Repair Care repair method P2.	£50.00
15.	To Window 32, carry out conservation joint repairs to both ends of bottom rail to bottom sash using Repair Care repair method P2.	£50.00
16.	To Window 32, remove decayed timber from both ends of cill and carry out two pack filler repairs using Repair Care repair method C1, each repair size < 50 cm <sup>3</sup> in volume.	£50.00
17.	To Window 32, carry out 150mm length splice repair to left hand end of bottom rail to bottom sash using Repair Care repair method C4.	£45.00
18.	To Window 33, carry out conservation joint repair to right hand end of bottom rail to top sash using Repair Care repair method P2.	£25.00
19.	To Window 33, remove decayed timber from right hand end of cill and carry out two pack filler repair using Repair Care repair method C1, repair size < 50 cm <sup>3</sup> in volume.	£25.00
	Sub Total	£800.00
	VAT @ 20%	£160.00
	TOTAL	£960.00

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Mrs M Hillgarth
Flat 5 Mitre House
c/o
Paul Brown-Constable
Mitre House Management Ltd
7 Mitre House
124 Kings Road
LONDON
SW3 4TP

INVOICE RECEIPT

4046

VAT REG NO. 652 8482 15

DATE

18 NOVEMBER 2014

YOUR REF

OUR REF: ADW/4474/LW

#### **RECEIPT & TAX INVOICE**

#### FLAT 5 MITRE HOUSE

To Carrying out window repairs as instructed.

640 | 00

Value Added Tax @ 20%

128 | 00

£ 768 00

### PAYMENT RECEIVED WITH THANKS

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY

SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Mr Segar Karupiah
Flat 2 Mitre House
c/o
Paul Brown-Constable
Mitre House Management Ltd
7 Mitre House
124 Kings Road
LONDON
SW3 4TP

INVOICE

RECEIPT 4045

VAT REG NO. 652 8482 15

DATE

18 NOVEMBER 2014

YOUR REF

OUR REF: ADW/4474/LW

## **RECEIPT & TAX INVOICE**

#### FLAT 2 MITRE HOUSE

To Carrying out window repairs as instructed.

585 | 00

Value Added Tax @ 20%

117 00

702 00

£

## PAYMENT RECEIVED WITH THANKS

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Dima International Ltd Flat 6 Mitre House c/o Paul Brown-Constable Mitre House Management Ltd 7 Mitre House 124 Kings Road LONDON SW3 4TP

INVOICE

RECEIPT 4047

VAT REG NO. 652 8482 15

DATE

18 NOVEMBER 2014

YOUR REF

OUR REF: ADW/4474/LW

#### **RECEIPT & TAX INVOICE**

#### FLAT 6 MITRE HOUSE

To Carrying out window repairs as instructed.

655 00

Value Added Tax @ 20%

131 | 00

£ 786 00

## PAYMENT RECEIVED WITH THANKS

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Chelsea & Belgravia Investments Ltd Flat 8 Mitre House c/o Paul Brown-Constable Mitre House Management Ltd 7 Mitre House 124 Kings Road LONDON SW3 4TP

INVOICE

**RECEIPT** 4048 VAT REG NO. 652 8482 15

DATE 18 NOVEMBER 2014 YOUR REF OUR REF: ADW/4474/LW

#### **RECEIPT & TAX INVOICE**

#### FLAT 8 MITRE HOUSE

To Carrying out window repairs as instructed. 745 00

Value Added Tax @ 20% 149 00

£ 894 00

## PAYMENT RECEIVED WITH THANKS

**BUILDERS & DECORATORS** 

72 PINE WALK CARSHALTON BEECHES SURREY SM5 4HD

Tel/Fax: 020 8642 3101 Tel/Fax: 020 8643 3482

E-mail: arlawrencemail@aol.com

Diago Fortunati
Flat 9 Mitre House
c/o
Paul Brown-Constable
Mitre House Management Ltd
7 Mitre House
124 Kings Road
LONDON
SW3 4TP

INVOICE

RECEIPT 4049

VAT REG NO. 652 8482 15

DATE

18 NOVEMBER 2014

YOUR REF

OUR REF: ADW/4474/LW

#### **RECEIPT & TAX INVOICE**

#### FLAT 9 MITRE HOUSE

To Carrying out window repairs as instructed.

800

Value Added Tax @ 20%

160 00

00

960 00

£

## PAYMENT RECEIVED WITH THANKS

## Mitre House Management Limited SERVICE CHARGE EXPENSE DETAIL REPORT Mitre House SW3 Year Ended 31/12/2014

Schedule/Expense	Date	Supplier	Description	Expenditure
INCOME				
Bank interest Received	09/01/14 10/02/14 10/03/14 11/04/14 10/05/14 10/05/14 10/06/14 10/07/14 12/08/14 09/09/14 11/10/14 10/11/14	Liloyds TSB	Net Credit Interest	£7.86 £8.21 £7.15 £7.61 £7.31 £7.71 £7.30 £8.13 £6.81 £7.11 £7.04 £4.57
EXPENDITURE			Tax Debit	£86.81
Cleaning	19/01/14 19/02/14 19/03/14 19/03/14 19/05/14 19/06/14 19/07/14 19/08/14 19/09/14 19/10/14 19/11/14	Office & General	Cleaning	£194.49 £194.49 £194.49 £194.49 £194.49 £194.49 £194.49 £194.49 £194.49
Additional Misc Cleaning	29/12/14	MHML	Misc Cleaning Supplies (not paid/due)	£237.12
				£2,571.00
Communal Electricity	28/03/14 22/04/14 30/06/14 30/06/14 22/08/14 15/09/14 20/11/14 23/12/14	British Gas British Gas British Gas British Gas British Gas British Gas British Gas British Gas	Electricity Useage	£40.61 £2.79 £19.02 £77.60 £11.76 £24.07 £40.78 £18.50
General Repairs:				
External Repairs - minor				£0.00
				20.00
Internal Repairs - minor				£0.00
Entryphone	16/06/14	Entryphone	Annual Contract	£239.18
				£239.18
Entryphone Repairs		Entryphone	Maintenance Additional Costs	£0.00
				£0.00
Draincleaning	30/06/14	MHML	Maintenance Roof Gutters	£257.50
				£257.50
Building Insurance	22/09/14	AXA Insurance	Freeholder's Building Insurance	£1,864.38

			_	£1,864.38
Engineering Insurance	02/07/14	Allianz	Lift Insurance	£437.81
			_	£437.81
Lift Maintenance	01/01/14	PIP Lifts	Lift Contract Maintenance	£365.74
	10/04/14	PIP Lifts	Lift Contract Maintenance	£376.72
	09/06/14	PIP Lifts	Lift Contract Maintenance	£376.72
	04/09/14	PIP Lifts	Lift Contract Maintenance	£376.72
	15/12/14	PIP Lifts	Lift Contract Maintenance	£376.72
			_	£1,872.62
Lift Repairs	02/06/14	Pip Lift	Lift Maintenance Additional Repair Costs	£891.60
			_	£891.60
Lift Telephone 0416	18/02/14	British Telecom	2075840416	£69.03
Lift Telephone 0410	20/05/14	British Telecom	2075840416	£68.97
	18/08/14	British Telecom	2075840416	£71.96
	17/11/14	British Telecom	2075840416	£71.96
			_	£281.92
Sundries (Light Bulbs)			_	£0.00
				£0.00
Sundries (Misc)	31/12/14	MHML	Photostats (not paid/due)	£39.02
				£39.02
Health & Safety Report Fees	16/06/14	ASI	Achastas Danart	£270.00
	16/06/14	ASI	Asbestos Report —	
				£270.00
Postage & Shipping				£0.00
				£0.00
Management Fees	31/01/14	MHML	Quarterly Management Fees	£1,080.00
	31/03/14	MHML	Quarterly Management Fees	£1,080.00
	30/06/14	MHML	Quarterly Management Fees	£1,080.00
	25/09/14	MHML	Quarterly Management Fees	£1,080.00
			_	£4,320.00
Bookeeping & Accountancy	21/08/14	Pemberton Professionals Limited	Annual Accounts	£695.00
			_	£695.00
Legal & Professional Fees	31/01/14	MHML	Section 20 Notices	£270.00
			_	£270.00
Pank Charges	20/01/11	I llevide TCD	Mankhir Danis Charres	27.67
Bank Charges	20/01/14 18/02/14	Llloyds TSB Llloyds TSB	Monthly Bank Charges Monthly Bank Charges	£7.60 £5.00
	17/03/14	Llloyds TSB Llloyds TSB	Monthly Bank Charges  Monthly Bank Charges	£5.00
	20/04/14	Llloyds TSB	Monthly Bank Charges	£18.00
	19/05/14	Llloyds TSB	Monthly Bank Charges	£8.90
	19/06/14	Llloyds TSB	Monthly Bank Charges	£7.60
	20/07/14	Llloyds TSB	Monthly Bank Charges	£13.45
	18/08/14 21/09/14	Llloyds TSB Llloyds TSB	Monthly Bank Charges Monthly Bank Charges	£7.60 £6.30
	19/10/14	Llloyds TSB Llloyds TSB	Monthly Bank Charges	£51.80
	17/11/14	Llloyds TSB	Monthly Bank Charges	£20.60
	19/12/14	Llloyds TSB	Monthly Bank Charges	£45.30
				£197.15

#### **Scheduled Major Works**

Reserves 30 Sept 2014				£98,262.00
			Adjustment Collected	£18,000.00
			Reserves (works budget)Total	£116,262.00
Surveyor Fees	13/02/14 24/03/14 22/09/14 31/10/14 09/12/14	Boyce Evens & Carpenter Boyce Evens & Carpenter Boyce Evens & Carpenter Boyce Evens & Carpenter Boyce Evens & Carpenter	Surveying Costs Surveying Costs Surveying Costs Surveying Costs Surveying Costs	£2,784.48 £2,452.87 £1,965.77 £1,369.31 £1,941.12
			_	£10,513.55
Main Contractor Costs	16/09/14 24/10/14 02/12/14 17/12/14 31/12/14	AR Lawrence & Sons Ltd AR Lawrence & Sons Ltd AR Lawrence & Sons Ltd AR Lawrence & Sons Ltd AR Lawrence & Sons Ltd	Works Costs Works Costs Works Costs Works Costs (not paid/due) Works Costs (not paid/due)	£12,656.85 £24,482.02 £17,452.44 £7,418.70 £1,590.00
Additional Works & Costs & fees	31/12/14 31/12/14	MHML Suppliers Misc Costs of additional works	Additional Workings Outside Schedule Additional Workings Outside Schedule	£15,572.85 £16,183.36
				£31,/50.21
			Total Major Scheduled Works 2014 s.20 dated 22 June 2014	£105,877.00 £105,019.00
			s.20 Budget overspend	£858.00
Unscheduled additional Works	14/10/14 07/11/14 31/12/14	Aerial Tec Houseman Water Ltd Workngs (CR)	Communal TVSky installation Replacement Mains Water Tank Misc costs refunded  — Adjustment Collected	£5,172.00 £5,850.00 -£317.00 £10,705.00 -12,858.00
			CREDIT (to Reserves) Negotiated due to scaffolding remaining in place as MHML had advised all lessees	-£2,153.00



(REPRESENTING THE NINE LEASEHOLD OWNERS OF MITTE HOUSE)

124 Kings Road • Chelsea • London SW3 4TP
Email: management@mitrehouse.org • www.mitrehouse.org
Telephone +44 (0)207 589 7502 Mbl: +44 (0)798 33 33 543

# 2014 Works' Invoices £105,877 AND Lessees' Windows Repair Accounts

(ORIGINALS & COPIES)

