Page 1 of 3

RISK ASSESSMENT REPORT

Assessor: G Hurford Date: November 2016 No. gen11

Principle Activity: Articulated vehicle movements

Location: Heathfield

Activity/Hazard	Severity	MPL	Probability	Risk scoring	Risk Rating
Falls from height	1	50	20	71	High risk

Risk to:

Lorry drivers, others who may cover trailers

Risk from:

Jumping down from lorry cab Falling from top of trailer

Risk of:

Sprains, broken limbs, death.

Existing controls:

Drivers are trained in load sheeting

Drivers step down backwards from cab using three point hold.

Bulk trailers are auto sheeted

Additional controls:

None

Residual	Severity 1	MPL	Probability 10	Residual score 31	Residual rating
risk	-	20	-		LOW RISK

Activity/Hazard	Severity	MPL	Probability	Risk scoring	Risk Rating
Slippery surfaces and oil on footwear	1	50	20	41	High risk

Risk to:

Lorry drivers

Risk from:

Slipping whilst covering load Feet slipping off control pedals

Risk of:

Sprains, broken limbs, death

Existing controls:

Ground regularly swept by crane Safety footwear with good tread

Soles checked for oil, grease etc before entering cab.

Additional controls:

None

Residual	Severity 1	MPL 50	Probability 10	Residual score 61	Residual rating
risk					HIGH RISK

Activity/Hazard	Severity	MPL	Probability	Risk scoring	Risk Rating
Un / Coupling trailers	1	50	20	71	High risk

Risk to:

Lorry driver, public

Risk from:

Vehicle becoming unstable

Collision with public

Risk of:

Broken limbs, major injuries, death.

Existing controls:

Drivers are trained in coupling trailers

Driver wears hi-viz jacket, safety shoes and hard hat.

Trailer is sited on solid ground with no side slope

Driver checks that trailer park brake is applied when uncoupling.

Driver checks for people / vehicles before reversing onto trailer

Driver checks brakes, lights, tyres, before moving off.

Additional controls:

None

Residual	Severity 1	MPL 35	Probability 10	Residual score 46	Residual rating
risk					MEDIUM RISK

Activity/Hazard	Severity	MPL	Probability	Risk scoring	Risk Rating
Reversing	1	50	10	61	High risk

Risk to:

Workers in area

Risk from:

Contact with vehicle

Risk of:

Up to fatal

Existing controls:

Yard operatives wear hi-viz jackets, safety shoes and hard hats

Driver seeks assistance of banksman when reversing

Residual	Severity 1	MPL	Probability 10	Residual score 31	Residual rating
risk		20			LOW RISK

Activity/Hazard	Severity	MPL	Probability	Risk scoring	Risk Rating
Tipping bulk trailers	1	50	10	61	High risk

Risk to:

Driver and workers in area

Risk from:

Contact with vehicle/ tail gate, trailer tipping over.

Risk of:

Minor fractures, broken limbs, fatal.

Existing controls:

Yard operatives wear hi-viz jackets, safety shoes and hard hats

Tractor and trailer are on firm level ground before tipping

Tractor is in line with trailer and not articulated when tipping.

Scrap handler removes load from tailgate to relieve pressure

Driver makes visual contact with scrap hamdler operator before approaching tailgate

Driver acts as banksman for scrap handler on blindside of vehicle

Driver ensures all safety clips are fitted to locking pins when closing tailgate.

		-			ā-
Residual	Severity 1	MPL	Probability 10	Residual score 31	Residual rating
risk		20	-		LOW RISK

Signature of Assessor	

DISTRIBUTION: Lorry drivers, yard office, health and safety file.