Station Log: KJVV Problems/Issues/ Etc.

Issue/Issuance/Info	Dates	Comments	
Construction Permit Granted.	09/21/11	Yeah!	2
MINOR MODIFICATION TO A CONSTRUCTION PERMIT	09/19/2014	SHORT SPACING SECTION 73.215 & CONTOUR PROTECTION	Eng. Eugene.
		THIS PROPOSAL MEETS THE SHORT SPACING REQUIREMENTS OF 47 CFR SECTION 73.215. PLEASE REFER TO THE ATTACHED SHORT SPACING TABLE.	
		THIS PROPOSAL PROVIDES THE NECESSARY CONTOUR PROTECTION TO LICENSED IST ADJACENT KXSB AUTHORIZATION AT CLASS A MAXIMUM PARAMETERS OF 100M HAAT AND 6.0KW. PLEASE REFER TO ATTACHED KXSB CONTOUR PROTECTION MAP.	
		THIS PROPOSAL PROVIDES THE NECESSARY CONTOUR PROTECTION FOR LICENSED CO-CHANNEL KSCA AUTHORIZATION AT CLASS MAXIMUM PARAMETERS OF 150M HAAT AND 50KW. PLEASE REFER TO ATTACHED KSCA CONTOUR PROTECTION MAP.	
LICENSE TO COVER	10/02/14	Granted	
PROGRAM TEST AUTHORITY	10/02/14	Granted.	
REMAIN SILENT AUTHORITY & SILENT NOTIFICATION	11/19/2014	Granted Technical Tower Company has issues with tower and needs surveys.	M.V.
EXTENSION OF REMAIN SILENT AUTHORITY	06/10/15	Granted Technical	M.V.
Resumption of Operations	09/30/15	Granted - TPO/ERP good.	M. V.
REMAIN SILENT AUTHORITY & SILENT NOTIFICATION Status:	03/18/2016	Granted TX – issues. Sent back to England for repairs. Loss Forward Power.	Eng. Faron
Resumption of Operations	Jan 17 2017 12:01AM	Tech. Issues resolved TX fixed. Forward power restored. TPO/ERP good.	Eng. Faron
Power outage 29 palms.	Mid January	Resent – automation software, repair bricks, etc. Up in no time.	Eng. Faron

ı	1	