




8 1" flange bearing

9 $\frac{5}{8}$ " eccentric bushing

10 $\frac{5}{8}$ x 7" pulley

11 $\frac{5}{8}$ eccentric drive shaft