



## **PC-2000C Clear Coating Cleaning and Maintenance Guidelines**

The following items should be strictly adhered to:

1. DO NOT USE ANY SOLVENT-BASED CLEANERS, ESPECIALLY DEGREASERS, ON ANY SURFACE THAT HAS BEEN COATED WITH OUR PC-2000C. SOLVENT-BASED CLEANERS WILL RUIN THE CLEAR FINISH.
2. Do not wash a clear coated surface for two (2) weeks. This allows the product to properly cure.
3. Do not use abrasive cleaners on a clear coated finish.
4. Do not wax or polish a clear coated surface.
5. Do not use any brushes, including brush wash systems, for two (2) weeks to clean a clear coated surface.
6. It is perfectly okay to use a fresh water rinse at any time, even immediately after application, to rinse a clear coated surface.
7. After the two (2) week cure period, a clear coated surface is best cleaned using Dawn dishwashing soap, 4 parts warm water to 1 part Dawn dishwashing soap in a pump up spray bottle.

Please call us at 1-888-739-2037 or 941-322-9449 for any questions.

Note: If unit has a clear coated (PC-2000C) exterior as well as a coated coil (PC-2000), to keep from using two different types of cleaners, you need to clean both clear coated panels and coated coils with Dawn dishwashing soap (non-scented) and warm water mixture.