

THE CITY OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF WATER POLLUTION CONTROL

BOROUGH OF RICHMOND

CERTIFICATE OF INSPECTION  
NEW SEWER HOUSE CONNECTION

The following described sewer house connection has been laid from the property line to the existing sewer at premises:

N.B.# 22/78 BLOCK 2674 LOT 30

UNDER PERMIT NO. 4260 ISSUED 3-25-80

PREMISES 45 COLLIER PLACE, S.I.  
(HOUSE NUMBER AND STREET)

LOCATED EAST SIDE 411.02 FEET South OF VICTORY BLVD

OWNER COLLIER PLACE COOP.

PLUMBER ARON KATZEN - JBL

SIZE AND TYPE OF PIPE LAID 6" CAST IRON

CONN. TO (SIZE, TYPE) 10" EASY SAU SEWER LOCATED IN

(STREET/AVENUE) COLLIER PLACE

I HEREBY CERTIFY THAT I MADE THE INSPECTION OF THE SEWER HOUSE CONNECTION DESCRIBED ABOVE AND THAT ALL WORK DONE UNDER THIS PERMIT HAS BEEN PROPERLY COMPLETED IN ACCORDANCE WITH EXISTING ORDINANCES AND RULES AND REGULATIONS.

DATE: July 23, 1978 NAME (PRINT) BRUCE SUCNER

SIGNED Bruce Sucner  
INSPECTOR-DIVISION OF SEWER CONSTRUCTION

NOTED [Signature]  
BOROUGH ENGINEER


PENALTY FOR FALSIFICATION:  
FALSIFICATION OF ANY STATEMENT MADE HEREIN IS AN OFFENSE PUNISHABLE BY A FINE OR IMPRISONMENT OR BOTH (N.Y.C. ADMINISTRATIVE CODE, SECTION 1251-9.0)

Copies to:      Borough Superintendent, Department of Buildings  
     Borough Office, Bureau of Water Register  
     Sewer Regulation and Control Section  
File original in Borough Construction Office

NOTE: The sewer to which the house connection is made is       
is not      connected to a private sewer treatment plant.  
Form No. WPC-15 Rev. B (6-77) [Yellow]

HOUSE NUMBER 45	STREET NAME Walter Place	BLOCK 2074	LOT 30
--------------------	-----------------------------	---------------	-----------

1. Was connection extended from existing curb connection? YES  NO
2. Was the connection placed on earth, stone or crushed rock, concrete cradle, concrete encasement, or reinforced concrete encasement? (Circle)
3. Was connection made to existing spur or riser or cut in? (Circle)
4. If connection was "cut in", was saddle or dutchman used? (Circle, if yes)
5. Length, size and material of new connection 25' 6" CAST IRON
6. Depth of connection at curb line is 7 feet.
7. All work was exposed and inspected.



DATE: July 27, 1978 SIGNED: \_\_\_\_\_ INSPECTOR-DIVISION OF SEWER CONSTRUCTION