

MONSTER DASH

MEASUREMENT SPECIFICATION -- FIT GUIDE

Mens Full Zip Performance Jacket



Details: Full Zip, Thumb Holes, Zipper Pockets, Embroidery, Breathable Fabric

Point of Measurement	Xsmall	Small	Medium	Large	Xlarge	2XLarge	3XLarge
Chest (inches)		41	44	46	50	52	
Waist (inches)		41	42	43	48	52	
Hips (inches)		38	40	40	46	48	
Sleeve (inches)		28	28	28	29	30	

How to Measure

Measure around the fullest part of your chest under your armpits with your arms relaxed at sides. Keep measuring tape parallel to the ground.

Waist Measure around the natural waist, which falls at the natural curve of the body -- the indentation between the hip and the ribcage. The measuring tape should be close to the body but not snug.

Hips Wrap measuring tape around the fullest part of the hips and buttocks. Keep measuring tape parallel to the ground.

****Body measurements are given in inches. If your measurement is on the borderline between two sizes, order the smaller size for a tighter fit or the larger size for a looser fit. If your body measurements for chest and the waist result in two different suggested sizes, order from your chest measurements.*