



PLEASE PRINT ALL CUT MARKS

ENVELOPE DELINE

- ✓ Please follow the exact die line. It is important to keep the work at 100%.
- ✓ It is essential that the grain runs in the direction specified by Cutting Edge Envelope.
- ✓ The position of the envelope is critical to insure proper breakdown in the die cutting process.
- ✓ Envelope machines cannot find perfect borders or bleeds. Designs with bleeds must exceed 1/8" around all sides.
- ✓ Mark your grain and gutter. Make sure stock is tapered. Print die marks.
- ✓ Envelope sizes must be true. Bleeds and margins. Otherwise glue or gum may fail.
- ✓ We cannot guarantee envelopes if our die line is not followed.
- ✓ Cut marks must be printed on bleed.
- ✓ There must be a minimum of 1/2" in any direction. This is industry standard.
- ✓ Please provide 10% or minimum of 1000 units.

PLEASE PRINT ALL CUT MARKS

#9 LITHO
FACE
(3-7/8" x 8-7/8")