

**RECOMMENDED**

**BUOY AND MOORING ANCHORING SYSTEM**

EQUIPMENT NEEDED:

- 2 - Empty 5 gallon buckets
- Enough cement to fill each bucket
- 2 - 1/2 inch threaded eye bolts
- 6 - Washers to be threaded onto eye bolts (3 for each eye bolt)
- Chain (enough chain to secure your 5 gallon buckets and to have 2 1/2 times the amount of chain for the water depth)
- Swivel shackle
- 2 shackles

EQUIPMENT ASSEMBLY

