ID	Project Description	Project Lead	Estimated	Proposed	D	Oonation of Funds or		
			Cost	Solution	N	⁄laterial		
1	Install Wheel Chair Ramp to Hall	Larry Wallace						
2	Repair Concrete (side walk)							
3	Repair Concrete (driveway)							
4	Church Door Closure							
5	Church Side Windows Repair							
6	Repair Outside Wall of Hall	Kelly						
	(East Wall)							
7	Paint Interior of House							
8	Paint House Porch	Riley Dillon						
9	Install New Water Line to							
	Church							
10	Painting the Nativity Hall							
11	Remove Moss from Church Roof							
12	RePainting the Pews							