



## **CLEANING INSTRUCTIONS**

WeatherMax™ fabrics may be spot washed by using a soapy solution of a mild detergent and lukewarm water. Rinse thoroughly with clean water to remove the soap and allow to air dry. For mildew stains, prepare a solution of one (1) cup of bleach plus half (1/2) cup of mild detergent per gallon of water. Spray on the entire area and allow soaking. Rinse with clean water and allow to air dry.