



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052602	INSPECT FIRST AID KIT INSPECTION	KTYR			MTH 05-Mar-2019 HRS 2230.8 LDG 2442		DUE DUE DUE DUE		31-Mar-2021	20 m 28 d
5-12-01 051201	INSPECTION DOCUMENT 1 (INTERVAL 1A)	KTYR			MTH 05-Mar-2019 HRS 2230.8 LDG 2442		300		2530.8	269.1
5-12-05 051205	INSPECTION DOCUMENT 5 (INTERVAL 1C)	KTYR			MTH 12-Nov-2018 HRS 2195.6 LDG 2398		12		30-Nov-2019	4 m 27 d
B342100	CAPACITY TEST STANDBY GYRO POWER SUPPLY PS-855 (LEAD ACID): INSPECTION DOCUMENT 5 (INTERVAL 1C)	KTYR		501-1712-01 3044	MTH 06-Dec-2018 HRS 2203.4 LDG 2408		12		31-Dec-2019	5 m 28 d
5-12-06	INSPECTION DOCUMENT 6 (INTERVAL 2C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 28-Jul-2009 HRS 0 LDG 0		24			
5-12-07 051207	INSPECTION DOCUMENT 7 (INTERVAL 3C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTYR			MTH 12-Dec-2017 HRS 1986.7 LDG 2130 ACH 975		36			
B236001	FUNCTIONAL CHECK STATIC DISCHARGE SYSTEM: INSPECTION DOCUMENT 7 (INTERVAL 3C)	KTYR			MTH 12-Dec-2017 HRS 1986.7 LDG 2130 ACH 975		36		31-Dec-2020	17 m 28 d
5-12-08 051208	INSPECTION DOCUMENT 8 (INTERVAL 4C)	KALN			MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		48		31-Oct-2021	27 m 28 d
5-12-09 051209	INSPECTION DOCUMENT 9 (INTERVAL 6C)	KGGG			MTH 03-Aug-2015 HRS 1631.6 LDG 1807		72		31-Aug-2021	25 m 28 d
A262002 CABIN 051209 : CABIN	SPECIAL DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 9 (INTERVAL 6C)	KGGG		C352TS X571080	MTH 03-Aug-2015 HRS 1631.6 LDG 1807		72		31-Aug-2021	25 m 28 d
A262002 COCKPIT 051209 : CKPT	SPECIAL DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 9 (INTERVAL 6C)	KGGG		C352TS X571078	MTH 03-Aug-2015 HRS 1631.6 LDG 1807		72		31-Aug-2021	25 m 28 d
5-12-11 051211	INSPECTION DOCUMENT 11 (INTERVAL 1A/1C)	KTYR			MTH 12-Nov-2018 HRS 2195.6 LDG 2398		12 300		30-Nov-2019 2495.6	4 m 27 d 233.9
5-12-12 051212	INSPECTION DOCUMENT 12 (INTERVAL 2A/2C)	KALN			MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		24 600		31-Oct-2019 2541.8	3 m 28 d 280.1
5-12-14 051214	INSPECTION DOCUMENT 14 (INTERVAL 4A/2C)	KALN			MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		24 1200		31-Oct-2019 3141.8	3 m 28 d 880.1
5-12-16 051216	INSPECTION DOCUMENT 16 (INTERVAL 8A/4C)	KALN			MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		48 2400		31-Oct-2021 4341.8	27 m 28 d 2080.1



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-17 051217	INSPECTION DOCUMENT 17 (INTERVAL CFR 91.207) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTYR		MTH 29-May-2019 HRS 2261.7 LDG 2461		12			
A256001	DETAILED INSPECTION ELT TRANSMITTER : INSPECTION DOCUMENT 17 (INTERVAL CFR 91.207)	KTYR	453-5000-999 07106	MTH 29-May-2019 HRS 2261.7 LDG 2461	-11	12		31-May-2020	10 m 28 d
B256001	OPERATIONAL CHECK ELT TRANSMITTER EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM: INSPECTION DOCUMENT 17 (INTERVAL CFR 91.207)	KTYR	453-5000-999 07106	MTH 29-May-2019 HRS 2261.7 LDG 2461		12		31-May-2020	10 m 28 d
5-12-18	INSPECTION DOCUMENT 18 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KALN		MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		24			
341055 NO. 1 051218 : L-ADC	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411): INSPECTION DOCUMENT 18	KALN	822-1109-014 39KWW	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975	-43	24		31-Aug-2019	1 m 28 d
341056 NO. 2 051218 : R-ADC	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411): INSPECTION DOCUMENT 18	KALN	822-1109-014 39KWX	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975	-43	24		31-Aug-2019	1 m 28 d
341057 STANDBY 051218 : STDBY	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411): INSPECTION DOCUMENT 18	KALN	501-1890-04 3409	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975	-43	24		31-Aug-2019	1 m 28 d
341060 051218 : RVSM	INSPECT RVSM SKIN WAVINESS: INSPECTION DOCUMENT 18	KALN		MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975	-43	24		31-Aug-2019	1 m 28 d
B341001 LEFT 051218 : L	FUNCTIONAL CHECK PITOT STATIC SYSTEM (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450): INSPECTION DOCUMENT 18	KALN		MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975	-43	24		31-Aug-2019	1 m 28 d
B341001 RIGHT 051218 : R	FUNCTIONAL CHECK PITOT STATIC SYSTEM (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450): INSPECTION DOCUMENT 18	KALN		MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975	-43	24		31-Aug-2019	1 m 28 d
B345001 NO. 1 051218 : 1	CALIBRATION CHECK TRANSPONDER (FAR 91.413) (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450): INSPECTION DOCUMENT 18	KICT	622-9210-501 23N2C	MTH 08-Feb-2018		24		29-Feb-2020	7 m 26 d
B345001 NO. 2 051218 : 2	CALIBRATION CHECK TRANSPONDER (FAR 91.413) (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450): INSPECTION DOCUMENT 18	KICT	622-9210-501 23N2G	MTH 08-Feb-2018		24		29-Feb-2020	7 m 26 d
5-12-19	INSPECTION DOCUMENT 19 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTYR		MTH 29-May-2019 HRS 2261.7 LDG 2461		6			
B262002 CABIN 051219 : CABIN	CABIN PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK : INSPECTION DOCUMENT 19	KTYR	C352TS X571080	MTH 29-May-2019 HRS 2261.7 LDG 2461		6		30-Nov-2019	4 m 27 d



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262002 COCKPIT 051219 : CKPT	COCKPIT PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK : INSPECTION DOCUMENT 19	KTYR		C352TS X571078	MTH 29-May-2019 HRS 2261.7 LDG 2461		6		30-Nov-2019	4 m 27 d
5-12-22 051222	INSPECTION DOCUMENT 22 (INTERVAL 4A/3C)	KALN			MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		36 1200		31-Oct-2020 3141.8	15 m 28 d 880.1
5-12-23 051223	INSPECTION DOCUMENT 23 (INTERVAL 1A/2C)	KTYL			MTH 18-May-2018 HRS 2123.2 LDG 2337		24 300		31-May-2020 2423.2	10 m 28 d 161.5
5-12-24 051224	INSPECTION DOCUMENT 24 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTYL			MTH 31-Aug-2018 HRS 2180.5 LDG 2384		36 1200			
A561001	INSPECT WINDSHIELD OPTICAL PRISM: INSPECTION DOCUMENT 24	KTYL			MTH 10-Aug-2018 HRS 2173.5 LDG 2373		36 1200		31-Aug-2021 3373.5	25 m 28 d 1111.8
5-12-32	INSPECTION DOCUMENT 32 (NDI INTERVAL) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 28-Jul-2009		A/R			
A324103 LEFT MAIN LANDING GEAR 051232 : L	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY (NDI): INSPECTION DOCUMENT 32 (NDI INTERVAL)	SMF		3-1607 2275	MTH 16-Jan-2014 HRS 1252 LDG 1387		T/C			
A324103 NOSE LANDING GEAR 051232 : NOSE	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY (NDI): INSPECTION DOCUMENT 32 (NDI INTERVAL)	SMF		3-1418OPT-2 8397	MTH 28-Aug-2013 HRS 1164.3 LDG 1280		T/C			
A324103 RIGHT MAIN LANDING GEAR 051232 : R	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY (NDI): INSPECTION DOCUMENT 32 (NDI INTERVAL)	SMF		3-1607-1 2252	MTH 16-Jan-2014 HRS 1252 LDG 1387		T/C			
5-12-34	INSPECTION DOCUMENT 34				DAYS 28-Jul-2009		14			
5-12-35	INSPECTION DOCUMENT 35 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTYR			MTH 05-Mar-2019 HRS 2230.8 LDG 2442		4 200			
A243301	CAPACITY CHECK BATTERY (LEAD ACID): INSPECTION DOCUMENT 35	KTYR		RG-380E/44LA2 40883415	MTH 05-Mar-2019 HRS 2230.8 LDG 2442		4 200		31-Jul-2019 2430.8	28 d 169.1
5-12-38 051238	INSPECTION DOCUMENT 38 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTYR			MTH 18-Jun-2019 HRS 2261.7 LDG 2461		6			
B342101	PERIODIC TEST/CHECK STANDBY GYRO POWER SUPPLY PS-855 (LEAD ACID): INSPECTION DOCUMENT 38	KTYR		501-1712-01 3044	MTH 18-Jun-2019 HRS 2261.7 LDG 2461		6		31-Dec-2019	5 m 28 d
5-12-39	INSPECTION DOCUMENT 39				MTH 28-Jul-2009 HRS 0		5000		5000	2738.3
5-12-40	INSPECTION DOCUMENT 40	KALN			MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		6			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-41	INSPECTION DOCUMENT 41	KALN		MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975				1475	340.8
5-12-42	INSPECTION DOCUMENT 42					500			
5-12-43	INSPECTION DOCUMENT 43			MTH HRS		7200		9380.5	7118.8
5-12-MA 0512MA	INSPECTION DOCUMENT MA	KTYR		MTH 15-Nov-2016 HRS 1825.8 LDG 1986 ACH 842.2		500		2325.8	64.1
5-12-MC 0512MC	INSPECTION DOCUMENT MC	KTYL		MTH 07-Nov-2017 HRS 1975 LDG 2116 ACH 975		2000		3975	1713.3
5-12-MD 0512MD	INSPECTION DOCUMENT MD	KTLR		MTH 08-Jan-2015 HRS 1504 LDG 1680		1500		3004	742.3
5-12-ME 0512ME	INSPECTION DOCUMENT ME (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	*CF		MTH 28-Jul-2009 LDG 0		5000			
A322001 NOSE LANDING GEAR	INSPECT FORK AND PISTON ASSEMBLY : INSPECTION DOCUMENT ME		6342350-4 361	MTH 28-Jul-2009 LDG 0		5000		5000	2539
5-12-MF 0512MF	INSPECTION DOCUMENT MF	*CF		MTH 28-Jul-2009 HRS 0		2500		2500	238.3
5-12-MG 0512MG	INSPECTION DOCUMENT MG	*CF		MTH 28-Jul-2009 HRS 0		5000		5000	2738.3
5-12-MH 0512MH	INSPECTION DOCUMENT MH	*CF		MTH 28-Jul-2009 HRS 0		5050		5050	2788.3
5-12-MI 0512MI	INSPECTION DOCUMENT MI	*CF		MTH 28-Jul-2009 HRS 0		6000		6000	3738.3
5-12-MJ 0512MJ	INSPECTION DOCUMENT MJ	*CF		MTH 28-Jul-2009 HRS 0		3000		3000	738.3
5-12-MK	INSPECTION DOCUMENT MK	KTYR		MTH 12-Nov-2018 HRS 2195.6 LDG 2398		12 330		30-Nov-2019 2525.6	4 m 27 d 263.9
5-12-ML	INSPECTION DOCUMENT ML			HRS		9000		9000	6738.3
5-12-MM	INSPECTION DOCUMENT MM			HRS		8000		8000	5738.3
5-12-MN	INSPECTION DOCUMENT MN			MTH 28-Jul-2009 HRS 0		10000		10000	7738.3
5-12-MO	INSPECTION DOCUMENT MO			MTH 28-Jul-2009 HRS 0		15000		15000	12738.3
5-12-MP	INSPECTION DOCUMENT MP			MTH 28-Jul-2009 HRS 0		9500		9500	7238.3
5-12-MQ	INSPECTION DOCUMENT MQ			MTH 28-Jul-2009 HRS 0		15000		15000	12738.3
5-12-MR	INSPECTION DOCUMENT MR			MTH 28-Jul-2009 HRS 0		11500		11500	9238.3
052001 E1	FJ44 CHECK 1	KTYL		MTH 18-May-2018 HRS 2123.2 LDG 2337	-8.4	300		(2372.7)2414.8	153.1
052001 E2	FJ44 CHECK 1	UNK		MTH 27-Feb-2018 HRS 2062.5 LDG 2289		300		(2341)2362.5	100.8



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052002 E1	FJ44 CHECK 2	KTYR	MTH HRS 1825.8 LDG 1986	22-Nov-2016		600		(2372.7)2425.8	164.1
052002 E2	FJ44 CHECK 2	UNK	MTH HRS 2062.5 LDG 2289	27-Feb-2018		600		(2641)2662.5	400.8
052003 E1	FJ44 CHECK 3	UNK	MTH HRS 2241 LDG 2272	08-Feb-2018	-198.9	12000		(14000)14042.1	11780.4
052003 E2	FJ44 CHECK 3	UNK	MTH HRS 2062.5 LDG 2289	27-Feb-2018	-41	12000		(14000)14021.5	11759.8
052004 E1	FJ44 CHECK 4		MTH HRS 42.1	28-Jul-2009	-8000	12000		(4000)4042.1	1780.4
052004 E2	FJ44 CHECK 4		MTH HRS 21.5	28-Jul-2009	-8000	12000		(4000)4021.5	1759.8
052005 E1	FJ44 CHECK 5		MTH HRS 42.1	28-Jul-2009	-6000	12000		(6000)6042.1	3780.4
052005 E2	FJ44 CHECK 5		MTH HRS 21.5	28-Jul-2009	-6000	12000		(6000)6021.5	3759.8
052006 E1	FJ44 CHECK 6		MTH HRS 42.1	28-Jul-2009	-4000	12000		(8000)8042.1	5780.4
052006 E2	FJ44 CHECK 6		MTH HRS 21.5	28-Jul-2009	-4000	12000		(8000)8021.5	5759.8
052007 E1	FJ44 CHECK 7		MTH HRS 42.1	28-Jul-2009	-2000	12000		(10000)10042.1	7780.4
052007 E2	FJ44 CHECK 7		MTH HRS 21.5	28-Jul-2009	-2000	12000		(10000)10021.5	7759.8
052008 E1	FJ44 CHECK 8		MTH HRS 42.1	28-Jul-2009		12000		(12000)12042.1	9780.4
052008 E2	FJ44 CHECK 8		MTH HRS 21.5	28-Jul-2009		12000		(12000)12021.5	9759.8
052009 E1	FJ44 CHECK 9		MTH HRS 42.1	28-Jul-2009		14000		(14000)14042.1	11780.4
052009 E2	FJ44 CHECK 9		MTH HRS 21.5	28-Jul-2009		14000		(14000)14021.5	11759.8
052010 E1	FJ44 CHECK 10		MTH HRS 42.1	28-Jul-2009		16000		(16000)16042.1	13780.4
052010 E2	FJ44 CHECK 10		MTH HRS 21.5	28-Jul-2009		16000		(16000)16021.5	13759.8
215018	REPLACE COMPRESSOR DRIVE MOTOR BRUSHES KALN		MTH HRS 1941.8 LDG 2089 ACH 975	02-Oct-2017		800		1775	640.8
D262001 LEFT 051220 : L	HYDROSTATIC TEST FIRE EXTINGUISHER BOTTLE	KTYR	30401102-2 77944B1	MTH		60		30-Nov-2023	52 m 27 d
D262001 RIGHT 051220 : R	HYDROSTATIC TEST FIRE EXTINGUISHER BOTTLE	KTYR	30401102-2 77946B1	MTH		60		30-Nov-2023	52 m 27 d
D262003 CABIN 051210 : CABIN	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER	*CF	C352TS X571080	MTH		144		31-Mar-2020	8 m 28 d
D262003 COCKPIT 051210 : CKPT	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER	*CF	C352TS X571078	MTH		144		31-Mar-2020	8 m 28 d
28-00-02-280	INSPECT AIRPLANES FUELED WITHOUT BIOCIDAL ADDITIVE			MTH					



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
28-00-02-281	INSPECT AIRPLANES FUELED WITH BIOCIDAL ADDITIVE		MTH	28-Jul-2009		-			
312001A LEFT	REPLACE DIGITAL CLOCK BATTERY	KTYR	M877A5V 19823	MTH HRS LDG	12-Nov-2018 2195.6 2398	12		30-Nov-2019	4 m 27 d
B323101 051207 : GEAR	HYDROSTATIC TEST EMERGENCY PNEUMATIC STORAGE BOTTLE	KTYR	40005320-2 2239	MTH	30-Nov-2017	36		30-Nov-2020	16 m 27 d
B351002 051225 : OXY	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER AND REGULATOR ASSEMBLY	KTYR	176276-50 556166102	MTH	19-Jun-2018	60		30-Jun-2023	47 m 27 d
531115 045317	INSPECT FUSELAGE FITTING TAPER LUG	*CF		MTH HRS	28-Jul-2009 0	1	12000	12001	9739.3
531120 045318	INSPECT FUSELAGE FRAME DOUBLER FS 340	*CF		MTH HRS	28-Jul-2009 0	1	12000	12001	9739.3
571010 LEFT WING 045701	INSPECT FRONT SPAR CAP, WS 3.8	*CF		MTH HRS	28-Jul-2009 0	1	15000	15001	12739.3
571015 RIGHT WING 045701	INSPECT FRONT SPAR CAP, WS 3.8	*CF		MTH HRS	28-Jul-2009 0	1	15000	15001	12739.3
571050 LEFT WING 045709	INSPECT MAIN SPAR, WS 183.50	*CF		MTH HRS	28-Jul-2009 0	1	10000	10001	7739.3
571055 RIGHT WING 045709	INSPECT MAIN SPAR, WS 183.50	*CF		MTH HRS	28-Jul-2009 0	1	10000	10001	7739.3
571060 LEFT WING 045703	INSPECT REAR SPAR CAP, WS 166.33	*CF		MTH HRS	28-Jul-2009 0	1	13000	13001	10739.3
571065 RIGHT WING 045703	INSPECT REAR SPAR CAP, WS 166.33	*CF		MTH HRS	28-Jul-2009 0	1	13000	13001	10739.3
571070 LEFT WING 045704	INSPECT FRONT SPAR SPLICE, WS 132.00	*CF		MTH HRS	28-Jul-2009 0	1	15000	15001	12739.3
571075 RIGHT WING 045704	INSPECT FRONT SPAR SPLICE, WS 132.00	*CF		MTH HRS	28-Jul-2009 0	1	15000	15001	12739.3
571080 LEFT WING 045705	INSPECT MAIN SPAR SPLICE, WS 132.00	*CF		MTH HRS	28-Jul-2009 0	1	9500	9501	7239.3
571085 RIGHT WING 045705	INSPECT MAIN SPAR SPLICE, WS 132.00	*CF		MTH HRS	28-Jul-2009 0	1	9500	9501	7239.3
571090 LEFT WING 045706	INSPECT REAR SPAR SPLICE, WS 132.00	*CF		MTH HRS	28-Jul-2009 0	1	15000	15001	12739.3
571095 RIGHT WING 045706	INSPECT REAR SPAR SPLICE, WS 132.00	*CF		MTH HRS	28-Jul-2009 0	1	15000	15001	12739.3
712003 LEFT ENGINE AFT	LEFT ENGINE AFT ISOLATOR MOUNT (INSPECTION)		LM-605-SA11 LK2984	MTH HRS		4000		4000	1738.3



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
712003 LEFT ENGINE FORWARD BOTTOM	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (INSPECTION)		LM-605-SA8 LK2118	MTH HRS				4000	1738.3
712003 LEFT ENGINE FORWARD TOP	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT (INSPECTION)		LM-605-SA8 LK2126	MTH HRS			4000	4000	1738.3
712003 RIGHT ENGINE AFT	RIGHT ENGINE AFT ISOLATOR MOUNT (INSPECTION)		LM-605-SA10 LK2762	MTH HRS			4000	4000	1738.3
712003 RIGHT ENGINE FORWARD BOTTOM	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (INSPECTION)		LM-605-SA8 LK2115	MTH HRS			4000	4000	1738.3
712003 RIGHT ENGINE FORWARD TOP	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT (INSPECTION)		LM-605-SA8 LK2110	MTH HRS			4000	4000	1738.3
712085 LEFT ENGINE 047103	INSPECT FORWARD ENGINE MOUNT AFT CHANNEL WEB	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
712090 RIGHT ENGINE 047103	INSPECT FORWARD ENGINE MOUNT AFT CHANNEL WEB	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
712095 LEFT ENGINE 047104	INSPECT FORWARD ENGINE MOUNT FORWARD CHANNEL WEB	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
712100 RIGHT ENGINE 047104	INSPECT FORWARD ENGINE MOUNT FORWARD CHANNEL WEB	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
712105 LEFT ENGINE 047107	INSPECT AFT ENGINE MOUNT	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
712110 RIGHT ENGINE 047107	INSPECT AFT ENGINE MOUNT	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
714015 LEFT ENGINE 047102	INSPECT FORWARD ENGINE BEAM AFT CUFF	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
714020 RIGHT ENGINE 047102	INSPECT FORWARD ENGINE BEAM AFT CUFF	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
714035 LEFT ENGINE 047105	INSPECT FORWARD ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
714040 RIGHT ENGINE 047105	INSPECT FORWARD ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
714045 LEFT ENGINE 047106	INSPECT AFT ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
714050 RIGHT ENGINE 047106	INSPECT AFT ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF		MTH HRS	28-Jul-2009 0	1		12000	9739.3
731020 E1	REPLACE FDU-TO-FLOWMETER FUEL TUBEASSEMBLY, FLOWMETER-TO-MANIFOLD FUEL TUBE ASSEMBLY, AND 69233 LOOP CLAMP BRACKET (RENTAL ENGINES ONLY)			MTH	28-Jul-2009			A/R	
731020 E2	REPLACE FDU-TO-FLOWMETER FUEL TUBEASSEMBLY, FLOWMETER-TO-MANIFOLD FUEL TUBE ASSEMBLY, AND 69233 LOOP CLAMP BRACKET (RENTAL ENGINES ONLY)			MTH	28-Jul-2009			A/R	



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211001 LEFT	PRESS SHUTOFF VALVE	KICT		5253-00-3 3301B	MTH 11-Feb-2018 HRS 2041 LDG 2272		O/C	0 0 0		
211001 RIGHT	PRESS SHUTOFF VALVE	KICT		5253-00-3 2326B	MTH 11-Feb-2018 HRS 2041 LDG 2272		O/C	0 0 0		
211002 LEFT	VARIABLE VALVE	*CF		2601-32 714	MTH 28-Jul-2009		O/C			
211002 RIGHT	VARIABLE VALVE	*CF		2601-32 718	MTH 28-Jul-2009		O/C			
211003	HEAT PRESS EXCHANGER			10905A 401	MTH 28-Jul-2009		O/C			
211005	EMER PRESS SHUTOFF VALVE	*CF		2601-23 9912422-2 1127	MTH 28-Jul-2009		O/C			
211006 NO.1	A/C CHECK VALVE	*CF		7125-320101 9912078-9 NSN	MTH 28-Jul-2009		O/C			
211006 NO.2	A/C CHECK VALVE	*CF		7125-320101 9912078-9 NSN	MTH 28-Jul-2009		O/C			
211006 NO.3	A/C CHECK VALVE	*CF		7125-320101 9912078-9 NSN	MTH 28-Jul-2009		O/C			
212001	BAGGAGE CMPT BLOWER	*CF		0113-12 1751	MTH 28-Jul-2009		O/C			
212003	THERMO AIR DIST SWITCH	*CF		1173T42-1 4073	MTH 28-Jul-2009		O/C			
212302	W/S AIR BLOWER MOTOR	*CF		7003-200 1684	MTH 28-Jul-2009		O/C			
212303	BLDC MOTOR ASSEMBLY BLOWER			1133270-2 SN-UNKNOWN	MTH 28-Jul-2009		O/C	0		
213001	PRIMARY OUTFLOW VALVE	KICT		52771-339 989B	MTH 17-Jun-2014 HRS 1348.1 LDG 1517		O/C	2 0 0		
213002	SEC OUTFLOW VALVE	*CF		52772-339 1137	MTH 28-Jul-2009		O/C			
213004 LEFT	OUTFLOW VALVE- 4IN VALVE	*CF		52812-103 1139B	MTH 28-Jul-2009		O/C			
213004 NO.1	SOLENOID BAGGAGE VALVE	*CF		5060-00-1 4010	MTH 28-Jul-2009		O/C			
213004 NO.2	SOLENOID BAGGAGE VALVE	*CF		5060-00-1 4013	MTH 28-Jul-2009		O/C			
213004 RIGHT	OUTFLOW VALVE-4IN VALVE	*CF		52812-103 1156B	MTH 28-Jul-2009		O/C			
215000 AFT	EVAPORATOR BLOWER MOTOR	*CF		1133210-7 1028	MTH 28-Jul-2009		O/C			
215000 FWD	EVAPORATOR BLOWER MOTOR	*CF		1260185-1 2729	MTH 28-Jul-2009		O/C			
215001	FWD EVAPORATOR MODULE	*CF		1134300-3 770	MTH 28-Jul-2009		O/C			
215002	AFT EVAPORATOR MODULE	*CF		1134820-15 811	MTH 28-Jul-2009		O/C			
215003	COMPRESSOR DRIVE MOTOR	KALN		1134146-1 055	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		O/C	0 0 0		
215004	COMPRESSOR DRIVE ASSEMBLY	*CF		1134610-1 842	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215005	CONDENSER ASSEMBLY 9912660-3	TYR		1134620-5 599	MTH 21-Jul-2014 HRS 1371.3 LDG 1534		O/C	0 0 0		
215006	BINARY SWITCH	*CF		1250232-10 NSN	MTH 28-Jul-2009		O/C			
215007	DRYER ASSY RECEIVER 9912583-3	*CF		1134275-1 NSN	MTH 28-Jul-2009		O/C			
215008	COMPRESSOR ASSEMBLY	*CF		1134130-5 920	MTH 28-Jul-2009		O/C			
215009	VANE AXIAL BLOWER ASSY	*CF		1250435-5 297	MTH 28-Jul-2009		O/C			
215010	A/C FLIGHT HOURMETER	*CF		1250703-3 NSN	MTH 16-Jan-2014		O/C			
215011	AIR CONDITIONER DRIVE BELT	*CF		225L100 NSN	MTH 28-Jul-2009		O/C			
216001	RAM AIR MOD VALVE	*CF		27241287-15 1BE9E	MTH 28-Jul-2009		O/C			
216002	TEMP CONTROLLER	*CF		1E58-7 11BD134	MTH 28-Jul-2009		O/C			
216003 AFT	CABIN TC007 SENSOR 9912085-3	*CF		27221274 1BE003	MTH 28-Jul-2009		O/C			
216003 FORWARD	COCKPIT UT006 SENSOR 9912085-3	*CF		27221274 1BE014	MTH 28-Jul-2009		O/C			
221002 AILERON	SERVO MOUNT SMT-65	*CF	1	622-5735-021 3H5FG	MTH 28-Jul-2009		O/C			
221002 ELEVATOR	SERVO MOUNT	*CF	1	622-5735-023 3H5GB	MTH 28-Jul-2009		O/C			
221002 RUDDER	SERVO MOUNT SMT-65	*CF	1	622-5735-022 3H5FJ	MTH 28-Jul-2009		O/C			
221003 AILERON	SERVO SVO-3000	*CF	3	822-1168-002 3CCPP	MTH 28-Jul-2009		O/C			
221003 ELEVATOR	SERVO SVO-3000	*CF	3	822-1168-001 3FXDP	MTH 28-Jul-2009		O/C			
221003 RUDDER	SERVO SVO-3000	*CF	3	822-1168-001 3FXPB	MTH 28-Jul-2009		O/C			
221004	AUTOPILOT PANEL	*CF	8	622-6208-223 356NK	MTH 28-Jul-2009		O/C			
231006 NO.1	VHF COMM TRANSCEIVER VHF-4000	KDAL	03	822-1468-102 37CDL	MTH 23-Jun-2015 HRS 1608.2 LDG 1789		O/C	0 0 0		
231006 NO.2	VHF COMM TRANSCEIVER VHF-4000	*CF	3	822-1468-102 37D1K	MTH 28-Jul-2009		O/C			
231007 NO.1	COMM ANTENNA	*CF		VC10-126-1 0665	MTH 28-Jul-2009		O/C			
231007 NO.2	COMM ANTENNA	*CF		VFS10-90-2 7351	MTH 28-Jul-2009		O/C			
232003	TELEPHONE TRANSCEIVER ST-3100 AIRCELL	*CF	T	400-10680-002 1068021767	MTH 28-Jul-2009		O/C			
232007 CABIN	AIRCELL FLITEFONE HANDSET KICT			P12199-002 1219952203	MTH 17-Jun-2014 HRS 1348.1 LDG 1517		O/C			
232007 CREW	AIRCELL FLITEFONE HANDSET	*CF		P12199-002 1219952302	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
232018	AIRCELL CONFIGURATION MODULE	KICT		P14126 1412612652	MTH 08-Jul-2014 HRS 1348.1 LDG 1517		O/C	0 0 0		
232019	AIRCELL CABIN ROUTER	KICT		P12083-001 1208372623	MTH 08-Jul-2014 HRS 1348.1 LDG 1517		O/C	0 0 0		
232020 FWD	AIRCELL ANTENNA	KICT		P12949 447999	MTH 08-Jul-2014 HRS 1348.1 LDG 1517		O/C	0 0 0		
232022 AFT	AIRCELL ANTENNA	KICT		P12949 448011	MTH 08-Jul-2014 HRS 1348.1 LDG 1517		O/C	0 0 0		
232024	AIRCELL ATG-5000 TRANSCEIVER	KICT		P15864-001 1586414119	MTH 08-Jul-2014 HRS 1348.1 LDG 1517		O/C	0 0 0		
235001	AUDIO AMPLIFIER	*CF		102025-2 4770109	MTH 28-Jul-2009		O/C			
235068 NO.1 345068 : 1	AUDIO CONTROL PANEL RADIO ACP-4130	*CF	B	822-2381-215 3HRFG	MTH 28-Jul-2009		O/C			
235068 NO.2 345068 : 2	AUDIO CONTROL PANEL RADIO ACP W/O HF & W/O ADF*CF	*CF	B	822-2381-215 3HRFF	MTH 28-Jul-2009		O/C			
237003	CVR MICROPHONE	*CF		S055-0067-00 000558140	MTH 28-Jul-2009		O/C			
237004	IMPACT CVR SWITCH	*CF		6895-D-2-X-5-5 8265	MTH 28-Jul-2009		O/C			
243003 LEFT	GENERATOR CONTROL UNIT	*CF		51525-001F P4896	MTH 28-Jul-2009		O/C			
243003 RIGHT	GENERATOR CONTROL UNIT	*CF		51525-001F P4897	MTH 28-Jul-2009		O/C			
243004	BATTERY TEMP MONITOR-	*CF		1529-1-1 5239	MTH 28-Jul-2009		O/C			
243006 LEFT	GEN LOAD AMMETER	*CF		MD130-7 M0810574	MTH 28-Jul-2009		O/C			
243006 RIGHT	GEN LOAD AMMETER	*CF		MD130-7 A0910770	MTH 28-Jul-2009		O/C			
243007	BATTERY	KTYL		RG-380E/44LA2 40883415	MTH 07-Nov-2017 HRS 1975 LDG 2116 ACH 975		O/C	0 0 0		
243008	RELAY-BATTERY	*CF		A931F 26139	MTH 28-Jul-2009		O/C			
243011	DC POWER VOLTMETER	*CF		C662502-0101 M0810582	MTH 28-Jul-2009		O/C			
245001 LEFT	START CONTROL PCB	*CF		6318038-1 0871	MTH 28-Jul-2009		O/C			
245001 RIGHT	START CONTROL PCB	*CF		6318038-1 0877	MTH 28-Jul-2009		O/C			
245002 LEFT	FUEL CONTROL PCB	*CF		6318037-6 0747	MTH 28-Jul-2009		O/C			
245002 RIGHT	FUEL CONTROL PCB	*CF		6318037-6 0748	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245003 LEFT	IGNITOR CNTRL PCB *CF			6318388-7 0240	MTH 28-Jul-2009		O/C			
245003 RIGHT	IGNITOR CNTRL PCB *CF			6318388-7 0239	MTH 28-Jul-2009		O/C			
245004 LEFT	ANTI ICE PCB *CF			6318342-29 0785	MTH 28-Jul-2009		O/C			
245004 RIGHT	ANTI ICE PCB *CF			6318342-29 0781	MTH 28-Jul-2009		O/C			
245006	ENVIRONMENTAL PCB KPDX			6318358-20 0219	MTH 26-Jul-2010 HRS 297.6 LDG 286		O/C	0 0 0		
245007	HYDRAULIC PCB *CF			6318035-7 0411	MTH 28-Jul-2009		O/C			
245008	TRIM RELAY PCB *CF			6518351-9 1218	MTH 28-Jul-2009		O/C			
245010	GEAR LOGIC 1 PCB *CF			6318398-6 0419	MTH 28-Jul-2009		O/C			
245011	FUEL FLOW PCB 9912417-3 *CF			85-230-2 0833993M2	MTH 28-Jul-2009		O/C			
245012	SPEEDBRAKE PCB *CF			6318034-6 0417	MTH 28-Jul-2009		O/C			
245014	GEAR LOGIC 2 PCB *CF			6318399-11 0407	MTH 28-Jul-2009		O/C			
245015	GEAR MONITOR PCB *CF			6318397-21 0485	MTH 28-Jul-2009		O/C			
245016	TAIL DEICE CONTROL PCB *CF			6318044-1 0484	MTH 28-Jul-2009		O/C			
245017	TAIL DEICE MONITOR PCB *CF			6318043-1 0485	MTH 28-Jul-2009		O/C			
245018	PRESSURIZATION PCB *CF			6318349-26 0165	MTH 28-Jul-2009		O/C			
245019	PCB-DIAGNOSTICS -- *CF			6318046-9 0168	MTH 28-Jul-2009		O/C			
245029 NO. 5 441-0080-100	AUX PORT KICT			106084-1 18780114	MTH 08-Jul-2014 HRS 1348.1 LDG 1517		O/C	0 0 0		
256001	ELT TRANSMITTER C406-2 *CF			453-5000-999 07106	MTH 28-Jul-2009		O/C			
256002	ELT BEACON BATTERY PACK KTYL			452-0133 376634-002	MTH 18-May-2018 HRS 2123.2 LDG 2337		DUE DUE DUE DUE	0 0 0 0	01-Apr-2023	44 m 29 d
Expiration Date: 01-Apr-2023										
256003	REMOTE SWITCH *CF			452-0010 NSN	MTH 28-Jul-2009		O/C			
256004	ELT ANTENNA C406-N *CF			110-340 280636	MTH 28-Jul-2009		O/C			
256008	FIRST AID KIT KTYR			39N788 NONE	MTH 05-Mar-2019 HRS 2230.8 LDG 2442		A/R	0 0 0		
261001 LEFT	ENGINE FIRE DETECTOR 9912416-1 *CF			3001-212-1004/455-9 210202	MTH 28-Jul-2009		O/C			
261001 RIGHT	ENGINE FIRE DETECTOR 9912416-1 *CF			3001-212-1004/455-9 210213	MTH 28-Jul-2009		O/C			
261002 AFT	SMOKE DETECTOR *CF			473597-17 1856	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
261002	SMOKE DETECTOR HEATER 9914772-1 *CF	76847-1 1216	MTH 28-Jul-2009		O/C			
262001	FIRE EXTINGUISHER BOTTLE LEFT 9912048-6 KTYR	30401102-2 77944B1	MTH 12-Nov-2018 HRS 2195.6 LDG 2398		O/C	0 0 0		
262001	FIRE EXTINGUISHER BOTTLE RIGHT 9912048-6 KTYR	30401102-2 77946B1	MTH 12-Nov-2018 HRS 2195.6 LDG 2398		O/C	0 0 0		
262002	FIRE EXTINGUISHER (REPLACE) CARTRIDGE LEFT ENGINE NO.1 KTYR	13083-5 SN-UNKNOWN	MTH 12-Nov-2018 HRS 2195.6 LDG 2398		72	0 0	30-Nov-2024	64 m 27 d
Manufacture Date: 05-Nov-2018								
262002	FIRE EXTINGUISHER (REPLACE) CARTRIDGE LEFT ENGINE NO.2 KTYR	13083-5 SN-UNKNOWN	MTH 12-Nov-2018 HRS 2195.6 LDG 2398		72	0 0	30-Nov-2024	64 m 27 d
Manufacture Date: 05-Nov-2018								
262002	FIRE EXTINGUISHER (REPLACE) CARTRIDGE RIGHT ENGINE NO.1 KTYR	13083-5 SN-UNKNOWN	MTH 12-Nov-2018 HRS 2195.6 LDG 2398		72	0 0	30-Nov-2024	64 m 27 d
Manufacture Date: 05-Nov-2018								
262002	FIRE EXTINGUISHER (REPLACE) CARTRIDGE RIGHT ENGINE NO.2 KTYR	13083-5 SN-UNKNOWN	MTH 12-Nov-2018 HRS 2195.6 LDG 2398		72	0 0	30-Nov-2024	64 m 27 d
Manufacture Date: 05-Nov-2018								
262003	PORTABLE FIRE EXTINGUISHER CABIN *CF	C352TS X571080	MTH 05-Mar-2008		O/C	0		
262003	PORTABLE FIRE EXTINGUISHER COCKPIT *CF	C352TS X571078	MTH 05-Mar-2008		O/C	0		
270001	SPEED BRAKE FILTER FITTING LEFT *CF	20666-6-250 NSN	MTH 28-Jul-2009		O/C			
270001	SPEED BRAKE FILTER FITTING RIGHT *CF	20666-6-250 NSN	MTH 28-Jul-2009		O/C			
272001	RUDDER BIAS SHUTOFF VALVE *CF	5307-1 1571C	MTH 28-Jul-2009		O/C			
273002	ELEV TRIM SERVO *CF 4	44430-3548 T1384	MTH 28-Jul-2009		O/C			
273003	ACTUATOR MOUNT ASSEMBLY *CF 1	44575-3415 T2477	MTH 28-Jul-2009		O/C			
275001	SHUTOFF VALVE *CF	4083-1 1004	MTH 28-Jul-2009		O/C			
275002	FLAP ACTUATOR *CF LEFT 9912365-6	2-8210-2 1024	MTH 28-Jul-2009		O/C			
275002	FLAP ACTUATOR *CF RIGHT 9912365-6	2-8210-2 1028	MTH 28-Jul-2009		O/C			
276001	SPEED BRAKE ACTUATOR LEFT 9912375-5 *CF	2-8209-2 AAA619P617	MTH 28-Jul-2009		O/C			
276001	SPEED BRAKE ACTUATOR RIGHT 9912375-5 *CF	2-8209-2 1043	MTH 28-Jul-2009		O/C			
281001	SURGE TANK FLOAT VALVE LEFT 9912016-2 *CF	35C10D 5107	MTH 28-Jul-2009		O/C			
281001	SURGE TANK FLOAT VALVE RIGHT 9912016-2 *CF	35C10D 5118	MTH 28-Jul-2009		O/C			
282001	FUEL BOOST PUMP *CF LEFT 9912553-1	1C7-23 1BE37	MTH 28-Jul-2009		O/C			
282001	FUEL BOOST PUMP *CF RIGHT 9912553-1	1C7-23 1BE41	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282002 LEFT AFT	EJECTOR FUEL AFT/SCAVENG PUMP 9912190-3	*CF		RG45880 B2402	MTH 28-Jul-2009		O/C			
282002 LEFT FORWARD	EJECTOR FUEL FWD/SCAVENG PUMP 9912190-3	*CF		RG45880 B2681	MTH 28-Jul-2009		O/C			
282002 RIGHT AFT	EJECTOR FUEL AFT/SCAVENG PUMP 9912190-3	*CF		RG45880 B2411	MTH 28-Jul-2009		O/C			
282002 RIGHT FORWARD	EJECTOR FUEL FWD/SCAVENG PUMP 9912190-3	*CF		RG45880 B2819	MTH 28-Jul-2009		O/C			
282004 LEFT	FUEL MOTOR VALVE 9912014-3	*CF		AV24B1507 AA185115	MTH 28-Jul-2009		O/C			
282004 RIGHT	FUEL MOTOR VALVE 9912014-3	*CF		AV24B1507 AA185117	MTH 28-Jul-2009		O/C			
282005 LEFT	EJECTOR FUEL PRIMARY PUMP 9912190-2	*CF		RG45310 C1822	MTH 28-Jul-2009		O/C			
282005 RIGHT	EJECTOR FUEL PRIMARY PUMP 9912190-2	*CF		RG45310 C1837	MTH 28-Jul-2009		O/C			
282006	TRANSFER VALVE 9914103-6	*CF		ZSV57 08120189	MTH 28-Jul-2009		O/C			
284001 LEFT	#5 UL005 FUEL PROBE 9912589-5	*CF		10664T05Y00 MN23002	MTH 28-Jul-2009		O/C			
284001 RIGHT	#5 UR005 FUEL PROBE 9912589-5	*CF		10664T05Y00 MN22863	MTH 28-Jul-2009		O/C			
284002 LEFT	#6 UL006 FUEL PROBE 9912589-6	*CF		10664T06Y00 MN23516	MTH 28-Jul-2009		O/C			
284002 RIGHT	#6 UR006 FUEL PROBE 9912589-6	*CF		10664T06Y00 MN22588	MTH 28-Jul-2009		O/C			
284003	FUEL QTY SIGNAL CONDITIONER 9912619-1	*CF		10713B01Y01 09010446	MTH 28-Jul-2009		O/C			
284004 LEFT	#3 UL003 FUEL PROBE 9912589-3	*CF		10664T03Y00 MN23163	MTH 28-Jul-2009		O/C			
284004 RIGHT	#3 UR003 FUEL PROBE 9912589-3	*CF		10664T03Y00 MN23165	MTH 28-Jul-2009		O/C			
284005 LEFT	#4 UL004 FUEL PROBE 9912589-4	*CF		10664T04Y00 MN19551	MTH 28-Jul-2009		O/C			
284005 RIGHT	#4 UR004 FUEL PROBE 9912589-4	*CF		10664T04Y00 MN22158	MTH 28-Jul-2009		O/C			
284006 LEFT	#2 UL002 FUEL PROBE 9912589-2	*CF		10664T02Y00 MN18744	MTH 28-Jul-2009		O/C			
284006 RIGHT	#2 UR002 FUEL PROBE 9912589-2	*CF		10664T02Y00 MN17904	MTH 28-Jul-2009		O/C			
284007 LEFT	#1 UL001 FUEL PROBE 9912589-1	*CF		10664T01Y00 MN19894	MTH 28-Jul-2009		O/C			
284007 RIGHT	#1 UR001 FUEL PROBE 9912589-1	*CF		10664T01Y00 MN16321	MTH 28-Jul-2009		O/C			
284008 LEFT	FUEL LOW LEVEL SWITCH L16H-14	*CF		1157	MTH 28-Jul-2009		O/C			
284008 RIGHT	FUEL LOW LEVEL SWITCH L16H-14	*CF		1174	MTH 28-Jul-2009		O/C			
284010 LEFT	FUEL QUANTITY TRANSMITTER 9912556-6	*CF		10634T11Y00 MN18770	MTH 28-Jul-2009		O/C			
284010 RIGHT	FUEL QUANTITY TRANSMITTER 9912556-6	*CF		10634T11Y00 MN15184	MTH 28-Jul-2009		O/C			
291002 LEFT	HYDRAULIC PUMP 9912062-6	*CF		24195-LAC 1500	MTH 28-Jul-2009		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-6	*CF		24195-LAC 1501	MTH 28-Jul-2009		O/C			
291005	HYDRAULIC RESERVOIR ASSEMBLY *CF			6317500-16 582	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
291006	LOADING VALVE 9912423-39	*CF		4134-4 1474	MTH 28-Jul-2009		O/C			
291007	PRESSURE SWITCH GAUGE 9912373-6	SMF		GPP1250-301 0935099	MTH 16-Jan-2010 HRS 160		O/C	0		
291008	HYD MANIFOLD ASSEMBLY 9912423-47	*CF		8250-2 0636	MTH 28-Jul-2009		O/C			
291009	RELIEF VALVE	*CF		2R4120 NSN	MTH 28-Jul-2009		O/C			
291010 LEFT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 AA187368	MTH 28-Jul-2009		O/C			
291010 RIGHT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 AA187371	MTH 28-Jul-2009		O/C			
291011 LEFT	FLOW SWITCH VALVE 9912194-5	*CF		V10F75 882A	MTH 28-Jul-2009		O/C			
291011 RIGHT	FLOW SWITCH VALVE 9912194-5	*CF		V10F75 866A	MTH 28-Jul-2009		O/C			
291012	SPDBK DUMP VALVE 9912423-33	*CF		4082-6 1065	MTH 28-Jul-2009		O/C			
291013	RELIEF, SYSTEM VALVE 9912423-46	*CF		2576-2 1196A	MTH 28-Jul-2009		O/C			
291014	VALVE-GEAR 9912423-44	*CF		4051-4 1039	MTH 28-Jul-2009		O/C			
291016 LEFT	SPDBK CHECK VALVE 9912423-31	*CF		9505-1 2121	MTH 28-Jul-2009		O/C			
291016 RIGHT	SPDBK CHECK VALVE 9912423-31	*CF		9505-1 2120	MTH 28-Jul-2009		O/C			
291017	THERM REL VALVE 9912423-32	*CF		2577-1 1086	MTH 28-Jul-2009		O/C			
291018	PNEUMATIC DUMP VALVE 9912423-34	*CF		9503-2 1072	MTH 28-Jul-2009		O/C			
291020	SPEED BRAKE VALVE 9912423-30	*CF		4052-3 1103	MTH 28-Jul-2009		O/C			
291021	FLAP VALVE 9912423-29	*CF		4052-4 1110	MTH 28-Jul-2009		O/C			
291022	CHECK VALVE	*CF		CV02-193 NSN	MTH 28-Jul-2009		O/C			
291023	GEAR VALVE SOLENOID	*CF		4051-4 NSN	MTH 28-Jul-2009		O/C			
301002 LEFT	PRESSURE SWITCH	*CF		1106P55-1 7301A	MTH 28-Jul-2009		O/C			
301002 RIGHT	PRESSURE SWITCH	*CF		1106P55-1 7304A	MTH 28-Jul-2009		O/C			
301003 LEFT	ANTI-ICE PRESSURE REGULATING VALVE 9914710-3	*CF		1H148-1 3BE16	MTH 28-Jul-2009 HRS 0		4500	0	4500	2238.3
301003 RIGHT	ANTI-ICE PRESSURE REGULATING VALVE 9914710-3	*CF		1H148-1 3BE17	MTH 28-Jul-2009 HRS 0		4500	0	4500	2238.3
301004 LEFT	TEMPERATURE SWITCH	*CF		1050C H7777	MTH 28-Jul-2009		O/C			
301004 RIGHT	TEMPERATURE SWITCH	*CF		1050C H7268	MTH 28-Jul-2009		O/C			
301006 LEFT	HORIZONTAL STAB BOOT	*CF		29S-4D5244-15 MBFB650	MTH 28-Jul-2009		O/C			
301006 RIGHT	HORIZONTAL STAB BOOT	*CF		29S-4D5244-16 MBCK130	MTH 28-Jul-2009		O/C			
301007	ENG BLEED SHUTOFF VALVE 9914552-2	*CF		2602-43 0334	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
302001 LEFT	PRESS REG VALVE	*CF		5285-00-3 2047	MTH 28-Jul-2009		O/C			
302001 RIGHT	PRESS REG VALVE	*CF		5285-00-3 2304	MTH 28-Jul-2009		O/C			
302002 LEFT	INLET TEMP SWITCH	*CF		1173T0759 5376	MTH 28-Jul-2009		O/C			
302002 RIGHT	INLET TEMP SWITCH	*CF		1173T0759 5266	MTH 28-Jul-2009		O/C			
303002 LEFT	PITOT TUBE	*CF		PH1100-1-VBW 1162603	MTH 28-Jul-2009		O/C			
303002 RIGHT	PITOT TUBE	*CF		PH1100-1-VBW 1162605	MTH 28-Jul-2009		O/C			
303003 STANDBY	PITOT TUBE S2800-493	*CF		PH1100-RW-RIGHT 1155505	MTH 28-Jul-2009		O/C			
304001	B/A TEMP MONITOR-	*CF		1169-1 4406	MTH 28-Jul-2009		O/C			
304002	HEAT EXCHANGER 9912041-3	*CF		10653A 2156	MTH 28-Jul-2009		O/C			
304003	PRESS REG VALVE 9912402-14	*CF		1962-00-3 4705	MTH 28-Jul-2009		O/C			
304004 AFT	FLOORBD TF006 SENSOR 9912085-3	*CF		27221274 11BD808	MTH 28-Jul-2009		O/C			
304004 FORWARD	T/C TT002 SENSOR 9912085-3	*CF		27221274 1BE005	MTH 28-Jul-2009		O/C			
304005	TEMP CONTROLLER 9912085-6	*CF		1E58-1 1BE13	MTH 28-Jul-2009		O/C			
304006	TEMP CONTROL VALVE 9912085-1	*CF		27241287 8BD141T	MTH 28-Jul-2009		O/C			
304007	ALCOHOL PUMP	*CF		476411E NSN	MTH 28-Jul-2009		O/C			
304008 LEFT	W/S BLEED AIR VALVE BYLB50168	*CF		1403-25 5151	MTH 28-Jul-2009		O/C			
304008 RIGHT	W/S BLEED AIR VALVE BYLB50168	*CF		1403-25 5186	MTH 28-Jul-2009		O/C			
304009	PRESSURE SWITCH	*CF		1115P25 4927AB	MTH 28-Jul-2009		O/C			
304010 NO. 1	UC038 CURRENT SENSOR	*CF		76250-6 8386	MTH 28-Jul-2009		O/C			
304010 NO. 2	UC039 CURRENT SENSOR	*CF		76250-6 8378	MTH 28-Jul-2009		O/C			
304010 NO. 3	UC040 CURRENT SENSOR	*CF		76552-1 7775	MTH 28-Jul-2009		O/C			
304010 NO. 4	UC041 CURRENT SENSOR	*CF		76552-1 7756	MTH 28-Jul-2009		O/C			
304010 NO. 5	UC042 CURRENT SENSOR	*CF		76552-1 7757	MTH 28-Jul-2009		O/C			
304010 NO. 6	UC043 CURRENT SENSOR	*CF		76250-6 8388	MTH 28-Jul-2009		O/C			
304011 LEFT	SOLENOID DEICE VALVE	*CF		3D2353-06 N085611	MTH 28-Jul-2009		O/C			
304011 RIGHT	SOLENOID DEICE VALVE	*CF		3D2353-06 N085616	MTH 28-Jul-2009		O/C			
312001 LEFT	DIGITAL CLOCK	*CF		M877A5V 19823	MTH 28-Jul-2009		O/C			
313001	FLIGHT HOURMETER 85071	*CF		C664503-0104 NSN	MTH 28-Jul-2009		O/C			
315002	ANNUNCIATOR PANEL	*CF		9912618-8 618000682	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
321001 LEFT	MAIN LANDING GEAR	*CF		6341350-5 321	MTH 28-Jul-2009		O/C			
321001 RIGHT	MAIN LANDING GEAR	*CF		6341350-6 324	MTH 28-Jul-2009		O/C			
321003 LEFT MAIN LANDING GEAR	TRUNNION ASSEMBLY	KALN		6341321-5 26648887	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975			0 0 0	17089	14628
321004 RIGHT MAIN LANDING GEAR	TRUNNION ASSEMBLY	KALN		6341321-6 26718423	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		15000	0 0 0	17089	14628
321005 LEFT MAIN LANDING GEAR	OLEO ASSEMBLY	KALN		6341301-16 670	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		15000	2089	15000	12539
321005 RIGHT MAIN LANDING GEAR	OLEO ASSEMBLY	KALN		6341301-16 674	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		15000	2089	15000	12539
321010 LEFT MAIN LANDING GEAR	TRAILING LINK	*CF		6341341-1 328	MTH 28-Jul-2009 LDG 0		15000	0	15000	12539
321010 RIGHT MAIN LANDING GEAR	TRAILING LINK	*CF		6341341-2 330	MTH 28-Jul-2009 LDG 0		15000	0	15000	12539
321011 321010	ANTISKID CONTROL VALVE	*CF		39-913 9912621-3 414	MTH 28-Jul-2009		O/C			
322001 NOSE LANDING GEAR	SHIMMY DAMPER	KTYR		6343001-10 26777147F	MTH 29-May-2019 HRS 2261.7 LDG 2461		O/C	0 0 0		
322002	NOSE LANDING GEAR ASSEMBLY	*CF		6342350-9 NSN	MTH 28-Jul-2009		O/C			
322003	NLG FORK	*CF		5542300-1 NSN	MTH 28-Jul-2009		O/C			
322004 NOSE LANDING GEAR	FORK AND PISTON ASSEMBLY	*CF		6342350-4 361	MTH 28-Jul-2009 LDG 0		12500	0	12500	10039
322005 NOSE LANDING GEAR	STRUT ASSEMBLY	*CF		6342350-8 333	MTH 28-Jul-2009 LDG 0		22500	0	22500	20039
322006	NLG CYLINDER BRAZE ASSEMBLY	*CF		5542100-3 NSN	MTH 28-Jul-2009		O/C			
323001 LEFT MAIN LANDING GEAR	ACTUATOR ASSEMBLY	*CF		2-8207-1 9912573-3 0711	MTH 28-Jul-2009 LDG 0		12000	0	12000	9539
323001 RIGHT MAIN LANDING GEAR	ACTUATOR ASSEMBLY	*CF		2-8207-1 9912573-3 0715	MTH 28-Jul-2009 LDG 0		12000	0	12000	9539
323002 LEFT	UPLOCK MAIN GEAR	*CF		6327504-6 2027	MTH 28-Jul-2009		O/C			
323002 RIGHT	UPLOCK MAIN GEAR	*CF		6327504-6 2552	MTH 28-Jul-2009		O/C			
323004 NOSE LANDING GEAR	ACTUATOR ASSEMBLY	KCLS		1541900-7 9912370-5 1521	MTH 05-Oct-2012 HRS 928.7 LDG 1029		7500	0 0	8529	6068
323005	NOSE LANDING GEAR UPLOCK ACTUATOR	*CF		6327504-7 1321	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323006	HYD SHUTTLE VALVE			98312 1877A	MTH 28-Jul-2009		O/C			
		*CF								
323007 NO.1	SHUTTLE, REGEN VALVE			5128-6 9914689-2	MTH 28-Jul-2009		O/C			
		*CF		701						
323007 NO.2	SHUTTLE, REGEN VALVE			5128-6 9914689-2	MTH 28-Jul-2009		O/C			
		*CF		711						
323020	EMERGENCY PNEUMATIC STORAGE BOTTLE				MTH 12-Dec-2017		288	227	31-Jan-2023	42 m 28 d
	9912368-2	KTYR		40005320-2 2239	HRS 1986.7 LDG 2130 ACH 975					
Manufacture Date: 31-Jan-1999										
323021	EMER GEAR BOTTLE GAUGE			19940932-1 025112	MTH 28-Jul-2009		O/C			
		*CF								
324001 LEFT MAIN LANDING GEAR	WHEEL ASSEMBLY	KPDX		3-1607 9912561-4	MTH 03-Dec-2010		O/C			
				2275	HRS 408.9 LDG 407					
324001 RIGHT MAIN LANDING GEAR	WHEEL ASSEMBLY	*CF		3-1607-1 9912561-5	MTH 28-Jul-2009		O/C			
				2252						
324002 NOSE LANDING GEAR	WHEEL ASSEMBLY	*CF		3-1418OPT-2 9914069-2	MTH 28-Jul-2009		O/C			
				8397						
324003 LEFT MAIN LANDING GEAR	TIRE	KTYR		026-618-0 8195R00082	MTH 24-Dec-2018		O/C	0		
					HRS 2207.3 LDG 2414			0		
324003 RIGHT MAIN LANDING GEAR	TIRE	KTYR		026-618-0 8197R00233	MTH 24-Dec-2018		O/C	0		
					HRS 2207.3 LDG 2414			0		
324004 NOSE LANDING GEAR	TIRE	KTYR		031-613-8 7074S00378	MTH 20-Jun-2017		O/C	0		
					HRS 1920.4 LDG 2071 ACH 842.2			0		
324005 LEFT MAIN LANDING GEAR	BRAKE ASSEMBLY	KTYR		2-1695 9912617-2	MTH 12-Nov-2018		O/C	0		
				0142	HRS 2195.6 LDG 2398			0		
324005 RIGHT MAIN LANDING GEAR	BRAKE ASSEMBLY	KTYR		2-1695 9912617-2	MTH 12-Nov-2018		O/C	0		
				0055	HRS 2195.6 LDG 2398			0		
324101	BRK ANTISKID/METERING VALVE			32-107-1 9912621-2	MTH 28-Jul-2009		O/C			
		*CF		390						
324102 LEFT	ANTISKID TRANSDUCER			40-955 9912305-2	MTH 28-Jul-2009		O/C			
		*CF		9220						
324102 RIGHT	ANTISKID TRANSDUCER			40-955 9912305-2	MTH 28-Jul-2009		O/C			
		*CF		9198						
324103	DIG ANTISKID CNTRL BOX			142-103 9912621-1	MTH 28-Jul-2009		O/C			
		*CF		3678						
324104	BRAKE PRESSURE SWITCH			GPP1250-69 9903354	MTH 28-Jul-2009		O/C			
		*CF								
324105	PARKING BRAKE VALVE			95853 9912388-1	MTH 28-Jul-2009		O/C			
		*CF		1650A						
324106	HYDRAULIC PUMP MOTOR			MP50B1 9912388-1	MTH 28-Jul-2009		O/C			
		*CF		4177						
324107	BRAKE ANTISKID ACCUMULATOR			7550-2 9912644-2	MTH 28-Jul-2009		O/C			
		*CF		0676						



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324108	LOW PRESSURE SWITCH *CF			GPP1250-79 084900	MTH 28-Jul-2009		O/C			
324109	BRAKE PRESSURE PUMP 9912364-2 *CF			640929 2524A	MTH 28-Jul-2009		O/C			
324110	EMERGENCY BRAKE VALVE 9912387-3 *CF			878208-03 V1047	MTH 28-Jul-2009		O/C			
324111	FAULT DISPLAY UNIT 9912305-9 *CF			42-92750 2482A	MTH 28-Jul-2009		O/C			
324204	DISCARD BRAKE HYDRAULIC PACK ASSEMBLY FILTER ELEMENT TASK# 32-42-05-960	KTYR		9912372-1 NONE	MTH 10-Aug-2018 HRS 2173.5 LDG 2373		36 1200	0 0	31-Aug-2021 3373.5	25 m 28 d 1111.8
324205	DISCARD BRAKE RESERVOIR AIR FILTER ELEMENT TASK# 32-42-04-960	KTYR		AN6237-1 NONE	MTH 10-Aug-2018 HRS 2173.5 LDG 2373		36 1200	0 0	31-Aug-2021 3373.5	25 m 28 d 1111.8
326001 LEFT	MLG UPLOCK SWITCH *CF			65-430087 NSN	MTH 28-Jul-2009		O/C			
326001 NOSE	NLG UPLOCK SWITCH *CF			65-430087 NSN	MTH 28-Jul-2009		O/C			
326001 RIGHT	MLG UPLOCK SWITCH *CF			65-430087 NSN	MTH 28-Jul-2009		O/C			
331001 LEFT	LIGHT UB001 DIMMER *CF			273-1 32VMH	MTH 28-Jul-2009		O/C			
331001 RIGHT	LIGHT UB002 DIMMER *CF			273-1 32Y1W	MTH 28-Jul-2009		O/C			
331003	INDIRECT LIGHTING CONTROL BOX *CF			CLC500-01 500003535	MTH 28-Jul-2009		O/C			
331097 AFT	2G FORCE SWITCH KICT			7212-2-000 1414	MTH 17-Jun-2014 HRS 1348.1 LDG 1517		O/C	0 0 0		
334001	GROUND REC LIGHT 9912679-4	KGGG		84003-3 000541	MTH 20-Apr-2015 HRS 1571.5 LDG 1751		O/C	0 0 0		
334004 LEFT	LANDING LAMP HOUSING KALN			LDL100-01 206000263	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		O/C			
334004 RIGHT	LANDING LAMP HOUSING KALN			LDL100-01 206000488	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		O/C			
334005 LEFT	ANTI-COLLISION LIGHT ASSEMBLY 9912679-1 *CF			84005-1 000442	MTH 28-Jul-2009		O/C			
334005 RIGHT	ANTI-COLLISION LIGHT ASSEMBLY 9912679-2 *CF			84005-1 000371	MTH 28-Jul-2009		O/C			
334006 LEFT	FLOOD TAIL LIGHT ASSEMBLY *CF			01-0770966-00 03553A	MTH 28-Jul-2009		O/C			
334007	TAIL LIGHT ASSEMBLY			PN SN-UNKNOWN	MTH 28-Jul-2009		O/C	0		
335000 LEFT	EMERGENCY EXIT BATTERY KALN			CBS28-1 3807M	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
335000 RIGHT	EMERGENCY EXIT BATTERY	KALN		CBS28-1 4009M	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		O/C			
341001 NO. 1	AIR DATA COMPUTER ADC-3000	*CF	6	822-1109-014 39KWV	MTH 28-Jul-2009		O/C			
341001 NO. 2	AIR DATA COMPUTER ADC-3000	*CF	6	822-1109-014 39KWV	MTH 28-Jul-2009		O/C			
341001 STANDBY	AIR DATA COMPUTER ADC-3000	*CF		501-1890-04 3409	MTH 28-Jul-2009		O/C			
341004	AOA COMPUTER	*CF		C-13406-1 859	MTH 28-Jul-2009		O/C			
341006	AOA INDICATOR	*CF		C12405-1 85100	MTH 28-Jul-2009		O/C			
341007	AOA SENSOR	*CF		C-12717-1 2388	MTH 28-Jul-2009		O/C			
341008	BAROMETRIC SWITCH	*CF		GBC300-156 0911783	MTH 28-Jul-2009		O/C			
341010 AFT	RADIO ALT ANTENNA	*CF		S67-2002 54346292	MTH 28-Jul-2009		O/C			
341010 FORWARD	RADIO ALT ANTENNA	*CF		S67-2002 54346293	MTH 28-Jul-2009		O/C			
341030	TEMP PROBE SENSOR	*CF		0129G A82224	MTH 28-Jul-2009		O/C			
341034	RADIO ALT TRANSMITTER ALT-4000	*CF	12	822-0615-206 39VVB	MTH 28-Jul-2009		O/C			
341101 NO.2	CONFIG CNTRL STRAPPING UNIT	*CF		822-1363-002 380GW	MTH 28-Jul-2009		O/C			
341103 : 2										
341103 NO.1	CONFIG CNTRL STRAPPING UNIT	*CF		822-1363-002 380CF	MTH 28-Jul-2009		O/C			
342000	TAWS COMPUTER TAWS8000	*CF		805-18000-001 -	MTH 28-Jul-2009		O/C			
342002 LEFT	AHRS COMPUTER AHC-3000	*CF	3	822-1110-002 3CFFF	MTH 28-Jul-2009		O/C			
342002 RIGHT	AHRS COMPUTER AHC-3000	*CF	3	822-1110-002 3CG9X	MTH 28-Jul-2009		O/C			
342004	DATA BASE UNIT -- DBU-5000	*CF	02	822-2215-602 3F9KH	MTH 28-Jul-2009		O/C			
342005 LEFT	FLT GUIDANCE COMPUTER	*CF	1	822-1108-033 3G3BP	MTH 28-Jul-2009		O/C			
342005 RIGHT	FLT GUIDANCE COMPUTER	*CF	1	822-1108-033 3G359	MTH 28-Jul-2009		O/C			
342006 LEFT	FLUX DETECTOR UNIT FDU-3000	*CF		822-1193-001 42368	MTH 28-Jul-2009		O/C			
342006 RIGHT	FLUX DETECTOR UNIT FDU-3000	*CF		822-1193-001 42367	MTH 28-Jul-2009		O/C			
342007 LEFT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-003 3CG8D	MTH 28-Jul-2009		O/C			
342007 RIGHT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-003 3CG7R	MTH 28-Jul-2009		O/C			
342008 LEFT	IAPS POWER SUPPLY PWR-3000	*CF	6	822-1137-001 380OMH	MTH 28-Jul-2009		O/C			
342008 RIGHT	IAPS POWER SUPPLY PWR-3000	*CF	6	822-1137-001 380OMR	MTH 28-Jul-2009		O/C			
342009	ENVIRONMENTAL CONTROL IEC-3001	*CF	3	822-1167-001 3804W	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342010 LEFT	OPER CONFIG MODULE *CF			822-1484-228 3BOKL	MTH 28-Jul-2009		O/C			
342010 RIGHT	OPER CONFIG MODULE *CF			822-1484-228 3BOKM	MTH 28-Jul-2009		O/C			
342011 LEFT	I/O CONCENTRATOR IAPS MODULE IOC-4100 *CF	5		822-2065-001 381LF	MTH 28-Jul-2009		O/C			
342011 RIGHT	I/O CONCENTRATOR IAPS MODULE IOC-4100 *CF	5		822-2065-001 3B1LG	MTH 28-Jul-2009		O/C			
342011	DETACHABLE CONFIG MODULE *CF			501-1803-153 3959	MTH 28-Jul-2009		O/C			
342012 RIGHT	IAPS - ICC CARD CAGE *CF			822-2191-001 N/A	MTH 28-Jul-2009		O/C			
342031	STANDBY GYRO POWER SUPPLY PS-855A	KTYR	08	501-1712-01 3044	MTH 06-Dec-2018 HRS 2203.4 LDG 2408		O/C			
342032	SECONDARY FLIGHT DISPLAY GH-3000	KPDX		501-1741-2103 0743	MTH 31-Aug-2012 HRS 891.2 LDG 974		O/C			
342033	MAINTENANCE DIAGNOSTIC COMPUTER MDC3110	KTYR	8	822-1987-007 30CDM	MTH 07-Aug-2017 HRS 1932.5 LDG 2083		O/C	0 0 0		
342055 LEFT	DATA CONCENTRATOR UNIT DCU-3001 *CF			822-1483-250 2TG4P	MTH 28-Jul-2009		O/C			
342055 RIGHT	DATA CONCENTRATOR UNIT DCU-3001 *CF			822-1483-250 35HMY	MTH 28-Jul-2009		O/C			
342055	MODULE MULTI-FUNCTION -- *CF			9118009-4 0170	MTH 28-Jul-2009		O/C			
342056 LEFT	AFD CONTROL DISPLAY PANEL DCP-3030 *CF			822-1828-102 3FD2V	MTH 28-Jul-2009		O/C			
342056 RIGHT	AFD CONTROL DISPLAY PANEL DCP-3030 *CF			822-1828-102 3FDOV	MTH 28-Jul-2009		O/C			
342057	AFD CRSR CONTROL PANEL CCP-3000 *CF	1		822-1746-102 3FCLL	MTH 28-Jul-2009		O/C			
342301 LEFT	MODE SELECTOR *CF	14		622-6209-020 356NY	MTH 28-Jul-2009		O/C			
342301 RIGHT	MODE SELECTOR *CF	14		622-6209-020 356PC	MTH 28-Jul-2009		O/C			
342301	COURSE/HEADING PANEL *CF	KPDX	1	822-1279-002 2X5TW	MTH 14-Feb-2013 HRS 1020 LDG 1139		O/C	0 0 0		
342302 CENTER	ADAPTIVE FLIGHT DISPLAY AFD-3010E *CF	30		822-1753-124 3F6PH	MTH 28-Jul-2009		O/C			
342302 LEFT	ADAPTIVE FLIGHT DISPLAY AFD-3010 *CF	30		822-1084-124 3F5DL	MTH 28-Jul-2009		O/C			
342302 RIGHT	ADAPTIVE FLIGHT DISPLAY AFD-3010 *CF	30		822-1084-124 3F5DK	MTH 28-Jul-2009		O/C			
342303	COURSE PANEL CKP-3000 *CF			822-1281-002 3FCKK	MTH 28-Jul-2009		O/C			
342304 CENTER	ADAPTIVE FLIGHT DISPLAY MOUNTING TRAY *CF			822-1140-101 3FTNP	MTH 28-Jul-2009		O/C			
342304 LEFT	ADAPTIVE FLIGHT DISPLAY MOUNTING TRAY *CF			822-1140-101 3FTPC	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342304 RIGHT	ADAPTIVE FLIGHT DISPLAY MOUNTING TRAY *CF			822-1140-101 3FTPB	MTH 28-Jul-2009		O/C			
343001	MARKER BEACON ANTENNA KALN			MB10-754 2358	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		O/C	0 0 0		
343002	DUAL GLIDESLOPE COUPLER *CF			82-70-01 2242	MTH 28-Jul-2009		O/C			
343003	GLIDESLOPE ANTENNA *CF			RGS10-48 14568	MTH 28-Jul-2009		O/C			
344002	WEATHER RADAR REC/XMTR ANTENNA RTA-800	*CF	38	822-1050-004 3CNYX	MTH 28-Jul-2009		O/C			
344011	STORMSCOPE PROCESSOR WX-1000E	*CF		78-8060-6086-5 000327	MTH 28-Jul-2009		O/C			
344012	STORMSCOPE ANTENNA WX-1000E	*CF	2	78-8051-9200-8 82177	MTH 28-Jul-2009		O/C			
344014	SATELLITE DATALNK WT RECEIVER XMWR-1000	*CF	01	822-2031-002 3CH3Y	MTH 28-Jul-2009		O/C			
344017 1	GPS XM ANTENNA 9154079-85	*CF		CI428-410 285073	MTH 28-Jul-2009		O/C			
344017 NO. 2	GPS XM ANTENNA --	*CF		CI428-410 285070	MTH 28-Jul-2009		O/C			
345001 NO.1	FORWARD DME ANTENNA *CF			DMNI50-2-2 123870	MTH 28-Jul-2009		O/C			
345002 NO.1	LEFT DME TRANSCEIVER DME-4000	*CF	4	822-1466-001 3CKOT	MTH 28-Jul-2009		O/C			
345005 LEFT	NAVIGATION ANTENNA *CF			VT11-767-3 1571	MTH 28-Jul-2009		O/C			
345005 RIGHT	NAVIGATION ANTENNA *CF			VT11-767-3 1570	MTH 28-Jul-2009		O/C			
345040 LEFT	DIVERSITY TRANSPONDER ANTENNA *CF			DMNI50-2-2 119202	MTH 28-Jul-2009		O/C			
345040 NO.1	TRANSPONDER ANTENNA *CF			DMNI50-2-2 123701	MTH 28-Jul-2009		O/C			
345040 NO.2	TRANSPONDER ANTENNA *CF			DMNI50-2-2 119268	MTH 28-Jul-2009		O/C			
345040 RIGHT	DIVERSITY TRANSPONDER ANTENNA KALN			DMNI50-2-2 140817	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		O/C	0 0 0		
345041 NO. 1	TRANSPONDER	KICT	29	622-9210-501 23N2C	MTH 11-Feb-2018 HRS 2041 LDG 2272		O/C			
345041 NO. 2	TRANSPONDER	KICT	29	622-9210-501 23N2G	MTH 11-Feb-2018 HRS 2041 LDG 2272		O/C			
345046 NO.1	FMS COMPUTER FMC-3000	KTYR	25	822-0883-038 3J9VP	MTH 01-Aug-2017 HRS 1932.5 LDG 2083 ACH 842.2		O/C	0 0 0		
345046 NO.2	FMS COMPUTER FMC-3000	*CF		822-0883-038 3G3VD	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345047 NO. 1	FMS CONTROL DISPLAY UNIT CDU-3000	*CF	7	822-0884-364 2YX3F	MTH 28-Jul-2009		O/C			
345050	FMS GPS DISPLAY GPS-500W	*CF	07	011-01062-10 23651089	MTH 28-Jul-2009		O/C			
345051	IRIDIUM/GPS PASSIVE ANTENNA IRIDIUM	*CF		S67-1575-165 4493236	MTH 28-Jul-2009		O/C			
345056 NO.1	GPS RECEIVER GPS-4000S	*CF	09	822-2189-002 349CN	MTH 26-Jul-2010		O/C			
345057 NO. 1	VOR/ADF/MRK BEACON/ILS RECEIVER NAV-4500	*CF		822-1579-001 39GBJ	MTH 28-Jul-2009		O/C			
345057 NO. 2	VOR/ADF/MRK BEACON/ILS RECEIVER NAV-4500	*CF	1	822-1579-001 39G1H	MTH 28-Jul-2009		O/C			
345058 NO.1	RADIO TUNING UNIT	*CF	15	822-0730-442 3CBDC	MTH 28-Jul-2009		O/C			
345058 NO.2	RADIO TUNING UNIT	*CF	15	822-0730-442 3CBDB	MTH 28-Jul-2009		O/C			
345061	TCAS PROCESSOR	*CF	14	822-1294-002 165548	MTH 28-Jul-2009		O/C			
345062 BOTTOM	TCAS II ANTENNA TCAS II ANTENNA	*CF	1	622-8973-001 2WRWY	MTH 28-Jul-2009		O/C			
345062 TOP	TCAS II ANTENNA TCAS II ANTENNA	*CF	1	622-8973-001 2WRWX	MTH 28-Jul-2009		O/C			
345064	DBASE CARD	*CF		805-18200-002 90969	MTH 28-Jul-2009		O/C			
345065	EXTERNAL - FSU COMPENSATION UNIT ECU-3000	*CF		822-1200-998 L 3CG4X	MTH 28-Jul-2009		O/C			
345066	FSU UNIT	*CF	2	822-1543-101 3FYWH	MTH 28-Jul-2009		O/C			
345067 NO.1	RADIO INTERFACE UNIT RIU-4110	*CF		822-1864-002 3B25R	MTH 28-Jul-2009		O/C			
345067 NO.2	RADIO INTERFACE UNIT RIU-4110	*CF		822-1864-002 3B26Y	MTH 28-Jul-2009		O/C			
350005	OXYGEN REGULATOR	*CF		172270-01 1906	MTH 28-Jul-2009		O/C			
350006	OXYGEN CYLINDER DOT E-10945	KTYR		176276-50 556166102	MTH 10-Aug-2018 HRS 2173.5 LDG 2373		180	63	31-May-2028	106 m 28 d
Manufacture Date: 01-May-2013										
350007	OXYGEN PRESSURE GAGE MD-97	*CF		C668512-0101 L0810073	MTH 28-Jul-2009		O/C			
351001	OXYGEN CONTROL VALVE	*CF		P21007 2441	MTH 28-Jul-2009		O/C			
351002 COPILOT	OXYGEN MASK 9914067-41	KICT	S	MC10-16-101 123114	MTH 11-Feb-2018 HRS 2041 LDG 2272		72	1 0 0	31-Jan-2024	54 m 28 d
351002 PILOT	OXYGEN MASK 9914067-41	KICT	S	MC10-16-101 SE60556	MTH 11-Feb-2018 HRS 2041 LDG 2272		72	1 0 0	31-Jan-2024	54 m 28 d
361001 LEFT	PRECOOL TEMP SENSOR 9912584-3	*CF		27431501-10 12BD361	MTH 28-Jul-2009		O/C			
361001 RIGHT	PRECOOL TEMP SENSOR 9912584-3	*CF		27431501-10 1BE24	MTH 28-Jul-2009		O/C			
361002 LEFT	B/A PRECOOLER ASSEMBLY LEFT	*CF		8292-1 S4883T0692	MTH 28-Jul-2009 HRS 0		3200	0	3200	938.3
361002 RIGHT	B/A PRECOOLER ASSEMBLY RIGHT	*CF		8292-1 S4883T0555	MTH 28-Jul-2009 HRS 0		3200	0	3200	938.3
361003 LEFT	MODULATING VALVE 9912584-1	*CF		1H139-1 7BD144	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
361003	MODULATING VALVE			1H139-2	MTH 28-Jul-2009		O/C			
RIGHT	9912584-2	*CF		4BD35						
361005	PRESSURE SWITCH	*CF		P18M30	MTH 28-Jul-2009		O/C			
				5067						
361006	OVERTEMP SWITCH	*CF		1173T181-2	MTH 28-Jul-2009		O/C			
LEFT	9914149-2			6241						
361006	OVERTEMP SWITCH	*CF		1173T181-2	MTH 28-Jul-2009		O/C			
RIGHT	9914149-2			6247						
361007	B/A PRESSURE REGULATOR	*CF		1H75-18	MTH 28-Jul-2009		O/C			
	9912510-1			5BE81						
450000	ARES RECORDER UNIT ASSY --	*CF		6918231-1	MTH 28-Jul-2009		O/C			
				1096						
521000	REPLACE CLEVIS HINGE PIN			PN	MTH		36		01-Jul-2021	23 m 28 d
				SN-UNKNOWN	HRS		900		3051.95	790.25
522001	INFLATABLE DOOR SEAL	*CF		S15501-4	MTH 28-Jul-2009		O/C			
	9912075-4			NSN						
530000	RADOME ASSEMBLY	KCLS		6313101-847-1	MTH 06-Feb-2014		O/C			
				1240	HRS 1265					
					LDG 1400					
531003	ACTUATOR FITTING	*CF		6511105-1	MTH 28-Jul-2009					
NOSE LANDING				SN-UNKNOWN	LDG 0		23900	0	23900	21439
GEAR										
531004	TRUNNION SUPPORT FITTING	*CF		5513056-7	MTH 28-Jul-2009					
LEFT NOSE				342	LDG 0		12000	0	12000	9539
LANDING GEAR										
531004	TRUNNION SUPPORT FITTING	*CF		5513056-8	MTH 28-Jul-2009					
RIGHT NOSE				337	LDG 0		12000	0	12000	9539
LANDING GEAR										
561001	WINDSHIELD ASSY, (LH)			93200-15	MTH 17-Jun-2014		O/C	0		
LEFT	9912064-15	KICT		3195	HRS 1348.1			0		
					LDG 1517			0		
561001	WINDSHIELD ASSY, (LH)			93200-16	MTH 28-Jul-2009		O/C			
RIGHT	9912064-16	*CF		2308						
561002	WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
CABIN DOOR	9912207-8			1424						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
LEFT NO. 2	9912207-8			4670						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
LEFT NO. 3	9912207-8			4804						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
LEFT NO. 4	9912207-8			4710						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
LEFT NO. 5	9912207-8			4805						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
LEFT NO. 6	9912207-8			4332						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
LEFT NO. 7	9912207-8			4705						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
RIGHT NO. 1	9912207-8			4399						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
RIGHT NO. 2	9912207-8			4825						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
RIGHT NO. 3	9912207-8			4770						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
RIGHT NO. 4	9912207-8			9169						
561002	CABIN WINDOW	*CF		93105-8	MTH 28-Jul-2009		O/C			
RIGHT NO. 5	9912207-8			9190						



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561002 RIGHT NO. 6	CABIN WINDOW 9912207-8	*CF		93105-8 9196	MTH 28-Jul-2009		O/C			
561002 RIGHT NO. 7	CABIN WINDOW 9912207-8	*CF		93105-8 4731	MTH 28-Jul-2009		O/C			
561003 COPILOT 561004 : R	SIDE WINDOW	*CF		6311263-2 2082	MTH 28-Jul-2009		O/C			
561003 PILOT	SIDE WINDOW	*CF		6311263-1 2041	MTH 28-Jul-2009		O/C			
571001 LEFT MAIN GEAR	SIDE BRACE FITTING *CF			6341324-1 608818F	MTH 28-Jul-2009 LDG 0		15000	0	15000	12539
571001 RIGHT MAIN GEAR	SIDE BRACE FITTING *CF			6341324-2 608819F	MTH 28-Jul-2009 LDG 0		15000	0	15000	12539
571002 LEFT MAIN GEAR	AFT TRUNNION FITTING *CF			6341326-5 608822B	MTH 28-Jul-2009 LDG 0		12000	0	12000	9539
571002 RIGHT MAIN GEAR	AFT TRUNNION FITTING *CF			6341326-6 608823B	MTH 28-Jul-2009 LDG 0		12000	0	12000	9539
571003 LEFT MAIN GEAR	FORWARD TRUNNION FITTING *CF			6341325-1 608820H	MTH 28-Jul-2009 LDG 0		12000	0	12000	9539
571003 RIGHT MAIN GEAR	FORWARD TRUNNION FITTING *CF			6341325-2 608821A	MTH 28-Jul-2009 LDG 0		12000	0	12000	9539
712002 LEFT ENGINE AFT	LEFT ENGINE AFT ISOLATOR MOUNT (OVERHAUL) 9912623-7	*CF		LM-605-SA11 LK2984	MTH 28-Jul-2009 HRS 0		8000	0	8000	5738.3
712002 LEFT ENGINE FORWARD BOTTOM	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (OVERHAUL) 9912623-6	*CF		LM-605-SA8 LK2118	MTH 28-Jul-2009 HRS 0		8000	0	8000	5738.3
712002 LEFT ENGINE FORWARD TOP	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT (OVERHAUL) 9912623-6	*CF		LM-605-SA8 LK2126	MTH 28-Jul-2009 HRS 0		8000	0	8000	5738.3
712002 RIGHT ENGINE AFT	RIGHT ENGINE AFT ISOLATOR MOUNT (OVERHAUL) 9912623-8	*CF		LM-605-SA10 LK2762	MTH 28-Jul-2009 HRS 0		8000	0	8000	5738.3
712002 RIGHT ENGINE FORWARD BOTTOM	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (OVERHAUL) 9912623-6	*CF		LM-605-SA8 LK2115	MTH 28-Jul-2009 HRS 0		8000	0	8000	5738.3
712002 RIGHT ENGINE FORWARD TOP	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT (OVERHAUL) 9912623-6	*CF		LM-605-SA8 LK2110	MTH 28-Jul-2009 HRS 0		8000	0	8000	5738.3
71EN1 NO. 1 710001 : E1**L	ENGINE FJ44-3A/9912614-1	SMF		67000-200 141683	MTH 12-Apr-2013 LDG 1187		E/C	1022		
71EN2 NO. 2 710001 : E2**R	ENGINE FJ44-3A/9912614-1	KTYR		67000-200 141684	MTH 20-Mar-2018 LDG 2289		E/C	2041		
720001 E1	FAN ROTOR *CF			72036 AU22040	MTH 28-Jul-2009 LDG 44		10000	0	(10000)10044	7583
720001 E2	FAN ROTOR *CF			72036 AU22032	MTH 28-Jul-2009 LDG 17		10000	0	(10000)10017	7556
720002 E1	IP COMPRESSOR ROTOR *CF			69026 HW30170	MTH 28-Jul-2009 LDG 44		10000	0	(10000)10044	7583
720002 E2	IP COMPRESSOR ROTOR *CF			69026 HW30130	MTH 28-Jul-2009 LDG 17		10000	0	(10000)10017	7556
720003 E1	COMPLETE LP SHAFT ASSEMBLY *CF			111423 RX08TK0360	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
720003 E2	COMPLETE LP SHAFT ASSEMBLY *CF	111423 RX08TK0364	MTH 28-Jul-2009		O/C			
720004 E1	HIGH PRESSURE SHAFT *CF	64711 RX07RT2027	MTH 28-Jul-2009		O/C			
720004 E2	HIGH PRESSURE SHAFT *CF	64711 RX07RT1995	MTH 28-Jul-2009		O/C			
720005 E1	HP COMPRESSOR COVER *CF	69885 AU21293	MTH 28-Jul-2009		O/C			
720005 E2	HP COMPRESSOR COVER *CF	69885 AU21219	MTH 28-Jul-2009		O/C			
720006 E1	DIFFUSER CASE ASSEMBLY PDX	116099 AU20937	MTH 02-Feb-2011 HRS 489.6 LDG 479		O/C	363.7 176		
720006 E2	DIFFUSER CASE ASSEMBLY UNK	116099 AU20134	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		O/C	6203.88 4690		
720007 E1	1ST STAGE LP TURBINE NOZZLE UNK	122196 AU20266	MTH 08-Feb-2018 HRS 2241 LDG 2272		O/C	1980.9 1495		
720007 E2	1ST STAGE LP TURBINE NOZZLE UNK	122141 AU22549	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		O/C	0 0 0		
720008 E1	ACCESS DRIVE GEARBOX *CF	78823 MX20064	MTH 28-Jul-2009		O/C			
720008 E2	ACCESS DRIVE GEARBOX UNK	120746 MX20081	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		O/C			
722010 E2	IP (STAGE 1 & 2) VANE ASSEMBLY UNK	115569 AU20444	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		O/C	3920 3092		
724035 E1	HP TURBINE COMBUSTER ASSEMBLY UNK	119263 AU20154	MTH 08-Feb-2018 HRS 2241 LDG 2272		O/C	4552.1 3913		
724035 E2	HP TURBINE COMBUSTER ASSEMBLY UNK	118731 AU20134	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		O/C	2527.3 2049		
725101 E1	HP COMPRESSOR ROTOR *CF	66055 HW30631	MTH 28-Jul-2009 LDG 44		8000	0	(8000)8044	5583
725101 E2	HP COMPRESSOR ROTOR *CF	66055 HW30592	MTH 28-Jul-2009 LDG 17		8000	0	(8000)8017	5556
725102 E1	HP TURBINE ROTOR UNK	111414 HW18930	MTH 08-Feb-2018 HRS 2241 LDG 2272		O/C	2050.1 1712		
725102 E2	HP TURBINE ROTOR UNK	111414 HW25486	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		O/C	1759.5 1242		
725103 E1	HP TURBINE DISK UNK	67093 HW18930	MTH 08-Feb-2018 HRS 2241 LDG 2272		8000	1712	(8516)8560	6099



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725103 E2	HP TURBINE DISK	UNK		67093 HW25486	MTH 27-Feb-2018 HRS 2062.5 LDG 2289			1759.5	(9030)9047	6586
725501 E1	1ST LP TURBINE DISK	*CF		72037 HW29823	MTH 28-Jul-2009 LDG 44		8000	0	(10000)10044	7583
725501 E2	1ST LP TURBINE DISK	*CF		72037 HW29800	MTH 28-Jul-2009 LDG 17		10000	0	(10000)10017	7556
725502 E1	2ND LP TURBINE DISK	*CF		66993 FT4443	MTH 28-Jul-2009 LDG 44		10000	0	(10000)10044	7583
725502 E2	2ND LP TURBINE DISK	*CF		66993 FT4422	MTH 28-Jul-2009 LDG 17		10000	0	(10000)10017	7556
730001 LEFT ENGINE	FUEL PRESS SWITCH 9912033-2	*CF		1103P0448 8923	MTH 28-Jul-2009		O/C			
730001 RIGHT ENGINE	FUEL PRESS SWITCH 9912033-2	*CF		1103P0448 8884	MTH 28-Jul-2009		O/C			
732500 LEFT ENGINE	FADEC	PDX		116724 CL6APW0397	MTH 25-Feb-2011 HRS 459 LDG 453		O/C	0 0		
732500 RIGHT ENGINE	FADEC	KPDX		117790 CL6APW0325	MTH 03-Jan-2014 HRS 1244.4 LDG 1374		O/C	649		
733001 LEFT ENGINE	FUEL FLOW TRANSMITTER 9912417-1	*CF		1573-4 0908012	MTH 28-Jul-2009		O/C			
733001 RIGHT ENGINE	FUEL FLOW TRANSMITTER 9912417-1	KGGG		1573-4 1088	MTH 03-Aug-2015 HRS 1631.6 LDG 1807 ACH 717.1		O/C			
730002 E1	FUEL NOZZLE ASSY	KTYL		50817 00005885	MTH 18-May-2018 HRS 2123.2 LDG 2337		O/C			
730002 E2	FUEL NOZZLE ASSY	UNK		50817 BCC00001720	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		O/C			
730003 E1	SEAL AND FUEL SLINGER ASSEMBLY	UNK		55608 AU201250	MTH 08-Feb-2018 HRS 2241 LDG 2272		O/C			
730003 E2	SEAL AND FUEL SLINGER ASSEMBLY	UNK		115471 AU201338	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		O/C			
732101 E1	FUEL DELIVERY UNIT 116190-01A10	KICT		119149 CL7APU0836	MTH 11-Feb-2018 HRS 2041 LDG 2272		8000	1695	(8303.9)8346	6084.3
732101 E2	FUEL DELIVERY UNIT	UNK		119148 CL6APU0491	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		8000	5021.6 4262	(5019.4)5040.9	2779.2
732301 E1	ELEC FUEL FILTER INDICATOR	UNK		57847 GE-2936	MTH 08-Feb-2018 HRS 2241 LDG 2272		O/C			
732301 E2	ELEC FUEL FILTER INDICATOR	UNK		57847 GE4103	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
741001 E1 INBOARD	IGNITION EXCITER	*CF		73489 BL17586	MTH 28-Jul-2009		O/C			
741001 E1 OUTBOARD	IGNITION EXCITER	*CF		73489 BL17615	MTH 28-Jul-2009		O/C			
741001 E2 INBOARD	IGNITION EXCITER	*CF		73489 BL17657	MTH 28-Jul-2009		O/C			
741001 E2 OUTBOARD	IGNITION EXCITER	*CF		73489 BL17916	MTH 28-Jul-2009		O/C			
741002 E1	SHORT IGNITOR LEAD	*CF		50852 NSN	MTH 28-Jul-2009		O/C			
741002 E2	SHORT IGNITOR LEAD	*CF		50852 NSN	MTH 28-Jul-2009		O/C			
741003 E1	LONG IGNITOR LEAD	*CF		50853 NSN	MTH 28-Jul-2009		O/C			
741003 E2	LONG IGNITOR LEAD	*CF		50853 NSN	MTH 28-Jul-2009		O/C			
741004 E1 INBOARD	IGNITOR	KTYL		68032 1001567-2018	MTH 18-May-2018 HRS 2123.2 LDG 2337		O/C			
741004 E1 OUTBOARD	IGNITOR	KTYL		68032 1001567-2018APR25- D	MTH 18-May-2018 HRS 2123.2 LDG 2337		O/C			
741004 E2 INBOARD	IGNITOR	KTYR		68032 CK-0802076	MTH 22-Nov-2016 HRS 1847.3 LDG 2003		O/C			
741004 E2 OUTBOARD	IGNITOR	KTYR		68032 CK-1400947	MTH 22-Nov-2016 HRS 1847.3 LDG 2003		O/C			
772001 LEFT NO. 1	ITT PROBE	*CF		62141 YYF021303	MTH 28-Jul-2009		O/C			
772001 LEFT NO. 2	ITT PROBE	*CF		62141 YYF021304	MTH 28-Jul-2009		O/C			
772001 LEFT NO. 3	ITT PROBE	*CF		62141 YYF021305	MTH 28-Jul-2009		O/C			
772001 LEFT NO. 4	ITT PROBE	*CF		62141 YYF021306	MTH 28-Jul-2009		O/C			
772001 LEFT NO. 5	ITT PROBE	*CF		62141 YYF021037	MTH 28-Jul-2009		O/C			
772001 LEFT NO. 6	ITT PROBE	*CF		62141 YYF021308	MTH 28-Jul-2009		O/C			
772001 RIGHT NO. 1	ITT PROBE	*CF		62141 YYF021423	MTH 28-Jul-2009		O/C			
772001 RIGHT NO. 2	ITT PROBE	*CF		62141 YYF021424	MTH 28-Jul-2009		O/C			
772001 RIGHT NO. 3	ITT PROBE	*CF		62141 YYF021425	MTH 28-Jul-2009		O/C			
772001 RIGHT NO. 4	ITT PROBE	*CF		62141 YYF021426	MTH 28-Jul-2009		O/C			
772001 RIGHT NO. 5	ITT PROBE	*CF		62141 YYF021427	MTH 28-Jul-2009		O/C			
772001 RIGHT NO. 6	ITT PROBE	*CF		62141 YYF021428	MTH 28-Jul-2009		O/C			
771001 E1	N1 DUAL MAGNETIC SPEED SENSOR	*CF		57355 MD0122327	MTH 28-Jul-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
771001 E2	N1 DUAL MAGNETIC SPEED SENSOR *CF			57355 MD0122319	MTH 28-Jul-2009		O/C			
771002 E1	N2 DUAL MAGNETIC SPEED SENSOR *CF			54831 MD0122164	MTH 28-Jul-2009		O/C			
771002 E2	N2 DUAL MAGNETIC SPEED SENSOR *CF			54831 MD0119218	MTH 28-Jul-2009		O/C			
771003 E1	TT2 SENSOR *CF			79646 GST4467	MTH 28-Jul-2009		O/C			
771003 E2	TT2 SENSOR *CF			79646 GST4470	MTH 28-Jul-2009		O/C			
793002 LEFT ENGINE	OIL PRESS SWITCH 9912178-4	UNK		S1103P89-3 3271	MTH 10-Dec-2013 HRS 1232.3 LDG 1362		O/C	1232.3 1362		
793002 RIGHT ENGINE	OIL PRESS SWITCH 9912178-4	UNK		S1103P89-3 3242	MTH 10-Dec-2013 HRS 1232.3 LDG 1362		O/C	1232.3 1362		
793003 LEFT ENGINE	OIL PRESS TRANSMITTER UNK	UNK		APTE-304-200G 765112349	MTH 10-Dec-2013 HRS 1232.3 LDG 1362		O/C	1232.3 1362		
793003 RIGHT ENGINE	OIL PRESS TRANSMITTER UNK	UNK		APTE-304A-200G 76516246	MTH 10-Dec-2013 HRS 1232.3 LDG 1362		O/C	1232.3 1362		
792201 E1	LUBE OIL COOLER *CF			110718 PP0320	MTH 28-Jul-2009		O/C			
792201 E2	LUBE OIL COOLER *CF			110718 PP0338	MTH 28-Jul-2009		O/C			
792401 E1	LUBE AND SCAVENGE PUMP *CF			114520 MX20755	MTH 28-Jul-2009 HRS 42.1		5000	0	(5000)5042.1	2780.4
792401 E2	LUBE AND SCAVENGE PUMP *CF			114520 MX20749	MTH 28-Jul-2009 HRS 21.5		5000	0	(5000)5021.5	2759.8
801101 LEFT	STARTER GENERATOR 9912125-2	KICT		300SGL129Q S00034	MTH 11-Feb-2018 HRS 2041 LDG 2272		1000	0	3041	779.3
801101 RIGHT	STARTER GENERATOR 9912125-2	KTYR		300SGL129Q 3477XL2	MTH 20-Jun-2017 HRS 1920.4 LDG 2071 ACH 842.2		1000	0	2920.4	658.7



CESSCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-05-1007 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	MOC :								
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS		INFORMATIONAL						-
	MOC :								
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS		INFORMATIONAL						-
	MOC :								
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS		INFORMATIONAL						-
	MOC :								
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS		RECOMMENDED	MTH					-
	MOC :								
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL		INFORMATIONAL						-
	MOC :								
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL		INFORMATIONAL						-
	MOC :								
SL 525B-20-01 R06	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL		INFORMATIONAL			A/R			
	MOC :								
SL 525B-20-05	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL		INFORMATIONAL						-
	MOC :								
SB 525B-21-04	AFT EVAPORATOR DRAIN HOSE IMPROVEMENT		DISCRETIONARY				A/R		
	MOC :								
SL 525B-21-04	AIR CONDITIONING - PRESSURIZATION PRINTED CIRCUIT BOARD REPLACEMENT								-
	MOC :								
SL 525B-23-03	COMMUNICATIONS - SITA DATALINK FREQUENCY CHANGE FOR NORTH AMERICA		INFORMATIONAL						-
	MOC :								
SL 525B-23-04	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE		OPTIONAL						-
	MOC :								
SL 525B-23-05	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE TO VERSION 2.8		OPTIONAL						-
	MOC :								
SB 525B-24-09	GENERATOR CONTROL UNIT WIRE BUNDLE ROUTING	SMF	MANDATORY	MTH 28-Aug-2013 HRS 1164.3 LDG 1280					Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB525B-24-09, BY REROUTING THE GCU WIRE BUNDLE PER ACCOMPLISHMENT INSTRUCTIONS.								
SB CIB-25-01	EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION		OPTIONAL						-
	MOC :								
SB CIB-25-02	EQUIPMENT/FURNISHINGS - BELTED TOILET SEAT INERTIA REEL MODIFICATION		RECOMMENDED						-
	MOC :								



CESSNA 441 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525B-25-03	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF B/E AEROSPACE SERVICE BULLETIN 2524.565-25-01 REPLACEMENT OF SWIVEL ASSEMBLY	SMF		MANDATORY	MTH 01-Aug-2011 HRS 597.1 LDG 611		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL525B-25-03 WITH THE TRANSMITTAL OF B/E AEROSPACE SERVICE BULLETIN 2524.565-25-01 INSPECTING THE CABIN SEATS P/N & S/N FOR POSSIBLE SWIVEL BASES THAT NEED TO BE REPLACED. AIRCRAFT DOES NOT HAVE SWIVEL BASE CABIN SEATS. NO FURTHER ACTION REQUIRED.										
SL 525B-25-05	EQUIPMENT/FURNISHINGS - TOILET DRIP TRAY INSTALLATION			OPTIONAL			-			
MOC :										
SB 525B-26-04	FORWARD SMOKE DETECTOR HEATER AND COVER INSTALLATION	PDX		RECOMMENDED	MTH 07-Feb-2011 HRS 447.5 LDG 435		A/R			Complete
MOC : COMPLIED WITH - C/W CESSNA SERVICE BULLETIN 525B-26-04. FORWARD SMOKE DETECTOR HEATER AND COVER INSTALLATION. KIT SB 525B -26-04. I/A/W CESSNA SB 525B-26-04 (SEPTEMBER 25TH 2009)										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY			-			
MOC :										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY	MTH		-			
MOC :										
SB CIB-28-01	FIREWALL SHUTOFF VALVE GROUND IMPROVEMENT			RECOMMENDED	MTH HRS		300		1648.1	-613.6 Over Due
MOC :										
SB 525B-29-03 R01	HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT			MANDATORY	MTH		A/R			
MOC :										
SB 525B-29-04	HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION			OPTIONAL			A/R			
MOC :										
SL 525B-29-02	HYDRAULIC POWER - ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION	KTYR		RECOMMENDED	MTH 10-Aug-2018 HRS 2173.5 LDG 2373		-			N/A
MOC : NOT APPLICABLE - BOTH LEFT AND RIGHT ENGINE DRIVEN HYDRAULIC PUMPS ARE P/N 9912062-6. THIS SL DOES NOT APPLY. PHILLIP GUIDRY A&P 3544634										
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
MOC :										
SL 525B-30-02	ICE AND RAIN PROTECTION - WING ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE INSPECTION			MANDATORY	DAYS		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO -0248 THRU -0256 ONLY.										
SB 525B-31-01 R01	INDICATING/RECORDING SYSTEMS - FLIGHT DATA RECORDER INSTALLATION			OPTIONAL			A/R			
MOC : - APPLICABLE TO AIRCRAFT -0135 AND ON.										
SB 525B-31-01	INDICATING/RECORDING SYSTEMS - FLIGHT DATA RECORDER INSTALLATION			OPTIONAL			A/R			
MOC :										



CESSNA 441 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION INFORMATIONAL								
MOC :									
SB 525B-31-01 31SB-01	FLIGHT DATA RECORDER INSTALLAT			MTH		O/C			
MOC : - OPEN									
SL 525B-31-03	TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001								
	KPDX		MANDATORY	MTH 31-Aug-2012		A/R			N/A
				HRS 891.2					
				LDG 974					
MOC : NOT APPLICABLE - THIS SERVICE BULLETIN IS NOT APPLICABLE TO THIS AIRCRAFT. THE EQUIPMENT IS NOT INSTALLED.									
SB 525B-32-09 32SB-09	BRAKE METERING VALVE CABLE INSPECTION			MTH 07-Feb-2011		-			Complete
	PDX		RECOMMENDED	HRS 447.5					
				LDG 435					
MOC : COMPLIED WITH - C/W CESSNA SERVICE BULLETIN 525B-32-09. STEPS 1-13. KIT SUPPLIED WITH SB. INSPECTION OF BRAKE METERING VALVE CABLE. I/A/W CESSNA 525B MM 32-42-02. OPS. CHECK GOOD.									
SB 525B-32-10	LANDING GEAR - NOSE LANDING GEAR ACTUATOR IMPROVEMENT								
	KCLS		DISCRETIONARY	MTH 05-Oct-2012		A/R			Complete
				HRS 928.7					
				LDG 1029					
MOC : COMPLIED WITH - COMPLIED WITH SB525B-32-10. OPERATIONAL CHECKS SATISFACTORY.									
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL INFORMATIONAL								
MOC :									
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION			MTH 17-Feb-2017		-			Complete
	KTYR		RECOMMENDED	HRS 1840.2					
				LDG 2004					
				ACH 842.2					
MOC : COMPLIED WITH - PROPER INSTALLATION OF NOSE GEAR UPLOCK ROLLER BRACKET CONFIRMED IN ACCORDANCE WITH SL CIL-32-03.									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION INFORMATIONAL								
MOC :									
SL 525B-32-01 R01 32SL-01 : 525B1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			MTH		-			
	*CF		OPTIONAL						
MOC :									
SL 525B-32-09 R02 32SL-09	EMERGENCY GEAR RELEASE INSPECTION			MTH 26-Jul-2010		A/R			Complete
	KPDX		MANDATORY	HRS 297.6					
				LDG 286					
MOC : COMPLIED WITH									
SL 525B-32-09 32SL-09	EMERGENCY GEAR RELEASE INSPECTION MANDATORY								
MUST BE ACCOMPLISHED IN CONJUNCTION WITH INSPECTION DOCUMENT 14.									
MOC :									
SL 525B-32-10	LANDING GEAR - MAIN LANDING GEAR TIRE INFLATION PLACARD INSPECTION								
	SMF		RECOMMENDED	MTH 09-Mar-2012		A/R			Complete
				HRS 749.3					
				LDG 837					
MOC : COMPLIED WITH - COMPLIED WITH SL525B-32-10 INSPECTING FOR THE PROPER MAIN GEAR TIRE INFLATION PLACARDS PER THE ACCOMPLISHMENT INSTRUCTIONS.									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525B-33-04	NAVIGATION/ANTI-COLLISION LIGHT SCREW CHANGE	SMF	RECOMMENDED	MTH 01-Aug-2011 HRS 597.1 LDG 611		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB525B-33-04 BY REPLACEMENT OF SCREWS HOLDING THE NAVIGATION/ANTI-COLLISION LIGHT PER ACCOMPLISHMENT INSTRUCTIONS.									
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY		INFORMATIONAL			-			
MOC :									
SB 525B-34-03 34SB-03	ENHANCED SURVEILLANCE TRANSPONDER UPGRADE	*CF	OPTIONAL	MTH		A/R			
MOC :									
SB 525B-34-11 34SB-11	GPS-4000S RECEIVER IMPROVEMENT	KPDX	MANDATORY	DAYS 26-Jul-2010 HRS 297.6 LDG 286		A/R			Complete
MOC : COMPLIED WITH									
SB 525B-34-21	NAVIGATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS II) SOFTWARE 7.1 UPGRADE		OPTIONAL			-			
MOC :									
SB 525B-34-26 R01	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION		OPTIONAL			-			
MOC :									
SB 525B-34-26 R02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION		OPTIONAL			-			
MOC :									
SB 525B-34-26	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION	KICT	OPTIONAL	MTH 11-Feb-2018 HRS 2041 LDG 2272		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525B-34-26 "AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION". THIS INSTALLATION MEETS THE REQUIREMENTS OF 14 CFR 91.225 & 91.227 AS DEFINED IN TSO-C166B & TSO-C154C.									
SB 525B-34-30	NAVIGATION - ADS-B OUT WIRING MODIFICATION	KICT	MANDATORY	MTH 11-Feb-2018 HRS 2041 LDG 2272		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED SB525B-34-30; ADS-B OUT WIRING MODIFICATION, DUE TO SB525B-34-26 FILL THE REQUIREMENTS.									
SB CIB-34-02	GPS-4000S SOFTWARE UPDATE		RECOMMENDED	MTH HRS		300		1638.1	-623.6 Over Due
MOC :									
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE		INFORMATIONAL			-			
MOC :									
SL 525B-34-09	NAVIGATION - TRANSMITTAL OF ROCKWELL COLLINS SERVICE INFORMATION LETTER 16-1 FUNCTION OF RESET OVERRIDE MODE SWITCH ON XM WEATHER RECEIVER FOR PROLINE 21/PROLINE FUSION		INFORMATIONAL			-			
MOC :									
SL CIL-35-01	TRANSMITTAL OF BE AEROSPACE SERVICE BULLETIN 118077-35-01	SMF	MANDATORY	MTH 16-Jan-2014 HRS 1252 LDG 1387		-			N/A
MOC : NOT APPLICABLE - SL CIL-35-01 DOES NOT APPLY TO THIS AIRCRAFT. BE AEROSPACE SMOKE GOGGLE NOT INSTALLED. ENTRY WAS MADE TO UPDATE CESCOM.									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KGGG	MANDATORY	MTH 02-Mar-2016 DAYS 1735.5 HRS 1907 LDG		-			N/A
MOC : NOT APPLICABLE - THIS SL CIL-35-05 DOES NOT APPLY DUE TO NOT APPLICABLE P/NS MC-10-16-101 AND S/NS 100110 AND 118376.									
SL 525B-35-02 R01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	SMF	MANDATORY	MTH 09-Mar-2012 HRS 749.3 LDG 837		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL525B-35-02 REVISION 1 TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 PER THE ACCOMPLISHMENT INSTRUCTIONS. THE PILOT AND COPILOT OXYGEN MASKS WERE REPLACED WITH OVERHAULED MASK. SEE SECTION 3 FOR PART CHANGE INFO.									
SL 525B-35-02 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240		MANDATORY			-			
MOC :									
SL 525B-35-02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240		MANDATORY			-			
MOC :									
SB 525B-36-03 R01	PNEUMATIC - MOISTURE TRAP INSTALLATION		OPTIONAL			-			
MOC :									
SB 525B-36-03	PNEUMATIC - MOISTURE TRAP INSTALLATION		OPTIONAL			-			
MOC :									
SL 525B-36-01 R01	PNEUMATIC - PRECOOLER LIFE LIMIT		INFORMATIONAL			-			
MOC :									
SL 525B-36-01	PRECOOLER LIFE LIMIT		INFORMATIONAL			-			
MOC :									
SL CIL-52-01	DOORS - EMERGENCY DOOR INSPECTION	SMF	MANDATORY	MTH 28-Aug-2013 HRS 1164.3 LDG 1280		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER CIL-52-01, BY INSPECTING THE EMERGENCY EXIT DOOR SEAL AND APPLYING A THIN COAT OF PETROLATUM TO THE SEAL PER ACCOMPLISHMENT INSTRUCTIONS.									
SL 525B-53-07	UPPER TAILCONE SKIN INSPECTION	KPDX	MANDATORY	MTH 26-Jul-2010 HRS 297.6 LDG 286		A/R			Complete
MOC : COMPLIED WITH									
SB 525B-54-02	NACELLES/PYLONS - FORWARD ENGINE BEAM INSPECTION ACCESS PANEL INSTALLATION		OPTIONAL			-			
MOC :									
SL 525B-54-01 R01	PYLON STRUCTURE INSPECTION		RECOMMENDED	MTH		A/R			
MOC :									
SL 525B-54-01 R02	PYLON INSPECTION		RECOMMENDED	HRS		300			
MOC :									
SL 525B-54-01	PYLON STRUCTURE INSPECTION		RECOMMENDED	MTH		A/R			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525B-57-02 R01	ANTI-ICE EXHAUST OUTLET IMPROVEMENT			MTH RECOMMENDED HRS			300		1659.7	-602 Over Due
MOC :										
SB 525B-57-02	WINGS - ANTI-ICE EXHAUST OUTLET IMPROVEMENT			RECOMMENDED			-			
MOC :										
SB 525B-71-03	COWL STIFFENER INSTALLATION KALN			MANDATORY MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975			-			Complete
MOC : COMPLIED WITH										
SL 525B-71-08 R02	POWERPLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT			MANDATORY			-			
MOC :										
SL 525B-71-09 R01	POWER PLANT - ENGINE ISOLATOR MOUNTS INSPECTION EXTENSION			OPTIONAL			-			
MOC :										
SL 525B-71-09	POWER PLANT - ENGINE ISOLATOR MOUNTS INSPECTION EXTENSION (SUPERSEDED BY SL525B-71-09 R01)			OPTIONAL			-			
MOC :										
SL 44-71-298 E2	SL44-71-298	KPDX		MTH 03-Jan-2014 HRS 1265.9 LDG 1391			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL44-71-298, NO PROBLEMS FOUND AT THIS TIME.										
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
MOC :										
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
MOC :										
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-078 R02 E1	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-078 R02 E2	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-078 R03 E1	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK			OPTIONAL			-			
MOC :										
SB FJ44-72-078 R03 E2	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK	UNK		OPTIONAL	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-080 R01 E1	ENGINE - 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE (SUPERSEDED BY FJ44-72-080 R02)			RECOMMENDED	HRS			DUE DUE	(4000)4042.1	1780.4
MOC :										
SB FJ44-72-080 R01 E2	ENGINE - 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE (SUPERSEDED BY FJ44-72-080 R02)	UNK		RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-085 R05 E1	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-72-085 R05 E2	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-72-086 R02 E1	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-086 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-72-086 R02 E2	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-086 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-72-086 R03 E1	ENGINE - BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-086 R03 E2	ENGINE - BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-093 R02 E1	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R03)			MANDATORY			-			
MOC :										
SB FJ44-72-093 R02 E2	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R03)			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-093 R11 E2	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R12)			MANDATORY			-			
MOC :										
SB FJ44-72-093 R12 E1	DIFFUSER CASE ASSEMBLY - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-72-093 R12 E2	DIFFUSER CASE ASSEMBLY - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-72-093 E1	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R01)	PDX		MANDATORY	MTH 02-Feb-2011 HRS 489.6 LDG 479		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-093 E2	ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R01)	PDX		MANDATORY	MTH 03-Feb-2011 HRS 469 LDG 452		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-097 R01 E1	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R02)			MANDATORY			-			
MOC :										
SB FJ44-72-097 R01 E2	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R02)			MANDATORY			-			
MOC :										
SB FJ44-72-097 R02 E1	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R03)			MANDATORY			-			
MOC :										
SB FJ44-72-097 R02 E2	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R03)			MANDATORY			-			
MOC :										
SB FJ44-72-097 R03 E1	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R04)			MANDATORY			-			
MOC :										
SB FJ44-72-097 R03 E2	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R04)			MANDATORY			-			
MOC :										
SB FJ44-72-097 R04 E1	CANCELLED - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-151)			MANDATORY			-			
MOC :										
SB FJ44-72-097 R04 E2	CANCELLED - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-151)			MANDATORY			-			
MOC :										
SB FJ44-72-097 E1	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R01)			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-097 E2	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R01)			MANDATORY			-			
MOC :										
SB FJ44-72-105 R03 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-105 R03 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-107 R02 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-107 R02 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE	UNK		RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-107 E1	ENGINE - 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-107 E2	ENGINE - 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-108 R01 E1	ACCESSORY DRIVE SHAFT - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(4000)4042.1	1780.4
MOC :										
SB FJ44-72-108 R01 E2	ACCESSORY DRIVE SHAFT - REPLACE	UNK		RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-108 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-108 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS		DUE DUE		(4000)4042.1	1780.4
MOC :										
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE	UNK		RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY										
SB FJ44-72-110 E1	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE			MANDATORY	HRS		DUE DUE		(4000)4042.1	1780.4
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-110 E2	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE	UNK		MTH HRS LDG	27-Feb-2018 2062.5 2289		-			Complete
	MOC : COMPLIED WITH									
SB FJ44-72-123 R01 E1	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-123 R01 E2	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-124 R01 E2	REPLACE HP TURBINE BLADES (SUPERSEDED BY FJ44-72-124 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-124 R02 E2	HP TURBINE BLADES - REPLACE (SUPERSEDED BY FJ44-72-124 R03)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-124 R03 E2	HP TURBINE BLADES - REPLACE	UNK		RECOMMENDED	MTH HRS LDG		-			Complete
	MOC : COMPLIED WITH									
SB FJ44-72-124 R04 E2	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-124 E1	HP TURBINE BLADES - REPLACE (SUPERSEDED BY FJ44-72-124 R01)	UNK		RECOMMENDED	MTH HRS LDG		-			Complete
	MOC : COMPLIED WITH									
SB FJ44-72-124 E2	HP TURBINE BLADES - REPLACE (SUPERSEDED BY FJ44-72-124 R01)			RECOMMENDED	MTH		-			
	MOC :									
SB FJ44-72-130 R01 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-130 R01 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
	MOC :									
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
	MOC :									
SB FJ44-72-130 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-130 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)									
				RECOMMENDED			-			
	MOC :									
SB FJ44-72-133 R01 E2	REPLACE 1ST LP TURBINE NOZZLE	UNK		RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
	MOC : COMPLIED WITH									
SB FJ44-72-133 E1	REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01)									
		UNK		RECOMMENDED	MTH 08-Feb-2018 HRS 2241 LDG 2272		-			Complete
	MOC : COMPLIED WITH									
SB FJ44-72-133 E2	REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01)									
				RECOMMENDED			-			
	MOC :									
SB FJ44-72-140 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION			MANDATORY	HRS		DUE		(4000)4042.1	1780.4
	MOC :									
SB FJ44-72-140 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION	UNK		MANDATORY	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
	MOC : COMPLIED WITH									
SB FJ44-72-143 R01 E2	BLEED VALVE SHAFT - REPLACE	UNK		RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
	MOC : COMPLIED WITH									
SB FJ44-72-143 E2	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-143 R01)									
				RECOMMENDED			-			
	MOC :									
SB FJ44-72-150 R01 E2	LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R02)	UNK		RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
	MOC : COMPLIED WITH									
SB FJ44-72-150 R02 E2	LP REAR BEARING SEAL RETAINER - REPLACE									
	MOC :									
SB FJ44-72-150 R03 E2	LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB FJ44-72-150 E2	LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R01)									
				RECOMMENDED			-			
	MOC :									
SB FJ44-72-151 R01 E2	BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-151 R02)									
				MANDATORY			-			
	MOC :									
SB FJ44-72-151 R02 E2	BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-151 R03)									
				MANDATORY			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-151 R03 E2	BEARING AND PINION ASSEMBLY - INSTALL	UNK		MTH HRS LDG	27-Feb-2018 2062.5 2289		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-151 E2	BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-151 R01)			MANDATORY			-			
MOC :										
SB FJ44-72-154 R01 E1	1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)			RECOMMENDED			-			
MOC :										
SB FJ44-72-154 R01 E2	1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)			RECOMMENDED			-			
MOC :										
SB FJ44-72-154 E1	1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-154 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-154 E2	1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-154 R01)			RECOMMENDED			-			
MOC :										
SL 44-72-325 R04 E1	1ST LP TURBINE DISK - INSPECTION						-			
MOC :										
SL 44-72-325 R04 E2	1ST LP TURBINE DISK - INSPECTION						-			
MOC :										
SL 44-72-327 E2	SL44-72-327	UNK		MTH HRS LDG	27-Feb-2018 2062.5 2289		-			Complete
MOC : COMPLIED WITH										
SB WI-72-1004 R03 E2	ENGINE - 1ST LP TURBINE NOZZLE - REPLACE						-			
MOC :										
SB WI-72-1004 R04 E2	1ST LP TURBINE NOZZLE - REPLACE	UNK		MTH HRS LDG	27-Feb-2018 2062.5 2289		-			Complete
MOC : COMPLIED WITH										
SB WI-72-1004 E1	1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY WISB-72-1004 R01)	UNK		MTH HRS LDG	08-Feb-2018 2241 2272		-			Complete
MOC : COMPLIED WITH										
SB WI-72-1004 E2	1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY WISB-72-1004 R01)						-			
MOC :										
SB FJ44-73-030 R07 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R08)			MANDATORY			A/R			
MOC :										
SB FJ44-73-030 R07 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R08)			MANDATORY			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-030 R08 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R09)	SMF		MANDATORY	MTH 01-Aug-2011 HRS 639.2 LDG 655		-			N/A
MOC : NOT APPLICABLE - BY PART NUMBER COMPLIED WITH WILLIAMS SB FJ44-73-030 R8, BY INSPECTION AND FOUND THIS SERVICE BULLETIN DOES NOT APPLY DUE TO PART NUMBER FADEC INSTALLED P/N (116724). NO FURTHER ACTION REQUIRED.										
SB FJ44-73-030 R08 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R09)	SMF		MANDATORY	MTH 01-Aug-2011 HRS 618.6 LDG 628		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH WILLIAMS SB FJ44-73-030 R8, BY INSPECTION AND FOUND SERVICE BULLETIN HAS BEEN PREVIOUSLY COMPLIED WITH. VERIFIED CORRECT SOFTWARE VERSION AND SW CHECKSUM INSTALLED.NO FURTHER ACTION REQUIRED										
SB FJ44-73-030 R09 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R10)			MANDATORY			-			
MOC :										
SB FJ44-73-030 R09 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R10)			MANDATORY			-			
MOC :										
SB FJ44-73-030 R10 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R11)			MANDATORY			-			
MOC :										
SB FJ44-73-030 R10 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R11)			MANDATORY			-			
MOC :										
SB FJ44-73-030 R11 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R12)			MANDATORY			A/R			
MOC :										
SB FJ44-73-030 R11 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R12)			MANDATORY			A/R			
MOC :										
SB FJ44-73-030 R12 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R13)			MANDATORY			-			
MOC :										
SB FJ44-73-030 R12 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R13)			MANDATORY			-			
MOC :										
SB FJ44-73-030 R13 E1	CANCELLED - ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06			CANCELLED			-			
MOC :										
SB FJ44-73-030 R13 E2	CANCELLED - ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06			CANCELLED			-			
MOC :										
SB FJ44-73-038 R01 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R02)			MANDATORY			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-038 R01 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R02)			MANDATORY			A/R			
MOC :										
SB FJ44-73-038 R02 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R03)			MANDATORY			A/R			
MOC :										
SB FJ44-73-038 R02 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R03)			MANDATORY			A/R			
MOC :										
SB FJ44-73-038 R03 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R04)			MANDATORY	MTH		-			
MOC :										
SB FJ44-73-038 R03 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R04)			MANDATORY	MTH		-			
MOC :										
SB FJ44-73-038 R04 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R05)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R04 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R05)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R05 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R06)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R05 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R06)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R06 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R07)			MANDATORY			-			
MOC :										
SB FJ44-73-038 R06 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R07)	KPDX		MANDATORY	MTH 03-Jan-2014 HRS 1265.9 LDG 1391		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB FJ44-73-038 R6 BY INSTALLATION OF A NEW FADEC. SEE SECTION 3 FOR COMPONENT CHANGE DETAILS.										
SB FJ44-73-038 R07 E1	DUAL CHANNEL FADEC - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-73-038 R07 E2	DUAL CHANNEL FADEC - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-73-038 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R01)			MANDATORY			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-038 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R01)			MANDATORY			A/R			
MOC :										
SB FJ44-73-039 R01 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R02)			MANDATORY			A/R			
MOC :										
SB FJ44-73-039 R01 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R02)			MANDATORY			A/R			
MOC :										
SB FJ44-73-039 R02 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R03)			MANDATORY			A/R			
MOC :										
SB FJ44-73-039 R02 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R03)			MANDATORY			A/R			
MOC :										
SB FJ44-73-042 R01 E1	REPLACE - ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET (SUPERSEDED BY FJ44-73-042 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R01 E2	REPLACE - ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET (SUPERSEDED BY FJ44-73-042 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R02 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R02 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R03 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R03 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R04 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R04 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 R05 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE			RECOMMENDED	HRS		-		(2000)2042.1	-219.6
MOC :										

Over Due



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-042 R05 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE	UNK		RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH										
SB FJ44-73-042 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-73-042 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-73-043 R02 E1	ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD			RECOMMENDED			-			
MOC :										
SB FJ44-73-043 R02 E2	ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD			RECOMMENDED			-			
MOC :										
SB FJ44-73-044 R01 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R02)			MANDATORY			-			
MOC :										
SB FJ44-73-044 R01 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R02)			MANDATORY			-			
MOC :										
SB FJ44-73-044 R02 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R03)			MANDATORY			-			
MOC :										
SB FJ44-73-044 R02 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R03)			MANDATORY			-			
MOC :										
SB FJ44-73-044 R03 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R04)			MANDATORY			-			
MOC :										
SB FJ44-73-044 R03 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R04)			MANDATORY			-			
MOC :										
SB FJ44-73-044 R04 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R05)			MANDATORY	MTH		-			
MOC :										
SB FJ44-73-044 R04 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R05)			MANDATORY	MTH		-			
MOC :										
SB FJ44-73-044 R05 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R06)			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-044 R05 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R06)		MANDATORY			-			
MOC :									
SB FJ44-73-044 R06 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R07)		MANDATORY			-			
MOC :									
SB FJ44-73-044 R06 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R07)		MANDATORY			-			
MOC :									
SB FJ44-73-044 R07 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE	ICT	MANDATORY	MTH 11-Feb-2018 HRS 2041 LDG 2272		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SBFJ44-73-044 REV7 DATED 24 AUG 2017. THIS SB IS COMPLETE DUE TO FUEL DELIVERY UNIT WITH PART NUMBER 119149 WAS INSTALLED DURING THIS VISIT, REFERENCE MTR ID# 2825959 DATED 11 FEB 2018.									
SB FJ44-73-044 R07 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE	UNK	MANDATORY	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH									
SB FJ44-73-044 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R01)		MANDATORY			-			
MOC :									
SB FJ44-73-044 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R01)		MANDATORY			-			
MOC :									
SB FJ44-73-061 E1	CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO)		RECOMMENDED			-			
MOC :									
SB FJ44-73-061 E2	CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO)		RECOMMENDED			-			
MOC :									
SB WI-73-1002 R02 -CN E1	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE		CANCELLED			-			
MOC :									
SB WI-73-1002 R02 -CN E2	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE		CANCELLED			-			
MOC :									
SB WI-73-1002 R02 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)		MANDATORY			-			
MOC :									
SB WI-73-1002 R02 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)	UNK	MANDATORY	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH									
SB WI-73-1002 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)		MANDATORY			-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-73-1002 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)		MANDATORY						
MOC :									
SB WI-73-1007 R01 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02								
MOC :									
SB WI-73-1007 R01 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02								
MOC :									
SB WI-73-1008 R01 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED						
MOC :									
SB WI-73-1008 R01 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED						
MOC :									
SB WI-73-1008 R02 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED						
MOC :									
SB WI-73-1008 R02 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED						
MOC :									
SB WI-73-1008 R03 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED						
MOC :									
SB WI-73-1008 R03 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED						
MOC :									
SB WI-73-1008 R04 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED	MTH HRS				(2372.7)2414.8	153.1
MOC :									
SB WI-73-1008 R04 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED	MTH HRS				(2341)2362.5	100.8
MOC :									
SB WI-73-1008 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED						
MOC :									
SB WI-73-1008 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE		RECOMMENDED						
MOC :									
SB WI-73-1009 R01 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE								
MOC :									
SB WI-73-1009 R01 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE								
MOC :									
SB WI-73-1009 R02 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE		RECOMMENDED	MTH HRS		DUE DUE DUE		(4000)4042.1	1780.4
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-73-1009 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(4000)4021.5	1759.8
MOC :										
SB WI-73-1009 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-73-1009 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
MOC :										
SL WI-73-1018 E1	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG						-			
MOC :										
SL WI-73-1018 E2	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG						-			
MOC :										
SB WI-74-1000 E1	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	KTYL		MANDATORY	MTH 18-May-2018 HRS 2123.2 LDG 2337		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH ON BOTH #1 AND #2 ENGINES. CLAMPING ARRANGEMENT IS A DESCRIBED IN WISB-74-1000 AND NO DAMAGE TO LEADS NOTED ON EITHER ENGINE.										
SB WI-74-1000 E2	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	KTYL		MANDATORY	MTH 18-May-2018 HRS 2123.2 LDG 2337		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH ON BOTH #1 AND #2 ENGINES. CLAMPING ARRANGEMENT IS A DESCRIBED IN WISB-74-1000 AND NO DAMAGE TO LEADS NOTED ON EITHER ENGINE.										
SB WI-75-1001 E1	R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH HRS		-		(4000)4042.1	1780.4
MOC :										
SB WI-75-1001 E2	R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH HRS		-		(4000)4021.5	1759.8
MOC :										
SB WI-75-1001 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1001 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB 525B-76-02	ENGINE CONTROLS - REMOVAL OF TRIM BOX WIRING			OPTIONAL			A/R			
MOC :										
SB 525B-76-03 R01	ENGINE CONTROLS - FADEC CONNECTOR WASHER REMOVAL	SMF		RECOMMENDED	MTH 01-Aug-2011 HRS 597.1 LDG 611		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB525B-76-03R1, BY INSPECTION AND FOUND THE WASHERS PREVIOUSLY REMOVED FROM THE MATING SIDE OF THE FADEC CONNECTORS PER ACCOMPLISHMENT INSTRUCTIONS.										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-77-009 R01 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY SB FJ44-77-011 R18)			RECOMMENDED			-			
MOC :										
SB FJ44-77-009 R01 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY SB FJ44-77-011 R18)			RECOMMENDED			-			
MOC :										
SB FJ44-77-011 R02 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R03)			RECOMMENDED			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED PER REVISION 3										
SB FJ44-77-011 R02 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R03)			RECOMMENDED			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED PER REVISION 3										
SB FJ44-77-011 R03 E1	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R04)			RECOMMENDED			-			
MOC : - SUPERSEDED BY REVISION 4										
SB FJ44-77-011 R03 E2	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R04)			RECOMMENDED			-			
MOC : - SUPERSEDED BY REVISION 4										
SB FJ44-77-011 R04 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R05)			MANDATORY			A/R			
MOC : - SUPERSEDED BY REVISION 5.										
SB FJ44-77-011 R04 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R05)			MANDATORY			A/R			
MOC : - SUPERSEDED BY REVISION 5.										
SB FJ44-77-011 R05 E1	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R06)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R05 E2	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R06)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R06 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R07)	SMF		MANDATORY	MTH 01-Aug-2011 HRS 639.2 LDG 655		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH WILLIAMS SB FJ44-77-011 R6, BY INSPECTING THE ENGINE FADEC HARNESS ASSEMBLY TO DETERMINE IF HARNESS IS AT RISK FOR CHAFING WITHIN THE FDU BACKSHELLS P11 AND P12 PER ACCOMPLISHMENT INSTRUCTIONS. NO DEFECTS NOTED.										
SB FJ44-77-011 R06 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R07)	SMF		MANDATORY	MTH 01-Aug-2011 HRS 618.6 LDG 628		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB525B-76-03R1, BY INSPECTION AND FOUND THE WASHERS PREVIOUSLY REMOVED FROM THE MATING SIDE OF THE FADEC CONNECTORS PER ACCOMPLISHMENT INSTRUCTIONS.										
SB FJ44-77-011 R07 E1	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R08)			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-77-011 R07 E2	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R08)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R08 E1	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R09)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R08 E2	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R09)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R09 E1	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R10)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R09 E2	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R10)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R10 E1	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R11)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R10 E2	ENGINE INDICATING ζ FADEC ENGINE HARNESS ASSEMBLY ζ INSPECTION (SUPERSEDED BY FJ44-77-011 R11)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R11 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R12)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R11 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R12)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R12 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R13)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R12 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R13)		MANDATORY			-			
MOC :									
SB FJ44-77-011 R13 E1	FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R14)		MANDATORY MTH			-			
MOC :									
SB FJ44-77-011 R13 E2	FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R14)		MANDATORY MTH			-			
MOC :									
SB FJ44-77-011 R14 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R15)		MANDATORY			-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-77-011 R14 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R15)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R15 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R16)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R15 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R16)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R16 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R17)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R16 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R17)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R17 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R18)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R17 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R18)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R18 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION			MANDATORY			-			
MOC :										
SB FJ44-77-011 R18 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION			MANDATORY			-			
MOC :										
SB FJ44-77-013 R01 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R01 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R02 E1	FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)			RECOMMENDED	MTH		-			
MOC :										
SB FJ44-77-013 R02 E2	FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)	UNK		RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH										
SB FJ44-77-013 R04 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-77-013 R04 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R05 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R05 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R06 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R06 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R07 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R07 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH										
SB FJ44-77-013 R09 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED	MTH HRS		-		(4000)4042.1	1780.4
MOC :										
SB FJ44-77-013 R09 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 E1	FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 E2	FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-79-009 R02 E1	ADJUST-LUBRICATION-OIL PRESSURE VALVE (SUPERSEDED BY FJ44-79-009 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-009 R02 E2	ADJUST-LUBRICATION-OIL PRESSURE VALVE (SUPERSEDED BY FJ44-79-009 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-009 R05 E1	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R06)			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-009 R05 E2	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R06)		RECOMMENDED			-			
MOC :									
SB FJ44-79-011 R01 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)		MANDATORY			-			
MOC :									
SB FJ44-79-011 R01 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)		MANDATORY			-			
MOC :									
SB FJ44-79-011 R03 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)		MANDATORY			-			
MOC :									
SB FJ44-79-011 R03 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)		MANDATORY			-			
MOC :									
SB FJ44-79-011 R04 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE		MANDATORY	MTH HRS		DUE DUE DUE		(4000)4042.1	1780.4
MOC :									
SB FJ44-79-011 R04 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE		MANDATORY	MTH HRS		DUE DUE DUE		(4000)4021.5	1759.8
MOC :									
SB FJ44-79-011 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)		MANDATORY			-			
MOC :									
SB FJ44-79-011 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)		MANDATORY			-			
MOC :									
SB FJ44-79-012 R01 E1	OIL - LUBE OIL COOLER - REWORK OR REPLACE		RECOMMENDED	MTH HRS		DUE DUE DUE		(4000)4042.1	1780.4
MOC :									
SB FJ44-79-012 R01 E2	OIL - LUBE OIL COOLER - REWORK OR REPLACE		RECOMMENDED	MTH HRS		DUE DUE DUE		(4000)4021.5	1759.8
MOC :									
SB FJ44-79-012 E1	LUBE OIL COOLER - REWORK OR REPLACE (SUPERSEDED BY FJ44-79-012 R01)		RECOMMENDED			-			
MOC :									
SB FJ44-79-012 E2	LUBE OIL COOLER - REWORK OR REPLACE (SUPERSEDED BY FJ44-79-012 R01)		RECOMMENDED			-			
MOC :									
SB FJ44-79-013 R01 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R02)		OPTIONAL			-			
MOC :									
SB FJ44-79-013 R02 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03)	UNK	RECOMMENDED	MTH 27-Feb-2018 HRS 2062.5 LDG 2289		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-013 R03 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R04 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R04 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R05 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE			RECOMMENDED	MTH HRS		-		(4000)4042.1	1780.4
MOC :										
SB FJ44-79-013 R05 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)	UNK		OPTIONAL	MTH 08-Feb-2018 HRS 2241 LDG 2272		-			Complete
MOC : COMPLIED WITH										
SB FJ44-79-013 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)			OPTIONAL			-			
MOC :										
SB FJ44-79-015 E1	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SB FJ44-79-015 E2	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SB FJ44-79-016 R04 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-79-T017 R01 E1	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST			RECOMMENDED			-			
MOC :										
SB FJ44-79-T017 R01 E2	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2007-23-16 24AD-01	INCORPORATE ELECTRICAL POWER RELAY CIRCUIT PROTECTION KIT PART NUMBER SB525B-24-02	*CF		MANDATORY	MTH 28-Jul-2009		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY AIRCRAFT MODEL SERIAL AND/OR UNIT NUMBER.										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2			MANDATORY			-			
MOC :										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK			MANDATORY			-			
MOC :										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS			MANDATORY			-			
MOC :										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT			MANDATORY	MTH		-			
MOC :										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KTYR			MTH 12-Nov-2018 HRS 2195.6 LDG 2398		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE DOES NOT APPLY AS THIS AIRCRAFT IS NOT EQUIPPED WITH AN AMERI-KING ELT.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT			MANDATORY			-			
MOC :										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS			MANDATORY			-			
MOC :										
FAA 2005-17-11 26AD-01	PREVENT INCORRECT INSTALLATION OF WIRES TO THE ENGINE FIRE EXTINGUISHER BOTTLES	*CF		MANDATORY	MTH 28-Jul-2009		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY AIRCRAFT MODEL SERIAL AND/OR UNIT NUMBER.										
FAA 2019-08-13	FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT			MANDATORY			-			
MOC :										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	KGGG		MANDATORY	MTH 26-Feb-2015 HRS 1532.4 LDG 1717		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE DOES NOT APPLY DUE TO INSTALLED UNIT BY PART NUMBER.										
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KALN		MANDATORY	MTH 02-Oct-2017 HRS 1941.8 LDG 2089 ACH 975		-			N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KTLR	MANDATORY	MTH 19-Dec-2015 DAYS 1703.3 HRS 1880 LDG		-			N/A
MOC : NOT APPLICABLE									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KTLR	MANDATORY	MTH 19-Dec-2015 HRS 1703.3 LDG 1880		-			N/A
MOC : NOT APPLICABLE - AD 2015-23-09 DOES NOT APPLY TO THE INSTALLED MASK PART NUMBERS AS FOLLOWS: PILOT = MC10-16-101, S/N 200110 AND COPILOT = MC10-16-101, S/N 118376.									
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KTLR	MANDATORY	MTH 19-Dec-2015 HRS 1703.3 LDG 1880		-			N/A
MOC : NOT APPLICABLE - AD 2015-23-09 DOES NOT APPLY TO THE INSTALLED MASK PART NUMBERS AS FOLLOWS: PILOT = MC10-16-101, S/N 200110 AND COPILOT = MC10-16-101, S/N 118376.									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KTYR	MANDATORY	MTH 23-Sep-2016 HRS 1806.5 LDG 1967 ACH 842.2		-			N/A
MOC : NOT APPLICABLE - THIS AIRCRAFT IS NOT EQUIPPED WITH A PBE POUCH. AD 2016-11-20 DOES NOT APPLY.									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KTYR	MANDATORY	MTH 23-Sep-2016 HRS 1806.5 LDG 1967		-			N/A
MOC : NOT APPLICABLE - THIS AIRCRAFT IS NOT EQUIPPED WITH A PBE POUCH. AD 2016-11-20 DOES NOT APPLY.									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KTYR	MANDATORY	MTH 23-Sep-2016 HRS 1806.5 LDG 1967		-			N/A
MOC : NOT APPLICABLE - THIS AIRCRAFT IS NOT EQUIPPED WITH A PBE POUCH. AD 2016-11-20 DOES NOT APPLY.									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	KTYR	MANDATORY	MTH 23-Sep-2016 HRS 1806.5 LDG 1967		-			N/A
MOC : NOT APPLICABLE - THIS AIRCRAFT IS NOT EQUIPPED WITH A PBE POUCH. AD 2016-11-20 DOES NOT APPLY.									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED		MANDATORY			-			
MOC :									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED		MANDATORY			-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KTYL	MANDATORY	MTH 11-Apr-2018 HRS 2075.1 LDG 2298		-			N/A
MOC : NOT APPLICABLE - THIS AD DOES NOT APPLY AS THIS AIRCRAFT IS NOT EQUIPPED WITH PBES.									
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES		MANDATORY			-			
MOC :									
FAA 2008-03-10 53AD-01	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE	*CF	AIRWORTHINESS	MTH 28-Jul-2009		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY AIRCRAFT MODEL SERIAL AND/OR UNIT NUMBER.									



CESCOM 10 - Aircraft Status Report

Owner: **FIRST AV GROUP, LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0327**
 Unit: **0327** Reg No: **N527DV**
 Airworthiness: **28-Jul-2009**
 Print Date: **03-Jul-2019 9:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2261.7	2461	30-Jun-2019	.15
ENG 1	2219.6	2417	30-Jun-2019	.15
ENG 2	2240.2	2444	30-Jun-2019	.15
AIR COND	1134.2		30-Jun-2019	.9

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
23FO501	MOBIL JET II OIL FACTORY OPTION			501 FO	MTH 28-Jul-2009		-			
23FO629S 23FO629 : S	WX-1000E LIGHTNING DETECTION L3 COMMUNICATIONS FACTORY OPTION			629S FO	MTH 28-Jul-2009		-			
23FO650	VOICE ANNUNCIATOR FACTORY OPTION			650 FO	MTH 28-Jul-2009		-			
23FO675G 23FO675 : G	AIRCELL ST-3100 FACTORY OPTION			675G FO	MTH 28-Jul-2009		-			
24FO655	ELECTRONIC CHARTS - JEPPESEN FACTORY OPTION			655 FO	MTH 28-Jul-2009		-			
25FO119E 25FO119 : E	SIDE FACING SEAT & CABINET FACTORY OPTION			119E FO	MTH 28-Jul-2009		-			
34FO141	BOSE HEADSET JACKS FACTORY OPTION			141 FO	MTH 28-Jul-2009		-			
34FO686Q 34FO686 : Q	FMS 2 GARMIN GPS-500 FACTORY OPTION			686Q FO	MTH 28-Jul-2009		-			