


PAC 40/48

**Fully-automatic
stitcher - gluer**
for single piece boxe

1 Stitching

2 Gluing

3 Taping



Machine speed :
1200 boxes/hour
Required operator : 1
Changeover time : 10 min




PAC 40/48

Semi-automatic stitcher - gluer

for single and two piece boxes

OPTIONS




PAC 40

	mm	inch
L mini.	350	13,78
L maxi.	1100	43,31
B mini.	250	9,84
B maxi.	800	31,5
H mini.	300	11,81
H maxi.	1600	62,99
D mini	1200	47,24
D maxi	3600	149,61

PAC 48

	mm	inch
L mini.	350	13,78
L maxi.	1600	62,99
B mini.	250	9,84
B maxi.	800	31,5
H mini.	300	11,81
H maxi.	2200	86,61
D mini	1200	47,24
D maxi	4800	198,98

H 4225



PAC 40 : 6700
PAC 48 : 7700

PAC 40 : 15000
PAC 48 : 19000

Non stop stacker



Non stop seeder



Pack250



Turnover device for bundles



Turnover device for bundles



Document not contractual, the manufacturer reserves the right to make technical modifications

