

CONTINENTAL MOTORS® AIRCRAFT ENGINE  
**SERVICE DOCUMENT MASTER INDEX**

**X33000**  
**INDEX**  
**FOR GENERAL**  
**DISTRIBUTION**

**SUBJECT:** Active Service Documents Master Indices

---

---

**I. Introduction**

This Service Document Master Index organizes an alphanumeric list of active and recently retired service documents. Service documents not included in this index (with release dates issued earlier than this index) are considered obsolete or inactive. Inactive service documents are no longer eligible for publication or release.

This document is comprised of multiple reorganized indices tailored for your specific point of reference:

**Table 1. Locating your Service Documents**

Section	Index sorted by	Description	Page
III	FAA AD	Sorted numerically by FAA AD number and their corresponding service document (if applicable).	2
IV	Recent Changes	A summary of all documents released since the last published Index. New, revised, and retired service documents sorted by most recently released date.	5
V	Subject Tables	Engine subsystem tables (grouped alphabetically by subject type). Active service documents are sorted by most recently released date.	7
VI	Engine Model	Cross-referenced index (grouped by engine model) with the applicable service document number and release date. Active service documents are sorted by most recently released date.	21

Continental Motors, Inc (CMI) issues service documents to announce product improvements and to address conditions that affect maintenance, preventive maintenance, safety and continued airworthiness. Compliance is required as specified in the **COMPLIANCE** section of each service document.

For the different categories of service documents released by CMI, refer to **SIL93-11B** (or most current version) for Continental® Aircraft Engine Service Documents and **SIL640** for Continental Motors, Inc. ® Ignition System Service Documents.

Information contained in service documents will be incorporated into engine parts, maintenance, and overhaul manuals at the next revision or reprinting of the affected manual. Once incorporated into all applicable manuals, the information becomes a part of the engines type design data and is required for continued airworthiness of the engine or components.

## II. Instructions For Continued Airworthiness (ICA, excerpt from SIL93-11B)

### WARNING

**New or updated Instructions for Continued Airworthiness (ICA) may be contained in Continental Motors, Inc. (CMI) service documents. Service documents applicable to the engine or accessories on which work is being performed must be consulted and complied with prior to performing any installation, maintenance, or overhaul function.**

In accordance with Title 14 of the Code of Federal Regulations (14 CFR) part 34, CMI issues Instructions for Continued Airworthiness (ICA) for the engines and components for which it holds the Type Certificate or Parts Manufacturing Authorization (PMA) authority. ICAs are primarily published in the form of Maintenance Manuals, Overhaul Manuals, or combined Maintenance and Overhaul Manuals. These manuals may be supplemented by service documents, which may contain updates to an ICA until such time that the updated ICA is incorporated into the appropriate manual. Additionally, service documents may address a specific issue and modify the published ICA for a limited purpose which may not be incorporated into the manual. (Reference the latest revision of **SIL93-11B** for more information).

### III. FAA AD

The following is a list of FAA Airworthiness Directives (AD) applicable to CMI engines and their corresponding service documents.

FAA AD No.	Document No.
46-36-01	M46-6 <sup>1</sup>
47-40-02	M47-9 <sup>1</sup>
49-50-01	M49-4 <sup>1</sup>
50-32-01	M48-14 <sup>1</sup> , M48-15 <sup>1</sup>
50-20-01	M50-2 <sup>1</sup>
51-26-03	M48-12, M51-2 <sup>1</sup>
53-09-04	NONE
56-06-01	M56-2 <sup>1</sup>
60-06-04	M57-4 <sup>1</sup>
60-12-01	M56-2 <sup>1</sup>
63-15-01	M60-1 <sup>1</sup>
69-18-05	M69-8 <sup>1</sup>
70-13-03	M70-5 <sup>1</sup>
70-14-07R2	M70-10R1 <sup>1</sup>
71-09-03	M70-17
72-06-05R2	M73-12
72-15-02	M73-6R1
72-20-02	M73-2
72-24-03	M76-20

FAA AD No.	Document No.
73-13-04	NONE
74-18-05	M74-18
74-18-07	NONE
74-18-08	M74-5
74-22-04	M74-21 <sup>1</sup>
74-26-09	BENDIX SB No. 556C
75-09-13	NONE
76-02-07	M75-30
76-07-12	BENDIX SB No. 583
76-13-09	M76-14 <sup>1</sup>
77-05-04	M77-6 Sup1 <sup>1</sup>
77-13-22	M90-17
78-06-01	M78-5 Rev3
78-18-04	BENDIX SB No. 590A
79-05-09	M79-2 Rev1 <sup>1</sup>
79-12-07	BENDIX SB No. 584B <sup>1</sup>
79-18-06	BENDIX SB No. 605A
80-01-04	NONE
80-09-11	NONE

<sup>1</sup> Corresponding CMI Service Documents removed from set.

FAA AD No.	Document No.
80-17-04	NONE
80-22-05	M81-9 (SS M80-20)
80-25-06R1	M80-30 Rev1 <sup>1</sup>
81-07-06	M81-8R1
81-12-06 R1	BENDIX SB No. 618, 619
81-13-10 R1	M81-23 R1
81-16-05	M81-13 R1
81-17-01	BENDIX SB No. 614
81-23-02	NONE
81-24-06	M80-26 Rev1 <sup>1</sup>
82-09-01	M82-5
82-11-05	BENDIX SB No. 617B
82-13-01	BENDIX SB 613 <sup>1</sup>
82-20-01	BENDIX SB 623A
82-27-03	M83-3
84-19-04	NONE
84-25-05	NONE
85-08-02	M85-3
86-08-07	NONE
86-13-04 R2	M86-7 R5 <sup>1</sup>
87-04-05	M87-6
87-14-02	M87-13
87-26-08	M87-25 / M87-26
88-03-06	M88-4
88-17-03	M87-24 / M88-5 / M88-6
89-14-01	M89-14
89-24-01 R1	M90-6
89-24-03	NONE
91-19-03	M90-14
92-04-09	M92-4 R1
93-08-17	M91-10R1
93-10-02	MSB93-12
93-11-03	NONE
93-16-15	MSB95-6 (SS M93-9R1)
93-19-04	NONE
93-22-05	CSB93-13
94-01-03	MSB644
94-05-05	NONE
94-06-09	CSB94-1

FAA AD No.	Document No.
95-03-14	MSB94-9
95-08-10	CSB95-1A
95-21-15	SB03-3/M88-10
96-12-04	NONE
96-12-06	MSB94-8D
96-12-22	NONE
97-21-02	CSB97-10A
97-27-16	CSB96-8
97-26-17	CSB96-8/MSB96-10
98-01-06	NONE
98-01-08	NONE
98-17-11	NONE
98-19-02	NONE
99-19-01	MSB99-3C/CSB99-6A
2000-23-21	MSB00-5D
2002-13-04	NONE
2004-08-10	NONE
2005-12-06	MSB645
2005-20-04	MSB94-4G
2007-05-15	MSB94-4G
2007-04-19	NONE
2007-16-10	MSB07-4
2008-08-17	MSB08-5
2009-02-03	NONE
2009-19-07	MSB09-1
2010-07-08	MSB10-3
2010-11-04	MSB09-8A
2011-13-03	SB10-8A
2011-25-51	MSB11-4
2011-26-07	MSB00-6D
2012-03-06	NONE
2012-24-09	NONE
2012-10-13	MSB13-7
2013-21-02	MSB11-4B
2014-05-29	MSB13-7

<sup>1</sup>Corresponding CMI Service Documents removed from set.

*Intentionally Left Blank*

#### IV. SERVICE DOCUMENTS, listed by most recent changes

Table	Subject Title	Page
2	New Service Documents (released after 2014-10-01) .....	5
3	Revised Service Documents (updates released after 2014-10-01).....	5
4	Retired Service Documents (removed after 2014-10-01) .....	5
5	Archived & Superseded Service Documents .....	6

NOTE: The following subject tables contain the service document number, release date, release status (**N** = new, **R** = revision *or* **X** = retired documents released after 2014-10-01), and document title/description. All services documents in this section are sorted by most recently released date.

**Table 2. New Service Documents (released after 2014-10-01)**

Document No.	Release Date	Status	Document Title/Description
SSI06-6A	2014-12-17	N	Alternator Mount Bracket Assembly Inspection

**Table 3. Revised Service Documents (updates released after 2014-10-01)**

Document No.	Release Date	Status	Document Title/Description
CSB09-11A	2014-11-12	R	Minimum Cruise RPM

**Table 4. Retired Service Documents (removed after 2014-10-01)**

Document No.	Release Date	Status	Document Title/Description
SIL04-1A	2005-05-31	X	Installation of the Optional Altitude Compensating Fuel Pump on IO240B Series Engines
631	1989-09-01	X	Recommended Lubricant for Tapered Drive on TCM Magnetos
M86-4	1986-01-09	X	Fuel Pumps
M85-14	1985-09-23	X	Magneto Pressurization Filter
M85-9R1	1985-08-06	X	Pistons to Cylinder Dome Clearance
M84-8	1984-06-19	X	Magneto Timing Indicator Plate
M71-14	1971-06-21	X	Slick Service Bulletin 1-71
M70-17	1971-04-01	X	Checking for Gasket Deformation and/or Fuel Leaks at the Fuel Injector Pump Variable Orifice Housing

**Table 5. Archived & Superseded Service Documents**

Superseded Document	Subsequent Revision	Superseded Document	Subsequent Revision	Superseded Document	Subsequent Revision
631	RETIRED	SB00-2	SB00-2A	SID97-3B	SID97-3C
CSB04-6	CSB04-6A	SB03-7	SB03-7A	SID97-3C	SID97-3D
CSB08-9	CSB08-9B	SB04-7	SB14-2	SID97-3D	SID97-3E
CSB09-11	CSB09-11A	SB05-10	M-18 MANUAL	SID97-3E	SID97-3F
CSB13-1	CSB13-1A	SB05-7	FI-2	SID97-4C	SID97-4D
M70-17	RETIRED	SB05-8	SB05-8A	SID97-4D	SID97-4E
M71-14	RETIRED	SB06-1	SB06-1A	SID97-4E	SID97-4F
M75-17	M70-17	SB07-8	SB07-8A	SIL02-4	RETIRED
M79-11	SB11-3	SB07-8A	CSB09-11	SIL03-2B	SIL03-2C
M81-25	MSB14-8	SB08-3	SB08-3A	SIL04-1A	RETIRED
M84-8	RETIRED	SB08-3A	SB08-3B	SIL04-3	RETIRED
M85-9R1	RETIRED	SB08-8	SB08-8A	SIL04-8	SB14-2
M85-14	RETIRED	SB08-8A	SB08-8B	SIL04-12	SIL04-12A
M86-4	RETIRED	SB09-3	SB09-3A	SIL05-3	SIL05-3A
M87-10	SB11-3	SB09-6	SB09-6A	SIL06-4	RETIRED
M89-5	SB11-3	SB10-8	SB10-8A	SIL07-7	SIL07-7A
M91-9	SID05-1A	SB13-4A	SB13-4B	SIL13-2	SIL13-2A
M92-11	RETIRED	SB13-6	SB13-6A	SIL14-4	SIL14-4A
MSB00-6C	MSB00-6D	SB94-8	MSB94-8	SIL93-11A	SIL93-11B
MSB08-2	MSB08-2B	SB96-11A	SB96-11B	SIL97-14	RETIRED
MSB09-1	MSB09-1A	SB96-7B	SB96-7C	SIL98-6B	SEE PARTS CATALOG
MSB09-1A	MSB09-1B	SB96-7C	SB96-7D	SIL98-9B	SIL98-9C
MSB09-8	MSB09-8A	SB97-6	SB97-6A	SIL98-9C	SIL98-9D
MSB11-4	MSB11-4A	SB97-6A	SB97-6B	SIL99-2B	SIL99-2C
MSB11-4A	MSB11-4B	SB97-6B	SB97-6C		
MSB94-8B	MSB94-8C	SB98-2	RETIRED		
MSB94-8C	MSB94-8D	SB99-8	SB99-8A		
MSB96-10	MSB96-10A	SID05-1	SID05-1A		

**V. SERVICE DOCUMENTS, listed by subject**

<b>Table</b>	<b>Subject Title</b>	<b>Page</b>
6	Alternators.....	8
7	Bearings .....	8
8	Camshafts / Lifters.....	8
9	Carburetors.....	9
10	Connecting Rods .....	9
11	Crankcases .....	9
12	Crankshafts.....	10
13	Cylinders .....	11
14	Electronic Systems.....	12
15	Fuel / Fuel Hoses / Fuel Injection .....	12
16	Gears .....	13
17	General Topics .....	14
18	Hoses / Control Cables / Linkages.....	15
19	Ignition / Magnetos .....	15
20	Induction / Air Intake.....	16
21	Lubrication / Oils .....	16
22	Miscellaneous.....	17
23	Pistons .....	17
24	Starters / Starter Adapters .....	18
25	Turbocharging / Exhaust Systems.....	19

NOTE: The following subject tables contain the service document number, release date, release status (**N** = new *or* **R** = revised documents released after 2014-10-01), and document title/description. All services documents in this section are sorted by most recently released date.

<sup>1</sup>Special Service Instructions (SSI) are issued to address an issue on specific model and/or serial number engines. CMI will distribute SSI notification directly to the owners of the affected engines. SSIs will not be included in the General Service Document set but will be made available through CMI Customer Service to owners of the affected engines only. For further information on SSIs refer to the latest revision of SIL93-11B or contact CMI Customer Service at 1 (251) 438-3411, ext. 8299.

**Table 6. Alternators**

Document No.	Release Date	N/R	Document Title/Description
SSI06-6A <sup>1</sup>	2014-12-17-	N	Alternator Mount Bracket Inspection
SIL14-4A	2014-08-14		24 Volt/70 Amp Belt-Driven Alternator Brace Alignment
SB14-5	2014-06-19		Hartzell Engine Technologies (HET) Service Bulletin (SB) No. 059
SIL13-2A	2014-01-15		Alternator Instructions for Continued Airworthiness
SB13-8	2014-01-15		Hartzell Engine Technologies Service Information Letter A-137
SB11-3	2011-03-18		Alternator and Drive Coupling Installation
SB11-1A	2011-03-17		Hartzell Engine Technologies Service Information Letter A-138
SB11-2	2011-01-13		Hartzell Engine Technologies Service Information Letter A-135
SB09-12	2009-10-16		Kelly Aerospace Energy Systems Serv Bull 038A Inspection of Slip Ring End Housing for Cracks ES1024-1, TCM 646802
CSB08-11	2008-07-16		Kelly Aerospace Power Systems Bulletin 033
SB95-3B	2005-10-25		Alternator / Generator Drive Coupling
SB01-3A	2002-12-10		Teledyne Continental Motors P/N 649304A1 and P/N 649305A1 Gear-Driven Alternators
SID97-8	1997-05-28		Interference of TCM 24 Volt 60 Ampere Gear Driven Alternator and Crankcase Through Bolt
M92-12	1992-08-27		New and Rebuilt Alternator Thru-Bolt Torque Inspection, P/N 649304, 649305 (with Drive Coupling), 649304R and 649305R (with Drive Coupling)
M87-15	1987-07-13		Alternator Ground Strap
M84-5	1984-02-13		Gear Driven Alternator Inspection Procedure
M81-15R1	1983-06-16		Prestolite 100 Amp Alternator Exchange
M81-12	1981-05-11		Installation Instructions and Rework Instructions for Part Nos. 642266 & 643935 Alternator Brackets
M76-7	1976-03-25		P/N 634021 Alternator Face Drive Gear Lockplates
M75-30	1975-12-19		Prestolite Alternators
M73-6R1	1973-06-11		Prestolite Alternator Cooling Fan Maintenance and Inspection

**Table 7. Bearings**

Document No.	Release Date	N/R	Document Title/Description
SB97-5	1997-03-31		Installation of Flanged Type Front Main Bearings
M93-5	1993-02-19		Chamfer of Crankcase Main Bearing Oil Feed Holes
M89-14	1989-06-29		Thru Bolt torque Check and Visual Inspection #2 Main Bearings
M78-9	1978-08-23		Crankcase, Crankshaft and Bearing Applications

**Table 8. Camshafts / Lifters**

Document No.	Release Date	N/R	Document Title/Description
SID05-1A	2014-05-02		Inspection Guidelines for CMI Camshafts and Hydraulic Lifters
MSB09-8A	2009-12-04		Inspection and Removal of Certain TCM Engine Hydraulic Lifters
SB05-8A	2009-07-16		Improved Camshaft Gear P/N 656818
SB00-1	2000-01-14		Camshaft Packaging
SIL98-5	1998-06-12		Production Release of P/N 654837A1 Camshaft Assembly
M86-13R1	1986-10-17		Camshaft Plug Inspection and Overhaul Manual Revision
M86-14	1986-10-01		Camshaft 629726 Rework



**Table 9. Carburetors**

Document No.	Release Date	N/R	Document Title/Description
SB09-6A	2009-06-22		Volare' Carburetors, LLC SB-5 Rev A Service Bulletin
SB09-5	2009-04-30		Volare Carburetors, LLC SB4 Service Bulletin, Carburetor Bowl to Float Clearance
SB09-3A	2009-04-24		Volare Carburetors, LLC SB2 Service Bulletin, Required Replacement of Foam and Hollow Floats
SB09-2	2009-03-17		Volare Carburetors, LLC SB1 Service Bulletin
SB08-7	2008-06-27		Precision Airmotive, LLC Mandatory Carburetor Service Bulletin MSA-14
SID97-7	1997-05-07		Precision Airmotive Corporation Service Bulletin MSA-10
SID94-12	1994-11-14		Precision Airmotive Corporation Service Bulletin - MSA-7
CSB93-13	1993-08-12		Carburetor Air Intake Housing Assembly Inspection
M92-5	1992-02-28		Precision Airmotive Corporation Mandatory Service Bulletins #MSA-1 Rev. 1 and MSA-2 Rev. 1
M88-15	1988-10-10		Facet Service Bulletin A1-88
M75-15	1975-07-14		New Carburetor Airbox
M73-12	1973-06-08		Marvel-Schebler Carburetor Bulletin A1-73

**Table 10. Connecting Rods**

Document No.	Release Date	N/R	Document Title/Description
SB07-1	2007-03-19		Connecting Rod Pistons Pin Bushing Installation
SB00-3A	2004-11-12		Crankshaft, Counterweight and Connecting Rod Repair Information
CSB96-13	1996-11-14		IO360, TSIO360 and LTSIO360 Series Engine Connecting Rod Inspection and Replacement
M72-17R1	1973-10-05		New Maximum Weight Difference Allowance between Connecting Rods and Pistons in the Same Engine

**Table 11. Crankcases**

Document No.	Release Date	N/R	Document Title/Description
SIL14-6	2014-09-16		Sandcast Crankcase Oil Gage Rod Housing/Housing Extension Installations on 470, 520, and 550 Engines
SB05-8A	2009-07-16		Improved Camshaft Gear P/N 656818
SB09-4A	2009-06-10		Crankcase Inspection for "Permold" Engines Equipped with Air Conditioner Systems Installed From 1998 to Present.
SID97-8	1997-05-28		Interference of TCM 24 Volt 60 Ampere Gear Driven Alternator and Crankcase Through Bolt
CSB97-9	1997-05-28		GTSIO-520 Crankcase Inspection
CSB96-2	1996-03-21		Crankcase Oil Passage Inspection
CSB94-15	1994-12-02		Crankcase Stud Inspection
MSB94-9	1994-10-21		Inspection of Engine Mount Bracket, Part Number 630695; Replacement of Engine Mount Brackets, Part Numbers 630694 and 630695
M93-5	1993-02-19		Chamfer of Crankcase Main Bearing Oil Feed Holes
M92-9	1992-05-29		Flanged 500 Thru Bolt Nut, P/N 652541
M92-7	1992-05-26		Crankcase Cylinder Deck Studs
M90-17	1990-08-23		Crankcase Inspection Criteria
M90-16	1990-08-22		7th Stud Improvement on TCM Crankcases
M89-14	1989-06-29		Thru Bolt torque Check and Visual Inspection #2 Main Bearings
M89-9	1989-04-21		Excessive Crankcase Pressures

**Table 11. Crankcases**

Document No.	Release Date	N/R	Document Title/Description
M86-9	1986-03-20		Crankcase Modification
M80-18	1980-09-02		Modified Breather System
M78-9	1978-08-23		Crankcase, Crankshaft and Bearing Applications
M77-9	1977-03-17		Thru Bolt Change
M70-3	1970-02-03		Crankcase Modification Recommended At Next Engine Major Overhaul

**Table 12. Crankshafts**

Document No.	Release Date	N/R	Document Title/Description
SB14-2	2014-09-16		Inspection and Replacement of IO240 Starter and Crankshaft Cluster Gear
SB13-6A	2014-04-10		Crankshaft Gear Replacement
CSB12-1	2012-05-11		P/N 641909 Lock Plate Inspection
SB09-14	2009-10-16		Crankshaft Corrosion Treatment
SB05-8A	2009-07-16		Improved Camshaft Gear P/N 656818
MSB96-10A	2008-10-14		Crankshaft Ultrasonic Inspection
SB08-12	2008-09-09		Crankshaft Gear Supersedure
SSI07-5 <sup>1</sup>	2007-08-22		Replacement of 6th order Crankshaft Counterweights, Pins, Bushings, Plates and Snaprings
SB06-5	2006-05-25		Crankshaft Oil Transfer Tube Inspection and Replacement
SIL06-3	2006-05-01		Crankshaft Gear Retaining Screw
MSB94-4G	2005-11-01		Starter Adapter Shaftgear and Crankshaft Gear Inspection
SB00-3A	2004-11-12		Crankshaft, Counterweight and Connecting Rod Repair Information
SB03-5	2003-11-06		New Limits for Crankshaft End Clearance
MSB00-5D	2001-10-17		Crankshaft Material Inspection
MSB99-3C	1999-07-27		Crankshaft Inspection
CSB99-6A	1999-07-21		GTSIO-520 & GIO-550 Crankshaft Inspection
SB96-3B	1996-10-14		Crankshaft Gear Bolt Inspection
CSB96-8	1996-06-25		Replacement of Airmelt (Non-Var) Crankshafts
SB94-7	1994-09-14		Crankshaft Flange Timing Marks
M93-4	1993-02-12		Crankshaft Counterweights
M87-23	1987-11-24		Crankshaft Counterweight Identification at Overhaul
M78-9	1978-08-23		Crankcase, Crankshaft and Bearing Applications
M78-3	1978-01-11		Governor Oil Transfer Collar Sleeves, Retaining Clips and Clearances
M76-4	1976-03-12		Installation Instructions for Propeller Shaft or Crankshaft Oil Seals



**Table 13. Cylinders**

Document No.	Release Date	N/R	Document Title/Description
SID97-4F	2014-08-13		Cylinder Bore and Pistons Fit Specifications
CSB14-1	2014-06-23		Cylinder Barrel Fin Inspection
SB00-2A	2014-05-02		IO346 Replacement Cylinder Assembly Kit
SSI13-5 <sup>1</sup>	2013-10-18		Amplified Operation, Maintenance and Servicing Requirements for Cirrus SR-20 Aircraft operated by CAFUC Only
MSB09-1B	2009-08-18		Cylinder Replacement
SB09-7	2009-07-16		Potential Push Rod Seal Leakage
SB08-1	2008-02-18		Rocker Shaft Inspection and Replacement
SID97-4D	2013-08-23		Cylinder Bore and Pistons Fit Specifications
SIL00-11B	2004-05-24		Release of New Cylinder Induction Port Drain Connector
SID97-2B	2004-04-19		Design, Operation, Maintenance and Warranty for TCM Cylinders
SIL04-2	2004-03-30		Cylinder Barrel Ultrasonic Inspection
SB03-3	2003-03-28		Differential Pressure Test and Borescope Inspection Procedures for Cylinders
SB02-9	2002-10-25		Cylinder Head to Barrel Seepage P/N 654972 Cylinder Assembly
SIL02-6A	2002-10-25		Production Release of Optional Intake and Exhaust Valves
SIL99-5	1999-05-25		TCM Part Number 629141 Thermo Unit
SB98-8	1998-10-22		Number One and Three Cylinder Intake Tube Modifications
SIL98-3A	1998-06-12		Production Release of New Intake and Exhaust Valve Springs
CSB98-1B	1998-06-01		Intake and Exhaust Valve Inspection
SIL97-14	1997-10-30		Replacement Cylinder Assembly
SB97-11	1997-08-10		Installation of Single Piece Rocker Assembly Bushings Part Numbers 652129 and 652963
SB96-12	1996-09-10		Continued Airworthiness Instructions for TCM Cylinders
CSB95-4	1995-08-10		Intake Valve Guide Seal P/N 646678 Inspection
SIL94-10	1994-11-14		Replacement of Intake Valve Rotocoils
SB94-13	1994-11-14		Pistons Ring Set, Part Number 649226 and Cylinder Kit Part Numbers 653443A3, 653443A3BP, 653443A5, 653443A5BP, 653444A4, 653444A4BP, 653455A2 and 653455A2BP
MSB93-12	1993-05-12		Valve Retainer Key Installation Inspection
M93-8	1993-02-19		Rocker Arm to Rotocoil Clearance
M92-11	1992-08-24		Liquid Cooled Cylinder Assembly, Spark Plug and Spark Plug Heli-Coil
M92-8	1992-05-29		Application of 4-1/6" Diameter Cylinder Assemblies
M92-6	1992-02-28		Rockershaft Retention Improvement for Inclined Valve Cylinder
M92-4R1	1992-02-05		IO and L/T/SIO360 Rocker Shaft Stud Inspection
M91-6	1991-03-20		Cylinder Barrel Inspection
M91-7	1991-03-20		Cylinder Barrel Ultrasonic Inspection
M90-15	1990-08-21		Rocker Arm and Push Rod Inspection
M90-13	1990-07-16		Exhaust Valve Stem Corrosion/Erosion
M89-7R1	1989-08-04		Engine Operation After Cylinder Replacement and/or Major Overhaul
M88-12	1988-09-09		Piper Aircraft Mandatory Service Bulletin No. 892
M87-8	1987-02-26		Exhaust Valve Inspection
M85-10	1985-07-18		Cylinder Hold Down Nuts

**Table 13. Cylinders**

Document No.	Release Date	N/R	Document Title/Description
M85-3	1985-02-04		Exhaust Valves In P/N 646680 Cylinder Assemblies
M81-25	1981-11-30		Exhaust Flange to Cylinder Installation Procedures
M78-16	1978-11-29		Number Two Cylinder Intake Elbow Tube, TCM Part No. 629138
M78-6	1978-03-03		Removal and Re-Installation of Special Rosan Exhaust Port Studs
M77-19	1977-08-12		Intake and Exhaust Rocker Arm Identification and Application
M76-12	1976-05-24		Chrome Plating of Cylinders
M76-8	1976-04-13		Intake Valve Change
M75-17	1975-07-17		Cylinder Head and Rocker Pivot Pin Change
M74-16	1974-06-17		Usage and Identification of Valve Springs
M73-13	1973-07-10		Reaming and Bushing Rocker Shaft Bosses
M73-2	1973-01-17		FAA Airworthiness Directive No. 72-20-2 (470 Cylinder)

**Table 14. Electronic Systems**

Document No.	Release Date	N/R	Document Title/Description
SSI07-6 <sup>1</sup>	2007-08-31		IOF-240-B Electronic Control Unit (ECU) Replacement

**Table 15. Fuel / Fuel Hoses / Fuel Injection**

Document No.	Release Date	N/R	Document Title/Description
SB99-8A	2014-04-10		Engine Fuel Injection System Preservation
SB13-4B	2014-01-15		Aneroid Equipped Fuel Pumps
SSI13-5 <sup>1</sup>	2013-10-18		Amplified Operation, Maintenance and Servicing Requirements for Cirrus SR-20 Aircraft operated by CAFUC Only
CSB08-3C	2013-07-17		Throttle and Mixture Control Levers
SIL13-3	2013-07-17		Placement of O-ring on specific fuel injector nozzles
SID97-3F	2013-05-10		Procedures and Specifications for Adjustment of Teledyne Continental Motors (TCM) Continuous Flow Fuel Injection Systems
CSB13-1A	2013-03-18		Replacement of Part No. 640560 Set Screws Installed on Part No. 642100-X (X= -1 Through -6 & -8), 646292-1 And 646663-1 And R-642100-3, -4, -5 And -6 Fuel Pressure Regulators
SID10-4	2010-07-21		Engine Maintenance for Volcanic Ash Contamination
SIL04-12A	2010-05-18		TCM Authorized Engine Adjustments, Component Replacement and Repositioning of Fitting Orientation
SIL08-10	2008-07-16		Precision Airmotive LLC SIL RS-88. RSA5, RSA10 Servo Inspections of Hex Head Plug
SB02-10A	2008-06-23		Fuel Injection System Servo Unit Vibration Damper
MSB08-2B	2008-09-17		Precision Airmotive LLC Fuel Injection Servo RSA-5, RSA-10
SB08-4	2008-03-14		Fuel Injection System Contamination
SB06-1A	2006-04-28		Teledyne Continental Motors (TCM) Fuel System Fuel Nozzle Inspection and Replacement
SB04-4A	2004-06-21		Replacement of Manifold Valve Spring P/N 630184
SIL01-2B	2001-09-04		Precision Airmotive Corporation SIL RS-59 Revision 2
SIL01-4	2001-09-04		Precision Airmotive Corporation SIL RS-60
CSB01-1	2001-04-25		Fuel Pump Inspection and Seal Leak Test
M81-8R1	2001-02-05		Fuel Pump Screen Restriction



**Table 15. Fuel / Fuel Hoses / Fuel Injection**

Document No.	Release Date	N/R	Document Title/Description
SB00-10	2000-12-19		Fuel Pump Seal P/N 649198
SB00-4A	2000-03-07		Australian AVGAS Contamination
SB99-8	1999-11-18		Engine Fuel Injection System Preservation
SB97-13	1997-10-30		Replacement Fuel Pump for TSIO520BE Engine
SB95-7	1995-12-08		Manifold Valve Cover Inspection
MSB95-6	1995-10-19		Fuel Pump Drive Coupling
M90-20	1990-12-20		Lear Romec Corporation, Service Bulletin No.101SB019
M90-19	1990-10-16		Fuel Inlet Tee
M89-19	1989-09-18		Re-Design of Lower Throttle Body Bracket
M88-10	1988-08-24		Contaminated Fuels
M87-6	1987-02-16		Romec Service Bulletin No. 101SB015 Fuel Pump P/N RR36090C (TCM P/N 643367)
M83-8R1	1983-07-15		Fuel Pump Replacement
M82-13	1982-10-27		Fuel Control Inlet Fitting
M82-5	1982-04-26		Fuel Pressure Regulator 642100-5 & 642100-6 on Engines Installed In Cessna 340 and 414 Series Aircraft
M82-3	1982-03-08		Lear Siegler, Inc., Romec Division, Fuel Pump, TCM P/N 643367A1
M81-6R2	1982-01-29		Fuel Hoses
M80-9R1	1980-06-30		Fuel Metering Shaft
M80-11	1980-04-14		Intake Manifold Tube Drain Bosses
M79-4	1979-02-14		Fuel Injection Adjustment and Flight Testing Procedures of TIARA 6-285 Series Engine
M77-3	1977-01-11		Use of Alternate Aviation Grade Fuels In Engines originally Certificated on 80/87, 91/96 and 100/130 Grade Fuels
M76-15	1976-06-17		Fuel Pumps
M75-14	1975-06-30		635014 Air Throttle Bracket Assemblies

**Table 16. Gears**

Document No.	Release Date	N/R	Document Title/Description
SB14-2	2014-09-16		Inspection and Replacement of IO240 Starter and Crankshaft Cluster Gear
SB03-7A	2014-04-10		IO240 Series Magneto Drive Gear
SB13-6A	2014-04-10		Crankshaft Gear Replacement
SB05-8A	2009-07-16		Improved Camshaft Gear P/N 656818
SB08-12	2008-09-09		Crankshaft Gear Supersedure
SIL06-3	2006-05-01		Crankshaft Gear Retaining Screw
MSB94-4G	2005-11-01		Starter Adapter Shaftgear and Crankshaft Gear Inspection
SB01-3A	2002-12-10		Teledyne Continental Motors P/N 649304A1 and P/N 649305A1 Gear-Driven Alternators
SB01-5	2001-10-18		Starter Adapter Bevel Gear Inspection
SID97-8	1997-05-28		Interference of TCM 24 Volt 60 Ampere Gear Driven Alternator and Crankcase Through Bolt
SB96-3B	1996-10-14		Crankshaft Gear Bolt Inspection
CSB96-5	1996-04-12		Oil Pump Drive Gears, P/N 649506 and 649681
SB96-4	1996-04-12		Improved Oil Pump Gears and Suction Screens

**Table 16. Gears**

Document No.	Release Date	N/R	Document Title/Description
CSB96-1	1996-03-01		Starter Gear and Clutch Assembly P/N 653575
M90-6	1990-02-26		Inspection and Replacement of Scavenge Pump Gears P/N 635334 and 639388
M84-5	1984-02-13		Gear Driven Alternator Inspection Procedure
M81-23R1	1982-02-12		360 Series Oil Pump Drive Gear
M76-7	1976-03-25		P/N 634021 Alternator Face Drive Gear Lockplates
M72-8	1972-06-21		New Design Splined Drive Scavenge Pump Shaft and Gear Assembly
M70-7	1970-03-17		Increasing Size of Oil Feed Holes to Starter Adapter Shaftgear

**Table 17. General Topics**

Document No.	Release Date	N/R	Document Title/Description
SIL99-2C	2014-09-16		Sealants, Lubricants, and Adhesives Authorized By CMI
SIL05-3A	2014-04-10		Engine Specification Numbers
SIL93-11B	2013-07-17		Service Document Format
SIL98-9C	2013-07-17		Time Between Overhaul Periods. (TBO)
SB97-6B	2009-11-18		Mandatory Replacement Parts
SB96-11B	2008-07-10		Propeller Strikes and Hydraulic Locks
SIL06-2	2006-05-01		Unapproved Parts Notification No. 2004-00053
SB05-11	2005-12-08		Piper Service Bulletin 1157A
SIL99-2B	2005-10-20		Current Listing of Sealants, Lubricants & Adhesives Authorized By TCM
SB96-7C	2005-02-09		Torque Limits
SIL00-9A	2004-09-10		Engine Data Plates
SB03-3	2003-03-28		Differential Pressure Test and Borescope Inspection Procedures for Cylinders
SIL03-1	2003-01-28		Cold Weather Operation - Engine Preheating
SB00-12	2000-12-19		Service Publications for Rolls Royce Manufactured Engines
SIL99-1	1999-03-25		Engine Preservation for Active and Stored Aircraft
SB95-2	1995-04-21		Inspection and Maintenance of Engine Control Cables and Linkage
SIL93-15	1993-09-13		General Practices for Use of Lock Wire, Tab Washers and Cotter Pins
SIL93-14	1993-08-17		CFC Warning Statement
M89-18	1989-08-10		Exhaust Gas Temperature (E.G.T.) Recommendations for Standard Engines (Leaning Lean)
M89-7R1	1989-08-04		Engine Operation After Cylinder Replacement and/or Major Overhaul
M87-21	1987-10-07		Operation and Service



**Table 18. Hoses / Control Cables / Linkages**

Document No.	Release Date	N/R	Document Title/Description
SIL04-12A	2010-05-18		TCM Authorized Engine Adjustments, Component Replacement and Repositioning of Fitting Orientation
SB08-13	2008-10-14		Induction System Hose and Clamp Installation
SIL02-5	2002-04-04		Induction Hose Clamp
SIL95-5	1995-08-30		Hose and Tubing Installation
SB94-3A	1995-05-23		Induction System Hose and Clamp Replacement
SB95-2	1995-04-21		Inspection and Maintenance of Engine Control Cables and Linkage
M84-3	1984-01-18		Induction Manifold Hose Inspection
M81-23R1	1982-02-12		360 Series Oil Pump Drive Gear
M81-6R2	1982-01-29		Fuel Hoses
M81-18	1981-08-05		Air Reference Hoses

**Table 19. Ignition / Magnetos**

Document No.	Release Date	N/R	Document Title/Description
SB03-7A	2014-04-10		IO240 Series Magneto Drive Gear
SIL03-2C	2013-04-03		Currently Active Approved Spark Plug Application
SB12-3	2012-10-08		Champion Aerospace Slick SB1-12
MSB00-6D	2010-11-19		Slick Service Bulletin SB1-00C
SIL04-12A	2010-05-18		TCM Authorized Engine Adjustments, Component Replacement and Repositioning of Fitting Orientation
MSB94-8D	2010-02-17		Magneto to Engine Timing
SB08-8B	2009-04-10		Slick Service Bulletin SB2-08A
CSB08-9A	2008-10-14		Slick Service Bulletin 03-8A
SB05-11	2005-12-08		Piper Service Bulletin 1157A
SB05-9	2005-10-20		Slick Service Bulletin SB1-88B
CSB04-5A	2004-08-30		Teledyne Continental Motors Ignition Systems Critical Service Bulletin CSB665A
CSB02-8	2002-09-06		Teledyne Continental Motors Ignition System Critical Service Bulletin CSB664
SB02-7	2002-06-28		Teledyne Continental Motors Ignition System Service Bulletin SB663
SB02-3	2002-01-31		Magneto Tachometer Sensors
SB97-15	1997-12-05		TCM Ignition System Service Bulletin SB660
SIL657A	1997-10-09		Supersedure of P/N 10-163136 and 10-361638 Covers and of 10-361637 Cover Kit
SID96-6	1996-05-03		TCM Ignition Systems Service Bulletin SB653
CSB94-1	1994-02-01		Teledyne Continental Motors Ignition Systems Critical Service Bulletin 641
M93-10	1993-03-01		TCM Ignition Systems Service Bulletin No. 639
M90-9	1990-04-20		New TCM Magneto and Harness Applications
M87-16	1987-08-14		Slick Service Bulletin 1-86A
M84-13	1984-10-27		Slick Service Bulletin 1-84
M83-6	1983-03-07		Slick Service Bulletin 2-82
M83-5	1983-03-07		Slick Service Bulletin 3-82
M81-26	1981-12-04		Pressurization of Magnetos in Mooney M20K Aircraft



**Table 19. Ignition / Magnetos**

Document No.	Release Date	N/R	Document Title/Description
M81-13R1	1981-07-18		Slick Service Bulletin 1-81 (Revised)
M78-8	1978-08-25		Ignition System Maintenance
M74-18	1974-09-16		Compliance with Slick Bulletin 1-74
M70-11	1970-06-22		Slick Electro Bulletin 1-70

**Table 20. Induction / Air Intake**

Document No.	Release Date	N/R	Document Title/Description
SSI13-5 <sup>1</sup>	2013-10-18		Amplified Operation, Maintenance and Servicing Requirements for Cirrus SR-20 Aircraft operated by CAFUC Only
SID10-4	2010-07-21		Engine Maintenance for Volcanic Ash Contamination
SB08-13	2008-10-14		Induction System Hose and Clamp Installation
SIL00-11B	2004-05-24		Release of New Cylinder Induction Port Drain Connector
SIL02-5	2002-04-04		Induction Hose Clamp
SB98-8	1998-10-22		Number One and Three Cylinder Intake Tube Modifications
SB94-3A	1995-05-23		Induction System Hose and Clamp Replacement
CSB93-13	1993-08-12		Carburetor Air Intake Housing Assembly Inspection
M89-23	1989-09-25		TSIO520CE Lower Throttle Body Support Bracket and Linkage
M88-13	1988-09-26		Induction Tube Cracking
M86-5	1986-02-04		Manifold Pressure Line Adapter Improvement
M84-3	1984-01-18		Induction Manifold Hose Inspection
M80-11	1980-04-14		Intake Manifold Tube Drain Bosses
M78-16	1978-11-29		Number Two Cylinder Intake Elbow Tube, TCM Part No. 629138

**Table 21. Lubrication / Oils**

Document No.	Release Date	N/R	Document Title/Description
SIL99-2C	2014-09-16		Sealants, Lubricants, and Adhesives Authorized By CMI
SSI13-5 <sup>1</sup>	2013-10-18		Amplified Operation, Maintenance and Servicing Requirements for Cirrus SR-20 Aircraft operated by CAFUC Only
SB12-2	2012-08-09		Oil Filler Tube Inspection and Support Bracket Installation
SSI10-9A <sup>1</sup>	2011-01-13		Replacement of Oil Gauge Rod PN657474 and 658164 with New Oil Gauge Rod 658252
SIL10-6	2010-07-30		Oil Cooler and Vernatherm Control Valve for Certain Engines Experiencing Low Oil Temperatures
SID10-4	2010-07-21		Engine Maintenance for Volcanic Ash Contamination
SSI10-5 <sup>1</sup>	2010-07-02		0200D Oil Sump and Material Inspection
SIL09-15	2009-08-06		Oil Gage Rod 632062-3, 4 and 14
CSB07-2	2007-05-25		Turbocharger Wastegate Oil Inlet Fitting Inspection and Replacement
SIL99-2B	2005-10-20		Current Listing of Sealants, Lubricants & Adhesives Authorized By TCM
SB03-4	2003-07-21		Inspection of Oil Gauge Rod and Cap Assemblies, P/N 652171-22 and P/N 652171-27
SIL00-7A	2001-02-05		Oil Gauge Rod Application
SIL96-9	1996-08-12		Oil Pressure Relief Valve Spring
CSB96-5	1996-04-12		Oil Pump Drive Gears, P/N 649506 and 649681





**Table 21. Lubrication / Oils**

Document No.	Release Date	N/R	Document Title/Description
SB96-4	1996-04-12		Improved Oil Pump Gears and Suction Screens
CSB95-1A	1995-04-05		Inspection and Replacement of Dukes Incorporated Turbocharger Oil Outlet Check Valve Part Number 367-00, (TCM P/N 641068)
SB94-11	1994-11-14		Oil Pump Gasket P/N 643749
SIL94-5	1994-06-14		Mobil AV1 Oil
SB94-2	1994-02-10		Oil Filter Adapter Mounting Stud
M92-14	1992-09-09		New Modine Oil Coolers, P/N 635996, 646685, 649479 and 652759
M91-12	1991-12-11		New Oil Gauge Rod Housing
M91-10R1	1991-11-27		Inspection for Correct Oil Pick-Up Tube Installation
M90-10	1990-04-11		Standby Vacuum Pump Oil Leak Check/Inspection
M88-4	1988-01-15		TCM Pro-Tech Oil Filter
M87-17	1987-08-28		Improved Oil Pump Suction Tube Assembly
M86-20	1986-12-15		Air/Oil Separator Drain Modification
M81-28R1	1982-08-23		Oil Filters
M81-23R1	1982-02-12		360 Series Oil Pump Drive Gear
M81-10	1981-03-09		Replace Dipstick P/N 632062-2 with P/N 632062-29
M78-3	1978-01-11		Governor Oil Transfer Collar Sleeves, Retaining Clips and Clearances
M78-2	1978-01-10		Turbocharger Oil Supply Line and Fitting Change: TCM Service Kit EQ6536
M76-20	1976-07-19		Oil Filters
M76-5R1	1976-05-25		Remote Mounted Oil Coolers
M75-7R1	1975-04-04		Oil Filter Change
M67-5	1967-05-02		Lagging Engine Breather Line on GTSIO520 Engines

**Table 22. Miscellaneous**

Document No.	Release Date	N/R	Document Title/Description
CSB09-11A	2014-11-12	R	Minimum Cruise RPM
SID10-4	2010-07-21		Engine Maintenance for Volcanic Ash Contamination
SSI06-7A <sup>1</sup>	2007-02-13		IOF-240-B4B Engine Conversion
SB05-2	2005-02-09		Overspeed Limitations
SIL97-1	1997-01-03		Airworthiness Limitations
M90-4	1990-02-01		Conversion of Rolls Royce Engines
M88-9	1988-08-24		Lightning Strikes
M75-6R1	1975-06-04		Conversion of Engines From one Model to Another

**Table 23. Pistons**

Document No.	Release Date	N/R	Document Title/Description
SID97-4F	2014-08-13		Cylinder Bore and Pistons Fit Specifications
CSB04-6A	2009-03-04		Inspection of TSIO-550 and TSIOL-550 Engines with P/N 654867 Pistons Installed
SB07-1	2007-03-19		Connecting Rod Pistons Pin Bushing Installation
SB04-10	2004-10-28		Pistons Position Marking

**Table 23. Pistons**

Document No.	Release Date	N/R	Document Title/Description
CSB97-10A	1997-07-15		Pistons Pin Plug Wear
SB94-13	1994-11-14		Pistons Ring Set, Part Number 649226 and Cylinder Kit Part Numbers 653443A3, 653443A3BP, 653443A5, 653443A5BP, 653444A4, 653444A4BP, 653455A2 and 653455A2BP
M91-4	1991-02-11		Pistons Identification and Pistons Ring Application Bulletin
M87-26	1987-12-21		Pistons Pin Replacement and Thru Bolt torque Check
M87-25	1987-12-15		Pistons Pin Replacement and Thru Bolt torque Check
M72-17R1	1973-10-05		New Maximum Weight Difference Allowance between Connecting Rods and Pistons in the Same Engine

**Table 24. Starters / Starter Adapters**

Document No.	Release Date	N/R	Document Title/Description
SB14-2	2014-09-16		Inspection and Replacement of IO240 Starter and Crankshaft Cluster Gear
MSB11-4B	2012-04-04		Starter Adapter Inspection
MSB94-4G	2005-11-01		Starter Adapter Shaftgear and Crankshaft Gear Inspection
CSB02-2C	2002-12-11		Starter Adapter Shaft Seal Inspection
SIL02-4	2002-04-02		Production Release of New Light Weight Starter Motors
SB01-5	2001-10-18		Starter Adapter Bevel Gear Inspection
SIL97-12	1997-10-14		Installation of Starter Adapter Shaft Seal and Associated Parts
CSB96-1	1996-03-01		Starter Gear and Clutch Assembly P/N 653575
M92-10	1992-08-14		Starter Adapter
M89-6	1989-03-10		Compressor Belt Sheave Alignment and Belt Tensioning
M88-5	1988-04-04		Starter Adapter Shafts (Reference Service Bulletin M87-24)
M87-24	1987-12-15		Broken Starter Adapter Shafts
M80-25	1980-10-24		Installation Instructions for Air Conditioning Kits
M80-14	1980-04-28		Freon Compressor Bracket
M79-15	1979-09-04		Freon Compressor Bracket Alignment
M79-12	1979-08-01		Starter Adapter Sheave
M71-20	1971-08-20		Installation Instructions for the Compressor Sheave to the Starter Adapter (637778)
M70-7	1970-03-17		Increasing Size of Oil Feed Holes to Starter Adapter Shaftgear



**Table 25. Turbocharging / Exhaust Systems**

Document No.	Release Date	N/R	Document Title/Description
MSB14-3	2014-05-02		Hartzell Engine Technologies (HET) Alert Service Bulletin (ASB) No. 057
MSB13-7	2014-01-15		Hartzell Engine Technologies Service Bulletin (ASB) 048-Rev1
SB10-8A	2011-01-12		Hartzell Engine Technologies Service Bulletin 040A - Turbocharger CHRA Contamination
MSB10-3	2010-05-18		Kelly Aerospace Service Bulletin 039-A
SB10-1	2010-01-28		Exhaust and Turbocharger System Inspection
MSB08-5	2008-06-23		Kelly Aerospace Turbocharger Bulletin 030
MSB07-4	2007-07-26		Kelly Aerospace Power Systems Turbocharger Replacement
CSB07-2	2007-05-25		Turbocharger Wastegate Oil Inlet Fitting Inspection and Replacement
SIL02-6A	2002-10-25		Production Release of Optional Intake and Exhaust Valves
SIL99-4	1999-05-19		TSIO520UB Exhaust Tail Pipe
SIL98-3A	1998-06-12		Production Release of New Intake and Exhaust Valve Springs
SB98-4	1998-06-12		Exhaust System Inspection
CSB98-1B	1998-06-01		Intake and Exhaust Valve Inspection
M90-13	1990-07-16		Exhaust Valve Stem Corrosion/Erosion
M90-8	1990-03-22		Exhaust System Inspection
M90-6	1990-02-26		Inspection and Replacement of Scavenge Pump Gears P/N 635334 and 639388
M89-18	1989-08-10		Exhaust Gas Temperature (E.G.T.) Recommendations for Standard Engines (Leaning Lean)
M87-14R1	1987-10-08		Turbocharger Check Valve Clamps
M87-8	1987-02-26		Exhaust Valve Inspection
M85-6	1985-04-25		Garrett Service Letter TP61-0001, Rev. E
M85-3	1985-02-04		Exhaust Valves In P/N 646680 Cylinder Assemblies
M84-7	1984-04-18		643797 Turbo Inlet Check Valve
M81-4R1	1983-04-29		Aid Service Bulletin TP60-0120 - Aid Service Letter Tp61-0046
M83-3	1983-02-14		Roto Master (Rajay) Service Letter 27 Revision A dated September 24, 1982 and Addendum Thereto dated February 9, 1983 In Response to FAA AD 82-07-03
M82-7	1982-05-13		Tube Assembly (Air Reference Tube)
M81-25	1981-11-30		Exhaust Flange to Cylinder Installation Procedures
M81-18	1981-08-05		Air Reference Hoses
M81-19	1981-08-05		Availability of New TCM P/N 646220 and 646019 Flexible Elbows
M81-17	1981-07-27		By-Pass Valve Codification - Airesearch Service Letter TP61-0039
M81-16	1981-07-27		Turbocharger Center Housings
M81-10	1981-03-09		Replace Dipstick P/N 632062-2 with P/N 632062-29
M81-9	1981-03-09		Nose Seal Retainer Plates
M80-24	1980-09-18		Exhaust Tailpipe Modification
M80-10	1980-03-28		Replacement of Some P/N 642232 Flexible Elbows
M78-5R3	1978-10-23		Flexible Elbow TCM Part Number 635930
M78-6	1978-03-03		Removal and Re-Installation of Special Rosan Exhaust Port Studs
M78-2	1978-01-10		Turbocharger Oil Supply Line and Fitting Change: TCM Service Kit EQ6536
M77-19	1977-08-12		Intake and Exhaust Rocker Arm Identification and Application

**Table 25. Turbocharging / Exhaust Systems**

<b>Document No.</b>	<b>Release Date</b>	<b>N/R</b>	<b>Document Title/Description</b>
M76-22	1976-08-30		Compliance with Rajay Bulletin #21A
M72-8	1972-06-21		New Design Splined Drive Scavenge Pump Shaft and Gear Assembly
M71-21	1971-11-22		Procedure for Freeing Turbocharger Turbine Shafts Which Are Dragging or Frozen By Rust Deposits
M64-18	1968-10-07		Field Conversion to Turbocharging of Continental Aircraft Engines
M67-12	1967-05-31		Overboost of Turbocharged Engines



**VI. SERVICE DOCUMENTS, *listed by engine model***

<b>Engine Model (released documents)</b>	<b>Page</b>
A65 (70 Documents Released) .....	22
C75/C85 (77 Documents Released) .....	23
C90 (78 Documents Released) .....	24
O200 (91 Documents Released) .....	25
O240 (34 Documents Released) .....	25
IO240 (84 Documents Released) .....	26
IOF240 (59 Documents Released) .....	26
E185 (74 Documents Released) .....	27
E225 (73 Documents Released) .....	28
O300 (86 Documents Released) .....	29
GO300 (72 Documents Released) .....	30
IO346 (82 Documents Released) .....	31
IO360 (105 Documents Released) .....	32
L&TSIO360 (132 Documents Released) .....	33
O470 (118 Documents Released) .....	34
IO470 (116 Documents Released) .....	35
TSIO470 (100 Documents Released) .....	36
IO520 (147 Documents Released) .....	37
GTSIO520 (125 Documents Released) .....	38
L&TSIO520 (195 Documents Released) .....	39
IO550 (134 Documents Released) .....	41
IOF550 (81 Documents Released) .....	42
TSIO550 (119 Documents Released) .....	43
TSIOF550 (69 Documents Released) .....	44
TSIOL550 (108 Documents Released) .....	45
TIARA (61 Documents Released) .....	46

**A65 (70 Documents Released)**

Document No.	Release Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
CSB08-3C	2013-07-17
SIL98-9C	2013-07-17
SIL93-11B	2013-07-17
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB07-1	2007-03-19
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10

Document No.	Release Date
CSB04-5A	2004-08-30
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
CSB02-8	2002-09-06
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
M81-8R1	2001-02-05
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
SB97-15	1997-12-05
SIL97-1	1997-01-03
SB96-12	1996-09-10
SID96-6	1996-05-03
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
M93-10	1993-03-01
M92-5	1992-02-28
M91-4	1991-02-11

Document No.	Release Date
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-9	1988-08-24
M88-10	1988-08-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-25	1981-11-30
M81-13R1	1981-07-18
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M74-16	1974-06-17
M72-17R1	1973-10-05
M73-13	1973-07-10
M73-12	1973-06-08
M70-11	1970-06-22
M64-18	1968-10-07



**C75/C85 (77 Documents Released)**

Document No.	Release Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB07-1	2007-03-19
SB95-3B	2005-10-25
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30

Document No.	Release Date
SIL04-2	2004-03-30
SB03-5	2003-11-06
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
M81-8R1	2001-02-05
SIL00-7A	2001-02-05
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SIL97-1	1997-01-03
SB96-12	1996-09-10
SID96-6	1996-05-03
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
CSB93-13	1993-08-12
M93-10	1993-03-01
M92-8	1992-05-29
M92-5	1992-02-28

Document No.	Release Date
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-10	1988-08-24
M88-9	1988-08-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-25	1981-11-30
M81-13R1	1981-07-18
M77-19	1977-08-12
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-8	1976-04-13
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M74-16	1974-06-17
M72-17R1	1973-10-05
M73-13	1973-07-10
M73-12	1973-06-08
M70-11	1970-06-22
M64-18	1968-10-07



**C90 (78 Documents Released)**

Document No.	Release Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
SIL98-9C	2013-07-17
SIL93-11B	2013-07-17
CSB08-3C	2013-07-17
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB95-3B	2005-10-25
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SIL04-2	2004-03-30

Document No.	Release Date
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
M81-8R1	2001-02-05
SIL00-7A	2001-02-05
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SIL97-1	1997-01-03
SB96-12	1996-09-10
SID96-6	1996-05-03
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
CSB93-13	1993-08-12
M93-10	1993-03-01
M92-8	1992-05-29
M92-5	1992-02-28
M91-4	1991-02-11

Document No.	Release Date
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-10	1988-08-24
M88-9	1988-08-24
M87-16	1987-08-14
M87-15	1987-07-13
M86-9	1986-03-20
M83-5	1983-03-07
M81-25	1981-11-30
M81-13R1	1981-07-18
M77-19	1977-08-12
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-8	1976-04-13
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M74-16	1974-06-17
M72-17R1	1973-10-05
M73-13	1973-07-10
M73-12	1973-06-08
M70-11	1970-06-22
M64-18	1968-10-07





**O200 (91 Documents Released)**

Document No.	Release Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
SIL05-3A	2014-04-10
SIL13-2A	2014-01-15
CSB08-3C	2013-07-17
SIL98-9C	2013-07-17
SIL93-11B	2013-07-17
SIL03-2C	2013-04-03
SB12-2	2012-08-09
SSI10-9A	2011-01-13
SID10-4	2010-07-21
SSI10-5	2010-07-02
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB08-1	2008-02-18
SB95-3B	2005-10-25
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30

Document No.	Release Date
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-5	2003-11-06
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
M81-8R1	2001-02-05
SIL00-7A	2001-02-05
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SIL97-1	1997-01-03
SB96-12	1996-09-10
SID96-6	1996-05-03
CSB96-1	1996-03-01
SIL95-5	1995-08-30
SB95-2	1995-04-21
SID94-12	1994-11-14
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
CSB93-13	1993-08-12
MSB93-12	1993-05-12
M93-10	1993-03-01
M92-8	1992-05-29
M92-5	1992-02-28

Document No.	Release Date
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M90-9	1990-04-20
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-10	1988-08-24
M88-9	1988-08-24
M87-16	1987-08-14
M87-15	1987-07-13
M86-9	1986-03-20
M83-5	1983-03-07
M81-25	1981-11-30
M81-13R1	1981-07-18
M77-19	1977-08-12
M77-3	1977-01-11
M76-15	1976-06-17
M76-5R1	1976-05-25
M76-8	1976-04-13
M76-4	1976-03-12
M75-15	1975-07-14
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M73-13	1973-07-10
M73-12	1973-06-08
M70-11	1970-06-22
M64-18	1968-10-07

**O240 (34 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SID05-1A	2014-05-02
SIL05-3A	2014-04-10
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SB09-6A	2009-06-22

Document No.	Released Date
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB05-9	2005-10-20
SB05-2	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SIL04-2	2004-03-30
SB03-3	2003-03-28

Document No.	Released Date
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
SIL00-7A	2001-02-05
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
SIL94-5	1994-06-14
M90-13	1990-07-16



**IO240 (84 Documents Released)**

Document No.	Released Date
SB14-2	2014-09-16
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
CSB14-1	2014-06-23
SB99-8A	2014-04-10
SIL05-3A	2014-04-10
SB03-7A	2014-04-10
SIL13-2A	2014-01-15
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB08-4	2008-03-14
SB07-1	2007-03-19
SIL05-6A	2005-11-01
SIL05-4A	2005-11-01
SB95-3B	2005-10-25
SB05-9	2005-10-20
SIL05-5	2005-02-28

Document No.	Released Date
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SIL04-9	2004-07-23
SB04-4A	2004-06-21
SIL00-11B	2004-05-24
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
CSB98-1B	1998-06-01
SB97-15	1997-12-05
CSB97-10A	1997-07-15
SIL97-1	1997-01-03
SB96-12	1996-09-10
SID96-6	1996-05-03
CSB96-1	1996-03-01

Document No.	Released Date
SB95-7	1995-12-08
SIL95-5	1995-08-30
CSB95-4	1995-08-10
SB95-2	1995-04-21
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-9	1988-08-24
M88-10	1988-08-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-25	1981-11-30
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M70-11	1970-06-22
M64-18	1968-10-07

**IOF240 (59 Documents Released)**

Document No.	Released Date
SSI06-6A	2014-12-17
SIL99-2C	2014-09-16
SB14-2	2014-09-16
SID97-4F	2014-08-13
CSB14-1	2014-06-23
SID05-1A	2014-05-02
SIL05-3A	2014-04-10
SB99-8A	2014-04-10
SB13-8	2014-01-22
SIL13-2A	2014-01-15
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL03-2C	2013-04-03
CSB12-1	2012-05-11
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16

Document No.	Released Date
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB08-4	2008-03-14
SSI07-6	2007-08-31
SB07-1	2007-03-19
SSI06-7A	2007-02-13
SSI06-6	2006-09-22
SB95-3B	2005-10-25
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
SIL00-11B	2004-05-24
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
SB00-4A	2000-03-07
SB00-1	2000-01-14

Document No.	Released Date
SIL99-1	1999-03-25
SIL97-1	1997-01-03
SB96-12	1996-09-10
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-5	1994-06-14
SIL93-15	1993-09-13
M90-17	1990-08-23
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-9	1988-08-24
M88-10	1988-08-24
M87-15	1987-07-13
M81-25	1981-11-30
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M72-17R1	1973-10-05
M64-18	1968-10-07



**E185 (74 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SID05-1A	2014-05-02
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB06-5	2006-05-25
SIL06-2	2006-05-01
SB95-3B	2005-10-25
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30

Document No.	Released Date
SB03-3	2003-03-28
SIL03-1	2003-01-28
SB02-9	2002-10-25
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
SIL00-7A	2001-02-05
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
SIL98-3A	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
CSB97-10A	1997-07-15
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SID96-6	1996-05-03
SIL95-5	1995-08-30
SB95-2	1995-04-21
SB94-13	1994-11-14
SIL94-10	1994-11-14
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17

Document No.	Released Date
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-9	1988-08-24
M88-10	1988-08-24
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-25	1981-11-30
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M74-16	1974-06-17
M72-17R1	1973-10-05
M73-12	1973-06-08
M64-18	1968-10-07



**E225 (73 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SID05-1A	2014-05-02
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB06-5	2006-05-25
SIL06-2	2006-05-01
SB95-3B	2005-10-25
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30

Document No.	Released Date
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
SB02-9	2002-10-25
CSB02-8	2002-09-06
SIL00-7A	2001-02-05
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
SIL98-3A	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
CSB97-10A	1997-07-15
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SID96-6	1996-05-03
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-10	1994-11-14
SB94-13	1994-11-14
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17

Document No.	Released Date
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-10	1988-08-24
M88-9	1988-08-24
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-25	1981-11-30
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M73-12	1973-06-08
M64-18	1968-10-07



**O300 (86 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
SIL05-3A	2014-04-10
SIL13-2A	2014-01-15
SIL93-11B	2013-07-17
CSB08-3C	2013-07-17
SIL98-9C	2013-07-17
SIL03-2C	2013-04-03
MSB00-6D	2010-11-19
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-13	2008-10-14
MSB96-10A	2008-10-14
SB96-11B	2008-07-10
SB08-1	2008-02-18
SB07-1	2007-03-19
SB06-5	2006-05-25
SB95-3B	2005-10-25
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09
SB00-3A	2004-11-12

Document No.	Released Date
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
SIL00-7A	2001-02-05
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SIL97-1	1997-01-03
SB96-12	1996-09-10
SID96-6	1996-05-03
CSB96-5	1996-04-12
SB96-4	1996-04-12
CSB96-1	1996-03-01
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12

Document No.	Released Date
M93-10	1993-03-01
M92-10	1992-08-14
M92-8	1992-05-29
M92-5	1992-02-28
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M90-9	1990-04-20
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-10	1988-08-24
M88-9	1988-08-24
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-25	1981-11-30
M77-19	1977-08-12
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-8	1976-04-13
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M73-13	1973-07-10
M73-12	1973-06-08
M64-18	1968-10-07



**GO300 (72 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
SIL05-3A	2014-04-10
SIL93-11B	2013-07-17
CSB08-3C	2013-07-17
SIL98-9C	2013-07-17
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB96-11B	2008-07-10
SB08-1	2008-02-18
SB07-1	2007-03-19
SB95-3B	2005-10-25
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12

Document No.	Released Date
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
CSB02-8	2002-09-06
SIL00-7A	2001-02-05
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SIL97-1	1997-01-03
SB96-12	1996-09-10
SID96-6	1996-05-03
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
M93-10	1993-03-01

Document No.	Released Date
M92-8	1992-05-29
M92-5	1992-02-28
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-10	1988-08-24
M88-9	1988-08-24
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-25	1981-11-30
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-8	1976-04-13
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M73-13	1973-07-10
M73-12	1973-06-08
M64-18	1968-10-07



**IO346 (82 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
SB00-2A	2014-05-02
SIL05-3A	2014-04-10
SB99-8A	2014-04-10
SIL13-2A	2014-01-15
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL98-9C	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB08-4	2008-03-14
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10

Document No.	Released Date
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
CSB98-1B	1998-06-01
SB97-15	1997-12-05
CSB97-10A	1997-07-15
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SID96-6	1996-05-03
SB95-7	1995-12-08
MSB95-6	1995-10-19
SIL95-5	1995-08-30
SB95-2	1995-04-21
MSB94-9	1994-10-21
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01

Document No.	Released Date
SIL93-15	1993-09-13
SIL93-14	1993-08-17
M93-10	1993-03-01
M93-8	1993-02-19
M92-9	1992-05-29
M92-7	1992-05-26
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-9	1988-08-24
M88-10	1988-08-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-25	1981-11-30
M77-9	1977-03-17
M77-3	1977-01-11
M76-20	1976-07-19
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M64-18	1968-10-07



**IO360 (105 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
CSB14-1	2014-06-23
SID05-1A	2014-05-02
SB99-8A	2014-04-10
SIL05-3A	2014-04-10
SB13-4B	2014-01-15
SSI13-5	2013-10-18
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
MSB00-6D	2010-11-19
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB08-13	2008-10-14
MSB96-10A	2008-10-14
SB96-11B	2008-07-10
SB08-4	2008-03-14
SB07-1	2007-03-19
SB06-5	2006-05-25
SB95-3B	2005-10-25
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SIL00-11B	2004-05-24

Document No.	Released Date
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
SB02-7	2002-06-28
SB01-5	2001-10-18
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-12	2000-12-19
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
SB98-8	1998-10-22
CSB98-1B	1998-06-01
SB97-15	1997-12-05
CSB97-10A	1997-07-15
SIL97-1	1997-01-03
CSB96-13	1996-11-14
SB96-12	1996-09-10
CSB96-8	1996-06-25
SID96-6	1996-05-03
SB96-4	1996-04-12
CSB96-5	1996-04-12
SB95-7	1995-12-08
SIL95-5	1995-08-30
CSB95-4	1995-08-10
SB95-2	1995-04-21
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-15	1993-09-13

Document No.	Released Date
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M92-10	1992-08-14
M92-7	1992-05-26
M92-4R1	1992-02-05
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-10	1988-08-24
M88-9	1988-08-24
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M87-8	1987-02-26
M83-5	1983-03-07
M81-23R1	1982-02-12
M81-25	1981-11-30
M81-13R1	1981-07-18
M80-18	1980-09-02
M77-9	1977-03-17
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M75-7R1	1975-04-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M64-18	1968-10-07



**L&TSIO360 (132 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
CSB14-1	2014-06-23
SID05-1A	2014-05-02
SIL05-3A	2014-04-10
SB99-8A	2014-04-10
MSB13-7	2014-01-15
SIL13-2A	2014-01-15
SB13-4B	2014-01-15
SIL93-11B	2013-07-17
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
SB10-8A	2011-01-12
MSB00-6D	2010-11-19
SID10-4	2010-07-21
MSB10-3	2010-05-18
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB08-13	2008-10-14
MSB96-10A	2008-10-14
MSB08-2B	2008-09-17
SB96-11B	2008-07-10
SB02-10A	2008-06-23
SB08-4	2008-03-14
CSB07-2	2007-05-25
SB07-1	2007-03-19
SB06-5	2006-05-25
SB06-1A	2006-04-28
SB05-11	2005-12-08
SB95-3B	2005-10-25
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30

Document No.	Released Date
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
SB02-7	2002-06-28
MSB00-5D	2001-10-17
SIL01-4	2001-09-04
SIL01-2B	2001-09-04
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
SB98-8	1998-10-22
SB98-4	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SB97-11	1997-08-10
CSB97-10A	1997-07-15
SIL97-1	1997-01-03
CSB96-13	1996-11-14
SB96-12	1996-09-10
CSB96-8	1996-06-25
SID96-6	1996-05-03
SB96-4	1996-04-12
CSB96-5	1996-04-12
SB95-7	1995-12-08
SIL95-5	1995-08-30
CSB95-4	1995-08-10
SB95-2	1995-04-21
CSB95-1A	1995-04-05
SIL94-10	1994-11-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M92-10	1992-08-14

Document No.	Released Date
M92-7	1992-05-26
M92-4R1	1992-02-05
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M90-4	1990-02-01
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-13	1988-09-26
M88-10	1988-08-24
M88-9	1988-08-24
M88-4	1988-01-15
M87-23	1987-11-24
M87-14R1	1987-10-08
M87-16	1987-08-14
M87-15	1987-07-13
M87-8	1987-02-26
M83-6	1983-03-07
M83-5	1983-03-07
M83-3	1983-02-14
M82-7	1982-05-13
M81-23R1	1982-02-12
M81-26	1981-12-04
M81-25	1981-11-30
M81-16	1981-07-27
M81-13R1	1981-07-18
M80-24	1980-09-18
M80-18	1980-09-02
M79-15	1979-09-04
M78-8	1978-08-25
M78-2	1978-01-10
M77-9	1977-03-17
M77-3	1977-01-11
M76-22	1976-08-30
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M75-7R1	1975-04-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M71-21	1971-11-22
M64-18	1968-10-07



**O470 (118 Documents Released)**

Document No.	Released Date
CSB09-11A	2014-11-12
SIL99-2C	2014-09-16
SIL14-6	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
SIL05-3A	2014-04-10
SIL13-2A	2014-01-15
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL98-9C	2013-07-17
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
MSB09-1B	2009-08-18
SIL09-15	2009-08-06
SB09-7	2009-07-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
MSB96-10A	2008-10-14
SB08-13	2008-10-14
SB08-12	2008-09-09
SB96-11B	2008-07-10
SB08-4	2008-03-14
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SIL06-2	2006-05-01
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19

Document No.	Released Date
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
SB02-9	2002-10-25
CSB02-8	2002-09-06
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-1	1999-03-25
SIL98-3A	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SB97-11	1997-08-10
CSB97-10A	1997-07-15
SID97-7	1997-05-07
SB97-5	1997-03-31
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SID96-6	1996-05-03
SIL95-5	1995-08-30
SB95-2	1995-04-21
CSB94-15	1994-12-02
SB94-13	1994-11-14
SB94-11	1994-11-14
SIL94-10	1994-11-14
SB94-7	1994-09-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M92-10	1992-08-14

Document No.	Released Date
M92-9	1992-05-29
M92-7	1992-05-26
M92-6	1992-02-28
M92-5	1992-02-28
M91-10R1	1991-11-27
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M90-9	1990-04-20
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-15	1988-10-10
M88-10	1988-08-24
M88-9	1988-08-24
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M85-3	1985-02-04
M83-5	1983-03-07
M83-6	1983-03-07
M81-25	1981-11-30
M81-12	1981-05-11
M81-10	1981-03-09
M81-9	1981-03-09
M78-9	1978-08-23
M78-3	1978-01-11
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M73-6R1	1973-06-11
M73-12	1973-06-08
M70-7	1970-03-17
M64-18	1968-10-07



**IO470 (116 Documents Released)**

Document No.	Released Date
SIL14-6	2014-09-16
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
SIL05-3A	2014-04-10
SB99-8A	2014-04-10
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
CSB09-11	2009-09-25
MSB09-1B	2009-08-18
SIL09-15	2009-08-06
SB09-7	2009-07-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-13	2008-10-14
MSB96-10A	2008-10-14
SB08-12	2008-09-09
SB96-11B	2008-07-10
SB08-4	2008-03-14
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-2	2006-05-01
SIL06-3	2006-05-01
SIL99-2B	2005-10-20
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19

Document No.	Released Date
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
SB02-9	2002-10-25
CSB02-8	2002-09-06
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-1	1999-03-25
SIL98-3A	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SB97-11	1997-08-10
CSB97-10A	1997-07-15
SID97-7	1997-05-07
SB97-5	1997-03-31
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SID96-6	1996-05-03
SIL95-5	1995-08-30
SB95-2	1995-04-21
CSB94-15	1994-12-02
SB94-13	1994-11-14
SB94-11	1994-11-14
SIL94-10	1994-11-14
SB94-7	1994-09-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M92-10	1992-08-14
M92-9	1992-05-29

Document No.	Released Date
M92-7	1992-05-26
M92-6	1992-02-28
M92-5	1992-02-28
M91-10R1	1991-11-27
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M90-9	1990-04-20
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-15	1988-10-10
M88-10	1988-08-24
M88-9	1988-08-24
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M85-9R1	1985-08-06
M85-3	1985-02-04
M84-8	1984-06-19
M83-6	1983-03-07
M83-5	1983-03-07
M81-25	1981-11-30
M81-12	1981-05-11
M81-9	1981-03-09
M81-10	1981-03-09
M78-9	1978-08-23
M78-3	1978-01-11
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M73-6R1	1973-06-11
M73-12	1973-06-08
M71-14	1971-06-21
M70-7	1970-03-17
M64-18	1968-10-07



**TSIO470 (100 Documents Released)**

Document No.	Released Date
CSB09-11A	2014-11-12
SIL99-2C	2014-09-16
SIL14-6	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
SB99-8A	2014-04-10
SIL05-3A	2014-04-10
SIL93-11B	2013-07-17
SIL98-9C	2013-07-17
CSB08-3C	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
MSB09-1B	2009-08-18
SB09-7	2009-07-16
SB08-13	2008-10-14
MSB96-10A	2008-10-14
SB08-12	2008-09-09
SB96-11B	2008-07-10
SB08-4	2008-03-14
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10

Document No.	Released Date
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-1	1999-03-25
SIL98-3A	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SB97-11	1997-08-10
CSB97-10A	1997-07-15
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SIL96-9	1996-08-12
SID96-6	1996-05-03
SB95-7	1995-12-08
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-10	1994-11-14
SB94-13	1994-11-14
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17

Document No.	Released Date
M93-10	1993-03-01
M93-4	1993-02-12
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-10	1988-08-24
M88-9	1988-08-24
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-6R2	1982-01-29
M81-25	1981-11-30
M81-16	1981-07-27
M78-9	1978-08-23
M78-3	1978-01-11
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M73-2	1973-01-17
M71-21	1971-11-22
M64-18	1968-10-07
M67-12	1967-05-31

**IO520 (147 Documents Released)**

Document No.	Released Date
CSB09-11A	2014-11-12
SIL14-6	2014-09-16
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SB14-5	2014-06-19
SID05-1A	2014-05-02
SB13-6A	2014-04-10
SIL05-3A	2014-04-10
SB99-8A	2014-04-10
SIL13-2A	2014-01-15
CSB08-3C	2013-07-17
SIL98-9C	2013-07-17
SIL93-11B	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
CSB12-1	2012-05-11
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
MSB09-1B	2009-08-18
SIL09-15	2009-08-06
SB05-8A	2009-07-16
SB09-7	2009-07-16
SB09-4A	2009-06-10
SB08-13	2008-10-14
MSB96-10A	2008-10-14
SB08-12	2008-09-09
SB96-11B	2008-07-10
SB08-4	2008-03-14
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19

Document No.	Released Date
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
CSB02-2C	2002-12-11
SB01-3A	2002-12-10
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-1	1999-03-25
SIL98-5	1998-06-12
SIL98-3A	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SIL97-12	1997-10-14
SB97-11	1997-08-10
CSB97-10A	1997-07-15
SID97-8	1997-05-28
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
CSB96-8	1996-06-25
SID96-6	1996-05-03
SB95-7	1995-12-08
MSB95-6	1995-10-19
SIL95-5	1995-08-30
SB95-2	1995-04-21
CSB94-15	1994-12-02
SB94-11	1994-11-14
SIL94-10	1994-11-14
MSB94-9	1994-10-21
SB94-7	1994-09-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12

Document No.	Released Date
M93-10	1993-03-01
M93-5	1993-02-19
M93-8	1993-02-19
M93-4	1993-02-12
M92-14	1992-09-09
M92-12	1992-08-27
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M92-6	1992-02-28
M91-10R1	1991-11-27
M91-6	1991-03-20
M91-7	1991-03-20
M91-4	1991-02-11
M90-17	1990-08-23
M90-16	1990-08-22
M90-13	1990-07-16
M90-9	1990-04-20
M89-19	1989-09-18
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M89-6	1989-03-10
M88-10	1988-08-24
M88-9	1988-08-24
M88-5	1988-04-04
M88-4	1988-01-15
M87-24	1987-12-15
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M86-13R1	1986-10-17
M86-14	1986-10-01
M85-10	1985-07-18
M84-5	1984-02-13
M81-15R1	1983-06-16
M83-6	1983-03-07
M83-5	1983-03-07
M81-25	1981-11-30
M81-13R1	1981-07-18
M81-12	1981-05-11
M81-9	1981-03-09
M80-25	1980-10-24
M80-14	1980-04-28



**GTSIO520 (125 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SID05-1A	2014-05-02
MSB14-3	2014-05-02
SIL05-3A	2014-04-10
SB99-8A	2014-04-10
SB13-4B	2014-01-15
SIL13-2A	2014-01-15
SIL98-9C	2013-07-17
SIL93-11B	2013-07-17
CSB08-3C	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
CSB13-1A	2013-03-18
SB11-3	2011-03-18
SB10-8A	2011-01-12
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB09-7	2009-07-16
SB08-13	2008-10-14
SB96-11B	2008-07-10
MSB08-5	2008-06-23
SB08-4	2008-03-14
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB06-1A	2006-04-28
MSB94-4G	2005-11-01
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28

Document No.	Released Date
SB01-3A	2002-12-10
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
CSB99-6A	1999-07-21
SIL99-1	1999-03-25
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SB97-11	1997-08-10
CSB97-10A	1997-07-15
CSB97-9	1997-05-28
SID97-8	1997-05-28
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SID96-6	1996-05-03
CSB96-2	1996-03-21
SB95-7	1995-12-08
SIL95-5	1995-08-30
SB95-2	1995-04-21
CSB94-15	1994-12-02
SIL94-10	1994-11-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M92-14	1992-09-09
M92-12	1992-08-27
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M91-7	1991-03-20
M91-6	1991-03-20

Document No.	Released Date
M91-4	1991-02-11
M90-20	1990-12-20
M90-17	1990-08-23
M90-16	1990-08-22
M90-15	1990-08-21
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-10	1988-08-24
M88-9	1988-08-24
M88-4	1988-01-15
M87-23	1987-11-24
M87-15	1987-07-13
M87-6	1987-02-16
M85-10	1985-07-18
M84-5	1984-02-13
M81-15R1	1983-06-16
M81-4R1	1983-04-29
M82-3	1982-03-08
M81-6R2	1982-01-29
M81-25	1981-11-30
M81-16	1981-07-27
M80-9R1	1980-06-30
M78-6	1978-03-03
M77-9	1977-03-17
M77-3	1977-01-11
M76-5R1	1976-05-25
M76-12	1976-05-24
M76-7	1976-03-25
M76-4	1976-03-12
M75-30	1975-12-19
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M71-21	1971-11-22
M71-20	1971-08-20
M70-3	1970-02-03
M64-18	1968-10-07
M67-12	1967-05-31
M67-5	1967-05-02

**L&TSIO520 (195 Documents Released)**

Document No.	Released Date
CSB09-11A	2014-11-12
SIL14-6	2014-09-16
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SB14-5	2014-06-19
MSB14-3	2014-05-02
SID05-1A	2014-05-02
SB99-8A	2014-04-10
SB13-6A	2014-04-10
SIL05-3A	2014-04-10
SIL13-2A	2014-01-15
SB13-4B	2014-01-15
CSB08-3C	2013-07-17
SIL98-9C	2013-07-17
SIL93-11B	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
CSB13-1A	2013-03-18
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB11-3	2011-03-18
SB10-8A	2011-01-12
SID10-4	2010-07-21
MSB10-3	2010-05-18
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB10-1	2010-01-28
SB97-6B	2009-11-18
SB09-14	2009-10-16
MSB09-1B	2009-08-18
SIL09-15	2009-08-06
SB05-8A	2009-07-16
SB09-7	2009-07-16
SB09-4A	2009-06-10
SB08-13	2008-10-14
MSB96-10A	2008-10-14
SB08-12	2008-09-09
SB96-11B	2008-07-10
MSB08-5	2008-06-23
SB08-4	2008-03-14
SSI07-5	2007-08-22
MSB07-4	2007-07-26
SB07-1	2007-03-19

Document No.	Released Date
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB06-1A	2006-04-28
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
CSB02-2C	2002-12-11
SB01-3A	2002-12-10
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-4	1999-05-19
SIL99-1	1999-03-25
SIL98-5	1998-06-12
SIL98-3A	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SB97-13	1997-10-30
SIL97-12	1997-10-14
SB97-11	1997-08-10
CSB97-10A	1997-07-15
SID97-8	1997-05-28
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SIL96-9	1996-08-12
CSB96-8	1996-06-25
SID96-6	1996-05-03
SB95-7	1995-12-08

Document No.	Released Date
MSB95-6	1995-10-19
SIL95-5	1995-08-30
SB94-3A	1995-05-23
SB95-2	1995-04-21
CSB94-15	1994-12-02
SB94-11	1994-11-14
SIL94-10	1994-11-14
SB94-7	1994-09-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-5	1993-02-19
M93-4	1993-02-12
M92-14	1992-09-09
M92-12	1992-08-27
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M92-6	1992-02-28
M91-12	1991-12-11
M91-10R1	1991-11-27
M91-7	1991-03-20
M91-6	1991-03-20
M91-4	1991-02-11
M90-19	1990-10-16
M90-17	1990-08-23
M90-16	1990-08-22
M90-15	1990-08-21
M90-13	1990-07-16
M90-9	1990-04-20
M90-10	1990-04-11
M90-8	1990-03-22
M90-6	1990-02-26
M89-23	1989-09-25
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-14	1989-06-29
M89-9	1989-04-21



**L&TSIO520 (201 Documents Released), continued**

Document No.	Released Date
M87-15	1987-07-13
M86-20	1986-12-15
M86-13R1	1986-10-17
M86-14	1986-10-01
M86-5	1986-02-04
M86-4	1986-01-09
M85-14	1985-09-23
M85-9R1	1985-08-06
M85-10	1985-07-18
M85-6	1985-04-25
M84-13	1984-10-27
M84-8	1984-06-19
M84-7	1984-04-18
M84-5	1984-02-13
M84-3	1984-01-18
M83-8R1	1983-07-15
M81-15R1	1983-06-16
M81-4R1	1983-04-29
M83-6	1983-03-07
M83-5	1983-03-07

Document No.	Released Date
M82-13	1982-10-27
M81-28R1	1982-08-23
M82-5	1982-04-26
M81-6R2	1982-01-29
M81-25	1981-11-30
M81-18	1981-08-05
M81-19	1981-08-05
M81-17	1981-07-27
M81-16	1981-07-27
M81-13R1	1981-07-18
M81-12	1981-05-11
M81-9	1981-03-09
M80-25	1980-10-24
M80-14	1980-04-28
M80-10	1980-03-28
M79-12	1979-08-01
M78-16	1978-11-29
M78-5R3	1978-10-23
M78-9	1978-08-23
M78-6	1978-03-03

Document No.	Released Date
M78-3	1978-01-11
M77-9	1977-03-17
M77-3	1977-01-11
M76-20	1976-07-19
M76-5R1	1976-05-25
M76-7	1976-03-25
M76-4	1976-03-12
M75-30	1975-12-19
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M73-6R1	1973-06-11
M72-8	1972-06-21
M71-21	1971-11-22
M71-14	1971-06-21
M70-17	1971-04-01
M70-7	1970-03-17
M64-18	1968-10-07
M67-12	1967-05-31



**IO550 (134 Documents Released)**

Document No.	Released Date
CSB09-11A	2014-11-12
SIL14-6	2014-09-16
SIL99-2C	2014-09-16
SIL14-4A	2014-08-14
SID97-4F	2014-08-13
SB14-5	2014-06-19
SID05-1A	2014-05-02
SIL05-3A	2014-04-10
SB99-8A	2014-04-10
SB13-6A	2014-04-10
SB13-8	2014-01-22
SIL13-2A	2014-01-15
SB13-4B	2014-01-15
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL98-9C	2013-07-17
SIL13-3	2013-07-17
SIL03-2C	2013-04-03
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB11-1A	2011-03-17
SB11-2	2011-01-13
SIL10-6	2010-07-30
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB09-12	2009-10-16
MSB09-1B	2009-08-18
SIL09-15	2009-08-06
SB09-7	2009-07-16
SB05-8A	2009-07-16
SB09-4A	2009-06-10
SB08-13	2008-10-14
SB08-12	2008-09-09
CSB08-11	2008-07-16
SB96-11B	2008-07-10
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09

Document No.	Released Date
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-4	2003-07-21
SB03-3	2003-03-28
SIL03-1	2003-01-28
CSB02-2C	2002-12-11
SB01-3A	2002-12-10
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
SIL02-5	2002-04-04
SB02-3	2002-01-31
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-1	1999-03-25
SIL98-5	1998-06-12
SIL98-3A	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SIL97-12	1997-10-14
SB97-11	1997-08-10
CSB97-10A	1997-07-15
SID97-8	1997-05-28
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SID96-6	1996-05-03
SB95-7	1995-12-08
MSB95-6	1995-10-19
SIL95-5	1995-08-30
SB95-2	1995-04-21
CSB94-15	1994-12-02
SB94-11	1994-11-14
SIL94-10	1994-11-14
MSB94-9	1994-10-21
SIL94-5	1994-06-14
SB94-2	1994-02-10

Document No.	Released Date
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-5	1993-02-19
M93-8	1993-02-19
M93-4	1993-02-12
M92-14	1992-09-09
M92-12	1992-08-27
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M92-6	1992-02-28
M91-10R1	1991-11-27
M91-6	1991-03-20
M91-7	1991-03-20
M91-4	1991-02-11
M90-17	1990-08-23
M90-16	1990-08-22
M90-13	1990-07-16
M90-9	1990-04-20
M89-19	1989-09-18
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M89-6	1989-03-10
M88-9	1988-08-24
M88-10	1988-08-24
M88-5	1988-04-04
M88-4	1988-01-15
M87-24	1987-12-15
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M86-13R1	1986-10-17
M85-10	1985-07-18
M81-25	1981-11-30
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M64-18	1968-10-07



**IOF550 (81 Documents Released)**

Document No.	Released Date
CSB09-11A	2014-11-12
SIL99-2C	2014-09-16
SIL14-4A	2014-08-14
SID97-4F	2014-08-13
SB14-5	2014-06-19
SID05-1A	2014-05-02
SB13-6A	2014-04-10
SB99-8A	2014-04-10
SIL05-3A	2014-04-10
SB13-8	2014-01-22
SIL13-2A	2014-01-15
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL98-9C	2013-07-17
SIL03-2C	2013-04-03
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB11-3	2011-03-18
SB11-1A	2011-03-17
SB11-2	2011-01-13
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-12	2009-10-16
SB09-14	2009-10-16
MSB09-1B	2009-08-18

Document No.	Released Date
SB09-7	2009-07-16
SB05-8A	2009-07-16
SB08-13	2008-10-14
SB08-12	2008-09-09
CSB08-11	2008-07-16
SB96-11B	2008-07-10
SB08-4	2008-03-14
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-4	2003-07-21
SB03-3	2003-03-28
SIL03-1	2003-01-28
SIL02-5	2002-04-04
MSB00-5D	2001-10-17
SIL00-7A	2001-02-05
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-1	1999-03-25

Document No.	Released Date
SIL97-1	1997-01-03
SB96-12	1996-09-10
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-10	1994-11-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
SIL93-15	1993-09-13
M93-8	1993-02-19
M93-4	1993-02-12
M92-9	1992-05-29
M92-7	1992-05-26
M90-17	1990-08-23
M89-7R1	1989-08-04
M89-9	1989-04-21
M89-6	1989-03-10
M88-9	1988-08-24
M88-10	1988-08-24
M87-23	1987-11-24
M87-15	1987-07-13
M85-10	1985-07-18
M81-25	1981-11-30
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M72-17R1	1973-10-05
M64-18	1968-10-07

**TSIO550 (119 Documents Released)**

Document No.	Released Date
CSB09-11A	2014-11-12
SIL99-2C	2014-09-16
SIL14-4A	2014-08-14
SID97-4F	2014-08-13
SB14-5	2014-06-19
SID05-1A	2014-05-02
SB99-8A	2014-04-10
SB13-6A	2014-04-10
SB13-8	2014-01-22
SIL13-2A	2014-01-15
SB13-4B	2014-01-15
CSB08-3C	2013-07-17
SIL98-9C	2013-07-17
SIL93-11B	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB11-3	2011-03-18
SB11-1A	2011-03-17
SB11-2	2011-01-13
SB10-8A	2011-01-12
SIL10-6	2010-07-30
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB10-1	2010-01-28
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB09-12	2009-10-16
SB05-8A	2009-07-16
SB09-4A	2009-06-10
CSB04-6A	2009-03-04
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB08-4	2008-03-14
MSB07-4	2007-07-26
SIL06-3	2006-05-01
SB06-1A	2006-04-28

Document No.	Released Date
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
CSB02-2C	2002-12-11
SB01-3A	2002-12-10
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
SB02-3	2002-01-31
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-1	1999-03-25
SIL98-3A	1998-06-12
SIL98-5	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SIL97-12	1997-10-14
SB97-11	1997-08-10
CSB97-10A	1997-07-15
SID97-8	1997-05-28
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SIL96-9	1996-08-12
SID96-6	1996-05-03
SB95-7	1995-12-08
MSB95-6	1995-10-19
SIL95-5	1995-08-30

Document No.	Released Date
SB94-3A	1995-05-23
SB95-2	1995-04-21
CSB94-15	1994-12-02
SIL94-10	1994-11-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-5	1993-02-19
M93-4	1993-02-12
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-9	1988-08-24
M88-10	1988-08-24
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M85-10	1985-07-18
M81-25	1981-11-30
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M71-21	1971-11-22
M64-18	1968-10-07
M67-12	1967-05-31



**TSIOF550 (69 Documents Released)**

Document No.	Released Date
CSB09-11A	2014-11-12
SIL99-2C	2014-09-16
SIL14-4A	2014-08-14
SID97-4F	2014-08-13
SB14-5	2014-06-19
SID05-1A	2014-05-02
SB99-8A	2014-04-10
SB13-6A	2014-04-10
SIL05-3A	2014-04-10
SB13-8	2014-01-22
SIL13-2A	2014-01-15
CSB08-3C	2013-07-17
SIL93-11B	2013-07-17
SIL98-9C	2013-07-17
SIL03-2C	2013-04-03
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB11-3	2011-03-18
SB11-1A	2011-03-17
SB11-2	2011-01-13
SB10-8A	2011-01-12
SID10-4	2010-07-21
SIL04-12A	2010-05-18

Document No.	Released Date
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-12	2009-10-16
SB09-14	2009-10-16
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB08-4	2008-03-14
SB07-1	2007-03-19
SIL06-3	2006-05-01
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28
SIL00-9A	2004-09-10
SID97-2B	2004-04-19
SB03-3	2003-03-28
SIL03-1	2003-01-28
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
SIL97-1	1997-01-03
SB96-12	1996-09-10
SIL95-5	1995-08-30

Document No.	Released Date
SB95-2	1995-04-21
SIL94-10	1994-11-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
SIL93-15	1993-09-13
M93-8	1993-02-19
M93-4	1993-02-12
M92-9	1992-05-29
M92-7	1992-05-26
M90-17	1990-08-23
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-9	1988-08-24
M88-10	1988-08-24
M87-23	1987-11-24
M87-15	1987-07-13
M85-10	1985-07-18
M81-25	1981-11-30
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M71-21	1971-11-22
M67-12	1967-05-31

**TSIOL550 (108 Documents Released)**

Document No.	Released Date
CSB09-11A	2014-11-12
SIL99-2C	2014-09-16
SID97-4F	2014-08-13
SB14-5	2014-06-19
SID05-1A	2014-05-02
SB99-8A	2014-04-10
SIL05-3A	2014-04-10
SB13-6A	2014-04-10
SIL13-2A	2014-01-15
CSB08-3C	2013-07-17
SIL98-9C	2013-07-17
SIL93-11B	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
CSB13-1A	2013-03-18
SB11-3	2011-03-18
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB05-8A	2009-07-16
CSB04-6A	2009-03-04
SB08-13	2008-10-14
SB96-11B	2008-07-10
MSB08-5	2008-06-23
SB08-4	2008-03-14
SB07-1	2007-03-19
SIL06-3	2006-05-01
SB06-1A	2006-04-28
SB05-9	2005-10-20
SB96-7C	2005-02-09
SB05-2	2005-02-09
SB00-3A	2004-11-12
SB04-10	2004-10-28

Document No.	Released Date
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SID97-2B	2004-04-19
SIL04-2	2004-03-30
SB03-3	2003-03-28
SIL03-1	2003-01-28
SB01-3A	2002-12-10
SIL02-6A	2002-10-25
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-4	1999-05-19
SIL99-1	1999-03-25
SIL98-3A	1998-06-12
SIL98-5	1998-06-12
CSB98-1B	1998-06-01
SB97-15	1997-12-05
SB97-11	1997-08-10
CSB97-10A	1997-07-15
SIL97-1	1997-01-03
SB96-3B	1996-10-14
SB96-12	1996-09-10
SIL96-9	1996-08-12
SID96-6	1996-05-03
SB95-7	1995-12-08
MSB95-6	1995-10-19
SIL95-5	1995-08-30
SB95-2	1995-04-21
CSB94-15	1994-12-02
SIL94-10	1994-11-14
SIL94-5	1994-06-14

Document No.	Released Date
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-15	1993-09-13
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-5	1993-02-19
M93-8	1993-02-19
M93-4	1993-02-12
M92-12	1992-08-27
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M92-6	1992-02-28
M91-4	1991-02-11
M90-17	1990-08-23
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-9	1988-08-24
M88-10	1988-08-24
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M87-15	1987-07-13
M85-10	1985-07-18
M81-25	1981-11-30
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M71-21	1971-11-22
M64-18	1968-10-07
M67-12	1967-05-31

**TIARA (61 Documents Released)**

Document No.	Released Date
SIL99-2C	2014-09-16
SIL93-11B	2013-07-17
SIL98-9C	2013-07-17
SID97-3F	2013-05-10
SIL03-2C	2013-04-03
SID10-4	2010-07-21
SIL04-12A	2010-05-18
MSB94-8D	2010-02-17
SB97-6B	2009-11-18
SB09-14	2009-10-16
SB08-13	2008-10-14
SB96-11B	2008-07-10
SB08-4	2008-03-14
SB07-1	2007-03-19
SB05-9	2005-10-20
SB05-2	2005-02-09
SB96-7C	2005-02-09
SB04-10	2004-10-28
SIL00-9A	2004-09-10
CSB04-5A	2004-08-30
SIL04-2	2004-03-30

Document No.	Released Date
SB03-3	2003-03-28
SIL03-1	2003-01-28
CSB02-8	2002-09-06
CSB01-1	2001-04-25
SIL00-7A	2001-02-05
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL99-1	1999-03-25
SB97-15	1997-12-05
SIL97-1	1997-01-03
SB96-12	1996-09-10
SID96-6	1996-05-03
SIL95-5	1995-08-30
SB95-2	1995-04-21
SIL94-5	1994-06-14
SIL93-15	1993-09-13
SIL93-14	1993-08-17
M93-10	1993-03-01
M92-7	1992-05-26
M91-4	1991-02-11
M90-17	1990-08-23

Document No.	Released Date
M90-13	1990-07-16
M89-18	1989-08-10
M89-7R1	1989-08-04
M89-9	1989-04-21
M88-9	1988-08-24
M88-10	1988-08-24
M87-16	1987-08-14
M87-15	1987-07-13
M81-25	1981-11-30
M79-4	1979-02-14
M78-6	1978-03-03
M77-3	1977-01-11
M76-20	1976-07-19
M76-5R1	1976-05-25
M76-4	1976-03-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M72-17R1	1973-10-05
M71-14	1971-06-21
M64-18	1968-10-07

