

West Virginia Department of Health & Human
Resources

Berkeley County Health Department



Public Health
Prevent. Promote. Protect.

GENERAL SANITATION INSPECTION REPORT

Establishment Information		
Facility Name Winchester Avenue Elementary	Facility Type School	
Licensee Name Berkeley Co. Board of Education	Facility Telephone # 304 267-3500	
Facility Address 650 Winchester Ave Martinsburg, WV	Licensee Address ,	
Inspection Information		
Inspection Type Routine	Inspection Date 01/23/2017	Total Time Spent 1.22

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

ObservedViolations**Total # 11****Repeated # 0**

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Ceiling in the library needs repaired, peeling paint

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Basement floor needs tile repaired in several locations

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: 2 nd floor water faucet needs repaired, not working at time of inspection

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: North staircase needs wall repaired, hole forming

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: 1st floor hole in floor needs repaired, drinking fountain needs repaired, very little water pressure

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Room 214 ceiling needs repaired, water stains in several areas of the ceiling

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: 202 and 209 need ceiling repaired, water stains in several areas of the ceilings

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Bathrooms need faucets metered to 15 seconds run time, ran 1-8 seconds

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Ceiling in the computer room needs patched next to the pipe,

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Room b-10 bathroom handicap toilet not working at time of inspection

64-18-18.5 - Poisons and other potentially hazardous items shall be properly labeled and stored in locked storage spaces not used for any other purpose. Keys for the storage spaces shall be available only to authorized staff members.

OBSERVATION: Cleaning chemicals need to be stored so children can not reach them in the storage/maintains closets, sitting on top of cabinets.

Inspection Outcome

Comments


Disclaimer

Person in Charge



Kathy Wright

Sanitarian



Glenn GCO Ondick