



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
051200	AGHME FLIGHT	LIT	MTH HRS 7003 LDG 4558 APUH 3347.5 APUS 5550	14-Aug-2016		24 1000		31-Aug-2018 8003	5 m 13 d 325.4
055001	ACCOMPLISH CHECK HARD/OVERWEIGHT LANDING	LIT	MTH HRS 5200.1 LDG 3371	28-Feb-2012		A/R			
055601	INSPECT WINDSHIELD SURFACE RE-SEAL	LIT	MTH HRS 3144	30-May-2008		O/C			
055602	INSPECT HUMP SEAL REPAIR	ALN	MTH HRS 3204	23-Jul-2008		O/C			
5-92-01 059201	INSPECTION DOCUMENT 1 BTL		MTH HRS 7677.6 LDG 5017	08-Mar-2018		12 600		31-Mar-2019 8277.6	12 m 13 d 600
5-92-02 059202	INSPECTION DOCUMENT 2 BTL		MTH HRS 7677.6 LDG 5017	08-Mar-2018		12		31-Mar-2019	12 m 13 d
5-92-03 059203	INSPECTION DOCUMENT 3 BTL		MTH HRS 7677.6 LDG 5017	08-Mar-2018		24 1200		31-Mar-2020 8877.6	24 m 13 d 1200
5-92-04 059204	INSPECTION DOCUMENT 4 BTL		MTH HRS 7677.6 LDG 5017	08-Mar-2018		24		31-Mar-2020	24 m 13 d
5-92-05 059205	INSPECTION DOCUMENT 5 KALN		MTH HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677	19-Jul-2017		48 1200		31-Jul-2021 8661.2	40 m 13 d 983.6
5-92-06 059206	INSPECTION DOCUMENT 6 KALN		MTH HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319	22-Jul-2016		36 1800		31-Jul-2019 8780.6	16 m 13 d 1103
5-92-07 059207	INSPECTION DOCUMENT 7 BTL		MTH HRS 7677.6 LDG 5017	08-Mar-2018	-6	36		31-Mar-2021	36 m 13 d
5-92-08 059208	INSPECTION DOCUMENT 8 KALN		MTH HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319	22-Jul-2016		48 2400		31-Jul-2020 9380.6	28 m 13 d 1703
5-92-09 059209	INSPECTION DOCUMENT 9 KALN		MTH HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677	19-Jul-2017		48 1200		31-Jul-2021 8661.2	40 m 13 d 983.6
5-92-10 059210	INSPECTION DOCUMENT 10 KALN		MTH HRS 6866.6 LDG 4463	10-Mar-2016	-15	48		29-Feb-2020	23 m 11 d
5-92-11 059211	INSPECTION DOCUMENT 11 BTL		MTH HRS 7677.6 LDG 5017	08-Mar-2018		24		31-Mar-2020	24 m 13 d
5-92-12 059212	INSPECTION DOCUMENT 12 LIT		MTH HRS 5981.3 LDG 3859	23-Aug-2013		3000		8981.3	1303.7



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-92-13	INSPECTION DOCUMENT 13	KALN		MTH HRS LDG	30-Jul-2014 6398.9 4127		72			
D291100 059213	DISCARD HYDRAULIC SYSTEM FILTERS: INSPECTION DOCUMENT 13	KALN		MTH HRS LDG	30-Jul-2014 6398.9 4127	-7	72		31-Jul-2020	28 m 13 d
D324010 059213	DISCARD BRAKE SYSTEMS FILTERS: INSPECTION DOCUMENT 13	KALN		MTH HRS LDG	30-Jul-2014 6398.9 4127	-7	72		31-Jul-2020	28 m 13 d
5-92-14 059214	INSPECTION DOCUMENT 14	KALN		MTH HRS LDG APUH APUS	22-Jul-2016 6980.6 4542 3196.9 5319		96		31-Jul-2024	76 m 13 d
5-92-15 059215	INSPECTION DOCUMENT 15	ICT		MTH HRS	23-Jul-2008 3204		144		31-Jul-2020	28 m 13 d
5-92-16 059216	INSPECTION DOCUMENT 16	LIT		MTH HRS LDG APUH APUS	27-Nov-2017 7614.5 4972 3435 5677		12 400		30-Nov-2018 8014.5	8 m 12 d 336.9
5-92-17 059217 : APU	INSPECTION DOCUMENT 17	BTL		MTH HRS LDG APUH	08-Mar-2018 7677.6 5017 3452.3		23 500		29-Feb-2020 3952.3	23 m 11 d 500
5-92-18 059218	INSPECTION DOCUMENT 18	BTL		MTH HRS LDG APUH	08-Mar-2018 7677.6 5017 3452.3		23 1000		29-Feb-2020 4452.3	23 m 11 d 1000
5-92-19 059219	INSPECTION DOCUMENT 19	BTL		MTH HRS LDG	08-Mar-2018 7677.6 5017		24 2400		31-Mar-2020 10077.6	24 m 13 d 2400
5-92-25 059225	INSPECTION DOCUMENT 25	BTL		MTH HRS LDG	08-Mar-2018 7677.6 5017		300		7977.6	300
5-92-26 059226A : APU	INSPECTION DOCUMENT 26	ICT		MTH APUH	23-Jul-2008 1637	-30	500			
A801103 APU	DETAILED INSPECTION STARTER/GENERATOR : INSPECTION DOCUMENT 26	LIT		300SGL138Q-6 6307XL MTH HRS LDG APUH	13-Nov-2015 6778.1 4408 3098.6		500		3598.6	146.3
5-92-30 059230	INSPECTION DOCUMENT 30	BTL		MTH HRS LDG APUH	08-Mar-2018 7677.6 5017 3452.3		1000		4452.3	1000
5-92-34	INSPECTION DOCUMENT 34	BTL		MTH HRS LDG	08-Mar-2018 7677.6 5017		6			
B342006 059234 : STDBY	OPERATIONAL CHECK L3 COM STANDBY BATTERY PACK (PERIODIC CHECK): INSPECTION DOCUMENT 34	BTL		MTH HRS LDG	08-Mar-2018 7677.6 5017	-6	6		30-Sep-2018	6 m 12 d
5-92-35	INSPECTION DOCUMENT 35	BTL		MTH HRS LDG	08-Mar-2018 7677.6 5017		12			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
B342005 059235 : STDBY	FUNCTIONAL CHECK L3 COM STANDBY BATTERY PACK(CAPACITY CHECK): INSPECTION DOCUMENT 35	BTL		MTH 08-Mar-2018 HRS 7677.6 LDG 5017	-6	12		31-Mar-2019	12 m 13 d
5-92-36	INSPECTION DOCUMENT 36			MTH 22-Mar-2002		24			
B237006 059236 : CVR	FUNCTIONAL CHECK CVR UNDERWATER LOCATOR BEACON COCKPIT VOICE RECORDER UNDERWATER LOCATING DEVICE (ULD): INSPECTION DOCUMENT 36	LIT	DK120 DU48639	MTH 18-Oct-2017 HRS 7572.7 LDG 4949 APUH 3435 APUS 5677	-18	24		30-Sep-2019	18 m 12 d
5-92-37	INSPECTION DOCUMENT 37 (NOT CURRENTLY USED)	KALN		MTH 13-Mar-2015 HRS 6556 LDG 4246		36			
5-92-40 059240	INSPECTION DOCUMENT 40	KALN		MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		36 1200		31-Jul-2019 8180.6	16 m 13 d 503
5-92-43	INSPECTION DOCUMENT 43			MTH 22-Mar-2002		A/R			
A324006 LEFT	NON DESTRUCTIVE TEST MAIN WHEEL ASSEMBLY : INSPECTION DOCUMENT 43	KALN	3-1571-6 1198	MTH		A/R			
A324006 NOSE	NON DESTRUCTIVE TEST WHEEL ASSEMBLY : INSPECTION DOCUMENT 43		3-1418 6466	MTH		A/R			
A324006 RIGHT	NON DESTRUCTIVE TEST MAIN WHEEL ASSEMBLY : INSPECTION DOCUMENT 43	KALN	3-1571-6 0585	MTH		A/R			
5-92-44 059244	INSPECTION DOCUMENT 44 (14 CFR 91.207)	BTL		MTH 08-Mar-2018 HRS 7677.6 LDG 5017		12		31-Mar-2019	12 m 13 d
5-92-45	INSPECTION DOCUMENT 45	KALN		MTH 31-Mar-2017 HRS 7313.2 LDG 4787		24			
B238002 NO. 1 059245 : XPDR1	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): INSPECTION DOCUMENT 45	KALN	7517400-902 01014815	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		24		31-Mar-2019	12 m 13 d
B238002 NO. 2 059245 : XPDR2	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): INSPECTION DOCUMENT 45	KALN	7517400-902 01116106	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		24		31-Mar-2019	12 m 13 d
B341100 NO. 1 059245 : ADC#1	CALIBRATION TEST (PILOT) AIR DATA COMPUTER (FAR 91.411) : INSPECTION DOCUMENT 45	KALN	7014700-914 02066336	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		24		31-Mar-2019	12 m 13 d
B341100 NO. 2 059245 : ADC#2	CALIBRATION TEST (COPILOT) AIR DATA COMPUTER (FAR 91.411) : INSPECTION DOCUMENT 45	KALN	7014700-914 02106649	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		24		31-Mar-2019	12 m 13 d
B341100 RVSM 059245	INSPECT SKIN WAVINESS: INSPECTION DOCUMENT 45	KALN		MTH 31-Mar-2017 HRS 7313.2 LDG 4787		24		31-Mar-2019	12 m 13 d
B341100 SECONDARY 059245 : ADU	CALIBRATION TEST ADU (FAR 91.411) : INSPECTION DOCUMENT 45	KALN	27101-01-01 M010943	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		24		31-Mar-2019	12 m 13 d



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-92-47	INSPECTION DOCUMENT 47	KALN			MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		3 200			
B243001 059247	FUNCTIONAL CHECK MAIN SHIP (UY006) BATTERY (CAPACITY CHECK) LEAD ACID : INSPECTION DOCUMENT 47	LIT		RG-380E/44LA3 40803219	MTH 14-Feb-2018 HRS 7671.3 LDG 5013	-23	3 200		30-Apr-2018 7871.3	1 m 12 d 193.7
5-92-48 059248	INSPECTION DOCUMENT 48	LIT			MTH 28-Jul-2017 HRS 7474 LDG 4887 APUH 3371.3 APUS 5677		500		7974	296.4
5-92-52	INSPECTION DOCUMENT 52	KALN			MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		1200		8180.6	503
5-92-MD 0592MD	INSPECTION DOCUMENT MD	KALN			MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		120 2400		31-Jul-2027 9861.2	112 m 13 d 2183.6
5-92-ME 0592ME	INSPECTION DOCUMENT ME	*CF			MTH 22-Mar-2002 HRS 0		15000		15000	7322.4
5-92-MF 0592MF	INSPECTION DOCUMENT MF	KALN			MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		1400		8861.2	1183.6
5-92-MJ 0592MJ	INSPECTION DOCUMENT MJ	*CF			MTH 22-Mar-2002 HRS 0		13000		13000	5322.4
5-92-ML 0592ML	INSPECTION DOCUMENT ML	*CF			MTH 22-Mar-2002 HRS 0		11500		11500	3822.4
5-92-MM 0592MM	INSPECTION DOCUMENT MM	*CF			MTH 22-Mar-2002 HRS 0		11000		11000	3322.4
5-92-MN 0592MN	INSPECTION DOCUMENT MN	*CF			MTH 22-Mar-2002 HRS 0		9000		9000	1322.4
5-92-MO 0592MO	INSPECTION DOCUMENT MO	*CF			MTH 22-Mar-2002 HRS 0		12500		12500	4822.4
057109 E1	OIL FILTER CHANGE	KALN			MTH 19-Jul-2017 HRS 7516.5		24 900		31-Jul-2019 8416.5	16 m 13 d 738.9
057109 E2	OIL FILTER CHANGE	KALN			MTH 19-Jul-2017 HRS 7461.2		24 900		31-Jul-2019 8361.2	16 m 13 d 683.6
057120 E1	INSPECTION LOW UTILIZATION	UNK			MTH 13-Feb-2012 HRS 5254.7 LDG 3457		120		28-Feb-2022	47 m 10 d
057120 E2	INSPECTION LOW UTILIZATION	BTL			MTH 08-Mar-2018 HRS 7677.6 LDG 5017		24		31-Mar-2020	24 m 13 d
057159 E1	MINOR INSPECTION	BTL			MTH 08-Mar-2018 HRS 7677.6 LDG 5017		12 600		31-Mar-2019 8277.6	12 m 13 d 600
057159 E2	MINOR INSPECTION				MTH 08-Mar-2018 HRS 7677.6 LDG 5017		12 600		31-Mar-2019 8277.6	12 m 13 d 600
12-26-00-6003	90 DAY LOW EXPOSURE AREA WASH	LIT			DAYS 14-Feb-2018 HRS 7671.3 LDG 5013		90		15-May-2018	1 m 27 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
A262003 CABIN <i>059213 : CABIN</i>	RESTORATION PORTABLE HALON FIRE EXTINGUISHER (INTERNAL INSPECTION)	KALN		C352 W-809529	MTH 13-Mar-2015 HRS 6556 LDG 4246		72		31-Mar-2021	36 m 13 d
A262003 COCKPIT <i>059213 : CKPT</i>	RESTORATION PORTABLE HALON FIRE EXTINGUISHER (INTERNAL INSPECTION)	KALN		C352 W-866521	MTH 13-Mar-2015 HRS 6556 LDG 4246		72		31-Mar-2021	36 m 13 d
B262004 CABIN <i>059241 : CABIN</i>	RESTORATION (HYDROSTATIC TEST) PORTABLE HALON FIRE EXTINGUISHER	KALN		C352 W-809529	MTH 10-Mar-2015		144		31-Mar-2027	108 m 13 d
B262004 COCKPIT <i>059241 : CKPT</i>	RESTORATION (HYDROSTATIC TEST) PORTABLE HALON FIRE EXTINGUISHER	KALN		C352 W-866521	MTH 10-Mar-2015		144		31-Mar-2027	108 m 13 d
B262005 APU <i>059238 : APU</i>	RESTORATION (HYDROSTATIC TEST) FIRE BOTTLE	KALN		30100033-7 50549A1	MTH 13-Jul-2016		60		31-Jul-2021	40 m 13 d
B262008 AFT <i>059238 : A</i>	RESTORATION (HYDROSTATIC TEST) ENGINE FIRE BOTTLE	KALN		30400037-1 52486B1	MTH 12-Jul-2016		60		31-Jul-2021	40 m 13 d
B262008 FORWARD <i>059238 : F</i>	RESTORATION (HYDROSTATIC TEST) ENGINE FIRE BOTTLE	KALN		30400037-1 49321B1	MTH 12-Jul-2016		60		31-Jul-2021	40 m 13 d
B320900 <i>059237 : N2</i>	RESTORATION PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE (HYDROSTATIC TEST)	BTL		40005347-3 2375	MTH 01-Feb-2018		36		28-Feb-2021	35 m 10 d
350000 <i>059237 : O2</i>	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER	KALN		804882-14 C16080705	MTH 01-Aug-2016		60		31-Aug-2021	41 m 13 d
054906	REPLACE FUEL NOZZLE ASSEMBLY ICT				APUH 20-Jan-2017 APUS 3272.6 5500		4000		9500	3822
710060 E1	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT, RECONNECT AND PERFORM ENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESS REPLACEMENT				MTH 08-Mar-2018 HRS 7677.6 LDG 5017		900		8577.6	900
710060 E2	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT, RECONNECT AND PERFORM ENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESS REPLACEMENT				MTH 08-Mar-2018 HRS 7677.6 LDG 5017		900		8577.6	900
720010 E1	ENGINE OVERHAUL	UNK			MTH 13-Feb-2012 HRS 5198.4 LDG 3368		5000		10198.4	2520.8
720010 E2	ENGINE OVERHAUL	DMO			MTH 11-Dec-2002 HRS 3149.7		5000		8149.7	472.1
720060 E1	HOT SECTION INSPECTION	BTL			MTH 20-Feb-2018 HRS 7677.6 LDG 5017		2500		10177.6	2500
720060 E2	HOT SECTION INSPECTION				MTH 31-Aug-2011 HRS 5205 LDG 3461		2500		8149.7	472.1
731030 E1	INSTALL NEW FUEL FILTER ELEMENT	KALN			MTH 19-Jul-2017 HRS 7516.5		24 900		31-Jul-2019 8416.5	16 m 13 d 738.9
731030 E2	INSTALL NEW FUEL FILTER ELEMENT	KALN			MTH 19-Jul-2017 HRS 7517.2		24 900		31-Jul-2019 8417.2	16 m 13 d 739.6
731100 E1	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	KALN			MTH 19-Jul-2017 HRS 7516.5		24 900		31-Jul-2019 8416.5	16 m 13 d 738.9



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
731100 E2	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	KALN		MTH 19-Jul-2017 HRS 7517.2		24 900		31-Jul-2019 8417.2	16 m 13 d 739.6
731110 E1	DIMENSIONAL CHECK EMERGENCY FUEL SHUTOFF PIN			MTH 25-Feb-2012 HRS 5198.4 LDG 3368		A/R			
740010 E1	CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION	LIT		MTH 21-Apr-2017 HRS 7348.6 LDG 4809	8.6	600		7957.2	279.6
740010 E2	CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION	LIT		MTH 21-Apr-2017 HRS 7348.6 LDG 4809	8.6	600		7957.2	279.6
751030 E1	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE			MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			
751030 E2	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE			MTH 15-Nov-2011 HRS 5205 LDG 3461		-			
790020 E1	CHANGE OIL	UNK		MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			
790020 E2	CHANGE OIL			MTH 28-Nov-2011 HRS 5205 LDG 3461		A/R			
790030 E1	MONITOR OIL QUALITY			MTH 22-Mar-2002		O/C			
790030 E2	MONITOR OIL QUALITY					O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211002	EMERGENCY PRESSURIZATION FLOW (UY005) VALVE *CF			27441482-06 11AU137	MTH 22-Mar-2002		O/C			
211120 LEFT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 1667A	MTH 22-Mar-2002		O/C			
211120 RIGHT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 1665A	MTH 22-Mar-2002		O/C			
212200	MOTOR AND BLOWER ASSEMBLY *CF			7003-400 292	MTH 22-Mar-2002		O/C			
213005	MANUAL TOGGLE VALVE 9912409-12	*CF		52773-114 988	MTH 22-Mar-2002		O/C			
213006	CABIN ALTITUDE (U1005) CONTROLLER 9912409-9	*CF		52770-114 1433	MTH 22-Mar-2002		O/C			
213007 PRIMARY	OUTFLOW VALVE 9912409-10	LIT	G	52771-114 974B	MTH 19-Jul-2010 HRS 4258 LDG 2701		O/C			
213007 SECONDARY	OUTFLOW VALVE 9912409-11	LIT	G	52772-114 963B	MTH 19-Jul-2010 HRS 4258 LDG 2701		O/C	0 0 0		
213101	ALT PRESSURE SWITCH 9910095-6	*CF		GB300NA161 0144985	MTH 22-Mar-2002		O/C			
215001	ENVIRONMENTAL CONTROL UNIT 9912493-1	*CF		2215460-2 339	MTH 22-Mar-2002		O/C			
215004	PAC OVERHEAT SWITCH 1173T0570	*CF		927223-2-1 749	MTH 22-Mar-2002		O/C			
215005	ACM COOLING TURBINE *CF			2206610-1 345	MTH 22-Mar-2002		O/C			
215006	HEAT EXCHANGER	*CF		2340594-6 382	MTH 22-Mar-2002		O/C			
215100	WATER SPRAY ECU ASPIRATOR 9912493-3	*CF		2215605-1 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
215101	WATER SEPARATOR TEMP 1 SENSOR 9914130-20	*CF		1E62-1 11AU270	MTH 22-Mar-2002		O/C			
216002	ENVIRONMENTAL TEMP CONTROLLER 9912518-4	LIT		1E64-1 8AW31	MTH 09-Feb-2005 HRS 1474		O/C	0		
216003 NO. 1	CABIN TEMP SENSOR 9914130-3	*CF		1E47-1 11AU321	MTH 22-Mar-2002		O/C			
216003 NO. 2	CABIN TEMP SENSOR 9914130-3	*CF		1E47-1 11AU322	MTH 22-Mar-2002		O/C			
216009 CABIN	ZONE TEMPERATURE (UC021) SENSOR 9914130-6	*CF		1E46-1 8AU137	MTH 22-Mar-2002		O/C			
216009 COCKPIT	ZONE TEMPERATURE (UF029) SENSOR 9914130-6	LIT		1E46-1 11BN112	MTH 19-Dec-2016 HRS 7168 LDG 4680 APUH 3196.9 APUS 5319		O/C	0 0		
216099 216100	ECU TEMP CONTROL VALVE 9912518-2	*CF		27241287-14 12AUH563	MTH 22-Mar-2002		O/C			
216100 LEFT	CABIN TEMPERATURE CONTROL (VT029) VALVE 9912518-2	*CF		27241287-14 10AU177	MTH 22-Mar-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
216100 RIGHT	COCKPIT TEMPERATURE CONTROL (VT030) VALVE 9912518-2	KMKE		27241287-14 9BA225F	MTH 20-Sep-2016 HRS 7055.6 LDG 4585		O/C	0 0		
216101 LEFT	CABIN DUCT OVERHEAT (SC013) SWITCH *CF			1173T42 2341	MTH 22-Mar-2002		O/C			
216101 RIGHT	COCKPIT DUCT OVERHEAT (SF034) SWITCH *CF			1173T42 2344	MTH 22-Mar-2002		O/C			
217001	WATER SEPARATOR 9912493-7	*CF		2341316-2 377	MTH 22-Mar-2002		O/C			
217101 LEFT	OZONE CONVERTER 9914523-2	*CF	D	31A437-1 04230780	MTH 22-Mar-2002		O/C			
217101 RIGHT	OZONE CONVERTER 9914523-2	*CF	D	31A437-1 04670909	MTH 22-Mar-2002		O/C			
221009	AUTOPILOT (PC400) CONTROLLER PC-400	*CF	A	7003897-923 01112597	MTH 22-Mar-2002		O/C			
221010 AILERON	DRIVE SERVO SM-200	*CF		4006719-906 01106391	MTH 22-Mar-2002		O/C			
221010 ELEVATOR	DRIVE SERVO SM-200			4006719-906 98040663	MTH 07-Jun-2005 HRS 1610		O/C	0		
221010 RUDDER	DRIVE SERVO SM-200	*CF		4006719-910 1086218	MTH 22-Mar-2002		O/C			
231003	HIGH FREQUENCY RECEIVER/EXCITER KALN			PN NOT INSTALLED	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		O/C			
231004	HF POWER AMP KALN			PN NOT INSTALLED	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		O/C			
231007	KHF950 HIGH FREQUENCY (KA594) ADAPTER KA-594	*CF		071-01268-0001 4440	MTH 22-Mar-2002		O/C			
231011	KHF950 HIGH FREQUENCY (KFS594) CONTROLLER KALN 8			PN NOT INSTALLED	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		O/C			
231500	SATELITE SATCOM DATA UNIT *CF	1		403068A-UAT 428	MTH 22-Mar-2002		O/C			
231501 NO. 2	SATCOM ANTENNA LIT			015-103306-001(S67- 1575-109) 10668	MTH 19-Jul-2010 HRS 4258 LDG 2701		O/C	0 0 0		
231502	FLITEPHONE VI RECEIVER TRANSMITTER *CF	2		403010H 00851902	MTH 22-Mar-2002		O/C			
232003 NO. 1	COMM ANTENNA *CF			S65-8282-1 1037	MTH 22-Mar-2002		O/C			
232003 NO. 2	COMM ANTENNA *CF			21-38-1RF/36 8395	MTH 22-Mar-2002		O/C			
232005	AFIS ANTENNA *CF			21-38-1RF/36 8155	MTH 22-Mar-2002		O/C			
232008 NO. 1	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT RCZ-833E	ICT		7510700-766 0117159	MTH 22-Mar-2004 HRS 1016		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
232008 NO. 2	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT RCZ-833E	ICT		7510700-766 01127180	MTH 22-Mar-2004 HRS 1016		O/C	0		
232010 NO. 1	COMM TRANSCEIVER TR-833	*CF		7510763-901 01114474	MTH 22-Mar-2002		O/C			
232010 NO. 2	COMM TRANSCEIVER TR-833	*CF		7510763-901 01114550	MTH 22-Mar-2002		O/C			
232013 NO. 1	CLUSTER COMM MODULE XC-833	*CF	J	7510784-835 01107605	MTH 22-Mar-2002		O/C			
232013 NO. 2	CLUSTER COMM MODULE XC-833	*CF	J	7510784-835 01107574	MTH 22-Mar-2002		O/C			
235001 NO. 1	AUDIO CONTROL PANEL AMPLIFIER AV-850A	KALN	Y	7511001-915 01117742	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C			
235001 NO. 2	AUDIO CONTROL PANEL AMPLIFIER AV-850A	KALN	Y	7511001-915 02027986	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C			
237001	COCKPIT VOICE RECORDER FA2100	*CF	4	2100-1020-02 000152187	MTH 22-Mar-2002		O/C			
237002	CVR GRAVITY SWITCH	*CF		6895D1-X-5-5 3511	MTH 22-Mar-2002		O/C			
237004	CVR CONTROL UNIT	*CF	4	S251-1120-00 000159349	MTH 22-Mar-2002		O/C			
237006	CVR UNDERWATER LOCATOR BEACON LIT			DK120 DU48639	MTH 30-Sep-2013 HRS 6053.2 LDG 3905		O/C			
237006A	CVR UNDERWATER LOCATOR BEACON BATTERY 266-E0305-00	LIT		810-2008/K 07012019	MTH 30-Sep-2013 HRS 6053.2 LDG 3905		DUE DUE DUE DUE	0 0 0 0	30-Jun-2019	15 m 12 d
Expiration Date: 30-Jun-2019										
238001	STDBY CONTROL UNIT CD-850	*CF	G	7513000-835 01092084	MTH 22-Mar-2002		O/C			
240001 LEFT	POWER CONTROL (UD015) UNIT 9914216-6	LIT		91479-1 547	MTH 15-Sep-2004 HRS 1228		O/C	0		
240001 RIGHT	POWER CONTROL (UE016) UNIT 9914216-6	KPDK		91479-1 1642	MTH 12-Apr-2016 HRS 6897.4 LDG 4488 APUH 3131 APUS 5223		O/C			
242050 LEFT	AC (UD017) GENERATOR 9914435-8	*CF		91372-3 460	MTH 22-Mar-2002		O/C			
242050 RIGHT	AC (UE018) GENERATOR 9914435-8	*CF		91372-3 489	MTH 22-Mar-2002		O/C			
243003 APU	GENERATOR (UT032) CONTROL UNIT *CF			51525-001F Y1943	MTH 22-Mar-2002		O/C			
243003 LEFT	GENERATOR (UT007) CONTROL UNIT ICT			51525-001F 95199	MTH 17-Jan-2010 HRS 3982		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
243003 RIGHT	GENERATOR (UT008) CONTROL UNIT ICT			51525-001F Y1465	MTH 17-Jan-2010 HRS 3982		O/C	2672		
243004 LEFT	DC (EI011) AMMETER S3439-1	*CF		MD144-1 K21523	MTH 22-Mar-2002		O/C			
243004 RIGHT	DC (EI010) AMMETER S3439-1	*CF		MD144-1 K21526	MTH 22-Mar-2002		O/C			
243005	DC (EI009) VOLTMETER MD129-1	*CF		C662502-0101 L21090	MTH 22-Mar-2002		O/C			
243007	MAIN SHIP (UY006) BATTERY S3597-4	KALN		RG-380E/44LA3 40803219	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C	0 0		
243008	OVERHEAT MONITOR *CF	A		1529-1 3591	MTH 22-Mar-2002		O/C			
243009	BATTERY TEMP INDICATOR *CF			1229-1 2824	MTH 22-Mar-2002		O/C			
243010	BATTERY TEMP SENSOR S3597-9	LIT		TS-C1A3 NSN	MTH 18-Nov-2008 HRS 3351		O/C	0		
243015	BATTERY DISCONNECT (KY001) RELAY *CF			A876K CM88682	MTH 22-Mar-2002		O/C			
243016	OVERVOLTAGE (UZ003) MONITOR LIT			1645-1-3 3019	MTH 18-Sep-2015 HRS 6730.1 LDG 4375		O/C	0 0 0		
245079 LEFT	START CNTL NZ013 PCB *CF			6318324-5 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
245079 RIGHT	START CNTL NZ012 PCB *CF			6318324-5 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
245080	TRIM NZ001 PCB *CF			6518351-7 533	MTH 22-Mar-2002		O/C			
245081	PRESS NZ002 PCB *CF			6518352-5 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
245082	DIMMING NZ023 PCB *CF			6518353-6 359	MTH 22-Mar-2002		O/C			
245083 LEFT	EEC INTERFACE NZ021 PCB ICT			6618002-3 594	MTH 24-May-2005 HRS 1595		O/C	1595		
245083 RIGHT	EEC INTERFACE NZ020 PCB ICT			6618002-3 593	MTH 24-May-2005 HRS 1595		O/C	1595		
245084	LANDING GEAR NZ004 PCB *CF			6618704-6 343	MTH 22-Mar-2002		O/C			
245085	TAIL DEICE NZ005 PCB *CF			6618705-6 342	MTH 22-Mar-2002		O/C			
245086	SQUAT SW NZ006 PCB *CF			6618706-1 339	MTH 22-Mar-2002		O/C			
245087	CABIN DOOR NZ007 PCB *CF			6618707-16 371	MTH 22-Mar-2002		O/C			
245091	NO TAKE-OFF NZ008 PCB LIT			6618708-1 SN-UNKNOWN	MTH 07-Apr-2004 HRS 1028		O/C	0		
245092 LEFT	FUEL NZ015 PCB *CF			6618714-11 581	MTH 22-Mar-2002		O/C			
245092 RIGHT	FUEL NZ014 PCB *CF			6618714-11 580	MTH 22-Mar-2002		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
245094	HYD NZ016 PCB	ICT		6618723-1 0274	MTH HRS 22-Mar-2004 1016		O/C	0		
245095	POS TAIL NZ017 PCB	ICT		6618721-1 0137	MTH HRS 22-Mar-2004 1016		O/C	0		
245096 LEFT	ANTI ICE NZ019 PCB	*CF		6618718-1 589	MTH 22-Mar-2002		O/C			
245096 RIGHT	ANTI-ICE NZ018 PCB	*CF		6618718-1 588	MTH 22-Mar-2002		O/C			
245097	FAN CONTROL NZ022 PCB	*CF		6618722-1 336	MTH 22-Mar-2002		O/C			
245098	RUDDER BIAS NZ029 PCB	*CF		6618812-1 348	MTH 22-Mar-2002		O/C			
245103	APU NZ025 PCB	ICT		6618808-16 SN-UNKNOWN	MTH HRS 14-May-2002 13		O/C	0		
245104	APU NZ026 PCB	*CF		6618809-1 278	MTH 22-Mar-2002		O/C			
252003	TEMPERATURE PROBE	*CF		102DB1AG A41275	MTH 22-Mar-2002		O/C			
252525	EXTERNALLY SERVICABLE TOILET KALN			15900-016 176/72477	MTH HRS LDG 10-Mar-2016 6866.6 4463		O/C	168 6866.6 4463		
256002	EMERGENCY LOCATOR TRANSMITTER C406-1	LIT		453-5002-336 170-9474	MTH HRS 20-Mar-2009 3524		O/C	0		
256003	EMERGENCY LOCATOR BEACON BATTERY PACK BTL			452-0133 376507-033	MTH HRS LDG 08-Mar-2018 7677.6 5017		60	0 0 0	31-Mar-2023	60 m 13 d
256004	ELT ANTENNA	LIT		110-338 269107	MTH HRS 20-Mar-2009 3524		O/C	0		
261002 LEFT	ENGINE FIRE DETECT (UT021) CONTROL UNIT 9912036-12	*CF		377-02838 0144193	MTH 22-Mar-2002		O/C			
261002 RIGHT	ENGINE FIRE DETECT (UT020) CONTROL UNIT 9912036-12	*CF		377-02838 0144202	MTH 22-Mar-2002		O/C			
262001 AFT	ENGINE FIRE BOTTLE	LIT		30400037-1 52486B1	MTH HRS LDG 13-Oct-2011 4965.8 3207		O/C	2 0 0		
262001 APU	FIRE BOTTLE	LIT		30100033-7 50549A1	MTH HRS LDG 13-Nov-2015 6778.1 4408		O/C	0 0		
262001 FORWARD	ENGINE FIRE BOTTLE	LIT		30400037-1 49321B1	MTH HRS LDG 13-Oct-2011 4965.8 3207		O/C	2 0 0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER KALN			C352 W-809529	MTH HRS LDG 13-Mar-2015 6556 4246		O/C			
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER KALN			C352 W-866521	MTH HRS LDG 13-Mar-2015 6556 4246		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
263004 262003 : APU	APU FIRE BOTTLE CARTRIDGE KALN			AE13083-5 NSN	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		120		31-Mar-2026	96 m 13 d
Manufacture Date: 31-Mar-2016										
263006 262003 : FL	FORWARD ENGINE BOTTLE FORWARD CARTRIDGE KALN			AE13083-5 NSN	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		120		31-Mar-2026	96 m 13 d
Manufacture Date: 31-Mar-2016										
263008 262003 : FR	FORWARD ENGINE BOTTLE AFT CARTRIDGE KALN			AE13083-5 NSN	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		120		31-Mar-2026	96 m 13 d
Manufacture Date: 31-Mar-2016										
263010 262003 : AL	AFT ENGINE BOTTLE FORWARD CARTRIDGE KALN			AE13083-5 NSN	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		120		31-Mar-2026	96 m 13 d
Manufacture Date: 31-Mar-2016										
263012 262003 : AR	AFT ENGINE BOTTLE AFT CARTRIDGE KALN			AE13083-5 NSN	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		120		31-Mar-2026	96 m 13 d
Manufacture Date: 31-Mar-2016										
272001	RUDDER BIAS SHUTOFF VALVE *CF			5307-1 333B	MTH 22-Mar-2002		O/C			
272002 LEFT	STICK SHAKER (MC001) UNIT *CF	A		201 5321	MTH 22-Mar-2002		O/C			
272002 RIGHT	STICK SHAKER (MF004) UNIT *CF	A		201 5253	MTH 22-Mar-2002		O/C			
272003	RUDDER BIAS ACTUATOR *CF			6660613-12 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
273004	SERVO ACTUATOR LBG			44430-3739 T306	MTH 11-Sep-2003 HRS 790		O/C	0		
273006 RIGHT	ELEVATOR TRIM ACTUATOR LIT			6660161-14 N/A	MTH 07-Aug-2014 HRS 6404.7 LDG 4132		O/C	0 0 0		
273020	AFT ELEVATOR TRIM CABLE ASSEMBLY KALN			6660003-1 NA	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		4800	0 0 0	10243.8	2566.2
273201	ELEV TRIM SWITCH *CF			8-405-04 B53269	MTH 22-Mar-2002		O/C			
274000	HORIZONTAL STABILIZER ACTUATOR 9912548-8 KALN			41016450-101 0129	MTH 13-Mar-2015 HRS 6556 LDG 4246		O/C			
274013	HORIZONTAL STABILIZER ISOLATION (UY015) VALVE *CF			13027-4 4658	MTH 22-Mar-2002		O/C			
274044	HORIZONTAL STAB VALVE ASSY *CF			65680 3889	MTH 22-Mar-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains	
275001	FLAP CONTROL (UY024) VALVE *CF	66720 2467	MTH 22-Mar-2002		O/C			
275003 LEFT	FLAP ACTUATOR 9912007-1 *CF	1535000-1 1513	MTH 22-Mar-2002		O/C			
275003 RIGHT	FLAP ACTUATOR 9912007-1 *CF	1535000-1 1504	MTH 22-Mar-2002		O/C			
275004 LEFT WING LEFT INBOARD	AFT FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275004 LEFT WING LEFT OUTBOARD	AFT FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275004 LEFT WING RIGHT INBOARD	AFT FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275004 LEFT WING RIGHT OUTBOARD	AFT FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275004 RIGHT WING LEFT INBOARD	AFT FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275004 RIGHT WING LEFT OUTBOARD	AFT FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275004 RIGHT WING RIGHT INBOARD	AFT FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275004 RIGHT WING RIGHT OUTBOARD	AFT FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275005 LEFT WING LEFT INBOARD	FORWARD FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275005 LEFT WING LEFT OUTBOARD	FORWARD FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	
275005 LEFT WING RIGHT INBOARD	FORWARD FLAP ROLLER CF-2920 KALN	S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000 0	9879	4862	

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
275005 LEFT WING RIGHT OUTBOARD	FORWARD FLAP ROLLER CF-2920	KALN		S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000	0	9879	4862
275005 RIGHT WING LEFT INBOARD	FORWARD FLAP ROLLER CF-2920	KALN		S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000	0	9879	4862
275005 RIGHT WING LEFT OUTBOARD	FORWARD FLAP ROLLER CF-2920	KALN		S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000	0	9879	4862
275005 RIGHT WING RIGHT INBOARD	FORWARD FLAP ROLLER CF-2920	KALN		S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000	0	9879	4862
275005 RIGHT WING RIGHT OUTBOARD	FORWARD FLAP ROLLER CF-2920	KALN		S3049-5F8 NSN	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		5000	0	9879	4862
276001 LEFT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 2121	MTH 22-Mar-2002		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 2014	MTH 22-Mar-2002		O/C			
276002	SPEED BRAKE CONTROL VALVE *CF			66720 2453	MTH 22-Mar-2002		O/C			
276003	SPEED BRAKE SAFETY VALVE *CF			68930 1233	MTH 22-Mar-2002		O/C			
280003 LEFT	FUEL RELIEF VALVE ASSY 9912501-2	*CF		840203-105 2436XP	MTH 22-Mar-2002		O/C			
280003 RIGHT	FUEL RELIEF VALVE ASSY 9912501-2	*CF		840203-105 2449XP	MTH 22-Mar-2002		O/C			
280004 LEFT	HIGH LVL FUEL VALVE 9914107-1	*CF		61087 3013	MTH 22-Mar-2002		O/C			
280004 RIGHT	HIGH LVL FUEL VALVE 9914107-1	*CF		61087 3001	MTH 22-Mar-2002		O/C			
281101 LEFT	FUEL VENT FLOAT VALVE 9914268-5	*CF		60221-4 574	MTH 22-Mar-2002		O/C			
281101 RIGHT	FUEL VENT FLOAT VALVE 9914268-5	*CF		60221-4 645	MTH 22-Mar-2002		O/C			
282011 LEFT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1576	MTH 22-Mar-2002		O/C			
282011 LEFT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1593	MTH 22-Mar-2002		O/C			
282011 LEFT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1589	MTH 22-Mar-2002		O/C			
282011 RIGHT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1603	MTH 22-Mar-2002		O/C			
282011 RIGHT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1580	MTH 22-Mar-2002		O/C			
282011 RIGHT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1579	MTH 22-Mar-2002		O/C			
282012 LEFT	FUEL BOOST CARTRIDGE *CF			LR55505 B576	MTH 22-Mar-2002		O/C			

282012A : L

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
282012 LEFT WING	BOOST FUEL ELECTRIC PUMP 9914421-2	*CF		LR55540 B567	MTH 22-Mar-2002		O/C			
282012 RIGHT	FUEL BOOST CARTRIDGE 9914421-2	*CF		LR55505 B618	MTH 22-Mar-2002		O/C			
282012A : R										
282012 RIGHT WING	BOOST FUEL ELECTRIC PUMP 9914421-2	*CF		LR55540 B605	MTH 22-Mar-2002		O/C			
282013 LEFT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 537	MTH 22-Mar-2002		O/C			
282013 RIGHT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 538	MTH 22-Mar-2002		O/C			
282014	FUEL CROSSFEED ACTUATOR 9914423-2	*CF		MA20A1029-1 U08999	MTH 22-Mar-2002		O/C			
282100 LEFT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE 9914423-4	*CF		80002-101 1225	MTH 22-Mar-2002		O/C			
282100 RIGHT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE 9914423-4	*CF		80002-101 1221	MTH 22-Mar-2002		O/C			
282106	FUEL CROSSFEED VALVE 9914423-4	*CF		125838AW U06199	MTH 22-Mar-2002		O/C			
282108 LEFT	MOTIVE FLOW SHUTOFF (UY009) VALVE KALN			4151 044	MTH 25-Feb-2012 HRS 5198.4 LDG 3368		O/C	0 0 0		
282108 RIGHT	MOTIVE FLOW SHUTOFF (UY008) VALVE LIT			4151 1842	MTH 21-Nov-2014 HRS 6492.9 LDG 4202		O/C	0 0 0		
282118 LEFT	FUEL SHUT-OFF VALVE 9914094-1	*CF		71498 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
282118 RIGHT	FUEL SHUT-OFF VALVE 9914094-1	*CF		71498 877	MTH 22-Mar-2002		O/C			
282200 LEFT	LOW LEVEL VALVE ASSY 9914094-1	*CF		726400-1 494	MTH 22-Mar-2002		O/C			
282200 RIGHT	LOW LEVEL VALVE ASSY 9914094-1	*CF		726400-1 495	MTH 22-Mar-2002		O/C			
282201	VALVE-REFUEL/DEFUEL 9914095-30	*CF		9036-351-2 644	MTH 22-Mar-2002		O/C			
282202 LEFT	FUEL VALVE ASSY 9914095-30	*CF		750800-2 633E	MTH 22-Mar-2002		O/C			
282202 RIGHT	FUEL VALVE ASSY 9914095-30	*CF		750800-2 627E	MTH 22-Mar-2002		O/C			
284011	FUEL TEMPERATURE (EI014) INDICATOR 9914095-30	*CF		10583N01T00 447	MTH 22-Mar-2002		O/C			
284012 LEFT	LOW FUEL LEVEL SENSOR KALN			L16H-15 383	MTH 24-Feb-2012 HRS 5198.4 LDG 3368		O/C	0 0 0		
284012 RIGHT	LOW FUEL LEVEL SENSOR 9914427-2	*CF		GIF5400-43 899	MTH 22-Mar-2002		O/C			
284013 LEFT WING	FUEL QTY W0 PROBE 9912498-8	*CF		10634T07Y00 989	MTH 22-Mar-2002		O/C			
284013 RIGHT WING	FUEL QTY W0 PROBE 9912498-8	*CF		10634T07Y00 984	MTH 22-Mar-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
284014 LEFT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 1011	MTH 22-Mar-2002		O/C			
284014 RIGHT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 1014	MTH 22-Mar-2002		O/C			
284015 LEFT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 993	MTH 22-Mar-2002		O/C			
284015 RIGHT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 987	MTH 22-Mar-2002		O/C			
284016 LEFT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 B1164	MTH 22-Mar-2002		O/C			
284016 RIGHT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 B1103	MTH 22-Mar-2002		O/C			
284017 LEFT WING	FUEL QTY W4 PROBE 9912498-4	*CF		10634T05Y00 B1135	MTH 22-Mar-2002		O/C			
284017 RIGHT WING	FUEL QTY W4 PROBE 9912498-4	*CF		10634T05Y00 B1120	MTH 22-Mar-2002		O/C			
284018 LEFT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 B1138	MTH 22-Mar-2002		O/C			
284018 RIGHT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 B1113	MTH 22-Mar-2002		O/C			
284019 LEFT WING	FUEL QTY W6 PROBE 9912498-6	*CF		10634T06Y00 B1128	MTH 22-Mar-2002		O/C			
284019 RIGHT WING	FUEL QTY W6 PROBE 9912498-6	*CF		10634T06Y00 B1132	MTH 22-Mar-2002		O/C			
284196	FUEL QUANTITY SIGNAL CONDITIONER 9912498-7	*CF		10635B01Y01 01100815	MTH 22-Mar-2002		O/C			
291001	HYDRAULIC RESERVOIR 9912542-1	*CF		7470 338	MTH 22-Mar-2002		O/C			
291002 LEFT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 3628	MTH 22-Mar-2002		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 3509	MTH 22-Mar-2002		O/C			
291005 LEFT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 5439	MTH 22-Mar-2002		O/C			
291005 RIGHT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 5440	MTH 22-Mar-2002		O/C			
291008	SPEED BRAKE THERMAL RELIEF VALVE *CF			OAS5322-3-1700 1075	MTH 22-Mar-2002		O/C			
291009	HYD RELIEF VALVE	ICT		4614 1443A	MTH 22-Mar-2004 HRS 1016		O/C	0		
291010	HYD PRESS SWITCH *CF			1106P59 3876	MTH 22-Mar-2002		O/C			
291012	HYD BYPASS VALVE *CF			61510-1 1909A	MTH 22-Mar-2002		O/C			
291013 LEFT	FIREWALL HYD SHUTOFF VALVE *CF			AV24B1325C5 U02948	MTH 22-Mar-2002		O/C			
291013 RIGHT	FIREWALL HYD SHUTOFF VALVE ICT			AV24B1325C5 U09826	MTH 22-Mar-2004 HRS 1016		O/C	361		
301001 LEFT WING	ANTI-ICE BLEED AIR UNDER TEMP SL013 SWITCH *CF			1173T42-4 1715	MTH 22-Mar-2002		O/C			
301001 RIGHT WING	ANTI-ICE BLEED AIR UNDER TEMP SR016 SWITCH *CF			1173T42-4 1723	MTH 22-Mar-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
301002	ISOLATION VALVE 9912403-2	*CF		2602-36 677	MTH 22-Mar-2002		O/C			
301008 LEFT	DEICE TAIL VALVE	LIT		3D2353-06* N031706	MTH 22-Dec-2011 HRS 5127.6 LDG 3316		O/C	0 0 0		
301008 RIGHT	DEICE TAIL VALVE	LIT		3D2353-06* N031710	MTH 22-Dec-2011 HRS 5127.6 LDG 3316		O/C	0 0 0		
301020	WINDSHIELD RAIN REMOVAL MN001 FAN LIT			011598-501 C00320292	MTH 23-Nov-2010 HRS 4457.9 LDG 2851		O/C	0		
301137 LEFT WING	INLET ANTI-ICE PRESSURE REG SHUTOFF VD001 VALVE 9912495-1	LIT		1962-00-7 1111	MTH 13-Nov-2014 HRS 6489.2 LDG 4197		O/C	1 0		
301137 RIGHT WING	INLET ANTI-ICE PRESSURE REG SHUTOFF VE002 VALVE 9912495-1	*CF		1962-00-7 1289	MTH 22-Mar-2002		O/C			
301201 LEFT	TAIL DEICE PRESSURE SV005 SWITCH LIT			1106P55-1 9296A	MTH 22-Dec-2011 HRS 5127.6 LDG 3316		O/C	0 0 0		
301201 RIGHT	TAIL DEICE PRESSURE SV004 SWITCH LIT			1106P55-1 9260A	MTH 22-Dec-2011 HRS 5127.6 LDG 3316		O/C	0 0 0		
301202 LEFT	HORIZ STAB DEICE BOOT KALN			P29S4D5280-11 NAO3070	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		O/C	0 0 0		
301202 RIGHT	HORIZ STAB DEICE BOOT KILG			P29S4D5280-12 NDZ6510	MTH 13-Dec-2017 HRS 7625.6 LDG 4981 APUH 3436 APUS 5678		O/C	0 0		
302101 LEFT	PRESSURE REG VALVE 9912495-4	LBG		1946-00-19 2641	MTH 07-Aug-2003 HRS 725		O/C	725		
302101 RIGHT	PRESSURE REG VALVE 9912495-4	LIT		1946-00-19 3815	MTH 03-Apr-2008 HRS 3055		O/C	0		
302104 LEFT	NACELLE INLET SWITCH LIT			1173T0759 1386	MTH 27-Apr-2017		O/C			
302104 RIGHT	NACELLE INLET SWITCH LIT			1173T0759 1352	MTH 27-Apr-2017		O/C			
303001 LEFT	PITOT TUBE	*CF		PH1100-1-VCW B6192	MTH 22-Mar-2002		O/C			
303001 RIGHT	PITOT TUBE	*CF		PH1100-1-VCW B6200	MTH 22-Mar-2002		O/C			
303001 STANDBY	PITOT TUBE	*CF		PH1100-1-RCDW B6467	MTH 22-Mar-2002		O/C			
304100 LEFT	WINDSHIELD CONTROLLER 9914411-1	*CF		856-1-1 0143217	MTH 22-Mar-2002		O/C			
304100 RIGHT	WINDSHIELD CONTROLLER 9914411-1	*CF		856-1-1 0143216	MTH 22-Mar-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
302005 E1	ANTI-ICING VALVE 31J2879-04	UNK		540-0406-4 2707	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C			
302005 E2	ANTI-ICING VALVE	DMO		31J2879-04 2864	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	0 2055.3 0		
312001 LEFT HAND	DIGITAL CLOCK	*CF		M877A5V 13083	MTH 22-Mar-2002		O/C			
312001 RIGHT HAND	DIGITAL CLOCK	*CF		M877A5V 13088	MTH 22-Mar-2002		O/C			
313001	FDR ACCELEROMETER	*CF		3001-01-101-3 06012921	MTH 22-Mar-2002		O/C			
313003 LEFT	ENGINE ACCELEROMETER	*CF		6222SM15 18138	MTH 22-Mar-2002		O/C			
313003 RIGHT	ENGINE ACCELEROMETER	*CF		6222SM15 18286	MTH 22-Mar-2002		O/C			
313008	FDR IMPACT SWITCH	*CF		6895-D-1-X-5-5 3202	MTH 22-Mar-2002		O/C			
313009	FDR CONVERTER	*CF		1226-1-1 0137159	MTH 22-Mar-2002		O/C			
315001	FDR FAIL ANNUNCIATOR	*CF		1304-1-12 0143224	MTH 22-Mar-2002		O/C			
315101 LEFT	WARNING GEN/MIXER UNIT	LIT		1287-1-2 206460243	MTH 23-Mar-2012 HRS 5233.3 LDG 3395		O/C			
315101 RIGHT	WARNING GEN/MIXER UNIT	KALN		1287-1-2 0031343	MTH 24-Feb-2012 HRS 5198.4 LDG 3368		O/C			
316001	TILT INDICATOR	*CF		3001J72 21960	MTH 22-Mar-2002		O/C			
321003 LEFT MAIN LANDING GEAR	TRUNNION	*CF		6641630-5 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		6900	0	6900	1883
321003 RIGHT MAIN LANDING GEAR	TRUNNION	*CF		6641630-6 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		6900	0	6900	1883
321004 LEFT MAIN LANDING GEAR	TRAILING LINK	*CF		6641648-15 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		40300	0	40300	35283
321004 RIGHT MAIN LANDING GEAR	TRAILING LINK	*CF		6641648-14 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		40300	0	40300	35283
321011 LEFT MAIN LANDING GEAR	TRAILING LINK SPACER	*CF		6641533-1 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		33300	0	33300	28283
321011 RIGHT MAIN LANDING GEAR	TRAILING LINK SPACER	*CF		6641533-1 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		33300	0	33300	28283
321020 LEFT MAIN LANDING GEAR	BREATHER VENT	BTL		QSB-5-SS SN-UNKNOWN	MTH 08-Mar-2018 HRS 7677.6 LDG 5017		12 600	0 0 0	31-Mar-2019 8277.6	12 m 13 d 600
321020 RIGHT MAIN LANDING GEAR	BREATHER VENT	BTL		QSB-5-SS SN-UNKNOWN	MTH 08-Mar-2018 HRS 7677.6 LDG 5017		12 600	0 0 0	31-Mar-2019 8277.6	12 m 13 d 600
322001 NOSE	LANDING GEAR ASSEMBLY	*CF		6642614-1 BMC173	MTH 22-Mar-2002 LDG 0		33300	0	33300	28283

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
322002 NOSE GEAR	SHIMMY DAMPER	LIT		5543001-11 122211X	MTH 04-Aug-2006 HRS 2259 LDG 1360		O/C	0		
322007 NOSE GEAR	TRUNNION	*CF		6642611-9 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
323001 LEFT MAIN LANDING GEAR	ACTUATOR 9912537-3	*CF		1550000-3 541	MTH 22-Mar-2002 LDG 0		70200	0	70200	65183
323001 RIGHT MAIN LANDING GEAR	ACTUATOR 9912537-4	*CF		1550000-4 529	MTH 22-Mar-2002 LDG 0		70200	0	70200	65183
323002 : R										
323003 NOSE LANDING GEAR	ACTUATOR	KALN		9912491-6 1117	MTH 05-Dec-2015 HRS 6792 LDG 4417		33300	0	37717	32700
323004 LEFT	UPLOCK ACTUATOR	*CF		5527504-3 2323	MTH 22-Mar-2002		O/C			
323004 NOSE	UPLOCK ACTUATOR	*CF		5527504-3 2315	MTH 22-Mar-2002		O/C			
323004 RIGHT	UPLOCK ACTUATOR	*CF		5527504-3 2308	MTH 22-Mar-2002		O/C			
323005	PRESSURE EMER GEAR GAUGE	*CF		19940929-1 009454	MTH 22-Mar-2002		O/C			
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE	BTL		9912505-2 40005347-3 2375	MTH 08-Mar-2018 HRS 7677.6 LDG 5017		288		30-Apr-2023	61 m 12 d
Manufacture Date: 01-Apr-1999										
323007	LANDING GEAR CONTROL (VY047) VALVE	*CF		71839-1 329	MTH 22-Mar-2002		O/C			
323008	DUMP VALVE	*CF		OAS5319-1 1271	MTH 22-Mar-2002		O/C			
323009	LANDING GEAR CONTROL	*CF		049801-001 199	MTH 22-Mar-2002		O/C			
323010 LEFT MAIN LANDING GEAR	OLEO ASSEMBLY	KALN		6641615-6 4612	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		38000	4542	38000	32983
323010 RIGHT MAIN LANDING GEAR	OLEO ASSEMBLY	LIT		6641615-4 108	MTH 02-Mar-2012 HRS 5201.4 LDG 3374		38000	3352	38022	33005
323011 LEFT MAIN LANDING GEAR	OLEO UPPER CAP	KALN		6641616-4 NSN	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		4600	0	9142	4125
323011 RIGHT MAIN LANDING GEAR	OLEO UPPER CAP			6641616-3 SN-UNKNOWN	MTH 02-Mar-2012 HRS 5201.4 LDG 3374		4600	0	7974	2957
324001 LEFT	MAIN WHEEL ASSEMBLY	KALN		3-1571-6 1198	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324001 RIGHT	MAIN WHEEL ASSEMBLY 9912487-11	LIT		3-1571-6 0585	MTH 18-Oct-2017 HRS 7572.7 LDG 4949 APUH 3435 APUS 5677		O/C	24 0		
324002 NOSE	WHEEL ASSEMBLY 9914069-2	LIT		3-1418 6466	MTH 26-May-2017 HRS 7407 LDG 4843 APUH 3347.5 APUS 5550		O/C	10 0		
324003 LEFT	MAIN BRAKE ASSEMBLY 9912487-7	LIT		2-1601 0174	MTH 23-Mar-2012 HRS 5233.3 LDG 3395		O/C	0 0 0		
324004 RIGHT	MAIN BRAKE ASSEMBLY 9912487-7	LIT		2-1601 1555	MTH 23-Mar-2012 HRS 5233.3 LDG 3395		O/C	0 0 0		
324005 LEFT	MAIN TIRE 9912488-3	KALN		M13702 6285S187	MTH 19-Jul-2017 HRS 7461.2 LDG 4879 APUH 3371.3 APUS 5677		O/C	0 0		
324005 RIGHT	MAIN TIRE 9912488-3	LIT		M13702 4244S176	MTH 18-Oct-2017 HRS 7572.7 LDG 4949 APUH 3435 APUS 5677		O/C	0 0		
324006	NOSE TIRE 9914070-1	LIT		031-613-8 5135S000352	MTH 26-May-2017 HRS 7407 LDG 4843 APUH 3347.5 APUS 5550		O/C	0 0 0		
324009	POWER BRAKE VALVE 9912489-8	*CF		32-077-1 357	MTH 22-Mar-2002		O/C			
324010 LEFT	EXTEND/RETRACT VALVE *CF			98120 1942	MTH 22-Mar-2002		O/C			
324010 NOSE	EXTEND/RETRACT VALVE *CF			98120 1258	MTH 22-Mar-2002		O/C			
324010 RIGHT	EXTEND/RETRACT VALVE *CF			98120 1941	MTH 22-Mar-2002		O/C			
324011 LEFT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-15	*CF		98281-3 603	MTH 22-Mar-2002		O/C			
324011 RIGHT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-15	*CF		98281-3 638	MTH 22-Mar-2002		O/C			
324012 LEFT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-16	*CF		98281-4 682	MTH 22-Mar-2002		O/C			
324012 RIGHT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-16	*CF		98281-4 634	MTH 22-Mar-2002		O/C			
324014	EMERGENCY AIR BRAKE CONTROL VALVE *CF			65830-4 627	MTH 22-Mar-2002		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324015 LEFT	BRAKE SHUTTLE VALVE *CF			211-114 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
324015 RIGHT	BRAKE SHUTTLE VALVE *CF			211-114 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
324019	BRAKE PRESS PUMP ASSEMBLY 9912166-3 *CF			640931 5744	MTH 22-Mar-2002		O/C			
324020	ANTISKID CONTROL (UY009) VALVE 9912489-4 *CF			39-837 379	MTH 22-Mar-2002		O/C			
324022	ANTISKID DIGITAL CONTROL 9912489-9 *CF			42-985-2 360	MTH 22-Mar-2002		O/C			
324023	POWER BRAKE ACCUMULATOR *CF			57C57652 1530	MTH 22-Mar-2002		O/C			
324024 LEFT	WHEEL TRANSDUCER 9912305-2 *CF			40-955 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
324024 RIGHT	WHEEL TRANSDUCER 9912305-2 *CF			40-955 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
324025	PRESSURE (SN011) SWITCH *CF			GPP1250-52 132343	MTH 22-Mar-2002		O/C			
324026	POWER PACK MOTOR LIT			MP50B1 2683	MTH 31-Aug-2010 HRS 4330 LDG 2751		O/C	1 0		
324027	ANTISKID FAULT DISPLAY 9912305-9 *CF			42-92750 959A	MTH 22-Mar-2002		O/C			
324101	PARKING BRAKE VALVE 9912388-2 *CF			95905 1094A	MTH 22-Mar-2002		O/C			
324153 3242153	PRESS ANTISKID BRK SWITCH *CF			GPP1250-73 129031	MTH 22-Mar-2002		O/C			
324200 324201	ANTISKID PRESSURE GAUGE *CF			19940929-1 9494	MTH 22-Mar-2002		O/C			
324206	ANTISKID HYD RELIEF VALVE *CF			1785-2 339	MTH 22-Mar-2002		O/C			
326005 LEFT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
326005 RIGHT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
326005	NOSE GEAR UP & LOCKED (SN001) SWITCH *CF			65-430087 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
331001 CENTER	5 VDC UN004 DIMMER POWER SUPPLY *CF			273-1 0122114	MTH 22-Mar-2002		O/C			
331001 LEFT	5 VDC UN002 DIMMER POWER SUPPLY *CF			273-1 0122111	MTH 22-Mar-2002		O/C			
331001 RIGHT	5 VDC UN006 DIMMER POWER SUPPLY *CF			273-1 0122123	MTH 22-Mar-2002		O/C			
331011	EL PANEL INVERTER *CF			EM2044-1 3518A	MTH 22-Mar-2002		O/C			
332001 LEFT NO. 1	LIGHT POWER SUPPLY *CF			AL750PS 14736	MTH 22-Mar-2002		O/C			
332001 LEFT NO. 2	LIGHT POWER SUPPLY *CF			AL750PS 14748	MTH 22-Mar-2002		O/C			
332001 LEFT NO. 3	LIGHT POWER SUPPLY *CF			AL750PS 14738	MTH 22-Mar-2002		O/C			
332001 LEFT NO. 4	LIGHT POWER SUPPLY KALN			AL750PS 8546	MTH 07-Mar-2013 HRS 5742.1 LDG 3814		O/C			
332001 LEFT NO. 5	LIGHT POWER SUPPLY *CF			AL750PS 14734	MTH 22-Mar-2002		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
332001 LEFT NO. 6	LIGHT POWER SUPPLY *CF			AL750PS 14737	MTH 22-Mar-2002		O/C			
332001 LEFT NO. 7	LIGHT POWER SUPPLY KALN			AL750PS 27281	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C	0 0		
332001 LEFT NO. 8	LIGHT POWER SUPPLY KALN			AL750PS 27153	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C	0 0		
332001 LEFT NO. 9	LIGHT POWER SUPPLY *CF			AL750PS 14735	MTH 22-Mar-2002		O/C			
332001 RIGHT NO. 10	LIGHT POWER SUPPLY *CF			AL750PS 14760	MTH 22-Mar-2002		O/C			
332001 RIGHT NO. 1	LIGHT POWER SUPPLY *CF			AL750PS 14757	MTH 22-Mar-2002		O/C			
332001 RIGHT NO. 2	LIGHT POWER SUPPLY *CF			AL750PS 14759	MTH 22-Mar-2002		O/C			
332001 RIGHT NO. 3	LIGHT POWER SUPPLY *CF			AL750PS 14761	MTH 22-Mar-2002		O/C			
332001 RIGHT NO. 4	LIGHT POWER SUPPLY *CF			AL750PS 14742	MTH 22-Mar-2002		O/C			
332001 RIGHT NO. 5	LIGHT POWER SUPPLY *CF			AL750PS 14753	MTH 22-Mar-2002		O/C			
332001 RIGHT NO. 6	LIGHT POWER SUPPLY *CF			AL750PS 14735	MTH 22-Mar-2002		O/C			
332001 RIGHT NO. 7	LIGHT POWER SUPPLY *CF			AL750PS 14763	MTH 22-Mar-2002		O/C			
332001 RIGHT NO. 8	LIGHT POWER SUPPLY KALN			AL750PS 27190	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C	0 0		
332001 RIGHT NO. 9	LIGHT POWER SUPPLY *CF			AL750PS 14746	MTH 22-Mar-2002		O/C			
332002	GLARESHIELD INVERTER *CF		A	6900173 3666	MTH 22-Mar-2002		O/C			
334001	PULSE LITE CONTROL LIT			2401S AR01679	MTH 27-Apr-2013 HRS 5812 LDG 3845		O/C	0 0 0		
334002	EMPENNAGE LIGHT ASSY *CF			01-0790044-37 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
334006 LEFT	STROBE POWER SUPPLY *CF			01-0790101-05 00585	MTH 22-Mar-2002		O/C			
334006 RIGHT	STROBE POWER SUPPLY *CF			01-0790101-05 00595	MTH 22-Mar-2002		O/C			
335001 AFT	EMERGENCY LIGHTING UC020 BATTERY PACK KALN			9913-1 303	MTH 30-Jul-2014 HRS 6398.9 LDG 4127		O/C			
335001 FORWARD	EMERGENCY LIGHTING UC019 BATTERY PACK KALN			9913-1 2022	MTH 30-Jul-2014 HRS 6398.9 LDG 4127		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
341009	SAFE FLIGHT AOA UF004 SENSOR *CF			C-12717-1 728	MTH 22-Mar-2002		O/C			
341010	SAFE FLIGHT AOA EI001 INDICATOR *CF			C12705-1 584	MTH 22-Mar-2002		O/C			
341011	SAFE FLIGHT AOA UC009 COMPUTER *CF			C13006-2 666	MTH 22-Mar-2002		O/C			
341014	SAFE FLIGHT AOA FI003 INDEXER *CF			C12763-1 488	MTH 22-Mar-2002		O/C			
341016 SECONDARY	ADU	LIT		27101-01-01 M010943	MTH 25-Mar-2011 HRS 4635.9 LDG 2976		O/C	0 0 0		
341017	MEGGITT SECONDARY FLIGHT (EI016) DISPLAY LIT	5		38102-00-01 M008861	MTH 25-Apr-2014 HRS 6273.5 LDG 4045		O/C	2 0 0		
341025	RAM AIR TEMP DISPLAY 9912552-3	*CF	1	65018-005 116553	MTH 22-Mar-2002		O/C			
341101	DIFFERENTIAL PRESSURE SWITCH TEB			D45C-24 1495	MTH 14-May-2012 HRS 5326 LDG 3448		O/C	0 0 0		
341107 NO. 1	(PILOT) AIR DATA COMPUTER AZ-850	LIT		7014700-914 02066336	MTH 25-Mar-2011 HRS 4635.9 LDG 2976		O/C			
341107 NO. 2	(COPILOT) AIR DATA COMPUTER AZ-850	LIT		7014700-914 02106649	MTH 25-Mar-2011 HRS 4635.9 LDG 2976		O/C			
342001 STANDBY	MAGNETIC COMPASS C2400-L4V2W-5B	LIT		C660501-0301 N/A	MTH 21-Jan-2011 HRS 4528.1 LDG 2906		O/C	0 0		
342023	RADAR CONTROLLER WC-880	*CF		7008471-407 01106368	MTH 22-Mar-2002		O/C			
342050 LEFT	FLUX DETECTOR FX-220	ICT		2594484 04016141	MTH 22-Mar-2004 HRS 1016		O/C	0		
342050 RIGHT	FLUX DETECTOR FX-220	*CF		2594484 1104950	MTH 22-Mar-2002		O/C			
342053	AERONETICS HSI-15 STANDBY HORIZONTAL SITUATION INDICATOR HSI-315B	*CF	B	520-3151-003 21041	MTH 22-Mar-2002		O/C			
342064	GYRO 2 (PS-835) BATTERY PACK PS-835	BTL		501-1228-04 80950	MTH 08-Mar-2018 HRS 7677.6 LDG 5017		O/C	0 0 0		
342065 NO. 1	AHRS 1 BATTERY PACK PS-835	BTL		501-1228-04 14610	MTH 08-Mar-2018 HRS 7677.6 LDG 5017		O/C	6238.6		
342069	HONEYWELL PRIMUS 1000 EFIS MC800 MULTIFUNCTION DISPLAY CONTROLLER MC-800	LIT	B	7007062-941 94081401	MTH 17-Oct-2016 HRS 7064.3 LDG 4605 APUH 3196.9 APUS 5319		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342072	MEGGITT STATIC CONVERTER *CF	6		501-1318-01 5099	MTH 22-Mar-2002		O/C			
342082 LEFT	LITEF LCR-93 AHRS TRAY *CF			140691 1704	MTH 22-Mar-2002		O/C			
342082 RIGHT	LITEF LCR-93 AHRS TRAY *CF			140691 1707	MTH 22-Mar-2002		O/C			
342083 LEFT	AHRS COMPUTER LIT			142185-1100 1939	MTH 16-Jun-2011 HRS 4755.2 LDG 3067		O/C	0 0 0		
342083 RIGHT	AHRS COMPUTER LIT			142185-3100 1148	MTH 18-Sep-2009 HRS 3809		O/C	2963		
342104 LEFT	MSU CALIBRATION PROM UNIT *CF			124282 2769	MTH 22-Mar-2002		O/C			
342104 RIGHT	MSU CALIBRATION PROM UNIT *CF			124282 2762	MTH 22-Mar-2002		O/C			
342500	HONEYWELL PRIMUS 1000 EFIS RI553 REMOTE INSTRUMENT CONTROLLER RI-553 LIT			7016954-907 00011049	MTH 09-Feb-2005 HRS 1474		O/C	1172		
342502	HONEYWELL PRIMUS 1000 EFIS BL871 BEZEL CONTROLLER BL-871 *CF			7014332-841 01105880	MTH 22-Mar-2002		O/C			
342503 COPILOT	FLT DISPLAY CONTROLLER BL-870 *CF			7014331-931 01114360	MTH 22-Mar-2002		O/C			
342503 PILOT	HONEYWELL PRIMUS 1000 EFIS BL870 BEZEL CONTROLLER BL-870 *CF			7014331-931 01114405	MTH 22-Mar-2002		O/C			
342504 COPILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER DC-550 *CF	D		7016986-747 01124224	MTH 22-Mar-2002		O/C			
342504 PILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER DC-550 *CF	D		7016986-747 01124205	MTH 22-Mar-2002		O/C			
342505 NO.1	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 INTEGRATED AVIONICS COMPUTER IC-600 ALN			7017000-82360 01024107	MTH 23-Jul-2008 HRS 3204		O/C	0		
342505 NO.2	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 INTEGRATED AVIONICS COMPUTER IC-600 ALN			7017000-83360 01105068	MTH 23-Jul-2008 HRS 3204		O/C	0		
342506	HONEYWELL PRIMUS 1000 EFIS MS560 MODE SELECTOR UNIT MS-560 LIT			7018341-803 03012299	MTH 03-Apr-2009 HRS 3551		O/C	1081		
342509 COPILOT 342501 : R	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-870 *CF	H		7014300-901 0111A609	MTH 22-Mar-2002		O/C			
342509 PILOT 342501 : L	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-870 KMKE	H		7014300-901 0804H126	MTH 20-Sep-2016 HRS 7055.6 LDG 4585		O/C			
342510 CENTER 342501 : CNTR	ELECTRONIC DISPLAY UNIT DU-870 *CF		H	7014300-901 0112A77	MTH 22-Mar-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
343001 NAVIGATION 343001A	ANTENNA COUPLER	ALN		CI-120-5 235670	MTH HRS		23-Jul-2008 3204	O/C 0		
343001	GLIDESLOPE ANTENNA COUPLER	*CF		CI503 1092140	MTH		22-Mar-2002	O/C		
343002 343001 : B	MARKER BEACON ANTENNA COUPLER	*CF		CI509 1073558	MTH		22-Mar-2002	O/C		
344005	RADAR TRANSCEIVER	L		7021450-801 01113581	MTH		22-Mar-2002	O/C		
344022	RADIO ALTIMETER ALT-55B TRANSCEIVER	*CF	11	622-2855-011 HHWN	MTH		22-Mar-2002	O/C		
344023 AFT	RADIO ALT RECEIVER ANTENNA	*CF		S67-2002 23596	MTH		22-Mar-2002	O/C		
344023 FORWARD	RADIO ALT TRANSMITTER ANTENNA	*CF		S67-2002 23595	MTH		22-Mar-2002	O/C		
344024	EGPWS COMPUTER	*CF	1	965-0976-040-204-204 S2800-422 1070	MTH		22-Mar-2002	O/C		
345004 LEFT NO. 1	XPNDR BOTTOM ANTENNA	*CF		DMNI50-2-2 83724	MTH		22-Mar-2002	O/C		
345004 RIGHT NO. 2	XPNDR BOTTOM ANTENNA	*CF		DMNI50-2-2 81741	MTH		22-Mar-2002	O/C		
345005 LEFT NO. 1	TOP TRANSPONDER DIVERSITY ANTENNA	*CF		85226 DMNI50-2-2 82210	MTH		22-Mar-2002	O/C		
345005 RIGHT NO. 2	TOP TRANSPONDER DIVERSITY ANTENNA	*CF		85226 DMNI50-2-2 82203	MTH		22-Mar-2002	O/C		
345007 NO.1	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA	*CF		85226 DMNI50-2-2 83714	MTH		22-Mar-2002	O/C		
345007 NO.2	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA	*CF		85226 DMNI50-2-2 82105	MTH		22-Mar-2002	O/C		
345011 NO. 1	ADF RECEIVER MODULE	K		7510114-901 DF-850 01105187	MTH		22-Mar-2002	O/C		
345011 NO. 2	ADF RECEIVER MODULE	A		7510112-901 01100518	MTH		22-Mar-2002	O/C		
345014 NO. 1	ADF ANTENNA	*CF		7510300-901 AT-860 01105926	MTH		22-Mar-2002	O/C		
345017	MARKER BEACON ANTENNA	*CF		31-10-01 4028	MTH		22-Mar-2002	O/C		
345018	GLIDESLOPE ANTENNA	*CF		RGS10-48 A8173	MTH		22-Mar-2002	O/C		
345029 NO. 1	NAV CLUSTER MODULE	E		7510164-921 XN-850 01106329	MTH		22-Mar-2002	O/C		
345029 NO. 2	NAV CLUSTER MODULE	E		7510164-921 XN-850 01106369	MTH		22-Mar-2002	O/C		
345032 NO. 1	VHF NAV RECEIVER	ICT		7510134-731 NV-850 01106479	MTH HRS		22-Mar-2004 1016	O/C 0		
345032 NO. 2	VHF NAV RECEIVER	ICT		7510134-731 NV-850 01106489	MTH HRS		22-Mar-2004 1016	O/C 0		
345034 NO. 1	ATC TRANSPONDER	LIT	E	7517400-902 XS-852 01014815	MTH HRS LDG		25-Mar-2011 4635.9 2976	O/C		



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345034 NO. 2	ATC TRANSPONDER XS-852	LIT	E	7517400-902 01116106	MTH 25-Mar-2011 HRS 4635.9 LDG 2976		O/C			
345036 NO. 1	DME INTERROGATOR DM-850	LIT		7510184-902 00034144	MTH 21-Dec-2007 HRS 2897		O/C	1881		
345036 NO. 2	DME INTERROGATOR DM-850	*CF	K	7510184-902 01106052	MTH 22-Mar-2002		O/C			
345038 NO. 1	INTEGRATED NAV UNIT RNZ-850	KALN		7510100-731 01035167	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		O/C			
345038 NO. 2	INTEGRATED NAV UNIT RNZ-850B	KALN		7510100-733 01106159	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		O/C			
345066	DATA INTERFACE UNIT UL-601 UNILINK	LIT		1066-10-000 595	MTH 16-May-2007 HRS 2580		O/C	0		
345077	DATA TRANSFER UNIT DTU-100	*CF	1	1406-01-1 1599	MTH 22-Mar-2002		O/C			
345079 NO. 1	GPS FLT MGMT COMPUTER UNS-1CSP	KALN		1019-41-201 661	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C			
345079 NO. 2	GPS FLT MGMT COMPUTER UNS-1CSP	KALN		1019-41-201 639	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C			
345088 NO. 1	RADIO MANAGEMENT UNIT KLIT			7013270-963 12048248	MTH 29-Nov-2012 HRS 5616.7 LDG 3640		O/C	0 0 0		
345088 NO. 2	RADIO MANAGEMENT UNIT KLIT			7013270-963 12048257	MTH 29-Nov-2012 HRS 5616.7 LDG 3640		O/C	0 0 0		
345093 NO.1	GPS ANTENNA ANTENNA	*CF		10706 7177	MTH 22-Mar-2002		O/C			
345093 NO.2	GPS ANTENNA ANTENNA	*CF		10706 7219	MTH 22-Mar-2002		O/C			
345201 LEFT	NAV ANTENNA CI120-200G/S-L	ALN		CI120-1-L 234208	MTH 23-Jul-2008 HRS 3204		O/C	0		
345201 RIGHT	NAV ANTENNA CI120-200G/S-L	ALN		CI120-1-L 234209	MTH 23-Jul-2008 HRS 3204		O/C	0		
345301 LEFT	DME INDICATOR DI-851	*CF	A	7513006-911 01102346	MTH 22-Mar-2002		O/C			
345301 RIGHT	DME INDICATOR DI-851	*CF	A	7513006-911 01102347	MTH 22-Mar-2002		O/C			
346001	TCAS PROCESSOR TPU-67A	LIT	26	066-01146-1211 42685	MTH 12-Jun-2012 HRS 5381.5 LDG 3486		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
346002 BOTTOM	TCAS ANTENNA ANT-67A	*CF		071-01548-0100 10747	MTH 22-Mar-2002		O/C			
346002 TOP	TCAS ANTENNA ANT-67A	*CF		071-01548-0200 8968	MTH 22-Mar-2002		O/C			
346012 346006	TCAS II MODULE	*CF		071-00097-1000 3326	MTH 22-Mar-2002		O/C			
351001	OXYGEN PRESSURE (EI002) GAGE MD-97	*CF		C668512-0101 L21205	MTH 22-Mar-2002		O/C			
351004 COPILOT	OXYGEN MASK	LIT		MC10-16-100 110880	MTH 02-Jan-2013 HRS 5656.9 LDG 3665		72	3	31-Oct-2018	7 m 13 d
351004 PILOT	OXYGEN MASK	KALN		MC10-16-100 98294	MTH 30-Jul-2014 HRS 6398.9 LDG 4127		72	3	30-Apr-2020	25 m 12 d
351006	OXYGEN CYLINDER	KALN		804882-14 C16080705	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		180		31-Aug-2031	161 m 13 d
Manufacture Date: 01-Aug-2016										
351007	OXYGEN REGULATOR	*CF		804881-01 563	MTH 22-Mar-2002		O/C	0		
351008	PASSENGER OXYGEN CONTROL VALVE 9914067-19	*CF		P21006 1561	MTH 22-Mar-2002		O/C			
352001	PASSENGER OXYGEN ALTITUDE PRESSURE SWITCH	*CF		P24032 363	MTH 22-Mar-2002		O/C			
361010	DOOR SOLENOID VALVE	*CF		5035-00-1 499	MTH 22-Mar-2002		O/C			
361011 LEFT	HEAT EXCHANGER ACTUATOR 9914519-4	LIT		1E50-2 2AU41	MTH 06-Feb-2009 HRS 3466		O/C	0		
361011 RIGHT	HEAT EXCHANGER ACTUATOR 9914519-4	LIT		1E50-2 10AU285	MTH 06-Feb-2009 HRS 3466		O/C	3466		
361100 LEFT	BLEED AIR TEMPERATURE (ST021) SWITCH	*CF		1173T0635 3262	MTH 22-Mar-2002		O/C			
361100 RIGHT	BLEED AIR TEMPERATURE (ST020) SWITCH	*CF		1173T0635 3306	MTH 22-Mar-2002		O/C			
361101 LEFT	BLEED AIR OVERTEMP (ST017) SWITCH 9914149-2	*CF		1173T181-2 1476	MTH 22-Mar-2002		O/C			
361101 RIGHT	BLEED AIR OVERTEMP (ST014) SWITCH 9914149-2	*CF		1173T181-2 1472	MTH 22-Mar-2002		O/C			
361102 LEFT	BLEED AIR MANIFOLD TEMPERATURE (TT001) SENSOR 9914519-2	LIT		1E51-1 4BC219	MTH 25-Feb-2008		O/C			
361102 RIGHT	BLEED AIR MANIFOLD TEMPERATURE (TT002) SENSOR 9914519-2	*CF		1E51-1 11AU420	MTH 22-Mar-2002		O/C			
361103 LEFT	HEAT B/A EXCHANGER 9912486-2	ALN		8230-2 S4883T1474	MTH 23-Jul-2008 HRS 3204		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
361103 RIGHT	HEAT B/A EXCHANGER 9912486-2	KALN		8230-2 S4883T3024	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C	0 0		
361104 LEFT	PRECOOLER VD003 VALVE *CF			1407-10 507A	MTH 22-Mar-2002		O/C			
361104 RIGHT	PRECOOLER VD003 VALVE *CF			1407-10 506A	MTH 22-Mar-2002		O/C			
361208 NO. 1	APU CHECK VALVE 9914171-1	*CF		8C210 3081	MTH 22-Mar-2002		O/C			
361208 NO. 2	APU CHECK VALVE 9914171-1	*CF		8C210 3051	MTH 22-Mar-2002		O/C			
361500 NO. 1	B/A CHECK VALVE 9914171-1	*CF		8C210 3071	MTH 22-Mar-2002		O/C			
361500 NO. 2	B/A CHECK VALVE 9914171-1	*CF		8C210 3075	MTH 22-Mar-2002		O/C			
361534	SERVICE AIR REGULATOR 9912510-1	*CF		1H75-18 10AU131	MTH 22-Mar-2002		O/C			
49APU1 490000	APU 9912484-1	LIT		3800722-1 P292	MTH 10-May-2012 HRS 5318.3 LDG 3445		E/C	2476.4		
490001	APU ELECTRONIC CONTROL LIT			2119552-4 128-LO484	APUH 18-Sep-2015 APUS 3076.8 5128		O/C			
490003	BLEED AIR SHUTOFF VALVE 9914047-1	BTL		50230-8 0619E	APUH 08-Mar-2018 3452.3		O/C	0 0		
490004	DC AMMETER S3439-3	*CF		MD144-3 K21309	22-Mar-2002		O/C			
490005	OVERHEAT DETECTOR 9912416-1	*CF		3001-212-1004/455-9 204035	22-Mar-2002		O/C			
490006	HOURLY METER C664503-0104 SN-UNKNOWN	*CF			22-Mar-2002		O/C			
492003	COMPRESSOR ROTOR UNK			3822523-003 010350102196	APUH 05-May-2012 APUS 2476.4 4084		12000	2476.4 4084	12000	6322
492004	TURBINE ROTOR UNK			3842340-2 12-156101-00333	APUH 05-May-2012 APUS 2476.4 4084		4000	0 0 0	8084	2406
493000	FUEL CONTROL ASSEMBLY UNK			3883900-1 0000142	APUH 05-May-2012 APUS 2476.4 4084		O/C	1389.4		
493001	TEE-FLOW DIVIDER VALVE *CF			3883921-2 SN-UNKNOWN	22-Mar-2002		O/C			
493002	FUEL SHUT-OFF VALVE PN SN-UNKNOWN				22-Mar-2002		O/C	0		
494000	ELECTRICAL IGNITER LEAD *CF			3888302-20 SN-UNKNOWN	22-Mar-2002		O/C			
494001	IGNITER PLUG LIT			304634-2 N/A	18-Jan-2017		O/C	0		
494002	IGNITION UNIT UNK			3888000-7 010218024590	APUH 05-May-2012 APUS 2476.4 4084		O/C	2476.4 4084		



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
497006	RPM/MAX INDICATOR *CF			M453 SN-UNKNOWN	22-Mar-2002		O/C			
499000	LOW OIL PRESSURE SWITCH *CF			3876351-1 010922700423	22-Mar-2002		O/C			
499001	LUBE PUMP ASSEMBLY UNK			3881825-1 P412	APUH 05-May-2012 APUS 2476.4 4084		O/C	2476.4 4084		
499002	OIL LEVEL SWITCH *CF			3876318-1 SN-UNKNOWN	22-Mar-2002		O/C			
521003	ACOUSTIC LOWER FWD SEAL *CF			9522-13 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
521004	ACOUSTIC UPPER SEAL LIT			9522-11 N/A	MTH 02-Jan-2013 HRS 5656.9 LDG 3665		O/C	0 0		
521005	ACOUSTIC LOWER AFT SEAL *CF			9522-15 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
527000	EMERGENCY EXIT SWITCH *CF			8-405-04 B52987	MTH 22-Mar-2002		O/C			
531001 LEFT NOSE LANDING GEAR	TRUNNION SUPPORT ASSEMBLY *CF			6613020-55 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		25500	0	25500	20483
531001 RIGHT NOSE LANDING GEAR	TRUNNION SUPPORT ASSEMBLY *CF			6613020-56 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		25500	0	25500	20483
531002 NOSE GEAR	ACTUATOR ATTACH FITTING *CF			6211190-41 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		25500	0	25500	20483
531201	RADOME ASSEMBLY LIT			6613101-833 012	MTH 14-Aug-2014 HRS 6421 LDG 4143		O/C			
561001 LEFT	MAIN WINDSHIELD 9914380-14	KALN		9914380-13 16155H3884	MTH 22-Jul-2016 HRS 6980.6 LDG 4542 APUH 3196.9 APUS 5319		O/C	0 0		
561001 RIGHT	MAIN WINDSHIELD 9914380-14	LIT		NP139731-2 08212H5231	MTH 11-Jan-2010 HRS 3974		O/C	0		
561004 LEFT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-5	*CF		NP139722-5 01228H5682	MTH 22-Mar-2002		O/C			
561004 RIGHT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-6	*CF		NP139722-6 01117H6625	MTH 22-Mar-2002		O/C			
561005 LEFT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-33	*CF		NP139703-3 735	MTH 22-Mar-2002		O/C			
561005 RIGHT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-34	*CF		NP139703-4 756	MTH 22-Mar-2002		O/C			
562001 LEFT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 LEFT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 LEFT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
562001 LEFT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 LEFT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 LEFT NO. 7	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 RIGHT NO. 1	EMERGENCY DOOR WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 RIGHT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 RIGHT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 RIGHT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 RIGHT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 RIGHT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
562001 RIGHT NO. 7	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
571001 LEFT MAIN LANDING GEAR	FORWARD TRUNNION FITTING *CF			6622123-1 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		23800	0	23800	18783
571001 RIGHT MAIN LANDING GEAR	FORWARD TRUNNION FITTING *CF			6622123-2 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		23800	0	23800	18783
571002 LEFT MAIN LANDING GEAR	AFT TRUNNION FITTING *CF			6622124-1 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		23800	0	23800	18783
571002 RIGHT MAIN LANDING GEAR	AFT TRUNNION FITTING *CF			6622124-2 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		23800	0	23800	18783
571003 LEFT MAIN LANDING GEAR	ACTUATOR FITTING ASSEMBLY *CF			6621125-5 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		23800	0	23800	18783
571003 RIGHT MAIN LANDING GEAR	ACTUATOR FITTING ASSEMBLY *CF			6621125-6 SN-UNKNOWN	MTH 22-Mar-2002 LDG 0		23800	0	23800	18783
712001 LEFT	ENGINE AFT ISOLATOR 9912480-2	*CF		LM451-SA2 LK0544	MTH 22-Mar-2002 HRS 0	9	10000	0	10009	2331.4
712001 RIGHT	ENGINE AFT ISOLATOR 9912480-2	*CF		LM451-SA2 LK0541	MTH 22-Mar-2002 HRS 0	9	10000	0	10009	2331.4
712002 LEFT BOTTOM	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LKO950	MTH 22-Mar-2002 HRS 0	9	10000	0	10009	2331.4
712002 LEFT UPPER	FORWARD ENGINE ISOLATOR 9912480-1	LIT		LM451-SA4 LK2179	MTH 23-Nov-2011 HRS 5064 LDG 3271		10000	0 0 0	15064	7386.4
712002 RIGHT BOTTOM	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LKO763	MTH 22-Mar-2002 HRS 0	9	10000	0	10009	2331.4
712002 RIGHT UPPER	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LKO717	MTH 22-Mar-2002 HRS 0	9	10000	0	10009	2331.4
712005	ENG VIBRATION MONITOR 9912519-2	*CF		2789 090119	MTH 22-Mar-2002		O/C			
71EN1 NO. 1	ENGINE	KALN		PW545A DB0493	MTH 24-Feb-2012 HRS 5198.4 LDG 3368		E/C	5064		

710001 : E1**L



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE	KALN		PW545A DB0529	MTH 31-Jul-2012 HRS 5445.1 LDG 3532		E/C	2477.4		
721010 E1	ACCESS GEARBOX SHAFT *CF			30J2201-01 A0011AR1	MTH 22-Mar-2002		O/C			
721010 E2	ACCESS GEARBOX SHAFT DMO			30J2201-01 A0013CRM	MTH 12-Dec-2002		O/C	0		
722001 E1	OIL PUMP ASSEMBLY	UNK		30J3365-01 45A465	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C	0 0 0		
722001 E2	OIL PUMP ASSEMBLY	UNK		03R30J2106-01 45A450	MTH 15-Nov-2011 HRS 5148 LDG 3372		O/C	2055.3		
723010 E1	LP COMPRESSOR FAN ROTOR UNK			30J2091-01 A0012EN9	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		15000	3271	15097	10080
723010 E2	LP COMPRESSOR FAN ROTOR DMO			30J2091-01 A0014AT0	MTH 12-Dec-2002 LDG 2029		15000	0	17029	12012
723020 E1	LP COMPRESSOR BOOST ROTOR UNK			30J2210-01 A00125KK	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		13500	3271	13597	8580
723020 E2	LP COMPRESSOR BOOST ROTOR DMO			30J2210-01 TX1A1164	MTH 12-Dec-2002 LDG 2029		13500	0	15529	10512
723030 E1	1ST STAGE HP COMPRESSOR ROTOR UNK			30J2821-01 A0011DME	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		13500	3271	13597	8580
723030 E2	1ST STAGE HP COMPRESSOR ROTOR DMO			30J2081-01 A0019K7L	MTH 12-Dec-2002 LDG 2029		13500	0	15529	10512
723040 E1	2ND STAGE HP COMPRESSOR ROTOR UNK			30J2122-01 A0011CB6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		13500	3271	13597	8580
723040 E2	2ND STAGE HP COMPRESSOR ROTOR DMO			30J2429-01 A0019P0D	MTH 12-Dec-2002 LDG 2029		13500	0	15529	10512
723060 E1	CENTRIFUGAL IMPELLER UNK			30J1450-01 A0011HRR	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		13500	3271	13597	8580
723060 E2	CENTRIFUGAL IMPELLER DMO			30J1450-01 A0019L4F	MTH 12-Dec-2002 LDG 2029		13500	0	15529	10512
724001 E1 INNER	COMBUSTION CHAMBER LINER *CF			30J2034-01 A0011TET	MTH 22-Mar-2002		O/C			
724001 E2 INNER	COMBUSTION CHAMBER LINER DMO			30J3396-01 A002YC08	MTH 31-Aug-2011 HRS 5205 LDG 3461		O/C	0 0 0		
724001 E2 OUTER	COMBUSTION CHAMBER LINER			30J3395-01 A002YW17	MTH 31-Aug-2011 HRS 5205 LDG 3461		O/C	0 0 0		
725010 E1	1ST-STAGE TURBINE DISK UNK			30J3461-01 A00342D1	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		13500	3271	13597	8580
725010 E2	1ST-STAGE TURBINE DISK DMO			30J1551-01 A0014KBH	MTH 31-Aug-2011 HRS 5205 LDG 3461		13500	0 2055.3 1432	15529	10512
725020 E1	2ND-STAGE TURBINE DISK UNK			30H3152 MAA31862	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		13500	3271	13597	8580

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
725020 E2	2ND-STAGE TURBINE DISK DMO			30H3152 75B182	MTH 12-Dec-2002 LDG 2029		13500	0	15529	10512
725030 E1	3RD-STAGE TURBINE DISK UNK			30H3153 67B928	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		13500	3271	13597	8580
725030 E2	3RD-STAGE TURBINE DISK DMO			30H3153 75B670	MTH 12-Dec-2002 LDG 2029		13500	0	15529	10512
725040 E1	4TH-STAGE TURBINE DISK UNK			30H3154 68B150	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		13500	3271	13597	8580
725040 E2	4TH-STAGE TURBINE DISK DMO			30H3154 68B198	MTH 12-Dec-2002 LDG 2029		13500	0	15529	10512
733001 LEFT	FUEL FLOW TRANSMITTER 9914413-1 *CF			9-231-28 L8258	MTH 22-Mar-2002		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER 9914413-1 LIT			9-231-28 L8300	MTH 14-Aug-2007 HRS 2704		O/C	0		
733004 LEFT	FUEL PRESSURE SWITCH 9914112-3 KALN			6057-3 1681	MTH 25-Feb-2012 HRS 5198.4 LDG 3368		O/C			
733004 RIGHT	FUEL PRESSURE SWITCH 9914112-3 KALN			6057-3 1686	MTH 25-Feb-2012 HRS 5198.4 LDG 3368		O/C			
731002 E1	FLOW DIVIDER VALVE 30J1415-02 UNK			819710-2 F53671	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C			
731002 E2	FLOW DIVIDER VALVE 30J2887-01 LIT			1006479-1 F68283	MTH 13-Jan-2014 HRS 6152.7 LDG 3969		O/C	1 0 0		
731011 E2	MAGNETIC CHIP COLLECTOR DMO			30J2027-01 SN-UNKNOWN	MTH 12-Dec-2002		O/C			
732001 E1	HYDROMECHANICAL FUEL CONTROL KALN			1012635-9 F49241	MTH 10-Mar-2016 HRS 6922.9 LDG 4552		1000	0	7922.9	245.3
732001 E2	HYDROMECHANICAL FUEL CONTROL DMO			1012635-3 F56582	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	2328		
741001 E1	IGNITION EXCITER 31J2807-07 UNK			500335-1 NNA06485869	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C	0 0 0		
741001 E2	IGNITION EXCITER 31J2807-07 LIT			500335-1 NNA05111438	MTH 22-Oct-2015 HRS 6756.2 LDG 4393		O/C	0 0		
742001 E1 INBOARD	IGNITER NNA16140625	LIT		30J2825-01 NNA16140625	MTH 21-Apr-2017 HRS 7348.6 LDG 4809		O/C	0 0		
742001 E1 OUTBOARD	IGNITER NNA16140620	LIT		30J2825-01 NNA16140620	MTH 21-Apr-2017 HRS 7348.6 LDG 4809		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
742001 E2 INBOARD	IGNITER	LIT		30J2825-01 NNA16450049	MTH 21-Apr-2017 HRS 7348.6 LDG 4809		O/C	0 0		
742001 E2 OUTBOARD	IGNITER	LIT		30J2825-01 NNA16450124	MTH 21-Apr-2017 HRS 7348.6 LDG 4809		O/C	0 0		
742002 E1	SHORT IGNITER LEAD	LIT		30J3125-01 NNA05341629	MTH 13-Feb-2012 HRS 5254.7		O/C	0		
742002 E2	SHORT IGNITER LEAD 31J2346-05	DMO		9059190-5 NSN	MTH 12-Dec-2002		O/C	0		
742003 E1	LONG IGNITER LEAD	ALN		30J3125-02 NN01034144	MTH 13-Feb-2012 HRS 5254.7		O/C	0 0		
742003 E2	LONG IGNITER LEAD 31J2346-06	DMO		9059190-6 NSN	MTH 12-Dec-2002		O/C	0		
751003 E1	COMPRESSOR BLEED VALVE ASSY	UNK		30J2207-01 44A926	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C			
751003 E2	COMPRESSOR BLEED VALVE ASSY ICT			30J2207-01 49A548	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	2055.3		
751004 E1	INTERCOMPRESSOR BLEED VALVE SERVO VALVE			30J3490-01 TR5760	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C	0 0 0		
751004 E2	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	DMO		30J3490-01 TR5277	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	0 0 0		
751005 E1	LINEAR TRANSDUCER	UNK		GM9424 2046	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C			
751005 E2	LINEAR TRANSDUCER	DMO		31J2071-01 1767	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	2055.3		
761001 LEFT	THROTTLE DETENT VALVE *CF			5303-2A 2167	MTH 22-Mar-2002		O/C			
761001 RIGHT	THROTTLE DETENT VALVE *CF			5303-2A 2169	MTH 22-Mar-2002		O/C			
761001 E1	ELECTRONIC ENGINE CONTROL	UNK		817962-8-010 01024552	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C			
761001 E2	ELECTRONIC ENGINE CONTROL	DMO		817962-8-011 98084046	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	1867.1		
771008 284010	FUEL QUANTITY FLOW INDICATOR	KALN		10638N01M01 0012677A	MTH 24-Feb-2012 HRS 5198.4 LDG 3368		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
774002 771004	N1 SPEED/ITT TEMP INDICATOR 9912497-8	LIT		10636N04M00 0012678B	MTH 11-Jun-2012 HRS 5381.5 LDG 3486		O/C	1 0 0		
774003 771005	N2/OIL PRESS/OIL TEMP INDICATOR 9912497-9	KALN		10637N04M00 01010683	MTH 24-Feb-2012 HRS 5198.4 LDG 3368		O/C			
771004 E1	SPEED N1 SENSOR	UNK		31J2072-01 CH815	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C			
771004 E2	SPEED N1 SENSOR	DMO		31J2072-01 CH850	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	2055.3		
771005 E1	SPEED N2 SENSOR	UNK		31J2073-01 CH1704	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C			
771005 E2	SPEED N2 SENSOR	DMO		31J2073-01 CH1734	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	2055.3		
772001 E1	TEMPERATURE SENSOR ICT			31J2113-03 RTK0344	MTH 24-May-2005 HRS 1785.7		O/C	0		
772001 E2	TEMPERATURE SENSOR DMO			31J2113-03 RTN2657	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	0 0 0		
774001 E1	DATA COLLECTION UNIT UNK			32205-01 DP01-1653	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C			
774001 E2	DATA COLLECTION UNIT			30J1557-01 DP01-1849	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	2055.3 0		
783001 LEFT ENGINE 783001X : E1**L	THRUST REVERSER ASSEMBLY 9912609-1 *CF			64ND-78002-3 481	MTH 22-Mar-2002		O/C			
783001 RIGHT ENGINE 783001X : E2**R	THRUST REVERSER ASSEMBLY *CF			64ND-78002-4 488	MTH 22-Mar-2002		O/C			
783002 LEFT	THRUST REVERSER VALVE *CF			65680 3855	MTH 22-Mar-2002		O/C			
783002 RIGHT	THRUST REVERSER VALVE *CF			65680 3853	MTH 22-Mar-2002		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR LIT			2564000-7 1003	MTH 16-Jun-2011 HRS 4755.2 LDG 3067		O/C	0 0 0		
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR *CF			64ND-78204-5 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR *CF			64ND-78204-5 SN-UNKNOWN	MTH 22-Mar-2002		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR *CF			64ND-78204-5 SN-UNKNOWN	MTH 22-Mar-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
783101 LEFT	ARM PRESSURE SWITCH *CF			6607A7-45 B042530	MTH 22-Mar-2002		O/C			
783101 RIGHT	ARM PRESSURE SWITCH *CF			6607A7-45 B042586	MTH 22-Mar-2002		O/C			
783102 LEFT	THRUST REVERSER ISOLATION VALVE *CF			13027-4 4572	MTH 22-Mar-2002		O/C			
783102 RIGHT	THRUST REVERSER ISOLATION VALVE *CF			13027-4 4581	MTH 22-Mar-2002		O/C			
783103 LEFT INBOARD	STOW LIMIT SWITCH SWF			53ND78304-1 N/A	MTH 05-May-2011 HRS 4706.3 LDG 3030		O/C	0 0 0		
783103 LEFT OUTBOARD	STOW LIMIT SWITCH SWF			53ND78304-1 N/A	MTH 05-May-2011 HRS 4706.3 LDG 3030		O/C	0 0 0		
783103 RIGHT	STOW LIMIT SWITCH -- LIT			53ND78304-1 NSN	MTH 21-Mar-2007 HRS 2511 LDG 1551		O/C	0		
783103 RIGHT INBOARD	STOW LIMIT SWITCH *CF			53ND78304-1 SN-UNKNOWN	MTH 27-Oct-2002		O/C			
783103 RIGHT OUTBOARD	STOW LIMIT SWITCH LIT			53ND78304-1 NSN	MTH 21-Mar-2007 HRS 2511 LDG 1551		O/C	0		
783104 LEFT	DEPLOY LIMIT SWITCH LIT			53ND78304-5 SN-UNKNOWN	MTH 06-May-2011 HRS 4709.1 LDG 3031		O/C	0 0 0		
783104 RIGHT	DEPLOY LIMIT SWITCH *CF			53ND78304-5 SN-UNKNOWN	MTH 27-Oct-2002		O/C			
793002 LEFT	OIL TEMP XMTR SENSOR *CF			102-00083 3827	MTH 22-Mar-2002		O/C			
793002 RIGHT	OIL TEMP XMTR SENSOR *CF			102-00083 3821	MTH 22-Mar-2002		O/C			
793102 LEFT	ENGINE OIL TRANSMITTER 9912464-1 *CF			APTE-237D-1000- 250D 66194319	MTH 22-Mar-2002		O/C			
793102 RIGHT	ENGINE OIL TRANSMITTER 9912464-1 *CF			APTE-237D-1000- 250D 66194332	MTH 22-Mar-2002		O/C			
793117 LEFT	OIL PRESSURE SWITCH 9912466-2 *CF			1153P0098-01 647	MTH 22-Mar-2002		O/C			
793117 RIGHT	OIL PRESSURE SWITCH 9912466-2 *CF			1153P0098-01 641	MTH 22-Mar-2002		O/C			
793003 E1	FUEL OIL HEAT EXCHANGER D2552-600B UNK			31J2955-02 M53487	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		O/C			
793003 E2	FUEL OIL HEAT EXCHANGER D2552-600B DMO			31J2955-02 M60485	MTH 15-Nov-2011 HRS 5205 LDG 3461		O/C	2055.3		
801000 LEFT ENGINE	STARTER/GENERATOR 9912499-6 LIT			300SGL138Q-4 3384XL	MTH 21-Sep-2015 HRS 6730.1 LDG 4375		1000	0	7730.1	52.5



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Components

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
801000	STARTER/GENERATOR			300SGL138Q-4	MTH 25-Apr-2016					
RIGHT ENGINE	9912499-6	LIT		4973XL	HRS 6922.9		1000	0	7922.9	245.3
					LDG 4506					
					APUH 3131					
					APUS 5223					
801100	STARTER/GENERATOR			300SGL138Q-6	MTH 03-Oct-2012			0		
APU	9912499-31	LIT		6307XL	HRS 5556			0		
					LDG 3602			0		
					APUH 2603.6		1000	0	3603.6	151.3



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 560XL-03-01 R01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SL 560XL-99-01 R04	CESCOM PRICES			INFORMATIONAL			-			
	MOC :									
SL 560XL-99-03 R01	MISCELLANEOUS - TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 560XL-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 560XL-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL 560XL-99-07	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SB 560XL-05-01 R01	TIME LIMITS/MAINTENANCE CHECKS - CONVERSION FROM CALENDAR SCHEDULE MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM (CANCELLED AND SUPERSEDED BY SL560XL-05-03)			CANCELLED			-			
	MOC :									
SB 560XL-05-01 05SB-01 : XL	TIME LIMITS/MAINTENANCE CHECKS - CONVERSION FROM CALENDAR SCHEDULE MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM (CANCELLED AND SUPERSEDED BY SL560XL-05-03),			OPTIONAL	MTH 04-Aug-2008 HRS 3204		A/R			Complete
	MOC : COMPLIED WITH									
SL 560XL-05-03	TIME LIMITS/MAINTENANCE CHECKS - CONVERSION FROM CALENDAR SCHEDULE MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM			OPTIONAL			-			
	MOC :									
SL CIL-99-01 R01	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R02)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R02	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED	MTH		-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)									
	INFORMATIONAL									
	-									
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)									
	RECOMMENDED									
	-									
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)									
	RECOMMENDED MTH									
	-									
	MOC :									
SL 560XL-20-01 R10	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560XL-20-01 R11)									
	INFORMATIONAL									
	A/R									
	MOC :									
SL 560XL-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL									
	INFORMATIONAL									
	-									
	MOC :									
SB 560XL-21-04 R01 21SB-04 : XLR1	AIR CONDITIONING - EXHAUST DUCT CONDENSATION CONTAINMENT	LBG		RECOMMENDED	MTH 13-Jun-2003 HRS 611		-			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE									
SB 560XL-21-11 21SB-11 : XL	AIR CONDITIONING - SERVICE PORT DRIP SHIELD IMPROVEMENT	ICT		RECOMMENDED	MTH 14-May-2002 HRS 13		-			Complete
	MOC : COMPLIED WITH									
SB 560XL-21-15 21SB-15 : XL	AIR CONDITIONING - COCKPIT TEMPERATURE SENSOR IMPROVEMENT			DISCRETIONARY	MTH		-			
	MOC :									
SB 560XL-21-18 R01 21SB-18 : XLR1	AIR CONDITIONING - TEMPERATURE CONTROLLER UPGRADE			RECOMMENDED			A/R			
	MOC :									
SB 560XL-21-19 R01 21SB-19 : XLR1	AIR CONDITIONING - EMERGENCY PRESSURIZATION OPERATION IMPROVEMENT	LIT		RECOMMENDED	MTH 29-Apr-2011 HRS 4695.2 LDG 3023		A/R			Complete
	MOC : COMPLIED WITH - NO NOTES									
SB 560XL-21-23 21SB-23 : XL	AIR CONDITIONING - FORWARD EVAPORATOR INSTALLATION AND WIRING MODIFICATION			OPTIONAL	MTH		A/R			
	MOC :									
SB 560XL-21-24 R01	AIR CONDITIONING - AFT EVAPORATOR INSTALLATION AND WIRING MODIFICATION			OPTIONAL			-			
	MOC :									
SB 560XL-21-24 21SB-24 : XL	AIR CONDITIONING - AFT EVAPORATOR INSTALLATION AND WIRING MODIFICATION (SUPERSEDED BY 560XL-21-24 R01)			OPTIONAL	MTH		A/R			
	MOC :									
SB 560XL-21-25 21SB-25 : XL	AIR CONDITIONING - BRUSHLESS GASPER AIR BOOST BLOWER INSTALLATION AND WIRING MODIFICATION			OPTIONAL	MTH		A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**

Aircraft Model: **560XL - CITATION XL (MSG)**

Aircraft Serial: **560XL-5239**

Unit: **5239** Reg No: **N192W**

Airworthiness: **22-Mar-2002**

Print Date: **18-Mar-2018 2:27PM**

MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT									
				INFORMATIONAL						
	MOC :									
SL CIL-21-03	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SB 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION									
		BTL		INFORMATIONAL	MTH 08-Mar-2018 HRS 7677.6 LDG 5017		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH CIL 21-03 AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 2341316-21-2828 INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR P/N 2341316-2 AND -3. RE-IDENTIFIED WATER SEPARATOR P/N 2341316-2 S/N 377 TO MOD 1.									
SL 560XL-21-06 21SL-06 : XL	AIR CONDITIONING - DROPPED AISLE DUCT IMPROVEMENT	HUR		RECOMMENDED	MTH 02-Oct-2002 HRS 299		-			Complete
	MOC :									
	COMPLIED WITH									
SL 560XL-21-07 21SL-07 : XL	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 2215460-21-2762, ENVIRONMENTAL CONTROL UNIT (ECU) - INSPECT AND REPLACE THE OVER TEMPERATURE SWITCH (SUPERSEDED BY SL560XL-21-07 R01)									
		ICT		RECOMMENDED	MTH 22-Mar-2004 HRS 1016			A/R		Complete
	MOC :									
	COMPLIED WITH									
SL 560XL-21-09 R01 21SL-09 : XLR1	AIR CONDITIONING - AIR CYCLE MACHINE INLET DUCT VANE REMOVAL	ALN		INFORMATIONAL	MTH 23-Jul-2008 HRS 3204			A/R		Complete
	MOC :									
	COMPLIED WITH									
SL 560XL-21-11 21SL-11 : XL	AIR CONDITIONING - AIR CYCLE MACHINE ASPIRATOR TUBING AND CLAMP INSPECTION			DISCRETIONARY	MTH			A/R		
	MOC :									
SL 560XL-22-02 22SL-02 : XL	AUTO FLIGHT - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 4006719-22-0019, SM-200 SERVO DRIVE			DISCRETIONARY	MTH			A/R		
	MOC :									
SB 560XL-23-03 23SB-03 : XL	COMMUNICATIONS - AIRSHOW CABIN DISPLAY MODIFICATION			OPTIONAL	MTH			-		
	MOC :									
SB 560XL-23-05 R01 23SB-05 : XLR1	COMMUNICATIONS - RNZ-850 NAVIGATION RADIO UPGRADE	ICT		MANDATORY	MTH 22-Mar-2004 HRS 1016			-		Complete
	MOC :									
	COMPLIED WITH									
SB 560XL-23-07 R02	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION (SUPERSEDED BY 560XL-23-07 R03)	KLIT		OPTIONAL	MTH 29-Nov-2012 HRS 5616.7 LDG 3640			-		Complete
	MOC :									
	COMPLIED WITH - ACCOMPLISHED SB560XL-23-07 REV 2. OPERATIONAL CHECK GOOD									
SB 560XL-23-07 R03	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION			OPTIONAL				-		
	MOC :									
SB 560XL-23-07	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION (SUPERSEDED BY 560XL-23-07 R01)			OPTIONAL				A/R		
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-23-04 R01 <i>23SL-04 : XLR1</i>	COMMUNICATIONS - AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE	LBG		RECOMMENDED	MTH 13-Jun-2003 HRS 611		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SL 560XL-23-05 <i>23SL-05 : XL</i>	COMMUNICATIONS - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN A21-3851-001, RCZ INTEGRATED COMMUNICATION UNIT	ICT		RECOMMENDED	MTH 22-Mar-2004 HRS 1016		-			Complete
MOC : COMPLIED WITH										
SL 560XL-23-07 <i>23SL-07 : XL</i>	COMMUNICATIONS - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7511001-23-6026 SRZ 850/851 INTEGRATED RADIO SYSTEM - REMOVE THE RISK OF AUDIO FEEDBACK WHEN POWER IS TURNED ON			DISCRETIONARY	MTH		-			
MOC :										
SL 560XL-23-10	COMMUNICATIONS - ATG 4000 SOFTWARE UPDATE			OPTIONAL			-			
MOC :										
SL 560XL-23-11	COMMUNICATIONS - ATG 4000 SOFTWARE UPDATE TO VERSION 2.8			OPTIONAL			-			
MOC :										
SB 560XL-24-02 R01 <i>24SB-02 : XLR1</i>	ELECTRICAL POWER - CONCORDE BATTERY INSTALLATION	*CF		OPTIONAL	MTH		-			
MOC :										
SB 560XL-24-02 <i>24SB-02 : XL</i>	ELECTRICAL POWER - CONCORDE BATTERY INSTALLATION (SUPERSEDED BY 560XL-24-02 R01)	LIT		OPTIONAL	MTH 20-Dec-2007 HRS 2886		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-24-11 R01 <i>24SB-11 : XLR1</i>	ELECTRICAL POWER - EMERGENCY LIGHTING BATTERY PACK CIRCUIT BREAKER MODIFICATION			DISCRETIONARY			A/R			
MOC :										
SB 560XL-24-14 <i>24SB-14 : XL</i>	ELECTRICAL POWER - APU STARTER/GENERATOR WIRING IMPROVEMENT (SUPERSEDED BY 560XL-24-14 R01)	ICT		RECOMMENDED	MTH 05-Oct-2009 HRS 3827		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-24-15 <i>24SB-15 : XL</i>	ELECTRICAL POWER - TAILCONE/STINGER ELECTRICAL CONNECTOR IMPROVEMENT			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560XL-24-20	ELECTRICAL POWER - AC J-BOX WIRE BUNDLE ANCHOR INSTALLATION	BTL		MANDATORY	MTH 08-Mar-2018 HRS 7677.6 LDG 5017		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB 560XL-24-20 ELECTRICAL POWER - AC J-BOX WIRE BUNDLE ANCHOR INSTALLATION										
SL 560XL-24-02 <i>24SL-02 : XL</i>	ELECTRICAL POWER - MAIN ENGINE AND APU GROUND INSTALLATION INSPECTION AND BOND CHECK			DISCRETIONARY	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-24-07	ELECTRICAL POWER - RIGHT AC GENERATOR WIRE ROUTING VERIFICATION	ICT		MANDATORY	DAYS 20-Jan-2017 HRS 7198.3 LDG 4708		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL560XL-24-07, DATED JAN 13, 2017; RIGHT AC GENERATOR WIRE ROUTING VERIFICATION.										
SB 560XL-25-08 25SB-08 : XL	EQUIPMENT/FURNISHINGS - AFT DIVIDER IMPROVEMENT			OPTIONAL	MTH		-			
MOC :										
SB 560XL-25-09 25SB-09 : XL	EQUIPMENT/FURNISHINGS - GALLEY STORAGE DOOR HINGE IMPROVEMENT	ALN		RECOMMENDED	MTH 23-Jul-2008 HRS 3204		-			Complete
MOC : COMPLIED WITH										
SB 560XL-25-10 R01 25SB-10 : XLR1	EQUIPMENT/FURNISHINGS - AFT DIVIDER DOOR SWITCH IMPROVEMENT			OPTIONAL			-			
MOC :										
SB 560XL-25-11 R01 25SB-11 : XLR1	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY 560XL-25-11 R02)			OPTIONAL			A/R			
MOC :										
SB 560XL-25-11 R02	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY 560XL-25-11 R03)			OPTIONAL			A/R			
MOC :										
SB 560XL-25-11 R03	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL			-			
MOC :										
SB 560XL-25-12 R01 25SB-12 : XLR1	EQUIPMENT/FURNISHINGS - GLARESHIELD LEATHER STRIP INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 560XL-25-15 25SB-15 : XL	EQUIPMENT/FURNISHINGS - IMPROVEMENT TO THE AFT DIVIDER (SUPERSEDED BY 560XL-25-15 R01)			OPTIONAL			A/R			
MOC :										
SL 560XL-25-02 25SL-02 : XL	EQUIPMENT/FURNISHINGS - TOILET SHROUD ASSEMBLY INSPECTION	ICT		RECOMMENDED	MTH 22-Mar-2004 HRS 1016		-			Complete
MOC : COMPLIED WITH										
SL 560XL-25-05 25SL-05 : XL	EQUIPMENT/FURNISHINGS - CABIN SYSTEMS AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) 920040 SERVICE BULLETIN 920040-44-01 SAVE MAIN CPU CMOS SETUP SETTINGS TO FLASH MEMORY			OPTIONAL	MTH		A/R			
MOC :										
SL 560XL-25-10 25SL-10 : XL	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE	LIT		MANDATORY	MTH 26-Mar-2008 HRS 3039		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SL 560XL-25-11 25SL-11 : XL	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF ROCKWELL COLLINS SERVICE BULLETIN 9200XX-44-4 AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) AND AIRSHOW GENESYS DATA COMMUNICATION UNIT (DCU)			DISCRETIONARY	MTH		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-25-17	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR RECOMMENDED									
	MOC :									
SB 560XL-26-01 26SB-01 : XL	FIRE PROTECTION - TRANSMITTAL OF PACIFIC SCIENTIFIC SERVICE BULLETIN 26-03-35071497, INSPECTION AND REPLACEMENT OF TEMPERATURE COMPENSATED PRESSURE SWITCH (SUPERSEDED BY 560XL-26-01 R01)									
	LBG			MANDATORY	MTH 13-Jun-2003 HRS 611		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-26-02 R01 26SB-02 : XLR1	FIRE PROTECTION - FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION									
	LIT			MANDATORY	MTH 27-Apr-2006 HRS 2120		-			Complete
	MOC : COMPLIED WITH									
SB 560XL-26-02 26SB-02 : XL	FIRE PROTECTION - FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION (SUPERSEDED BY 560XL-26-02 R01)									
	LIT			MANDATORY	MTH 25-Mar-2005 HRS 1515		A/R			Complete
	MOC : COMPLIED WITH									
ASL 560XL-26-01 R02 26ASL-01 : XLR2	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 THERMISTORS DETECTORS									
	LIT			MANDATORY	MTH 25-Sep-2007 HRS 2762		A/R			N/A
	MOC : NOT APPLICABLE									
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING									
	LIT			MANDATORY	MTH 31-Oct-2016 HRS 7071.9 LDG 4612 APUH 3196.9 APUS 5319		-			Complete
	MOC : COMPLIED WITH - CIL-26-01 P/C/W.									
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)									
	KALN			MANDATORY	MTH 22-Jul-2016 HRS 6980.6 LDG 4542		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH CIL-26-01 FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING.									
SB 560XL-27-13 R01 27SB-13 : XLR1	FLIGHT CONTROLS - AFTAILERON SECTOR TUBE FINISH IMPROVEMENT (SUPERSEDED BY 560XL-27-13 R02)									
	ICT			RECOMMENDED	MTH 22-Mar-2004 HRS 1016		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-27-13 R02 27SB-13 : XLR2	FLIGHT CONTROLS - AFTAILERON SECTOR TUBE FINISH IMPROVEMENT									
	ICT			RECOMMENDED	MTH 24-May-2005 HRS 1595		-			Complete
	MOC : COMPLIED WITH									
SB 560XL-27-17 R02 27SB-17 : XLR2	FLIGHT CONTROLS - ELEVATOR TRIM TAB INSPECTION/REPAIR									
	LBG			RECOMMENDED	MTH 13-Jun-2003 HRS 611		-			Complete
	MOC : COMPLIED WITH									
SB 560XL-27-20 27SB-20 : XL	FLIGHT CONTROLS - RUDDER FAIRLEAD TUBE SUPPORT MODIFICATION (SUPERSEDED BY 560XL-27-20 R01)									
	LBG			RECOMMENDED	MTH 13-Jun-2003 HRS 611		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-27-21 R01 27SB-21 : XLR1	FLIGHT CONTROLS - AILERON PULLEY BRACKET ACCESS IMPROVEMENT			OPTIONAL	MTH		A/R			
MOC : - SERVICE BULLETIN ON HOLD.										
SB 560XL-27-22 R01 27SB-22 : XLR1	FLIGHT CONTROLS - AILERON WING CABLE PULLEY BRACKET REPLACEMENT	ALN		MANDATORY	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-27-26 27SB-26 : XL	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSTALLATION IMPROVEMENT (SUPERSEDED BY 560XL-27-26 R01)	ICT		RECOMMENDED	MTH 24-May-2005 HRS 1595		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-27-28 27SB-28 : XL	FLIGHT CONTROLS - RUDDER PEDAL POSITION ADJUSTMENT MODIFICATION			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560XL-27-29 R01 27SB-29 : XLR1	FLIGHT CONTROLS - SPEED BRAKE ELECTRICAL CONNECTOR REPLACEMENT			RECOMMENDED			A/R			
MOC :										
SB 560XL-27-31 27SB-31 : XL	FLIGHT CONTROLS - FLAP HANDLE AND FLAP HANDLE GUARD IMPROVEMENT			OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-27-32	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION (SUPERSEDED BY 560XL-27-32 R01)			RECOMMENDED			A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER SUPERSEDED BY REVISION 1										
SB 560XL-27-34	FLIGHT CONTROLS - ELEVATOR TRIM CABLE REPLACEMENT	KALN		MANDATORY	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED THE SB560XL-27-34 PER THE SB INSTRUCTIONS										
SB 560XL-27-35 R01	FLIGHT CONTROLS - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT			OPTIONAL			-			
MOC :										
SB 560XL-27-35	FLIGHT CONTROLS - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT (SUPERSEDED BY 560XL-27-35 R01)			OPTIONAL			-			
MOC :										
ASL 560XL-27-10 27ASL10 : XL	FLIGHT CONTROLS - TRANSMITTAL OF FAA APPROVED AIRPLANE FLIGHT MANUAL TEMPORARY CHANGE 56XFM TC-09-04	HUR		MANDATORY	MTH 07-Feb-2003 HRS 451		-			Complete
MOC : COMPLIED WITH										
ASL 560XL-27-12 27ASL12 : XL	FLIGHT CONTROLS - AILERON WING CABLE INSPECTION (SUPERSEDED BY ASL560XL-27-12 R01)	LBG		MANDATORY	MTH 17-Dec-2003 HRS 906		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-27-06 27SL-06 : XL	FLIGHT CONTROLS - ELEVATOR ELECTRIC TRIM TAB ACTUATOR MOUNT INSPECTION	HUR		RECOMMENDED	MTH 02-Oct-2002 HRS 299		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-27-08 27SL-08 : XL	FLIGHT CONTROLS - RUDDER ASSEMBLY CONDUIT TUBE INSPECTION	LBG		RECOMMENDED	MTH 13-Jun-2003 HRS 611		-			Complete
MOC : COMPLIED WITH										
SL 560XL-27-13 27SL-13 : XL	FLIGHT CONTROLS - ELEVATOR TRIM CABLE INSPECTION	ICT		RECOMMENDED	MTH 24-May-2005 HRS 1595		-			Complete
MOC : COMPLIED WITH										
SL 560XL-27-14 27SL-14 : XL	FLIGHT CONTROLS - HORIZONTAL AND VERTICAL STABILIZER EROSION BOOT INSTALLATION			OPTIONAL			-			
MOC :										
SL 560XL-27-17 27SL-17 : XL	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION	LIT		RECOMMENDED	MTH 22-Jun-2009 HRS 3688		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-27-18	FLIGHT CONTROLS - ELEVATOR TRIM CABLE REPLACEMENT INTERVALS			INFORMATIONAL			-			
MOC :										
SL 560XL-27-20 R01	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION (SUPERSEDED BY SL560XL-27-20 R02)			MANDATORY	MTH		-			
MOC :										
SL 560XL-27-20 R02	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION	LIT		MANDATORY	MTH 27-Jan-2014 HRS 6169 LDG 3980		-			Complete
MOC : COMPLIED WITH - SL 560XL-27-20 R2, NO DEFECTS NOTED.										
SL 560XL-27-20	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION (SUPERSEDED BY SL560XL-27-20 R01)			MANDATORY	MTH		-			
MOC :										
SL 560XL-27-21	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY INSPECTION	LIT		MANDATORY	MTH 27-Jan-2014 HRS 6169 LDG 3980		-			Complete
MOC : COMPLIED WITH - SL 560XL-27-21, NO DEFECTS NOTED.										
SL 560XL-27-33	FLIGHT CONTROLS - ELEVATOR CABLE INSPECTION AT THE AFT CANTED BULKHEAD	KALN		MANDATORY	MTH 22-Jul-2016 HRS 6980.6 LDG 4542		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560XL-27-33 ELEVATOR CABLE INSPECTION AT THE AFT CANTED BULKHEAD. NO DEFECTS NOTED.										
SL 560XL-27-34 R01	FLIGHT CONTROLS - RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION	KALN		MANDATORY	MTH 19-Jul-2017 HRS 7461.2 LDG 4879		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH, NO DEFECTS NOTED AT THIS TIME.										
SL 560XL-27-34	FLIGHT CONTROLS - RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION (SUPERSEDED BY SL560XL-27-34 R01)			MANDATORY	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-27-35	FLIGHT CONTROLS - AFT AILERON SECTOR ASSEMBLY INSPECTION	KALN		MANDATORY	MTH 22-Jul-2016 DAYS 6980.6 HRS 4542 LDG		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560XL-27-35 FLIGHT CONTROLS - AFT AILERON SECTOR ASSEMBLY INSPECTION. INSTALLED NEW AFT AILERON SECTOR.										
SB 560XL-28-02 28SB-02 : XL	FUEL - WING FUEL BOOST PUMP FAIRING INSULATION INSTALLATION (SUPERSEDED BY 560XL-28-02 R01)	ICT		RECOMMENDED	MTH 24-May-2005 HRS 1595		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-28-03 28SB-03 : XL	FUEL - WING FUEL BOOST PUMP FAIRING INSULATION INSTALLATON	LIT		MANDATORY	MTH 25-Mar-2005 HRS 1515		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE										
SL 560XL-28-05 R01	FUEL - FUEL BOOST PUMP INSPECTION	LIT		MANDATORY	MTH 27-Jan-2014 HRS 6169 LDG 3980		-			Complete
MOC : COMPLIED WITH - SL 560XL-28-05 R1, FOUND P/N LR55505 FUEL PUMPS INSTALLED, NO FURTHER ACTION REQUIRED.										
SL 560XL-28-05	FUEL - FUEL BOOST PUMP INSPECTION (SUPERSEDED BY SL560XL-28-05 R01)			MANDATORY	MTH		-			
MOC :										
SB 560XL-29-03 29SB-03 : XL	HYDRAULIC POWER - HYDRAULIC SHUT-OFF VALVE INSTALLATION IMPROVEMENT			OPTIONAL	MTH		-			
MOC :										
SB 560XL-29-04 29SB-04 : XL	HYDRAULIC POWER - WHEEL WELL HYDRAULIC LINE SUPPORT IMPROVEMENT	LIT		MANDATORY	MTH 25-Mar-2005 HRS 1515		-			Complete
MOC : COMPLIED WITH										
SL 560XL-29-01 29SL-01 : XL	HYDRAULIC POWER - HYDRAULIC RESERVOIR INSPECTION	HUR		RECOMMENDED	MTH 02-Oct-2002 HRS 299		-			Complete
MOC : COMPLIED WITH										
SL 560XL-29-03 29SL-03 : XL	HYDRAULIC POWER - ENGINE HYDRAULIC HOSE INSPECTION			RECOMMENDED			A/R			
MOC :										
SL 560XL-29-05	HYDRAULIC POWER - ENGINE DRIVEN PUMP HYDRAULIC VERIFICATION	KALN		RECOMMENDED	MTH 19-Jul-2017 HRS 7461.2 LDG 4879		-			Complete
MOC : COMPLIED WITH - BOTH PUMPS ARE PART NUMBER 9912062-4 (LEFT S/N 3628, RIGHT S/N 3448). THIS SERVICE LETTER ONLY APPLIES TO PART NUMBER 9912062-7 PUMPS. NO FURTHER ACTION REQUIRED.										
SB 560XL-30-04 30SB-04 : XL	ICE AND RAIN PROTECTION - WING LEADING EDGE PICCOLO TUBE IMPROVEMENT	LBG		RECOMMENDED	MTH 13-Jun-2003 HRS 611		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-30-06 30SB-06 : XL	ICE AND RAIN PROTECTION - HORIZONTAL LIT			STABILIZER DEICE SYSTEM PRESSURE SWITCH INSTALLATION IMPROVEMENT DISCRETIONARY	MTH 22-Dec-2011 HRS 5127.6 LDG 3316		A/R			Complete
MOC : COMPLIED WITH - BY INSTALLING KIT P/N SB560XL-30-06 IN ACCORDANCE WITH SERVICE BULLETIN										
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES INFORMATIONAL						-			
MOC :										
SB 560XL-31-02 31SB-02 : XL	INDICATING/RECORDING SYSTEMS - STAB MISCOMPARE ANNUNCIATION IMPROVEMENT (SUPERSEDED BY 560XL-31-02 R01) ICT			MANDATORY	MTH 22-Mar-2004 HRS 1016		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION INFORMATIONAL						-			
MOC :										
SL 560XL-31-03 R01 31SL-03 : XLR1	INDICATING/RECORDING SYSTEMS - INSTRUMENTAL PANEL INSTALLATION MODIFICATION DISCRETIONARY			MTH			A/R			
MOC :										
SL 560XL-31-05	INDICATING/RECORDING SYSTEMS - TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001 KALN			MANDATORY	MTH 07-Mar-2013 HRS 5742.1 LDG 3814		A/R			Complete
MOC : COMPLIED WITH - NO FDR INSTALLED AND CVR IS P/N 2100-1020-02 S/N 000152187, THE CVR SERIAL NUMBER IS NOT LISTED IN THE L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001 AND DOESNOT APPLY										
SB 560XL-32-18 R02 32SB-18 : XLR2	LANDING GEAR - NLG ACTUATOR ISOLATOR INSTALLATION IMPROVEMENT OPTIONAL						-			
MOC :										
SB 560XL-32-20 R02 32SB-20 : XLR2	LANDING GEAR - NOSE GEAR TORQUE-LINK QUICK DISCONNECT OPTIONAL			MTH			A/R			
MOC :										
SB 560XL-32-23 R01 32SB-23 : XLR1	LANDING GEAR - UPLOCK SUPPORT FITTING LOCATION DISCRETIONARY			MTH			-			
MOC :										
SB 560XL-32-24 R01 32SB-24 : XLR1	LANDING GEAR - EMERGENCY GEAR EXTENSION BOTTLE ACTUATOR HANDLE PIVOT SCREW REPLACEMENT LIT			MANDATORY	MTH 07-Sep-2004 HRS 1215		-			Complete
MOC : COMPLIED WITH										
SB 560XL-32-26 R01 32SB-26 : XLR1	LANDING GEAR - NOSE LANDING GEAR DOOR MECHANISM IMPROVEMENT (SUPERSEDED BY 560XL-32-26 R02) LIT			MANDATORY	MTH 27-Apr-2006 HRS 2120		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-32-26 R02 32SB-26 : XLR2	LANDING GEAR - NOSE LANDING GEAR DOOR MECHANISM IMPROVEMENT LIT			MANDATORY	MTH 21-Mar-2007 HRS 2511		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-32-27 32SB-27 : XL	LANDING GEAR - MAIN LANDING GEAR TRAILING LINK PIVOT PIN RETENTION IMPROVEMENT	ALN		RECOMMENDED	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-32-29 32SB-29 : XL	LANDING GEAR - NOSE WHEEL STEERING PULLEY BRACKET IMPROVEMENT			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560XL-32-32 32SB-32 : XL	LANDING GEAR - BRAKE HYDRAULIC PACK FILTER BOWL REPLACEMENT	ALN		RECOMMENDED	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-32-37 32SB-37 : XL	LANDING GEAR - NOSE LANDING GEAR STEERING HARDWARE REPLACEMENT			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560XL-32-40 32SB-40 : XL	LANDING GEAR ANNUNCIATION WIRING MODIFICATION	ALN		RECOMMENDED	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-32-41 R01	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-7	KALN		MANDATORY	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		A/R			Complete
MOC : COMPLIED WITH - INSPECTED THE LH & RH WHEEL ASSEMBLIES AND FOUND EACH WHEEL AS BEEN PREVIOUSLY ACCOMPLISHED PER THE CESSNA SB560XL-32-41REV1 WHICH MEETS THE FAA AD 2012-09-01 REQUIREMENTS.										
SB 560XL-32-42 R01	LANDING GEAR - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT (SUPERSEDED BY 560XL-32-42 R02)			OPTIONAL			-			
MOC :										
SB 560XL-32-42 R02	LANDING GEAR - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT			OPTIONAL			-			
MOC :										
SB 560XL-32-42	LANDING GEAR - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT (SUPERSEDED BY 560XL-32-42 R01)			OPTIONAL			-			
MOC :										
SB 560XL-32-43	LANDING GEAR - COPILOT LEFT BRAKE CYLINDER HOSE REPLACEMENT			OPTIONAL			-			
MOC :										
SB 560XL-32-44	LANDING GEAR - NOSE LANDING GEAR BEARING GREASE FITTING INSTALLATION			OPTIONAL			-			
MOC :										
ASL 560XL-32-13 32ASL13 : XL	LANDING GEAR - EMERGENCY BRAKE, FLAPS, EMERGENCY GEAR AND SPEED BRAKE HYDRAULIC/PNEUMATIC LINE CLAMP INSPECTION	LBG		MANDATORY	MTH 11-Sep-2003 HRS 790		-			Complete
MOC : COMPLIED WITH										
ASL 560XL-32-14 32ASL14 : XL	LANDING GEAR - NOSE LANDING GEAR OLEO PRESSURE INSPECTION	LIT		MANDATORY	MTH 25-Mar-2005 HRS 1515		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION INFORMATIONAL						-			
MOC :										
SL 560XL-32-15 32SL-15 : XL	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-1 OPTIONAL			MTH			A/R			
MOC :										
SL 560XL-32-16 32SL-16 : XL	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1601-32-4, LANDING GEAR - BRAKE ASSEMBLY - P/N 2-1601-1, INTRODUCTION OF NEW O-RING			MTH			A/R			
MOC :										
SL 560XL-32-18 32SL-18 : XL	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETINS 3-1571-32-2 AND 3-1571-32-3 RECOMMENDED						A/R			
MOC :										
SL 560XL-32-19 R01 32SL-19 : XLR1	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-4 INTRODUCTION OF IMPROVED THERMAL RELIEF PLUG ASSEMBLY DISCRETIONARY	ALN		MTH 23-Jul-2008 HRS 3204			A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-32-20 32SL-20 : XL	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE LETTER 2056 RECOMMENDED	ALN		MTH 23-Jul-2008 HRS 3204 LDG 2005			A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-32-22 32SL-22 : XL	LANDING GEAR - COMPONENT PLACARD INSTALLATION OPTIONAL			MTH			A/R			
MOC :										
SL 560XL-32-23 32SL-23 : XL	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION RECOMMENDED						A/R			
MOC :										
SL 560XL-32-24 R01	LANDING GEAR - TRANSMITTAL OF CURTISS WRIGHT SB 049801-32-01, LANDING GEAR CONTROL ALTERNATE LED LIGHTING BULB (CANCELLED) CANCELLED						-			
MOC :										
SL 560XL-32-26	LANDING GEAR - REPLACEMENT OF THE COTTER PIN FOR THE EMERGENCY GEAR-RELEASE LIT			MANDATORY	MTH 26-Aug-2011 HRS 4860 LDG 3139		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-33-04 R01 33SB-04 : XLR1	LIGHTS - INDIRECT LIGHTING RELAY REPLACEMENT OPTIONAL						-			
MOC :										
SB 560XL-33-05 R01 33SB-05 : XLR1	LIGHTS - LED TAIL POSITION LIGHT INSTALLATION (SUPERSEDED BY 560XL-33-05 R02) ALN			OPTIONAL	MTH 23-Jul-2008 HRS 3204		-			Complete
MOC : COMPLIED WITH										
SB 560XL-33-05 R02	LIGHTS - LED TAIL POSITION LIGHT INSTALLATION OPTIONAL						-			
MOC :										
SB 560XL-33-06 R01	LIGHTS - CABIN UPWASH/DOWNWASH INDIRECT LIGHTING IMPROVEMENT OPTIONAL						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-33-06 33SB-06 : XL	LIGHTS - CABIN UPWASH/DOWNWASH INDIRECT LIGHTING IMPROVEMENT (SUPERSEDED BY 560XL-33-06 R01)			OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-33-08 R02 33SB-08 : XLR2	LIGHTS - CHART LIGHT MODIFICATION	ALN		RECOMMENDED	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-33-09 33SB-09 : XL	LIGHTS - LIGHT EMITTING DIODE (LED) EMERGENCY OVERWING LIGHTING INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 560XL-33-11 33SB-11 : XL	LIGHTS - DROPPED AISLE LIGHT EMITTING DIODE (LED) INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-33-15 33SB-15 : XL	LIGHTS - WING TIP NAVIGATION AND ANTI-COLLISION LED LIGHT INSTALLATION	KALN		OPTIONAL	MTH 24-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-33-16 33SB-16 : XL	LIGHTS - GROUND RECOGNITION LIGHT LED UPGRADE			OPTIONAL	MTH		A/R			
MOC :										
SL 560XL-33-04 33SL-04 : XL	LIGHTS - AFT EMERGENCY LIGHTING BATTERY PACK COVER REMOVAL	ALN		OPTIONAL	MTH 23-Jul-2008 HRS 3204		-			Complete
MOC : COMPLIED WITH										
SL 560XL-33-10	LIGHTS - AFT SIDELEDGE DIVIDER LIGHT INSPECTION/REPLACEMENT			RECOMMENDED			A/R			
MOC :										
SB 560XL-34-26 R01 34SB-26 : XLR1	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER SOFTWARE UPGRADE	LBG		RECOMMENDED	MTH 13-Jun-2003 HRS 611		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SB 560XL-34-27 34SB-27 : XL	NAVIGATION - UNIVERSAL AVIONICS PERFORMANCE DATABASE			OPTIONAL	MTH		-			
MOC : - SERVICE BULLETIN ON HOLD.										
SB 560XL-34-28 34SB-28 : XL	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) WIRING UPGRADE TO ENABLE THE -213-213 SOFTWARE FEATURES			OPTIONAL	MTH		-			
MOC :										
SB 560XL-34-29 34SB-29 : XL	NAVIGATION - HONEYWELL PRIMUS 1000 PHASE 3.0 SOFTWARE UPGRADE	LBG		RECOMMENDED	MTH 17-Dec-2003 HRS 906		-			Complete
MOC : COMPLIED WITH										
SB 560XL-34-30 34SB-30 : XL	NAVIGATION - HONEYWELL PRIMUS 1000 PHASE 3.0 SOFTWARE UPGRADE	LBG		RECOMMENDED	MTH 13-Jun-2003 HRS 611		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-34-32 R01 <i>34SB-32 : XLR1</i>	NAVIGATION - CATEGORY II OPERATIONS (SUPERSEDED BY 560XL-34-32 R02)			OPTIONAL MTH			-			
MOC :										
SB 560XL-34-32 R02	NAVIGATION - CATEGORY II OPERATIONS			OPTIONAL			-			
MOC :										
SB 560XL-34-37 <i>34SB-37 : XL</i>	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) STEEP APPROACH SWITCH INSTALLATION			OPTIONAL MTH			-			
MOC :										
SB 560XL-34-38 R01 <i>34SB-38 : XLR1</i>	NAVIGATION - UNS1-CSP TO UNS1-CSP+ AND UNS1-ESP UPGRADE TO SOFTWARE CONTROL NUMBER (SCN) 802.2 (SUPERSEDED BY 560XL-34-38 R02)			OPTIONAL			A/R			
MOC :										
SB 560XL-34-38 R02	NAVIGATION - UNS1-CSP TO UNS1-CSP+ AND UNS1-ESP UPGRADE TO SOFTWARE CONTROL NUMBER (SCN) 802.2			OPTIONAL			A/R			
MOC :										
SB 560XL-34-39 R01 <i>34SB-39 : XLR1</i>	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SWITCH (EGPWS) -219-219 SOFTWARE UPGRADE			OPTIONAL MTH			-			
MOC :										
SB 560XL-34-40 R01 <i>34SB-40 : XLR1</i>	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) UPGRADE			OPTIONAL MTH			A/R			
MOC :										
SB 560XL-34-41 R02 <i>34SB-41 : XLR2</i>	NAVIGATION - HONEYWELL TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE			OPTIONAL MTH			A/R			
MOC :										
SB 560XL-34-44 R02 <i>34SB-44 : XLR2</i>	NAVIGATION - HONEYWELL MODE S TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE (SUPERSEDED BY 560XL-34-44 R03)			OPTIONAL MTH			A/R			
MOC : - SERVICE BULLETIN ON HOLD.										
SB 560XL-34-44 R03	NAVIGATION - HONEYWELL MODE S TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE			OPTIONAL			A/R			
MOC :										
SB 560XL-34-45 R01 <i>34SB-45 : XLR1</i>	NAVIGATION - ENHANCED VISION SYSTEMS (EVS) INSTALLATION			OPTIONAL MTH			A/R			
MOC :										
SB 560XL-34-46 <i>34SB-46 : XL</i>	NAVIGATION - HONEYWELL CD-820 FLIGHT MANAGEMENT SYSTEM (FMS) WIRING MODIFICATION			RECOMMENDED			A/R			
MOC :										
SB 560XL-34-47 <i>34SB-47 : XL</i>	NAVIGATION - UNIVERSAL PERFORMANCE DATABASE DISABLEMENT	LIT		MANDATORY MTH	02-Aug-2005		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 560XL-34-49 R01 <i>34SB-49 : XLR1</i>	NAVIGATION - RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) AUDIO INHIBIT SWITCH INSTALLATION			OPTIONAL			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-34-50 R01 <i>34SB-50 : XLR1</i>	NAVIGATION - IC-615 VERTICAL GLIDE PATH AND FLIGHT DIRECTOR IMPROVEMENTS (SUPERSEDED BY 560XL-34-50 R02)	ALN		RECOMMENDED	MTH 23-Jul-2008 HRS 3204		A/R			N/A
MOC : NOT APPLICABLE										
SB 560XL-34-50 R02 <i>34SB-50 : XLR2</i>	NAVIGATION - IC-615 VERTICAL GLIDE PATH AND FLIGHT DIRECTOR IMPROVEMENTS			RECOMMENDED			A/R			
MOC :										
SB 560XL-34-52 R01 <i>34SB-52 : XLR1</i>	NAVIGATION - UNIVERSAL PERFORMANCE DATABASE INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-34-54 R02	NAVIGATION - MEGGITT MARK I SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA UNIT REPLACEMENT OR MARK II SECONDARY FLIGHT DISPLAY INDICATOR REPLACEMENT (SUPERSEDED BY 560XL-34-54 R03)			OPTIONAL			-			
MOC :										
SB 560XL-34-54 R03	NAVIGATION - MEGGITT MARK I SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA UNIT REPLACEMENT OR MARK II SECONDARY FLIGHT DISPLAY INDICATOR REPLACEMENT			OPTIONAL			-			
MOC :										
SB 560XL-34-56 R01 <i>34SB-56 : XLR1</i>	NAVIGATION - UNIVERSAL UNS1-ESP AND UNS1-CSP+ UPGRADE TO SOFTWARE CONTROL NUMBER (SCN) 803.0			OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-34-57 <i>34SB-57 : XL</i>	NAVIGATION - IC-600 FLIGHT DIRECTOR IMPROVEMENTS	ALN		DISCRETIONARY	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-34-58 R01 <i>34SB-58 : XLR1</i>	NAVIGATION - IC-615 FLIGHT DIRECTOR IMPROVEMENTS	ALN		DISCRETIONARY	MTH 23-Jul-2008 HRS 3204		A/R			N/A
MOC : NOT APPLICABLE										
SB 560XL-34-60	NAVIGATION - UNIVERSAL UNS-1ESPW FMS WIDE AREA AUGMENTATION SYSTEM (WAAS) UPGRADE			OPTIONAL			-			
MOC :										
SB 560XL-34-66 R01	NAVIGATION - INSTALLATION OF SCN 802.8 FOR UNS-1 FMS	LIT		RECOMMENDED			-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME.										
SB 560XL-34-66	NAVIGATION - INSTALLATION OF SCN 802.8 FOR UNS-1 FMS (SUPERSEDED BY 560XL-34-66 R01)			RECOMMENDED			-			
MOC :										
SB 560XL-34-70	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE			OPTIONAL			A/R			
MOC :										
SB 560XL-34-71 R01	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0	LIT		MANDATORY	MTH 30-Jan-2015 HRS 6534.3 LDG 4231		-			N/A
MOC : NOT APPLICABLE - SB560XL-34-71R1 N/A, EQUIPMENT NOT INSTALLED.										
SB 560XL-34-71	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0 (SUPERSEDED BY 560XL-34-71 R01)			MANDATORY			-			
MOC :										
SB 560XL-34-72 R01	NAVIGATION - TCAS 2000 UPDATE SOFTWARE TO VERSION 7.1			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-34-72	NAVIGATION - TCAS 2000 UPDATE SOFTWARE TO VERSION 7.1 (SUPERSEDED BY 560XL-34-72 R01)			OPTIONAL			-			
	MOC :									
SB 560XL-34-75 R01	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL			-			
	MOC :									
SB 560XL-34-75	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE (SUPERSEDED BY 560XL-34-75 R01)			OPTIONAL			-			
	MOC :									
SB 560XL-34-77 R01	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560XL-34-77 R02)			OPTIONAL			-			
	MOC :									
SB 560XL-34-77 R02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560XL-34-77 R03)			OPTIONAL			-			
	MOC :									
SB 560XL-34-77 R03	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDERINSTALLATION			OPTIONAL			-			
	MOC :									
SB 560XL-34-77	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560XL-34-77 R01)			OPTIONAL			-			
	MOC :									
SB 560XL-34-78	NAVIGATION - UNIVERSAL UNS-1ESPW FMS SOFTWARE UPGRADE 1000.8			OPTIONAL			-			
	MOC :									
SB 560XL-34-80	NAVIGATION - LITEF LCR-93 AHRS OBSOLESCENCE			OPTIONAL			-			
	MOC :									
ASL 560XL-34-08 34ASL08 : XL	NAVIGATION - TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001	RUH		MANDATORY	MTH 18-Mar-2003 HRS 532		-			Complete
	MOC : COMPLIED WITH									
SL CIL-34-01	NAVIGATION - TRANSMIT UNIVERSAL AVIONICS ALERT SERVICE BULLETIN 3XXX.()-34-3508			INFORMATIONAL			-			
	MOC :									
SL CIL-34-02	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM	LIT		MANDATORY	MTH 30-Sep-2013 HRS 6053.2 LDG 3905		-			Complete
	MOC : COMPLIED WITH - INSPECTED, FOUND RADIOS TO BE IN COMPLIANCE.									
SL CIL-34-03 R01	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R02)						-			
	MOC :			RECOMMENDED						
SL CIL-34-03 R02	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-34-03	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R01)							
		RECOMMENDED						
	MOC :							
SL CIL-34-06 R01	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201206000008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE							
		INFORMATIONAL						
	MOC :							
SL 560XL-34-07 34SL-07 : XL	NAVIGATION - TRANSMITTAL OF HONEYWELL PUBLICATION NUMBER A21-3440-001, PRIMUS 1000/2000 INTEGRATED AVIONICS SYSTEM- AZ840/850 MICRO AIR DATA COMPUTER (MADC) - INSPECT FOR PRESENCE OF VENDOR SPECIFIC COMPONENTS AND REPLACE AS REQUIRED							
			MTH 17-Dec-2003					Complete
	LBG	RECOMMENDED	HRS 906					
	MOC : COMPLIED WITH							
SL 560XL-34-11 34SL-11 : XL	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014700-34-0040							
		RECOMMENDED	MTH 22-Mar-2004					Complete
	ICT		HRS 1016					
	MOC : COMPLIED WITH							
SL 560XL-34-13 34SL-13 : XL	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 965-0976-XXX-34-70, ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) (SUPERSEDED BY SL560XL-34-13 R01)							
		DISCRETIONARY	MTH 17-Dec-2003		A/R			Complete
	LBG		HRS 906					
	MOC : COMPLIED WITH - NOT APPLICABLE							
SL 560XL-34-17 34SL-17 : XL	NAVIGATION - TRANSMITTAL OF HONEYWELL SOFTWARE BULLETIN SWB TPU 67A-SW8							
		DISCRETIONARY	MTH		A/R			
	MOC :							
SL 560XL-34-18 34SL-18 : XL	NAVIGATION - ELEMENTARY SURVEILLANCE TRANSPONDER PRODUCT IMPROVEMENT							
		MANDATORY	MTH 21-Mar-2007					N/A
	LIT		HRS 2511					
	MOC : NOT APPLICABLE							
SL 560XL-34-24 R01	NAVIGATION - SERVICE INFORMATION FROM HONEYWELL							
		INFORMATIONAL						
	MOC :							
SL 560XL-34-24	NAVIGATION - SERVICE INFORMATION FROM HONEYWELL (SUPERSEDED BY SL560XL-34-24 R01)							
		INFORMATIONAL			A/R			
	MOC :							
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001							
		MANDATORY	MTH 01-Feb-2016					N/A
	LIT		DAYS 6846.2					
			HRS 4450					
			LDG					
	MOC : NOT APPLICABLE - CIL-35-05 DOES NOT APPLY, AFFECTED MASKS NOT INSTALLED							
SL 560XL-35-04 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL560XL-35-04 R02)							
		SUPERSEDED						
	MOC : - SUPERCEDED BY SL560XL-35-04 REV 2							
SL 560XL-35-04 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240							
		MANDATORY	MTH 02-Jan-2013					N/A
	LIT		HRS 5656.9					
			LDG 3665					
	MOC : NOT APPLICABLE - SL560XL-35-04R2 N/A DUE TO DATE CODES ON INSTALLED MASKS.							



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-35-04	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL560XL-35-04 R01)			SUPERSEDED			-			
	MOC : - SUPERCEDED BY SL560XL-35-04 REV 1									
SB 560XL-36-05 36SB-05 : XL	PNEUMATIC - BLEED AIR OVERHEAT ANNUNCIATION IMPORVEMENT (SUPERSEDED BY 560XL-36-05 R01)	LBG		RECOMMENDED	MTH 13-Jun-2003 HRS 611		A/R			Complete
	MOC : COMPLIED WITH									
SL 560XL-36-01 R01 36SL-01 : XLR1	PNEUMATIC - PARTICULATE TRAP DRAIN HOLE ADDITION	ICT		RECOMMENDED	MTH 14-May-2002 HRS 13		-			Complete
	MOC : COMPLIED WITH									
SL 560XL-36-01 36SL-01 : XL	PNEUMATIC - PARTICULATE TRAP DRAIN HOLE ADDITION (SUPERSEDED BY SL560XL-36-01 R01)	ICT		RECOMMENDED	MTH 22-Mar-2002 HRS 9		A/R			Complete
	MOC : COMPLIED WITH									
SL 560XL-36-02 36SL-02 : XL	PNEUMATIC - ENGINE BLEED AIR COUPLING SAFETY WIRE ADDITION	ICT		MANDATORY	MTH 22-Mar-2002 HRS 9		-			Complete
	MOC : COMPLIED WITH									
SL 560XL-36-03 36SL-03 : XL	PNEUMATIC - APU BLEED AIR ORIFICE REPLACEMENT			OPTIONAL	MTH		-			
	MOC :									
SB 560XL-38-02 R01	WATER/WASTE - EXTERNALLY SERVICEABLE TOILET IMPROVEMENT			OPTIONAL			A/R			
	MOC :									
SB 560XL-38-02 38SB-02 : XL	WATER/WASTE - EXTERNALLY SERVICEABLE TOILET IMPROVEMENT (SUPERSEDED BY 560XL-38-02 R01)			OPTIONAL	MTH		-			
	MOC :									
SB 560XL-38-03	WATER/WASTE - TOILET OVERRIDE RELAY INSTALLATION			OPTIONAL			-			
	MOC :									
SL 560XL-38-01	WATER/WASTE - TRANSMITTAL OF MONOGRAM SYSTEMS SERVICE INFORMATION LETTER SIL15900-023	LIT		RECOMMENDED			A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 560XL-49-02 R01 49SB-02 : XLR1	AUXILIARY POWER - APU MAINTENANCE DATA PORT INSTALLATION	*CF		OPTIONAL	MTH		-			
	MOC :									
SB 560XL-49-09 49SB-09 : XL	AUXILIARY POWER UNIT PRINTED CIRCUIT BOARD IMPROVEMENT	ICT		RECOMMENDED	MTH 14-May-2002 HRS 13		-			Complete
	MOC : COMPLIED WITH									
SB 560XL-49-10 49SB-10 : XL	AUXILIARY POWER - APU TO ENGINE START IMPROVEMENT (SUPERSEDED BY 560XL-49-10 R01)	ICT		RECOMMENDED	MTH 14-May-2002 HRS 13		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-49-11 49SB-11 : XL	AUXILIARY POWER UNIT GENERATOR CONTROL UNIT WIRING IMPROVEMENT (SUPERSEDED BY 560XL-49-11 R01)	LBG		RECOMMENDED	MTH 13-Jun-2003 HRS 611		A/R			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-49-15 49SB-15 : XL	AUXILIARY POWER - APU ADD OIL LIGHT REMOVAL DISCRETIONARY			MTH			A/R			
MOC :										
SB 560XL-49-16 49SB-16 : XL	AUXILIARY POWER - APU STARTER GENERATOR COOLING KIT INSTALLATION ALN			DISCRETIONARY	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-49-17	AUXILIARY POWER - AUXILIARY POWER UNIT MOUNT BOLT CHANGE OPTIONAL						-			
MOC :										
SL 560XL-49-11 49SL-11 : XL	AUXILIARY POWER - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-7896 OIL DIPSTICK REPLACEMENT DISCRETIONARY			MTH			A/R			
MOC :										
SB 3615880-49- 8149 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 3615880-49- 8149 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 3822101-49- 8148 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 3822101-49- 8148 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 3881800-49- 7523 R04	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LOW OIL PRESSURE SWITCH, PN 3876255-2 WITH PN 3876351-1 AND REIDENTIFY LUBE PUMP FROM PN 3881800-1 TO PN 3881825-1, ON RE100[XL] AND RE100[LJ] APUS			RECOMMENDED			-			
MOC :										
SB 49-7933 R04	OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R5)						-			
MOC :										
SB 49-7933 R05	OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R6)						-			
MOC :										
SB 49-7933 R06	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R7)						-			
MOC :										
SB 49-7933 R07	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R08)						-			
MOC :										
SB 49-7933 R08	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						-			
MOC :										
SB 49-7992 R01	REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4 OPTIONAL						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 49-7992	REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4	LIT		OPTIONAL	APUH 18-Sep-2015 APUS 3076.8 5128		-			Complete
MOC : COMPLIED WITH - COMPLIED BY REPLACING APU GENERATOR CONTROL UNIT P/N 2119552-2 WITH A 2119552-4 GCU. ALL WORK PERFORMED IN ACCORDANCE WITH CITATION 560XL MAINTENANCE MANUAL, CHAPTER 49.										
SB 49-7997 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES	UNK			APUH 04-May-2012 APUS 2476.4 4084		-			Complete
MOC : COMPLIED WITH - SB 49-7997 AIRBORNE AUXILIARY POWER - GAS TURBINEENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES										
SB 49-7997 R03	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						-			
MOC :										
SB 49-7997 R04	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						-			
MOC :										
SB 49-7997 R05	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						-			
MOC :										
SB 70721598-49-8168 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 70721598-49-8168 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 70721725-49-8152 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 70721725-49-8152 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SIL APU-49 R10	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED			-			
MOC :										
SB RE100-49-7896 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL FILLER NECK AND (DIPSTICK) CAP, PN 361-530-9354, WITH OIL FILLER NECK CAP, PN 361-530-9355, ON THE RE100 APU			OPTIONAL			-			
MOC :										
SB RE100-49-7933 R03	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS			RECOMMENDED			-			
MOC :										
SB RE100-49-8139	INCREASE THE INSTALLATION TORQUE AND ADD THE USE OF LOCKING COMPOUND DURING CARBON SEAL ASSEMBLY ON THE RE100 APU			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**

Aircraft Model: **560XL - CITATION XL (MSG)**

Aircraft Serial: **560XL-5239**

Unit: **5239** Reg No: **N192W**

Airworthiness: **22-Mar-2002**

Print Date: **18-Mar-2018 2:27PM**

MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-52-06 52SB-06 : XL	DOORS - CABIN DOOR UPPER LATCH PLATE INSPECTION (SUPERSEDED BY 560XL-52-06 R01)	HUR		MANDATORY	MTH 23-Jul-2002 HRS 142		-			Complete
MOC : COMPLIED WITH										
SB 560XL-52-13 R02 52SB-13 : XLR2	DOORS - BAGGAGE DOOR HINGE CHANNEL IMPROVEMENT DISCRETIONARY						A/R			
MOC :										
SB 560XL-52-14 R01	DOORS - CABIN DOOR REINFORCEMENT MODIFICATION DISCRETIONARY						A/R			
MOC :										
SB 560XL-52-14 52SB-14 : XL	DOORS - CABIN DOOR REINFORCEMENT MODIFICATION (SUPERSEDED BY 560XL-52-14 R01)	ALN		DISCRETIONARY	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-52-15 R01 52SB-15 : XLR1	DOORS - CABIN ENTRY DOOR COUNTERBALANCE SPRING REPLACEMENT	LIT		DISCRETIONARY	MTH 03-Apr-2011 HRS 4645.7 LDG 2984		A/R			Complete
THIS SB SHOULD BE ACCOMPLISHED WITH THE PHASE 5 INSPECTION.										
MOC : COMPLIED WITH - KIT P/N: SB560XL52-15										
SB 560XL-52-17 52SB-17 : XL	DOORS - CABIN ENTRY DOOR OPERATION IMPROVEMENT (SUPERSEDED BY 560XL-52-17 R01)	ALN		RECOMMENDED	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-52-18 52SB-18 : XL	DOORS - AFT BAGGAGE DOOR HINGE MONEL RIVET REPLACEMENT (SUPERSEDED BY 560XL-52-18 R01)	ALN		RECOMMENDED	MTH 23-Jul-2008 HRS 3204		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-52-02 52SL-02 : XL	DOORS - EMERGENCY EXIT DOOR CHAFING INSPECTION AND REPAIR	ICT		MANDATORY	MTH 22-Mar-2004 HRS 1016		-			Complete
MOC : COMPLIED WITH										
SL 560XL-52-03 52SL-03 : XL	DOORS - CABIN DOOR ANNUNCIATION IMPROVEMENT (SUPERSEDED BY SL560XL-52-03 R01)	ICT		RECOMMENDED	MTH 24-May-2005 HRS 1595		-			Complete
MOC : COMPLIED WITH										
SL 560XL-52-07	DOORS - EXTERIOR DOOR SWITCH IMPROVEMENT INFORMATIONAL						A/R			
MOC :										
SB 560XL-53-13 R01	FUSELAGE - NOSE DRIP CAP BOND INSPECTION	KALN		MANDATORY	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED THE SB560XL-53-13REV1 PER THE SB INSTRUCTIONS										
SB 560XL-53-13	FUSELAGE - NOSE DRIP CAP BOND INSPECTION (SUPERSEDED BY 560XL-53-13 R01)			MANDATORY	MTH		A/R			
MOC :										
SB 560XL-53-14	FUSELAGE - CARBON FIBER STRAKE MODIFICATION OPTIONAL						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-53-16	FUSELAGE - STINGER DRAIN INSTALLATION	KALN		MANDATORY	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED THE SB560XL-53-16 PER THE SB INSTRUCTIONS										
ASL 560XL-53-08 R01	FUSELAGE - AFT CANTED BULKHEAD DRAIN INSTALLATION	LIT		MANDATORY	DAYS 21-Mar-2011 HRS 4618.4 LDG 2963		A/R			Complete
MOC : COMPLIED WITH - C/W ASL560XL-53-08R1.										
ASL 560XL-53-08	FUSELAGE - AFT CANTED BULKHEAD DRAIN INSTALLATION (SUPERSEDED BY ASL560XL-53-08 R01)			MANDATORY	DAYS		A/R			
MOC : - SUPERSEDED BY REVISION 1										
SL 560XL-53-05 53SL-05 : XL	FUSELAGE STINGER DRAIN HOLE INSTALLATION	ICT		MANDATORY	MTH 24-May-2005 HRS 1595		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-53-06 53SL-06 : XL	FUSELAGE FS 528.50 FRAME DRAIN HOLE INSTALLATION	LIT		RECOMMENDED	MTH 25-Sep-2007 HRS 2762		-			Complete
MOC : COMPLIED WITH										
SL 560XL-53-17	FUSELAGE - DORSAL DUCT INSPECTION	KALN		RECOMMENDED	MTH 07-Mar-2013 HRS 5742.1 LDG 3814		-			Complete
MOC : COMPLIED WITH - SL560XL-53-17. NO DEFECTS NOTED.										
SL 560XL-55-01 R02	STABILIZERS - PIVOT FITTING INSPECTION (SUPERSEDED BY SL560XL-55-01 R03)			MANDATORY			-			
MOC :										
SL 560XL-55-01 R03	STABILIZERS - PIVOT FITTING INSPECTION	KALN		CANCELLED	MTH 22-Jul-2016 HRS 6980.6 LDG 4542		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH SL560XL-55-01 R3 STABILIZERS - PIVOT FITTING INSPECTION. SL560XL-55-01 REV 3 CANCELS THIS SERVICE LETTER TITLED STABILIZERS - PIVOT FITTING INSPECTION. NO FURTHER ACTION REQUIRED AT THIS TIME.										
SL 560XL-56-01 56SL-01 : XL	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION	LIT		MANDATORY	MTH 21-Dec-2006 HRS 2442		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-56-03	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION			MANDATORY	MTH		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER SEE SERVICE LETTER FOR APPLICABILITY.										
SB 560XL-57-03 57SB-03 : XL	WINGS - WING WIRE BUNDLE ANCHOR IMPROVEMENT (SUPERSEDED BY 560XL-57-03 R01)	LBG		RECOMMENDED	MTH 11-Sep-2003 HRS 790		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-57-04 R02 57SB-04 : XLR2	WINGS - VORTEX GENERATOR ADHESIVE IMPROVEMENT			RECOMMENDED	MTH	-341	A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-57-04	WINGS - VORTEX GENERATOR ADHESIVE IMPROVEMENT (SUPERSEDED BY 560XL-57-04 R01)	LIT		RECOMMENDED	MTH 19-Jul-2010 HRS 4258 LDG 2701		A/R			Complete
MOC : COMPLIED WITH - 5001] SB560XL-57-Q4 (VORTEX GENERATORS) COMPLIED WITH IN ACCORDANCE WITH SERVICE BULLETIN INSTRUCTIONS.										
SB 560XL-71-06 71SB-06 : XL	POWER PLANT - COWLING IMPROVEMENT	ICT		MANDATORY	MTH 14-May-2002 HRS 13		-			Complete
MOC : COMPLIED WITH										
SB 560XL-71-07 71SB-07 : XL	POWER PLANT - MOTIVE FLOW FUEL LINE/OIL LINE CLEARANCE IMPROVEMENT (SUPERSEDED BY 560XL-71-07 R01)	ICT		RECOMMENDED	MTH 24-May-2005 HRS 1595		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-71-09 71SB-09 : XL	POWER PLANT - ENGINE OIL DOOR DOUBLER INSTALLATION			RECOMMENDED			A/R			
MOC :										
SB 560XL-71-11 R01	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION			OPTIONAL			-			
MOC :										
SB 560XL-71-11	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION (SUPERSEDED BY 560XL-71-11 R01)	KALN		OPTIONAL	MTH 24-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-71-12	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE REMOVAL			OPTIONAL			-			
MOC :										
SL CIL-71-01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30463			OPTIONAL			-			
MOC :										
SL 560XL-71-02 R01 71SL-02 : XLR1	POWER PLANT - ENGINE ELECTRICAL GROUND INSPECTION FOR RTV	LBG		RECOMMENDED	MTH 13-Jun-2003 HRS 611		-			Complete
MOC : COMPLIED WITH										
SL 560XL-71-03 71SL-03 : XL	POWER PLANT - ENGINE MOUNT BOLT TORQUE INSPECTION	LBG		MANDATORY	MTH 11-Sep-2003 HRS 790		-			Complete
MOC : COMPLIED WITH										
SL 560XL-71-04 71SL-04 : XL	POWER PLANT - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30240 REPLACEMENT OF THE ALTERNATOR SHAFT PLAIN SEAL	ICT		DISCRETIONARY	MTH 24-May-2005 HRS 1595		-			Complete
MOC : COMPLIED WITH										
SL 560XL-71-05 71SL-05 : XL	POWER PLANT - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30274 INSPECTION OF AC ALTERNATOR DRIVE SPUR GEARSHAFT ASSEMBLY	ICT		RECOMMENDED	MTH 24-May-2005 HRS 1595		-			Complete
MOC : COMPLIED WITH										
SL 560XL-71-06 71SL-06 : XL	POWER PLANT - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30248 TURBOFAN ENGINE FRONT FAN CASE ASSEMBLY VIBRATION DAMPER RING-INSTALLATION			RECOMMENDED	DAYS 42		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-71-07 71SL-07 : XL	POWER PLANT - TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SPECIAL INSTRUCTION NUMBER 17-2005, PW500 AUTO SHUT - OFF MECHANISM INSPECTION.	LIT		MANDATORY	MTH 27-Apr-2006 HRS 2120		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL 560XL-71-08 71SL-08 : XL	POWER PLANT - BLEED AIR TUBE SLEEVING INSTALLATION IMPROVEMENT	LIT		RECOMMENDED	MTH 25-Sep-2007 HRS 2762		-			Complete
MOC : COMPLIED WITH										
SL 560XL-71-09	POWER PLANT - TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SB NUMBER 30294R2, TURBOFAN ENGINE OIL TANK FILLER CAP INSPECTION			INFORMATIONAL	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - BY PW500-72-30294 R2										
ASL 560XL-72-19 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO - VALVE - INSPECTION/REPLACEMENT OF	LIT		MANDATORY	MTH 31-Aug-2010 HRS 4330 LDG 2751		A/R			N/A
MOC : NOT APPLICABLE										
ASL 560XL-72-19 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE-INSPECTION/REPLACEMENT OF	LIT		MANDATORY	MTH 31-Aug-2010 HRS 4330 LDG 2751		A/R			N/A
MOC : NOT APPLICABLE										
SL 560XL-72-09 72SL-09 : XL	ENGINE - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30217, TURBOFAN ENGINE FUEL TUBE - INSPECTION OF	HUR		RECOMMENDED	MTH 02-Oct-2002 HRS 299		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-72-11 R01 LEFT ENGINE 72SL-11 : XLR1	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30252 NUMBER FOUR BEARING OIL PRESSURE AND OIL SCAVENGE TUBES - REPLACEMENT OF			CANCELLED	MTH HRS		300			
SERVICE BULLETIN/LETTER CANCELLED OR SUPERSEDED										
MOC :										
SL 560XL-72-11 R01 RIGHT ENGINE 72SL-11 : XLR1	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30252 NUMBER FOUR BEARING OIL PRESSURE AND OIL SCAVENGE TUBES - REPLACEMENT OF			CANCELLED	MTH HRS		300			
SERVICE BULLETIN/LETTER CANCELLED OR SUPERSEDED										
MOC :										
SL 560XL-72-12 72SL-12 : XL	ENGINE - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30331 MODIFICATION OF FUEL PRESSURE HOSE AND TUBE ROUTING			OPTIONAL	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - BY PW500-72-30331										
SL 560XL-72-13 LEFT ENGINE 72SL-13 : XL	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPE INSPECTION OF			RECOMMENDED			A/R			
THIS SERVICE LETTER IS DUE AT HOT SECTION BUT NOT TO EXCEED 4100 TOTAL ENGINE HOURS.										
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-72-13 RIGHT ENGINE 72SL-13 : XL	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPE INSPECTION OF	RECOMMENDED			A/R			
THIS SERVICE LETTER IS DUE AT HOT SECTION BUT NOT TO EXCEED 4100 TOTAL ENGINE HOURS.								
MOC :								
SL 560XL-72-14 LEFT ENGINE 72SL-14 : XL	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30306 TURBOFAN ENGINE NEW TRANSFER TUBES WITH HEAT SHIELD	RECOMMENDED			A/R			
MOC :								
SL 560XL-72-14 RIGHT ENGINE 72SL-14 : XL	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30306 TURBOFAN ENGINE NEW TRANSFER TUBES WITH HEAT SHIELD	RECOMMENDED			A/R			
MOC :								
SL 560XL-72-17 LEFT ENGINE 72SL-17 : E1**L	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	MANDATORY	MTH 17-Feb-2012 HRS 5198.4 LDG 3368		22 1600			Complete
CESCOM DEFAULTS TO MOST RESTRICTIVE TBO. PLEASE NOTIFY CESCOM OF CORRECT DUE POINT FOR YOUR AIRCRAFT.								
MOC : COMPLIED WITH - BY PW500-72-30409 R7								
SL 560XL-72-17 RIGHT ENGINE 72SL-17 : E2**R	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	MANDATORY	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - BY PW500-72-30409 R7								
SB PW300-72-30446 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY				A/R			
MOC :								
SB PW500-72-30026 E2	REPLACEMENT OF COMBUSTOR SUPPORT PIN	CATEGORY 5	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION								
SB PW500-72-30035 E2	REPLACEMENT OF IGNITER FAIRING GASKET AND REAR FUEL DRAIN GASKET	CATEGORY 7	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION								
SB PW500-72-30037 E2	REPLACEMENT OF COMPRESSOR RETAINING NUT	CATEGORY 6	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION								
SB PW500-72-30039 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET	CATEGORY 7	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION								
SB PW500-72-30040 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT	CATEGORY 7	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION								
SB PW500-72-30041 E2	MODIFICATION OF FRONT FAN CASE ASSEMBLY	CATEGORY 3	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION								
SB PW500-72-30042 R1 E2	IDENTIFICATION OF OIL PRESSURE TUBE IN TURBINE EXHAUST CASE	CATEGORY 6	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION								



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30046 E2	REPLACEMENT OF HIGH PRESSURE TURBINE LINER SEGMENTS CATEGORY 3			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30047 E2	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR ASSEMBLY CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30048 R1 E2	REPLACEMENT OF IGNITION EXCITER TO IGNITOR CABLE CATEGORY 3			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30053 R1 E2	REPLACEMENT/MODIFICATION OF HIGH COMPRESSOR ROTOR CATEGORY 5			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30054 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 3			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30055 E2	REPLACEMENT OF ENGINE ELECTRONIC CONTROL (EEC) UNK CATEGORY 3			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30057 E2	REPLACEMENT OF REAR BYPASS DUCT AND REAR BYPASS DUCT ASSEMBLY CATEGORY 3			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30060 R1 E2	VIBRATION DAMPER/INSULATION BLANKET-REMOVAL OF-COMPRESSOR STATOR ASSEMBLY-REPLACEMENT OF CATEGORY 3			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30061 R1 E2	REPLACEMENT OF THIRD STAGE TURBINE BLADE ASSEMBLY CATEGORY 9			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30062 R3 E2	CUSTOMER (CESSNA) REQUESTED CHANGES TO ENGINE INSTALLATION/INTERFACE CATEGORY 3			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30065 E2	REPLACEMENT OF FUEL NOZZLE CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30066 E2	REPLACEMENT OF SELF LOCKING NUTS WITH ANTI-SEIZE COMPOUND CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30067 E2	REPLACEMENT OF FRONT ENGINE LIFTING BRACKETS CATEGORY 3			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30068 R2 E2	REPLACEMENT/MODIFICATION OF LOW PRESSURE TURBINE (LPT) VANE ASSEMBLIES CATEGORY 9			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30069 R1 E2	REPLACEMENT OF ENGINE ELECTRONIC CONTROL (EEC) CATEGORY 3			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30070 R3 E2	REPLACEMENT OF SERVO FOR INTERCOMPRESSOR BLEED VALVE CATEGORY 3			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30073 R1 E1	REPLACEMENT OF T1/FCU TEMPERATURE SENSOR CATEGORY 7						-			
MOC :										
SB PW500-72-30073 R1 E2	REPLACEMENT OF T1/FCU TEMPERATURE SENSOR CATEGORY 7						-			
MOC :										
SB PW500-72-30073 E2	REPLACEMENT OF T1 TEMPERATURE SENSOR CATEGORY 7			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30074 E2	REPLACEMENT OF ACCESSORY GEARBOX OIL BAFFLE ASSEMBLY CATEGORY 3			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30075 R1 E1	REPLACEMENT OF MOUNTING HARDWARE CATEGORY 8						-			
MOC :										
SB PW500-72-30075 R1 E2	REPLACEMENT OF MOUNTING HARDWARE CATEGORY 8						-			
MOC :										
SB PW500-72-30075 E2	REPLACEMENT OF EXTERNAL MOUNTING HARDWARE CATEGORY 8			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30076 R1 E2	REPLACEMENT OF NO. 5 BEARING HEAT SHIELD CATEGORY 7			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30077 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY GAS GENERATOR CASE ASSEMBLY 2ND STAGE HIGH COMPRESSOR ROTOR CATEGORY 7			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30078 E2	REPLACEMENT OF FUEL NOZZLE AND FAN CASE FRONT FLANGE BOLTS CATEGORY 5			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30080 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL AND HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 3			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30082 E2	REPLACEMENT OF FAN ROTOR BALANCING ASSEMBLY CATEGORY 7			MTH	11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30083 R2 E2	REPLACEMENT OF COMPRESSOR BLEED VALVE ASSEMBLY CATEGORY 8			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30084 R2 E1	REPLACEMENT OF FAN CASE ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW500-72-30084 R2 E2	REPLACEMENT OF FAN CASE ASSEMBLY CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30086 R1 E2	REPLACEMENT OF FLOW DIVIDER/ECOLOGY VALVE CATEGORY 8			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30087 R3 E2	REPLACEMENT/MODIFICATION OF FUEL CONTROL UNIT (FCU) CATEGORY 5			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30088 R1 E2	INTRODUCTION OF GASKETS AND ADDITIONAL WASHERS FOR FRONT FAN CASE FLANGE CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30090 E2	REPLACEMENT OF ENGINE MOUNT CADMIUM BOLTS/T6 BUS BAR BOLTS CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30092 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30093 R1 E2	INTRODUCTION OF SILVER PLATED NUT OPTIONS CATEGORY 5			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30094 E2	INTRODUCTION OF NEW LOW PRESSURE TURBINE ROTOR BALANCING ASSEMBLY CATEGORY 9			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30095 E2	REPLACEMENT OF WIRING HARNESS CATEGORY 9			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30096 R5 E2	REPLACEMENT OF SECOND AND THIRD STAGE VANE LPT VANE RING CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30097 R2 E2	REPLACEMENT OF TURBINE CASE AND TURBINE VANE RING ASSEMBLIES CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30098 E2	REPLACEMENT OF FIRST STAGE HIGH COMPRESSOR ROTOR CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30099 R2 E2	REPLACEMENT OF HIGH PRESSURE TURBINE BRUSH SEALS CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30100 E2	REPLACEMENT OF NO. T4 BEARING CARBON SEAL CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30102 E2	REPLACEMENT OF HIGH TEMPERATURE PREFORMED PACKING CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30103 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVESHAFT CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30104 E2	REPLACEMENT OF GRAFOIL GASKETS CATEGORY 5			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30105 E2	REPLACEMENT EXCITER TO IGNITER CABLES CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30106 E2	REPLACEMENT OF FAN EXIT VANE RING ASSEMBLY CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30107 R1 E2	REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY CATEGORY 9			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30110 R1 E2	REPLACEMENT OF OIL LEVEL INDICATOR CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30111 R1 E2	REPLACEMENT OF IGNITION EXCITER CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30112 R1 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30113 E2	REPLACEMENT OF FAN RETAINING KEY WASHER CATEGORY 5			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30114 R1 E2	REPLACEMENT OF LOW COMPRESSOR ROTOR CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30117 E2	REPLACEMENT OF HEAT SHIELD ASSEMBLY CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30120 E2	INTRODUCTION OF ELECTRONIC CHIP DETECTOR CATEGORY 8				MTH 11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30122 E2	REPLACEMENT OF FUEL TUBE CATEGORY 3				MTH 11-Dec-2002		N/A			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30125 E2	REPLACEMENT OF POLYESTER GASKETS CATEGORY 5				MTH 11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30126 R1 E2	REPLACEMENT OF INTERMEDIATE CASE CATEGORY 7				MTH 11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30126 R2 E1	REPLACEMENT OF INTERMEDIATE CASE CATEGORY 7						-			
	MOC :									
SB PW500-72-30126 R2 E2	REPLACEMENT OF INTERMEDIATE CASE CATEGORY 7						-			
	MOC :									
SB PW500-72-30127 E2	REPLACEMENT OF INERTIAL P3 AIR SEPERATOR CATEGORY 7				MTH 11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30131 R2 E1	REPLACEMENT OF COLD START VALVE ASSEMBLY CATEGORY 3						A/R			
	MOC :									
SB PW500-72-30131 R2 E2	REPLACEMENT OF COLD START VALVE ASSEMBLY CATEGORY 3				MTH 11-Dec-2002		A/R			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30133 R1 E2	REPLACEMENT OF DIFFUSER SET CATEGORY 7				MTH 11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30135 R1 E2	REPLACEMENT OF OIL FILLER CAP CATEGORY 6				MTH 11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30137 E2	REPLACEMENT OF ANGLE BRACKET (P3 AIR JUNCTION TUBE ASSEMBLY) CATEGORY 8				MTH 11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30139 E2	REPLACEMENT OF ACCESSORY GEARBOX MANIFOLD ASSEMBLY CATEGORY 7				MTH 11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									
SB PW500-72-30140 R2 E2	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7				MTH 11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30141 R1 E1	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR ASSEMBLY CATEGORY 7						A/R			
	MOC :									
SB PW500-72-30141 R1 E2	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR ASSEMBLY CATEGORY 7			MTH	11-Dec-2002		A/R			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30143 R1 E2	INTRODUCTION OF NEW NO. 3 BEARING CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30147 R1 E2	REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) LINER SEGMENTS CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30148 R2 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND LIP SEAL CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30150 E2	REPLACEMENT OF REAR BY-PASS DUCT CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30151 R1 E2	REPLACEMENT OF GAS GENERATOR CASE CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30154 R1 E2	REPLACEMENT OF GREEK ASCOLOY TO WASPALOY BOLTS CATEGORY 8			MTH	11-Dec-2002		-			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30155 E2	REPLACEMENT OF NO.4 BEARING OIL SCAVENGE TUBE ASSEMBLY CATEGORY 8			MTH	11-Dec-2002		-			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30156 R1 E1	REPLACEMENT OF ANTI-ICING VALVE CATEGORY 7						-			
	MOC :									
SB PW500-72-30156 R1 E2	REPLACEMENT OF ANTI-ICING VALVE CATEGORY 7						-			
	MOC :									
SB PW500-72-30156 E2	REPLACEMENT ANTI-ICING VALVE CATEGORY 7			MTH	11-Dec-2002		-			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30157 E2	REPLACEMENT OF LPT 2ND STAGE VANE ASSEMBLY CATEGORY 6			MTH	11-Dec-2002		-			Complete
	MOC :	COMPLIED WITH -	IN PRODUCTION							
SB PW500-72-30158 R1 E1	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30158 R1 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT CATEGORY 7						-			
MOC :										
SB PW500-72-30158 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT CATEGORY 7				MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30160 E2	REPLACEMENT OF REAR BY-PASS DUCT ASSEMBLY CATEGORY 9				MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30163 E2	REPLACEMENT OF P3 BLEED AIR COVER ASSEMBLY CATEGORY 7				MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30164 R4 E2	REPLACEMENT OF ACCESSORY DRIVE AND ALTERNATOR DRIVE GEARSHAFTS CATEGORY 8				MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30165 E1	INTRODUCTION OF IMPROVED COMBUSTION CHAMBER LINER (IC) UNK CATEGORY 9				MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30165 E2	INTRODUCTION OF IMPROVED COMBUSTION CHAMBER LINER (IC) CATEGORY 9				MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30166 R1 E2	REPLACEMENT OF HIGH PRESSURE TURBINE LINER SEGMENTS CATEGORY 8				MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30167 E2	REPLACEMENT OF DIFFUSER SET CATEGORY 7				MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30169 R1 E2	REPLACEMENT OF FUEL NOZZLE CATEGORY 7				MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30169 R2 E1	REPLACEMENT OF FUEL NOZZLE CATEGORY 7						-			
MOC :										
SB PW500-72-30169 R2 E2	REPLACEMENT OF FUEL NOZZLE CATEGORY 7						-			
MOC :										
SB PW500-72-30174 R1 E2	REPLACEMENT OF IGNITION EXCITER BOX CATEGORY 9				MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30176 R2 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30176 R2 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7				-			
	MOC :							
SB PW500-72-30176 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30177 E2	REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) SEAL RING CATEGORY 6	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30179 R2 E2	REPLACEMENT OF HIGH PRESSURE TURBINE VANE RING ASSEMBLY CATEGORY 7	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30180 E2	REPLACEMENT OF DUCT SUPPORT RING ASSEMBLY CATEGORY 7	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30182 R1 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30186 E2	REPLACEMENT OF DIFFUSER EXIT DUCT ASSEMBLY CATEGORY 9	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30190 E2	REPLACEMENT OF LPT 2ND STAGE VANE ASSEMBLY CATEGORY 6	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30196 R3 E2	REPLACEMENT OF P3 BELLOWS SEALS CATEGORY 3	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30197 R5 E2	INTRODUCTION OF NEW FUEL MANIFOLD CATEGORY 3	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30201 E1	INTRODUCTION OF IMPROVED COMBUSTION CHAMBER LINER UNK CATEGORY 7	MTH	13-Feb-2012		-			Complete
		HRS	5198.4					
		LDG	3368					
	MOC : COMPLIED WITH - AT OVERHAUL							
SB PW500-72-30201 E2	INTRODUCTION OF IMPROVED COMBUSTION CHAMBER LINER CATEGORY 7	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30202 R1 E1	INTRODUCTION OF RE-PROFIED GRAFOIL GASKETS CATEGORY 5				-			
	MOC :							
SB PW500-72-30202 R2 E1	INTRODUCTION OF RE-PROFIED GRAFOIL GASKETS CATEGORY 5				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30202 R2 E2	INTRODUCTION OF RE-PROFIED GRAFOIL GASKETS CATEGORY 5				-			
	MOC :							
SB PW500-72-30202 E2	INTRODUCTION OF RE-PROFIED GRAFOIL GASKETS CATEGORY 5	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30203 R1 E1	REPLACEMENT OF ALTERNATOR SHAFT PLAIN SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30203 R1 E2	REPLACEMENT OF ALTERNATOR SHAFT PLAIN SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30203 E2	REPLACEMENT OF ALTERNATOR SHAFT PLAIN SEAL CATEGORY 7	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30205 R01 E1	REPLACEMENT OF LPT SECOND-STAGE VANE ASSEMBLY CATEGORY 6				-			
	MOC :							
SB PW500-72-30205 R01 E2	REPLACEMENT OF LPT SECOND-STAGE VANE ASSEMBLY CATEGORY 6				-			
	MOC :							
SB PW500-72-30205 E1	REPLACEMENT OF LPT 2ND STAGE VANE ASSEMBLY UNK CATEGORY 6	MTH HRS LDG	13-Feb-2012 5198.4 3368		-			Complete
	MOC : COMPLIED WITH - AT OVERHAUL							
SB PW500-72-30205 E2	REPLACEMENT OF LPT 2ND STAGE VANE ASSEMBLY CATEGORY 6	MTH HRS LDG	31-Aug-2011 5205 3461		-			Complete
	MOC : COMPLIED WITH - EMBODIED THIS VISIT							
SB PW500-72-30213 R1 E2	INSPECTION OF FUEL TUBE CATEGORY 3	MTH	11-Dec-2002		-			Complete
	MOC : COMPLIED WITH - IN PRODUCTION							
SB PW500-72-30216 E1	INTRODUCTION OF IMPROVED COMBUSTION CHAMBER LINER ASSEMBLY UNK CATEGORY 7	MTH HRS LDG	13-Feb-2012 5198.4 3368		-			Complete
	MOC : COMPLIED WITH - AT OVERHAUL							
SB PW500-72-30217 R02 E2	INSPECTION OF FUEL TUBE CATEGORY 3	MTH HRS LDG	09-May-2003 3273 2159		-			Complete
	MOC : COMPLIED WITH - EMBODIED							
SB PW500-72-30221 R2 E1	REPLACEMENT OF T1/FCU TEMPERATURE SENSOR UNK CATEGORY 8	MTH HRS LDG	13-Feb-2012 5198.4 3368		-			Complete
	MOC : COMPLIED WITH - AT OVERHAUL							



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30222 R1 E2	REPLACEMENT OF HIGH COMPRESSOR ROTOR			CATEGORY 7	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30226 R1 E1	REPLACEMENT OF LPT 2ND STAGE VANE ASSEMBLY	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30226 R1 E2	REPLACEMENT OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 6	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30231 R4 E2	REPLACEMENT OF REAR INNER-BYPASS-DUCT			CATEGORY 7	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30237 R1 E1	INTRODUCTION OF IMPROVED COMBUSTION CHAMBER LINER ASSEMBLY	UNK		CATEGORY 7	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30238 E1	REPLACEMENT OF 2ND AND 3RD STAGE LOW PRESSURE TURBINE ROTOR BLADE-RETAING-RIVETS	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30238 E2	REPLACEMENT OF 2ND AND 3RD STAGE LOW PRESSURE TURBINE ROTOR BLADE-RETAING-RIVETS			CATEGORY 6	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30240 R3 E2	REPLACEMENT OF ALTERNATOR SHAFT PLAIN SEAL			CATEGORY 8	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30240 R4 E1	REPLACEMENT OF ALTERNATOR SHAFT PLAIN SEAL			CATEGORY 8			-			
MOC :										
SB PW500-72-30240 R4 E2	REPLACEMENT OF ALTERNATOR SHAFT PLAIN SEAL			CATEGORY 8			-			
MOC :										
SB PW500-72-30245 R4 E2	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL			CATEGORY 6	MTH 11-Dec-2002		-			Complete
MOC : COMPLIED WITH - IN PRODUCTION										
SB PW500-72-30245 R5 E1	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30245 R5 E2	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30260 E1	REPLACEMENT OF ACCESSORY GEARBOX OIL BAFFLE ASSEMBLY	UNK		CATEGORY 7	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30262 R01 E1	MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30262 R01 E2	MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30267 R3 E1	REPLACEMENT OF INLET COMPRESSOR VANE RINGS	UNK		CATEGORY 7	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30267 R4 E1	REPLACEMENT OF INLET COMPRESSOR VANE RINGS			CATEGORY 7			-			
MOC :										
SB PW500-72-30267 R4 E2	REPLACEMENT OF INLET COMPRESSOR VANE RINGS			CATEGORY 7			-			
MOC :										
SB PW500-72-30270 R1 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSY			CATEGORY 7			-			
MOC :										
SB PW500-72-30270 R1 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSY			CATEGORY 7			-			
MOC :										
SB PW500-72-30271 E1	MODIFICATION/REPLACEMENT OF FAN ROTOR BALANCING ASSEMBLY	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30274 R1 E1	INSPECTION OF AC ALTERNATOR DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 3	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		600			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30278 R1 E2	REPLACEMENT OF GAS GENERATOR CASE			CATEGORY 7	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30280 E1	REPLACEMENT/INSPECTION OF OIL PUMP GEARSHAFT SPUR	UNK		CATEGORY 8	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30281 R1 E1	REPLACEMENT OF FUEL NOZZLE GASKET UNK			CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30288 R2 E1	MODIFICATION OF TURBINE CASE ASSEMBLY CATEGORY 6						A/R			
MOC :										
SB PW500-72-30288 R2 E2	MODIFICATION OF TURBINE CASE ASSEMBLY CATEGORY 6				MTH 31-Aug-2011 HRS 5205 LDG 3461		A/R			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30291 R1 E1	REPLACEMENT OF FIRST STAGE HIGH COMPRESSOR ROTOR CATEGORY 6				MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30294 R2 (PART A) E1	INSPECT INSPECTION OF OIL TANK FILLER CAP USING FINGER CATEGORY 3				MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30294 R2 (PART A) E2	INSPECT INSPECTION OF OIL TANK FILLER CAP USING FINGER CATEGORY 3				MTH 09-May-2008		A/R			Complete
MOC : COMPLIED WITH - EMBODIED										
SB PW500-72-30294 R2 (PART B) E1	INSPECT INSPECTION OF OIL TANK FILLER CAP USING TORQUE WRENCH CATEGORY 3				MTH 13-Feb-2012 HRS 5254.7 LDG 3457		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30294 R2 (PART B) E2	INSPECT INSPECTION OF OIL TANK FILLER CAP USING TORQUE WRENCH CATEGORY 3				MTH 09-May-2008		-			Complete
MOC : COMPLIED WITH - EMBODIED										
SB PW500-72-30294 R2 E1	INSPECTION OF OIL TANK FILLER CAP UNK			CATEGORY 3	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30294 R2 E2	INSPECTION OF OIL TANK FILLER CAP CATEGORY 3				MTH 09-May-2008		A/R			Complete
MOC : COMPLIED WITH - EMBODIED										
SB PW500-72-30296 R2 E2	INSPECTION OF HFC RATIO UNIT SETSCREW ADJUSTMENT CATEGORY 3				MTH 09-May-2008		A/R			Complete
MOC : COMPLIED WITH - EMBODIED										
SB PW500-72-30300 R3 E1	REPLACEMENT OF OIL PUMP PLAIN SEAL UNK			CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30306 R05 E1	NEW TRANSFER TUBES WITH HEAT SHIELD			CATEGORY 5			-			
	MOC :									
SB PW500-72-30306 R05 E2	NEW TRANSFER TUBES WITH HEAT SHIELD			CATEGORY 5			-			
	MOC :									
SB PW500-72-30306 R3 E2	NEW TRANSFER TUBE WITH HEATSHIELD			CATEGORY 5	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
	MOC : COMPLIED WITH - EMBODIED THIS VISIT									
SB PW500-72-30306 R4 E2	NEW TRANSFER TUBES WITH HEAT SHIELD			CATEGORY 5	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
	MOC : COMPLIED WITH - EMBODIED THIS VISIT									
SB PW500-72-30308 E1	REPLACEMENT COMPRESSOR RETAINING NUT	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30309 R4 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30309 R4 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30316 R1 E2	REPLACEMENT OF TRANSFER TUBE ASSEMBLY			CATEGORY 5	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
	MOC : COMPLIED WITH - EMBODIED THIS VISIT									
SB PW500-72-30323 E1	FAN CASE WITH ADDITIONAL DRAIN HOLES - ON-WING MODIFICATION	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
	MOC : COMPLIED WITH - AT OVERHAUL									
SB PW500-72-30325 R03 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30325 R03 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30325 R2 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30325 R2 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30327 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30331 E1	MODIFICATION OF FUEL PRESSURE HOSE & TUBE ROUTING	UNK		CATEGORY 5	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30331 E2	MODIFICATION OF FUEL PRESSURE HOSE & TUBE ROUTING			CATEGORY 5	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30332 R2 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30334 R3 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30335 R1 E2	BORESCOPE INSPECTION OF GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS			CATEGORY 3	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30336 R1 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
MOC :										
SB PW500-72-30336 R1 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
MOC :										
SB PW500-72-30339 R2 E1	REPLACEMENT/MODIFICATION OF FRONT FAN CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30340 R2 E1	REPLACEMENT OF IGNITERS AND IGNITION CABLES	UNK		CATEGORY 7	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30340 R2 E2	REPLACEMENT OF IGNITERS AND IGNITION CABLES			CATEGORY 7	MTH 10-Mar-2009 HRS 4761.3 LDG 3119		-			Complete
MOC : COMPLIED WITH - EMBODIED										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30343 R6 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30343 R6 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30344 R1 E1	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30344 R1 E2	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30353 R1 E1	REPLACEMENT OF INTERSHAFT CARBON SEALS	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
	MOC :									
SB PW500-72-30356 R1 E1	REPLACEMENT/MODIFICATION HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
	MOC :									
SB PW500-72-30356 R2 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30356 R2 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30358 R1 E1	P3 AIR INERTIAL SEPARATOR WITH NO SILVER PLATING	UNK		CATEGORY 7	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
	MOC :									
SB PW500-72-30362 E1	REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
	MOC :									
SB PW500-72-30362 E2	REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS			CATEGORY 6	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
	MOC :									
SB PW500-72-30364 R1 E1	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS			CATEGORY 7			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**

Aircraft Model: **560XL - CITATION XL (MSG)**

Aircraft Serial: **560XL-5239**

Unit: **5239** Reg No: **N192W**

Airworthiness: **22-Mar-2002**

Print Date: **18-Mar-2018 2:27PM**

MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30369 R1 E1	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30371 R1 E2	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING			CATEGORY 6	MTH 31-Aug-2011 HRS 5205 LDG 3461		A/R			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30371 R1 E1	TURBOFAN ENGINE - ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE - INTRODUCTION			CATEGORY 10			-			
MOC :										
SB PW500-72-30371 R2 E1	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE			CATEGORY 10			-			
MOC :										
SB PW500-72-30371 R2 E2	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE			CATEGORY 10			-			
MOC :										
SB PW500-72-30371 E1	INTRODUCTION OF ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE	UNK		CATEGORY 10	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30376 R1 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30376 R2 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
MOC :										
SB PW500-72-30376 R2 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
MOC :										
SB PW500-72-30381 R2 E1	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING			CATEGORY 3	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30381 R2 E2	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING			CATEGORY 3	MTH 10-Mar-2008 HRS 4761.3 LDG 3119		A/R			Complete
MOC : COMPLIED WITH - EMBODIED										
SB PW500-72-30384 R1 E1	REPLACEMENT OF AIR/OIL SEPARATOR	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30384 R1 E2	REPLACEMENT OF AIR/OIL SEPARATOR			CATEGORY 6	MTH 31-Aug-2011 HRS 5205 LDG 3461		A/R			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30387 R1 E1	REPLACEMENT/MODIFICATION REAR BY-PASS DUCT ASSEMBLY	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30387 R2 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R2 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30387 R3 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R3 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R4 E1	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R4 E2	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R5 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R5 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30389 E1	REPLACEMENT OF CARBON SEAL, NO. 4 BEARING	UNK		CATEGORY 7	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30390 R5 E1	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R8, DATED JUNE 20, 2012)			CATEGORY 10			-			
MOC :										
SB PW500-72-30398 E1	REPLACEMENT OF BOLTS			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30398 E2	REPLACEMENT OF BOLTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30400 R1 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 R2 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
	MOC :									
SB PW500-72-30400 R3 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R3 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R4 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R4 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30403 R02 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R02 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R03 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R03 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R1 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
	MOC :									
SB PW500-72-30405 R04 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30405 R04 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R1 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
	MOC :									
SB PW500-72-30405 R2 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R3 E1	REPLACEMENT OF - FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	MOC :									
SB PW500-72-30408 E1	REPLACEMENT OF ENGINE GASKET	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
	MOC :									
SB PW500-72-30409 R10 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30409 R10 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30409 R3 E1	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30409 R3 E2	REPLACEMENT/MODIFICATION OF HYDROMACHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30409 R6 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30409 R7 E1	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF	UNK		CATEGORY 7	MTH 13-Feb-2012 HRS 5254.7 LDG 3457		-			Complete
	MOC :									
SB PW500-72-30409 R8 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3			-			
	MOC :									
SB PW500-72-30409 R8 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
	MOC :									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**

Aircraft Model: **560XL - CITATION XL (MSG)**

Aircraft Serial: **560XL-5239**

Unit: **5239** Reg No: **N192W**

Airworthiness: **22-Mar-2002**

Print Date: **18-Mar-2018 2:27PM**

MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30409 R9 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30409 R9 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30413 R10 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R10 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R1 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30413 R2 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30413 R3 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30413 R4 E1	INTRODUCTION OF DEEPER SUMP UNK			CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
	MOC : COMPLIED WITH - AT OVERHAUL									
SB PW500-72-30413 R5 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R5 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R6 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R6 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R7 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R7 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**

Aircraft Model: **560XL - CITATION XL (MSG)**

Aircraft Serial: **560XL-5239**

Unit: **5239** Reg No: **N192W**

Airworthiness: **22-Mar-2002**

Print Date: **18-Mar-2018 2:27PM**

MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30413 R8 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R8 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R9 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R9 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30415 R1 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R1 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R2 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R2 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R3 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R3 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30416 R1 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
	MOC :									
SB PW500-72-30416 R1 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
	MOC :									
SB PW500-72-30416 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL						A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30416 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL				MTH 31-Aug-2011 HRS 5205 LDG 3461		A/R			Complete
	MOC : COMPLIED WITH - EMBODIED THIS VISIT									
SB PW500-72-30417 R1 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 5						A/R			
	MOC :									
SB PW500-72-30417 R2 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 5						A/R			
	MOC :									
SB PW500-72-30417 R3 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 5						A/R			
	MOC :									
SB PW500-72-30417 R4 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 5						A/R			
	MOC :									
SB PW500-72-30417 R5 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 5						A/R			
	MOC :									
SB PW500-72-30417 R6 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 5						A/R			
	MOC :									
SB PW500-72-30417 R7 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 7						A/R			
	MOC :									
SB PW500-72-30417 R8 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 10						-			
	MOC :									
SB PW500-72-30417 R8 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 10						-			
	MOC :									
SB PW500-72-30417 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING CATEGORY 5						A/R			
	MOC :									
SB PW500-72-30419 R1 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER CATEGORY 7						-			
	MOC :									
SB PW500-72-30419 R1 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER CATEGORY 7						-			
	MOC :									
SB PW500-72-30419 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER UNK CATEGORY 7				MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
	MOC : COMPLIED WITH - AT OVERHAUL									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30419 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			MTH HRS LDG	31-Aug-2011 5205 3461		-			Complete
	MOC : COMPLIED WITH - EMBODIED THIS VISIT									
SB PW500-72-30420 R1 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6			-			
	MOC : - -SUPERSEDED BY REVISOIN 2									
SB PW500-72-30420 R2 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE	UNK		CATEGORY 6	MTH HRS LDG		-			Complete
	MOC : COMPLIED WITH - AT OVERHAUL									
SB PW500-72-30420 R2 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6	MTH HRS LDG		-			Complete
	MOC : COMPLIED WITH - EMBODIED THIS VISIT									
SB PW500-72-30420 R4 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6	MTH		-			
	MOC :									
SB PW500-72-30420 R4 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6	MTH		-			
	MOC :									
SB PW500-72-30420 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			N/A
	MOC : NOT APPLICABLE - SUPERSEDED SUPERSEDED BY REVISION 1									
SB PW500-72-30423 R1 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30423 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH HRS LDG		A/R			Complete
	MOC : COMPLIED WITH - AT OVERHAUL									
SB PW500-72-30425 R1 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL	LIT		CATEGORY 3	MTH HRS LDG		A/R			
	MOC : DECLINED - OWNER DOES NOT WISH TO COMPLY AT THIS TIME									
SB PW500-72-30425 R2 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL						A/R			
	MOC :									
SB PW500-72-30425 R2 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL				MTH HRS LDG		A/R			Complete
	MOC : COMPLIED WITH - EMBODIED THIS VISIT									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30425 R3 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10			-			
	MOC :									
SB PW500-72-30425 R3 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10			-			
	MOC :									
SB PW500-72-30425 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 3			A/R			
	MOC :									
SB PW500-72-30427 R1 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30427 R2 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30427 R3 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30427 R3 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30428 R05 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R05 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R1 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
	MOC :									
SB PW500-72-30428 R2 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R3 E1	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R4 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R4 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30429 R06 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 6						-			
MOC :										
SB PW500-72-30429 R06 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 6						-			
MOC :										
SB PW500-72-30429 R1 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R2) CATEGORY 6						A/R			
MOC :										
SB PW500-72-30429 R2 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R3) CATEGORY 6	UNK			MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30429 R2 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R3) CATEGORY 6				MTH 31-Aug-2011 HRS 5205 LDG 3461		A/R			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB PW500-72-30429 R3 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R4) CATEGORY 6						-			
MOC :										
SB PW500-72-30429 R3 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R4) CATEGORY 6						-			
MOC :										
SB PW500-72-30429 R4 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R5) CATEGORY 6						-			
MOC :										
SB PW500-72-30429 R4 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R5) CATEGORY 6						-			
MOC :										
SB PW500-72-30429 R5 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R06) CATEGORY 6						-			
MOC :										
SB PW500-72-30429 R5 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R06) CATEGORY 6						-			
MOC :										
SB PW500-72-30429 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R1) CATEGORY 6						A/R			
MOC :										
SB PW500-72-30432 R1 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF CATEGORY 7						A/R			
MOC :										
SB PW500-72-30432 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF CATEGORY 7						A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30436 R1 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30436 R1 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30436 R2 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30436 R2 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30436 R3 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30436 R3 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30436 E1	LPT 2ND STAGE VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF CATEGORY 7						A/R			
	MOC :									
SB PW500-72-30440 R1 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY CATEGORY 6						A/R			
	MOC :									
SB PW500-72-30440 R2 E1	REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY UNK CATEGORY 6				MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
	MOC : COMPLIED WITH - AT OVERHAUL									
SB PW500-72-30440 R3 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW500-72-30440 R3 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY CATEGORY 6				MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
	MOC : COMPLIED WITH - EMBODIED									
SB PW500-72-30440 R4 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW500-72-30440 R4 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW500-72-30440 R5 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY CATEGORY 6						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30440 R5 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30440 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30442 R1 E1	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT	UNK		CATEGORY 7	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
	MOC :									
SB PW500-72-30442 R2 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30442 R3 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30442 R3 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30442 E1	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30446 R1 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY	UNK		CATEGORY 7	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
	MOC :									
SB PW500-72-30446 R2 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30446 R2 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30447 R1 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30447 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30449 R1 E1	TURBOFAN ENGINE - HP TURBINE DISK ASSEMBLY - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 R2 E1	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30449 R2 E2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 E1	REPLACEMENT OF HP TURBINE DISK ASSEMBLY	UNK			MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
	MOC :									
SB PW500-72-30453 R03 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R03 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R1 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R1 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R2 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R2 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30455 R1 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R2 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R2 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R3 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R3 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30455 R4 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
MOC :										
SB PW500-72-30455 R4 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
MOC :										
SB PW500-72-30455 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT UNK			CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30462 R02 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 CATEGORY 8						-			
MOC :										
SB PW500-72-30462 R02 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 CATEGORY 8						-			
MOC :										
SB PW500-72-30462 R1 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 CATEGORY 8						-			
MOC :										
SB PW500-72-30462 R1 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 CATEGORY 8						-			
MOC :										
SB PW500-72-30462 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 CATEGORY 8						-			
MOC :										
SB PW500-72-30462 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 CATEGORY 8						-			
MOC :										
SB PW500-72-30463 R1 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL CATEGORY 7						-			
MOC :										
SB PW500-72-30463 R1 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL CATEGORY 7						-			
MOC :										
SB PW500-72-30463 R2 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL CATEGORY 7						-			
MOC :										
SB PW500-72-30463 R2 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL CATEGORY 7						-			
MOC :										
SB PW500-72-30463 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30464 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS CATEGORY 7						-			
	MOC :									
SB PW500-72-30464 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS CATEGORY 7						-			
	MOC :									
SB PW500-72-30465 R1 E1	REPLACEMENT OF FUEL MANIFOLD TUBES CATEGORY 7						-			
	MOC :									
SB PW500-72-30465 R1 E2	REPLACEMENT OF FUEL MANIFOLD TUBES CATEGORY 7						-			
	MOC :									
SB PW500-72-30465 R2 E1	REPLACEMENT OF FUEL MANIFOLD TUBES CATEGORY 7						-			
	MOC :									
SB PW500-72-30465 R2 E2	REPLACEMENT OF FUEL MANIFOLD TUBES CATEGORY 7						-			
	MOC :									
SB PW500-72-30465 E1	REPLACEMENT OF FUEL MANIFOLD TUBES CATEGORY 7						-			
	MOC :									
SB PW500-72-30465 E2	REPLACEMENT OF FUEL MANIFOLD TUBES CATEGORY 7						-			
	MOC :									
SB PW500-72-30466 R1 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY CATEGORY 7						-			
	MOC :									
SB PW500-72-30466 R1 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY CATEGORY 7						-			
	MOC :									
SB PW500-72-30466 E1	REPLACEMENT OF 2ND STAGE TURBINE VANE ASSY CATEGORY 7						-			
	MOC :									
SB PW500-72-30470 R1 E1	REPLACEMENT OF DATA COLLECTION UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30470 R1 E2	REPLACEMENT OF DATA COLLECTION UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30470 E1	REPLACEMENT OF DATA COLLECTION UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30470 E2	REPLACEMENT OF DATA COLLECTION UNIT CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30472 R1 E1	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 R1 E2	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 PART A E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 PART A E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 PART B E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 PART B E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 PART A E1	ACCOMPLISH REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 PART A E2	ACCOMPLISH REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 PART B E1	ACCOMPLISH REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 PART B E2	ACCOMPLISH REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30475 R3 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30479 R1 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R1 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R2 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R2 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R3 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R3 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R4 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R4 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R5 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R5 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R6 E1	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 3	MTH HRS		DUE DUE DUE		10254.7	2577.1
	MOC :									
SB PW500-72-30479 R6 E2	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 3	MTH HRS		DUE DUE DUE		8149.7	472.1
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30479 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30479 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30482 R1 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
	MOC :									
SB PW500-72-30482 R1 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
	MOC :									
SB PW500-72-30482 R2 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT	LIT		CATEGORY 3	MTH 25-Mar-2014 HRS 6229.5 LDG 4023		-			Complete
	MOC :									
SB PW500-72-30482 R2 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT	LIT		CATEGORY 3	MTH 03-Jun-2014 HRS 6339.3 LDG 4081		-			Complete
	MOC :									
	MOC :				COMPLIED WITH - NO DEFECTS NOTED AT THIS TIME					
SB PW500-72-30482 R2 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT	LIT		CATEGORY 3	MTH 03-Jun-2014 HRS 6339.3 LDG 4081		-			Complete
	MOC :									
	MOC :				COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN PW500-72-3048 R2. ONE NUT MISSING, WITHIN LIMITS OF SERVICE BULLETIN. NO FURTHER ACTION REQUIRED AT THIS TIME.					
SB PW500-72-30482 R3 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30482 R3 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30482 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30482 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30483 R1 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R1 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R2 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**

Aircraft Model: **560XL - CITATION XL (MSG)**

Aircraft Serial: **560XL-5239**

Unit: **5239** Reg No: **N192W**

Airworthiness: **22-Mar-2002**

Print Date: **18-Mar-2018 2:27PM**

MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30483 R2 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R3 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30483 R3 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30483 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R02 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R02 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R1 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R1 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30486 R1 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING			CATEGORY 7			-			
	MOC :									
SB PW500-72-30486 R1 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING			CATEGORY 7			-			
	MOC :									
SB PW500-72-30486 R2 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING.			CATEGORY 7			-			
	MOC :									
SB PW500-72-30486 R2 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING.			CATEGORY 7			-			
	MOC :									
SB PW500-72-30486 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30486 E2	REPLACEMENT OF BREATHING ADAPTER PREFORMED PACKING CATEGORY 7						-			
MOC :										
SB PW500-72-30487 R3 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502) CATEGORY 10						-			
MOC :										
SB PW500-72-30487 R3 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502) CATEGORY 10						-			
MOC :										
SB PW500-72-30487 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL						-			
MOC :										
SB PW500-72-30487 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL						-			
MOC :										
SB PW500-72-30491 R1 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW500-72-30491 R1 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW500-72-30491 R2 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW500-72-30491 R2 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW500-72-30491 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW500-72-30491 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW500-72-30492 R1 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 7						-			
MOC :										
SB PW500-72-30492 R1 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 7						-			
MOC :										
SB PW500-72-30492 R2 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 7						-			
MOC :										
SB PW500-72-30492 R2 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30492 R3 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 6						-			
	MOC :									
SB PW500-72-30492 R3 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 6						-			
	MOC :									
SB PW500-72-30492 R4 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 6						-			
	MOC :									
SB PW500-72-30492 R4 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 6						-			
	MOC :									
SB PW500-72-30492 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 7						-			
	MOC :									
SB PW500-72-30492 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER CATEGORY 7						-			
	MOC :									
SB PW500-72-30495 R1 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE CATEGORY 10						-			
	MOC :									
SB PW500-72-30495 R1 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE CATEGORY 10						-			
	MOC :									
SB PW500-72-30495 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30498) CATEGORY 10						-			
	MOC :									
SB PW500-72-30495 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30498) CATEGORY 10						-			
	MOC :									
SB PW500-72-30496 E1	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE CATEGORY 6						-			
	MOC :									
SB PW500-72-30496 E2	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE CATEGORY 6						-			
	MOC :									
SB PW500-72-30498 R02 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30498 R02 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30498 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30498 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30498 R1 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30498 R1 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30498 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30498 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW500-72-30500 E1	REPLACEMENT OF PREFORMED PACKING CATEGORY 7						-			
	MOC :									
SB PW500-72-30500 E2	REPLACEMENT OF PREFORMED PACKING CATEGORY 7						-			
	MOC :									
SB PW500-72-30501 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS CATEGORY 3						-			
	MOC :									
SB PW500-72-30501 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS CATEGORY 3						-			
	MOC :									
SB PW500-72-30502 R1 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL CATEGORY 7						-			
	MOC :									
SB PW500-72-30502 R1 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL CATEGORY 7						-			
	MOC :									
SB PW500-72-30502 R2 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL CATEGORY 7						-			
	MOC :									
SB PW500-72-30502 R2 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL CATEGORY 7						-			
	MOC :									
SB PW500-72-30502 R2 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30502 R2 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R2 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R2 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R3 PART A E1	ACCOMPLISH REPLACE FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R3 PART A E2	ACCOMPLISH REPLACE FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R3 PART B E1	ACCOMPLISH REPLACE ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R3 PART B E2	ACCOMPLISH REPLACE ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R3 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R3 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R4 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R4 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R4 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R4 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R4 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R4 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30502 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL CATEGORY 7						-			
MOC :										
SB PW500-72-30502 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL CATEGORY 7						-			
MOC :										
SB PW500-72-30504 R1 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER CATEGORY 7						-			
MOC :										
SB PW500-72-30504 R1 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER CATEGORY 7						-			
MOC :										
SB PW500-72-30504 R2 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER CATEGORY 7						-			
MOC :										
SB PW500-72-30504 R2 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER CATEGORY 7						-			
MOC :										
SB PW500-72-30504 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER CATEGORY 7						-			
MOC :										
SB PW500-72-30504 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER CATEGORY 7						-			
MOC :										
SB PW500-72-30505 R1 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS KALN CATEGORY 3				MTH 13-Mar-2015 HRS 6612.3 LDG 4335		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PW500-72-30505 R1 NO. 1 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS.TRANS.										
SB PW500-72-30505 R1 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS KALN CATEGORY 3				MTH 13-Mar-2015 HRS 6613 LDG 4335		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PW500-72-30505 R1 NO. 2 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS.										
SB PW500-72-30505 R2 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS CATEGORY 3						-			
MOC :										
SB PW500-72-30505 R2 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS CATEGORY 3						-			
MOC :										
SB PW500-72-30505 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS CATEGORY 3						-			
MOC :										
SB PW500-72-30505 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS CATEGORY 3						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30506 R1 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30506 R1 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30506 R2 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30506 R2 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30506 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30506 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30508 R1 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30508 R1 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30508 R2 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30508 R2 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30508 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30508 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30511 R1 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30511 R1 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30511 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30511 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS CATEGORY 6						-			
MOC :										
SB PW500-72-30512 R1 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL CATEGORY 3						-			
MOC :										
SB PW500-72-30512 R1 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL CATEGORY 3						-			
MOC :										
SB PW500-72-30512 R2 E1	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL KALN CATEGORY 3				MTH 10-Mar-2016 HRS 6922.9 LDG 4552		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PW500-72-30512 R2 NO. 1 ENGINE - INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL, SERVICE BULLETIN.										
SB PW500-72-30512 R2 E2	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL LIT CATEGORY 3				MTH 01-Feb-2016 HRS 6903.2 LDG 4539		-			N/A
MOC : NOT APPLICABLE - SB PW500-72-30512 R2 DOES NOT APPLY										
SB PW500-72-30512 R3 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL CATEGORY 3				MTH		-			
MOC :										
SB PW500-72-30512 R3 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL CATEGORY 3				MTH		-			
MOC :										
SB PW500-72-30512 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL CATEGORY 3				MTH		-			
MOC :										
SB PW500-72-30512 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL CATEGORY 3				MTH		-			
MOC :										
SB PW500-72-30516 R1 E1	REPLACEMENT OF HP TURBINE SEAL RINGS CATEGORY 7						-			
MOC :										
SB PW500-72-30516 R1 E2	REPLACEMENT OF HP TURBINE SEAL RINGS CATEGORY 7						-			
MOC :										
SB PW500-72-30516 R2 E1	REPLACEMENT OF HP TURBINE SEAL RINGS CATEGORY 7						-			
MOC :										
SB PW500-72-30516 R2 E2	REPLACEMENT OF HP TURBINE SEAL RINGS CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72- 30517 R1 E1	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
	MOC :									
SB PW500-72- 30517 R1 E2	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
	MOC :									
SB PW500-72- 30517 E1	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
	MOC :									
SB PW500-72- 30517 E2	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
	MOC :									
SB PW500-72- 30518 E1	SALEABILITY CHANGE - TURBINE EXHAUST CASE END CONE			CATEGORY 9			-			
	MOC :									
SB PW500-72- 30518 E2	SALEABILITY CHANGE - TURBINE EXHAUST CASE END CONE			CATEGORY 9			-			
	MOC :									
SB PW500-72- 30521 R1 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
	MOC :									
SB PW500-72- 30521 R1 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
	MOC :									
SB PW500-72- 30523 R1 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
	MOC :									
SB PW500-72- 30523 R1 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
	MOC :									
SB PW500-72- 30523 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
	MOC :									
SB PW500-72- 30523 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
	MOC :									
SB PW500-72- 30526 E1	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72- 30526 E2	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72- 30527 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30527 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	MOC :									
SB PW500-72-30532 E1	REPLACEMENT OF RETAINING RINGS			CATEGORY 9			-			
	MOC :									
SB PW500-72-30532 E2	REPLACEMENT OF RETAINING RINGS			CATEGORY 9			-			
	MOC :									
SB PW500-72-30534 R01 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R01 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R02 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R02 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R03 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R03 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 R01 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 R01 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30540 E1	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL					-			
	MOC :								
SB PW500-72-30540 E2	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL					-			
	MOC :								
SB PW500-72-30541 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL		CATEGORY 7			-			
	MOC :								
SB PW500-72-30541 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL		CATEGORY 7			-			
	MOC :								
SB PW500-72-30541 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL		CATEGORY 7			-			
	MOC :								
SB PW500-72-30541 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL		CATEGORY 7			-			
	MOC :								
SB PW500-72-30541 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL		CATEGORY 7			-			
	MOC :								
SB PW500-72-30541 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL		CATEGORY 7			-			
	MOC :								
SB PW500-72-30543 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS		CATEGORY 7			-			
	MOC :								
SB PW500-72-30543 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS		CATEGORY 7			-			
	MOC :								
ASB PW500-72-A30421 R2 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE		CATEGORY 3			-			
	MOC :								
ASB PW500-72-A30421 R2 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE		CATEGORY 3			-			
	MOC :								
ASB PW500-72-A30452 R1 E1	TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP		CATEGORY 3 MTH			-			
	MOC :								
ASB PW500-72-A30452 R2 E1	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED)		CATEGORY 10			-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
ASB PW500-72-A30452 R2 E2	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED) CATEGORY 10						-			
MOC :										
ASB PW500-72-A30452 E1	TURBOFAN ENGINE OIL SYSTEM - SPECIAL INSPECTION OF MOP	UNK		CATEGORY 3	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB 560XL-73-01 73SB-01 : XL	ENGINE FUEL AND CONTROL - ENGINE FUEL LINE FITTING INSPECTION	HUR		MANDATORY	MTH 07-Feb-2003 HRS 451		-			Complete
MOC : COMPLIED WITH										
ASL 560XL-73-11 LEFT ENGINE 73ASL-11 : E1**L	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN A30319 TURBOFAN ENGINE NEW FUEL MANIFOLD-INTRODUCTION OF	LIT		MANDATORY	MTH 25-Sep-2007 HRS 2762		A/R			Complete
MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.										
ASL 560XL-73-11 RIGHT ENGINE 73ASL-11 : E2**R	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN A30319 TURBOFAN ENGINE NEW FUEL MANIFOLD-INTRODUCTION OF	LIT		MANDATORY	MTH 25-Sep-2007 HRS 2762		A/R			Complete
MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.										
SL 560XL-73-03 73SL-03 : XL	ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&WC SERVICE BULLETIN 30249 TURBOFAN ENGINE FUEL MANIFOLD - INSPECTION/REPLACEMENT OF AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03008	ICT		RECOMMENDED	MTH 22-Mar-2004 HRS 1016		-			Complete
MOC : COMPLIED WITH										
SL 560XL-73-04 73SL-04 : XL	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30253: TURBOFAN ENGINE FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR INTRODUCTION OF MODEL APPLICATION PW545A AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03012 (SUPERSEDED BY SL560XL-73-04 R01)	LBG		RECOMMENDED	MTH 16-Dec-2003 HRS 906		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-73-08 73SL-08 : XL	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN NUMBER 30296R1, TURBOFAN ENGINE HFC RATIO UNIT SETSCREW ADJUSTMENT - INSPECTION OF	LIT		MANDATORY	MTH 14-Jul-2006 HRS 2221		-			Complete
MOC : COMPLIED WITH										
SL 560XL-73-12 R01	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE/FAIRING/REPLACEMENT OF			RECOMMENDED	MTH 22-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - BY PW500-72-30381 R2										
SB PW500-72-30266 R1 E1	REPLACEMENT/MODIFICATION OF IGNITION EXCITER CATEGORY 7						A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30343 R5 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30404 R3 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30414 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 10			A/R			
MOC :										
ASB PW500-72-A30421 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE	LIT		CATEGORY 3	MTH 31-Aug-2010 HRS 4520.7 LDG 2937		-			N/A
MOC : NOT APPLICABLE - ASB PW500-72-A30421 DOES NOT APPLY, BLEED VALVE HAS NOT BEEN REPLACED IN THE PREVIOUS 250 HOURS.										
SB 560XL-78-02 78SB-02 : XL	EXHAUST - THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT			OPTIONAL	MTH		-			
MOC :										
SB PW500-72-30325 R1 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL	UNK		CATEGORY 6	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
SB PW500-72-30325 R1 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6	MTH 31-Aug-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED THIS VISIT										
SB 560XL-80-03 80SB-03 : XL	STARTING - APU GENERATOR CONTROL UNIT (GCU) CURRENT LIMITING	ICT		RECOMMENDED	MTH 24-May-2005 HRS 1595		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2003-03-21 E1	TO PREVENT A FIRE IN THE ENGINE NACELLE AREA	UNK		MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - EMBODIED									
FAA 2003-03-21 E2	TO PREVENT A FIRE IN THE ENGINE NACELLE AREA			MTH 15-Nov-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED									
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	LIT	MANDATORY	DAYS 30-Sep-2013 HRS 6053.2 LDG 3905		-			N/A
MOC : NOT APPLICABLE - N/A, FREON AIR CONDITIONING NOT INSTALLED.									
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	LIT	MANDATORY	DAYS 30-Sep-2013 HRS 6053.2 LDG 3905		-			N/A
MOC : NOT APPLICABLE - N/A, FREON AIR CONDITIONING NOT INSTALLED.									
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	LIT	MANDATORY	MTH 30-Sep-2013 HRS 6053.2 LDG 3905		-			N/A
MOC : NOT APPLICABLE - N/A, FREON AIR CONDITIONING NOT INSTALLED									
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM	LIT	MANDATORY	MTH 30-Sep-2013 HRS 6053.2 LDG 3905		A/R			N/A
MOC : NOT APPLICABLE - N/A, FREON AIR CONDITIONING NOT INSTALLED									
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM	LIT	MANDATORY	MTH 30-Sep-2013 HRS 6053.2 LDG 3905		A/R			N/A
MOC : NOT APPLICABLE - N/A, FREON AIR CONDITIONING NOT INSTALLED									
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS	LIT	MANDATORY	DAYS 30-Sep-2013 HRS 6053.2 LDG 3905		-			N/A
MOC : NOT APPLICABLE - N/A, FREON AIR CONDITIONING NOT INSTALLED									
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	LIT	MANDATORY	MTH 30-Sep-2013 HRS 6053.2 LDG 3905		-			N/A
MOC : NOT APPLICABLE - N/A, FREON AIR CONDITIONING NOT INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2006-19-04 34AD-14 : XL	APPLIANCE AD - HONEYWELL RCZ COMM & XPDRS LIT			MANDATORY	MTH 10-Nov-2006 HRS 2380		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2017-04-14 PARA (G)	ACCOMPLISH GENERAL VISUAL INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES FOR EVIDENCE OF DAMAGE, ALL APPLICABLE ADJUSTMENTS, AND ALL APPLICABLE CORRECTIVE ACTIONS	KALN		MANDATORY	DAYS 31-Mar-2017 HRS 7313.2 LDG 4787		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH FAA AD2017-04-14 PARA (G) BY THE COMPLETION OF SL560XL-24-07. SL560XL-24-07 WAS COMPLETED BY TEXTRON AVIATION SERVICE CRS# CNQR918C. REFERENCE MTR # 2674337 DATED 20/JAN/2017										
FAA 2017-04-14 PARA (H)	SUBMIT A REPORT OF THE FINDINGS (BOTH POSITIVE AND NEGATIVE) OF THE INSPECTIONS REQUIRED BY PARAGRAPH (G) OF THIS AD TO TEXTRON AVIATION	KALN		MANDATORY	DAYS 31-Mar-2017 HRS 7313.2 LDG 4787		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH FAA AD2017-04-14 (H) BY THE COMPLETION OF SL560XL-24-07. SL560XL-24-07 WAS COMPLETED BY TEXTRON AVIATION SERVICE CRS# CNQR918C. REFERENCE MTR # 2674337 DATED 20/JAN/2017										
FAA 2017-04-14	ELECTRICAL POWER - INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES	KALN		MANDATORY	MTH 31-Mar-2017 HRS 7313.2 LDG 4787		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH FAA 2017-04-14 BY THE COMPLETION OF SL560XL-24-07. SL560XL-24-07 WAS COMPLETED BY TEXTRON AVIATION SERVICE CRS# CNQR918C. REFERENCE MTR # 2674337 DATED 20/JAN/2017.										
FAA 1974-08-09 R02 053801	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION LIT			MANDATORY	MTH 05-Dec-2011 HRS 5090.5 LDG 3291		-			Complete
MOC : COMPLIED WITH										
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION LIT			MANDATORY	MTH 31-Oct-2016 HRS 7071.9 LDG 4612 APUH 3196.9 APUS 5319		1000		8071.9	Complete 394.3
MOC : COMPLIED WITH - C/W AD74-08-09R3 BY INSPECTION, CK OK.										
FAA 1998-25-10 25AD-01 : XL	APPLIANCE AD - AIRCRAFT BELT INSPECTION ICT			MANDATORY	MTH 22-Mar-2002 HRS 9		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	KALN		MANDATORY	MTH 22-Jul-2016 HRS 6980.6 LDG 4542		-			N/A
MOC : NOT APPLICABLE - FAA 2014-18-01 APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION... NOT APPLICABLE TO THIS AIRCRAFT, HONEYWELL TRANSPONDERSINSTALLED.										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	KALN		MANDATORY	MTH 22-Jul-2016 HRS 6980.6 LDG 4542		-			N/A
MOC : NOT APPLICABLE - FAA 2014-18-01 APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION... NOT APPLICABLE TO THIS AIRCRAFT, HONEYWELL TRANSPONDERSINSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	KALN		MANDATORY	MTH 22-Jul-2016 HRS 6980.6 LDG 4542		-			N/A
MOC : NOT APPLICABLE - FAA 2014-18-01 APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION... NOT APPLICABLE TO THIS AIRCRAFT, HONEYWELL TRANSPONDERSINSTALLED.										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KALN		MANDATORY	MTH 22-Jul-2016 HRS 6980.6 LDG 4542		-			Complete
MOC : COMPLIED WITH - FAA 2014-18-01 APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION... NOT APPLICABLE TO THIS AIRCRAFT, HONEYWELL TRANSPONDERSINSTALLED.										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS			MANDATORY	MTH		12		24-Oct-2018	7 m 6 d
MOC :										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT			MANDATORY			-			
MOC :										
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS			MANDATORY			-			
MOC :										
FAA 2003-26-14 26AD-02 : XL	APPLIANCE AD - KIDDE AEROSPACE HAND HELD BOTTLE	ICT		MANDATORY	MTH 22-Mar-2004 HRS 1016		A/R			Complete
MOC : COMPLIED WITH										
FAA 2006-04-10 26AD-03 : XL	INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.	LIT		MANDATORY	MTH 27-Apr-2006 HRS 2120		A/R			Complete
MOC : COMPLIED WITH										
FAA 2007-11-17 26AD-05 : XL	IDENTIFY WIRES FOR FIRE EXTINGUISHING BOTTLES	LIT		MANDATORY	MTH 25-Sep-2007 HRS 2762		A/R			Complete
MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.										
FAA 2000-15-51 27AD-01 : XL	AILERON CABLE FAIRLEAD TUBE AND AILERON CABLE SECTOR	ICT		MANDATORY	MTH 22-Mar-2002 HRS 9		-			Complete
MOC : COMPLIED WITH										
FAA 2012-09-01	LANDING GEAR - TORQUE LUG - INSPECTION	KALN		MANDATORY	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED THE FAA AD 2012-09-01 AMENDMENT # 39-17036 EFFECTIVE 7JUN2012. INSPECTED THE LH & RH WHEEL ASSEMBLIES AND FOUND EACH WHEEL AS BEEN PREVIOUSLY ACCOMPLISHEDPER THE CESSNA SB560XL-32-41REV1										
FAA 1995-22-01 33AD-01 : XL	APPLIANCE AD - AEROSPACE LIGHTING POWER UNIT	ICT		MANDATORY	MTH 22-Mar-2002 HRS 9		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1997-05-03 R01 <i>34AD-07 : XLR1</i>	APPLIANCE AD - GNX-XLS AND GNS-XL GPS ICT			MANDATORY	MTH 22-Mar-2002 HRS 9		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 1999-23-22 R01	APPLIANCE AD - TRANSPORT CATEGORY MODE C XPD MANDATORY						-			
MOC :										
FAA 1999-23-22 R02	APPLIANCE AD - TRANSPORT CATEGORY MODE C XPD KALN			MANDATORY	MTH 22-Jul-2016 HRS 6980.6 LDG 4542		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH FAA 1999-23-22 R2 TRANSPORT CATEGORY MODE C XPD. TRANSPONDERS INSTALLED ARE MODE S.										
FAA 2001-23-17 <i>34AD-09 : XL</i>	APPLIANCE AD - GARMIN INTERNATIONAL GNS 430 ICT			MANDATORY	MTH 22-Mar-2002 HRS 9		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2003-04-06 <i>34AD-03 : XL</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM ICT			SUPERSEDED	MTH 22-Mar-2004 HRS 1016		A/R			Complete
MOC : COMPLIED WITH										
FAA 2006-16-18 <i>34AD-13 : XL</i>	APPLIANCE AD - SANDEL AVI MOD ST3400 TAWS/RM LIT			MANDATORY	MTH 21-Mar-2007 HRS 2511		A/R			N/A
MOC : NOT APPLICABLE										
FAA 2006-22-05 <i>34AD-15 : XL</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM ALN			MANDATORY	MTH 23-Jul-2008 HRS 3204		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE										
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	LIT		MANDATORY	MTH 30-Sep-2013 HRS 6053.2 LDG 3905		A/R			Complete
MOC : COMPLIED WITH - AD2010-07-02 P/C/W, NO FURTHER ACTION REQUIRED.										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	LIT		MANDATORY	MTH 30-Jan-2015 HRS 6534.3 LDG 4231		-			N/A
MOC : NOT APPLICABLE - AD2012-02-08 N/A, EQUIPMENT NOT INSTALLED.										
FAA 2012-26-15 PARA (G)(1)	REMOVE IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01) AFFECTED ADC, ADM, ADAHRS, OR DADC	LIT		MANDATORY	DAYS 15-Jan-2013 HRS 5670 LDG 3671		-			N/A
MOC : NOT APPLICABLE - DUE TO S/N OF INSTALLED COMPONENTS. NO FURTHER ACTION REQUIRED										
FAA 2012-26-15 PARA (G)(2)	PERFORM IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01) PITOT-STATIC CERTIFICATION TEST	LIT			DAYS 15-Jan-2013 HRS 5670 LDG 3671		-			N/A
MOC : NOT APPLICABLE - DUE TO S/N OF INSTALLED COMPONENTS. NO FURTHER ACTION REQUIRED										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2012-26-15 R01	APPLIANCE AD - AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC) MANDATORY MTH				-			
MOC :								
FAA 2012-26-15	APPLIANCE AD - IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01) LIT MANDATORY MTH 15-Jan-2013 HRS 5670 LDG 3671				-			N/A
MOC : NOT APPLICABLE - DUE TO S/N OF INSTALLED COMPONENTS. NO FURTHER ACTION REQUIRED								
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION KALN MANDATORY MTH 22-Jul-2016 HRS 6980.6 LDG 4542				-			N/A
MOC : NOT APPLICABLE - FAA 2014-18-01 APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION... NOT APPLICABLE TO THIS AIRCRAFT, HONEYWELL TRANSPONDERS INSTALLED.								
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS. MANDATORY MTH				-			
MOC :								
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS KALN MANDATORY MTH 22-Jul-2016 HRS 6980.6 LDG 4542				-			N/A
MOC : NOT APPLICABLE - FAA 2015-10-51 APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIM... OT APPLICABLE TO THIS AIRCRAFT, NO AVIDYNE FLIGHT DISPLAYS ARE INSTALLED								
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011 KALN MANDATORY MTH 31-Mar-2017 HRS 7313.2 LDG 4787				-			N/A
MOC : NOT APPLICABLE - BOTH HARNESSES ARE OUT OF THE APPLICABLE DATE RANGE. NO FURTHER ACTION REQUIRED, AT THIS TIME.								
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES KALN MANDATORY MTH 31-Mar-2017 HRS 7313.2 LDG 4787				-			N/A
MOC : NOT APPLICABLE - BOTH HARNESSES ARE OUT OF THE APPLICABLE DATE RANGE. NO FURTHER ACTION REQUIRED, AT THIS TIME.								
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES KALN MANDATORY MTH 31-Mar-2017 HRS 7313.2 LDG 4787				-			N/A
MOC : NOT APPLICABLE - BOTH HARNESSES ARE OUT OF THE APPLICABLE DATE RANGE. NO FURTHER ACTION REQUIRED, AT THIS TIME.								
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER LIT MANDATORY MTH 01-Feb-2016 DAYS 6846.2 HRS 4450 LDG				-			N/A
MOC : NOT APPLICABLE - AD 2015-23-09 PARA(G),(H)(1)(2)(I)(II),(I) DOES NOT APPLY, AFFECTED MASKS NOT INSTALLED.								



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-23-09 PARA (H)(1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	LIT		MANDATORY	MTH 01-Feb-2016 DAYS 6846.2 HRS 4450 LDG		-			N/A
MOC : NOT APPLICABLE - AD 2015-23-09 PARA(G),(H)(1)(2)(I)(II),(I) DOES NOT APPLY, AFFECTED MASKS NOT INSTALLED.										
FAA 2015-23-09 PARA (H)(2)(I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	LIT		MANDATORY	MTH 01-Feb-2016 DAYS 6846.2 HRS 4450 LDG		-			N/A
MOC : NOT APPLICABLE - AD 2015-23-09 PARA(G),(H)(1)(2)(I)(II),(I) DOES NOT APPLY, AFFECTED MASKS NOT INSTALLED.										
FAA 2015-23-09 PARA (H)(2)(II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	LIT		MANDATORY	MTH 01-Feb-2016 DAYS 6846.2 HRS 4450 LDG		-			N/A
MOC : NOT APPLICABLE - AD 2015-23-09 PARA(G),(H)(1)(2)(I)(II),(I) DOES NOT APPLY, AFFECTED MASKS NOT INSTALLED.										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	LIT		MANDATORY	MTH 01-Feb-2016 HRS 6846.2 LDG 4450		-			N/A
MOC : NOT APPLICABLE - AD 2015-23-09 PARA(G),(H)(1)(2)(I)(II),(I) DOES NOT APPLY, AFFECTED MASKS NOT INSTALLED.										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	LIT		MANDATORY	MTH 01-Feb-2016 HRS 6846.2 LDG 4450		-			N/A
MOC : NOT APPLICABLE - AD 2015-23-09 PARA(G),(H)(1)(2)(I)(II),(I) DOES NOT APPLY, AFFECTED MASKS NOT INSTALLED.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12	LIT		MANDATORY	MTH 31-Oct-2016 HRS 7071.9 LDG 4612 APUH 3196.9 APUS 5319		-			N/A
MOC : NOT APPLICABLE - AD 2016-11-20 N/A, EQUIPMENT NOT INSTALLED.										
FAA 2016-11-20 PARA (H)(1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	LIT		MANDATORY	MTH 31-Oct-2016 HRS 7071.9 LDG 4612 APUH 3196.9 APUS 5319		-			N/A
MOC : NOT APPLICABLE - AD 2016-11-20 N/A, EQUIPMENT NOT INSTALLED.										
FAA 2016-11-20 PARA (H)(2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	LIT		MANDATORY	MTH 31-Oct-2016 HRS 7071.9 LDG 4612 APUH 3196.9 APUS 5319		-			N/A
MOC : NOT APPLICABLE - AD 2016-11-20 N/A, EQUIPMENT NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12									
		LIT		MANDATORY	MTH 31-Oct-2016 HRS 7071.9 LDG 4612 APUH 3196.9 APUS 5319		-			N/A
	MOC : NOT APPLICABLE - AD 2016-11-20 N/A, EQUIPMENT NOT INSTALLED.									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED									
				MANDATORY			-			
	MOC :									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED									
				MANDATORY			-			
	MOC :									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.									
				MANDATORY	MTH		6		16-Apr-2018	29 d
	MOC :									
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES									
				MANDATORY			-			
	MOC :									
FAA 2012-06-01	MODIFY THE DRAIN INSTALLATION OF THE TAILCONE STINGER ON THE AFT CANTED BULKHEAD									
		KALN		MANDATORY	MTH 27-Jul-2012 HRS 5443.8 LDG 3531		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED THE FAA AD 2012-06-01 AMENDMENT # 39-16982 EFFECTIVE 25APR2012 PER THE CESSNA SB560XL-53-16 INSTRUCTIONS									
FAA 2010-18-09 PARA (E)(2) E1	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE									
		LIT		MANDATORY	MTH 31-Aug-2010 HRS 4520.7 LDG 2937		-			N/A
	MOC : NOT APPLICABLE - AD2010-18-09 PAR (E)(2) DOES NOT APPLY.									
FAA 2010-18-09 PARA (E)(2) E2	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE									
				MANDATORY	MTH 15-Nov-2011 HRS 5205 LDG 3461		-			Complete
	MOC : COMPLIED WITH - EMBODIED									
FAA 2010-18-09 PARA (E)(3) E1	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING									
		LIT		MANDATORY	MTH 31-Aug-2010 HRS 4520.7 LDG 2937		-			N/A
	MOC : NOT APPLICABLE - AD2010-18-09 PAR (E)(3) DOES NOT APPLY.									
FAA 2010-18-09 PARA (E)(3) E2	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING									
				MANDATORY	MTH 15-Nov-2011 HRS 5205 LDG 3461		-			Complete
	MOC : COMPLIED WITH - EMBODIED									
FAA 2010-18-09 E1	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE									
		UNK		MANDATORY	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
	MOC : COMPLIED WITH - EMBODIED									



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
Aircraft Model: **560XL - CITATION XL (MSG)**
Aircraft Serial: **560XL-5239**
Unit: **5239** Reg No: **N192W**
Airworthiness: **22-Mar-2002**
Print Date: **18-Mar-2018 2:27PM**
MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2010-18-09 E2	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE			MANDATORY	MTH 15-Nov-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED										
TCCA CF-2002-42 E1	PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A, AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES	UNK		MANDATORY	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		-			Complete
MOC : COMPLIED WITH - EMBODIED										
TCCA CF-2002-42 E2	PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A, AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES			MANDATORY	MTH 15-Nov-2011 HRS 5205 LDG 3461		-			Complete
MOC : COMPLIED WITH - EMBODIED										
TCCA CF-2010-19 STEP A,B,C,D,E,F,G E1	INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421			MANDATORY	MTH 13-Feb-2012 HRS 5254.7 LDG 3457		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
TCCA CF-2010-19 STEP A,B,C,D,E,F,G E2	INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421	UNK		MANDATORY	MTH 15-Nov-2011 HRS 5205 LDG 3461		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 STEP H. E1	TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A			MANDATORY	MTH 13-Feb-2012 HRS 5254.7 LDG 3457		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
TCCA CF-2010-19 STEP H. E2	TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A	UNK		MANDATORY	MTH 15-Nov-2011 HRS 5205 LDG 3461		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 E1	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION			MANDATORY	MTH 13-Feb-2012 HRS 5198.4 LDG 3368		A/R			Complete
MOC : COMPLIED WITH - AT OVERHAUL										
TCCA CF-2010-19 E2	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION	UNK		MANDATORY	MTH 15-Nov-2011 HRS 5148 LDG 3372		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **WINDSTREAM COMMUNICATIONS, INC.**
 Aircraft Model: **560XL - CITATION XL (MSG)**
 Aircraft Serial: **560XL-5239**
 Unit: **5239** Reg No: **N192W**
 Airworthiness: **22-Mar-2002**
 Print Date: **18-Mar-2018 2:27PM**
 MSG-3 Program Applied Date: **04-Aug-2008**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7677.6	5017	08-Mar-2018	.62
ENG 1	7486.9	4831	08-Mar-2018	.62
ENG 2	4527.9	2988	08-Mar-2018	.62
APU	3452.3	5678	08-Mar-2018	.17

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
21FO-04XL <i>21FO-04 : XL</i>	REMOTE CABIN TEMP CONTROL FACTORY OPTION	*CF		16 FO	MTH 22-Mar-2002		-			
23FO-04XL/T <i>23FO-04 : XL/T</i>	HF COMM: KHF-950 SM CONTROL HEAD FACTORY OPTION	*CF		631T FO	MTH 22-Mar-2002		-			
23FO-05XL/J <i>23FO-05 : XL/J</i>	RECORDER: FLT DATA PROVISION FACTORY OPTION	*CF		634J FO	MTH 22-Mar-2002		-			
23FO-06XL/Z <i>23FO-06 : XL/Z</i>	VHF: UNILINK UNIVERSAL FACTORY OPTION	*CF		674Z FO	MTH 22-Mar-2002		-			
24FO-01XL/N <i>24FO-01 : XL/N</i>	BATTERY: SEALED LEAD ACID FACTORY OPTION	*CF		186N FO	MTH 22-Mar-2002		-			
25FO-03XL <i>25FO-03 : XL</i>	PLUMBING: EXTERNAL SERV TOILET FACTORY OPTION	*CF		130 FO	MTH 22-Mar-2002		-			
25FO-04XL <i>25FO-04 : XL</i>	COCKPIT SPEAKER MUTE FACTORY OPTION	*CF		674B FO	MTH 22-Mar-2002		-			
25FO-12XL/A <i>25FO-12 : XL/A</i>	PEDESTAL: DOUBLE-WIDE FACTORY OPTION	*CF		649A FO	MTH 22-Mar-2002		-			
33FO-02XL/D <i>33FO-02 : XL/D</i>	PULSE LITE: GND OPERATION FACTORY OPTION	*CF		56D FO	MTH 22-Mar-2002		-			
34FO-06XL/K <i>34FO-06 : XL/K</i>	FMS: 2ND UNS-1CSP FACTORY OPTION	*CF		696N FO	MTH 22-Mar-2002		-			
34FO-06XL/P <i>34FO-06 : XL/P</i>	DTU: PERMANENT UNS-1CSP FACTORY OPTION	*CF		696P FO	MTH 22-Mar-2002		-			
34FO-08XL/B <i>34FO-08 : XL/B</i>	TCAS II: TPU-67A FACTORY OPTION	*CF		635B FO	MTH 22-Mar-2002		-			
35FO-02XL/C <i>35FO-02 : XL/C</i>	OXY SYSTEM: 76 CU FT FACTORY OPTION	*CF		66C FO	MTH 22-Mar-2002		-			
49FO-01XL/G <i>49FO-01 : XL/G</i>	AUXILIARY POWER UNIT FACTORY OPTION	*CF		46G FO	MTH 22-Mar-2002		-			
49FO-02XL <i>49FO-02 : XL</i>	HOURLMETER: APU FACTORY OPTION	*CF		47 FO	MTH 22-Mar-2002		-			
73FO-01XL <i>73FO-01 : XL</i>	CHIP DETECTOR: ENGINE FACTORY OPTION	*CF		10M FO	MTH 22-Mar-2002		-			