

ORDINANCE NO. 296

AN ORDINANCE AMENDING SECTION 2 OF ORDINANCE NO. 201 OF THE CITY OF ROLLA, NORTH DAKOTA, REGULATING THE SPECIFICATIONS FOR EXCAVATING UPON PAVED OR HARD-SURFACED STREETS OF ROLLA, NORTH DAKOTA.

BE IT ORDAINED BY THE CITY COUNCIL OF THE CITY OF ROLLA, NORTH DAKOTA.

Section 1. Section 2 of Ordinance No. 201 of the City of Rolla is hereby amended and re-enacted to read as follows:

"Section 2. Bond. A permit to excavate upon the paved or hard-surfaced streets of the City of Rolla shall not be issued until the applicant therefor has furnished a cash bond, or a surety company bond, or a bond with two personal sureties approved as to sufficiency by the street committee of the City Council, which bond in any case shall be in a sum equal to \$10.00 per lineal foot of excavation authorized, not over three feet wide at any point, and which bond shall run to the City of Rolla and be conditioned that said applicant will properly refill such excavation, properly tamped, and resurfaced with six inches of concrete, (1 part cement to 5 parts aggregate and of such character as to reach 3,500 pounds per square inch of compressive strength) or asphalt concrete which has the approval of the Street Department, in such a manner that the same will not settle below the surface street level for a period of 18 months, and that in event of such settling said applicant will remove the settled concrete, re-tamp, and re-pour the same within said time, in which case such bond shall be cancelled and returned, otherwise the amount of such bond shall be forthwith paid over into the general funds of the City of Rolla as liquidated damages for such defective refilling of such excavation."

Section 2. Effective date. This ordinance shall be in full force and effect and take effect immediately upon its final passage and approval.

First reading: Oct 2, 1978


Second reading and final passage: 11/6/78

Approval: 11/6/78



DONALD ENGBRECHT
Mayor, City of Rolla, N.D.

ATTEST:



CAROLINE SIMMERING
City Auditor.

Amended in
#301