

THE CITY OF NEW YORK
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF WATER POLLUTION CONTROL

BOROUGH OF RICHMOND

CERTIFICATE OF INSPECTION
NEW SEWER HOUSE CONNECTION

The following described sewer house connection has been laid from the property line to the existing sewer at premises:

N.B.# 17/98 BLOCK 2874 LOT 23

UNDER PERMIT NO. 4255 ISSUED 3-25-80

PREMISES 57 COLLIER PLACE, 5F.
(HOUSE NUMBER AND STREET)

LOCATED EAST SIDE, 532.93 FEET South OF Victory BLVD

OWNER COLLIER PLACE CORP.

PLUMBER BROOKLYN - JBL

SIZE AND TYPE OF PIPE LAID 6" CAST IRON

CONN. TO (SIZE, TYPE) 10" ESVP SAN SEWER LOCATED IN

(STREET/AVENUE) COLLIER PLACE

I HEREBY CERTIFY THAT I MADE THE INSPECTION OF THE SEWER HOUSE CONNECTION DESCRIBED ABOVE AND THAT ALL WORK DONE UNDER THIS PERMIT HAS BEEN PROPERLY COMPLETED IN ACCORDANCE WITH EXISTING ORDINANCES AND RULES AND REGULATIONS.

DATE: July 24, 1978 NAME (PRINT) BRUCE SICKER

SIGNED Bruce Sicker
INSPECTOR-DIVISION OF SEWER CONSTRUCTION

NOTED [Signature]
BOROUGH ENGINEER


PENALTY FOR FALSIFICATION:
FALSIFICATION OF ANY STATEMENT MADE HEREIN IS AN OFFENSE PUNISHABLE BY A FINE OR IMPRISONMENT OR BOTH (N.Y.C. ADMINISTRATIVE CODE, SECTION 1121-9.0)

Copies to: Borough Superintendent, Department of Buildings
Borough Office, Bureau of Water Register
Sewer Regulation and Control Section
File original in Borough Construction Office

NOTE: The sewer to which the house connection is made is is not connected to a private sewer treatment plant.
Form No. WPC-15 Rev. B (6-77) (Yellow)

HOUSE NUMBER 59	STREET NAME COURT PLACE	BLOCK 20A	LOT 23
--------------------	----------------------------	--------------	-----------

1. Was connection extended from existing curb connection? YES NO
2. Was the connection placed on (earth) stone or crushed rock, concrete cradle, concrete encasement, or reinforced concrete encasement? (Circle)
3. Was connection made to existing spur or riser or cut in? (Circle)
4. If connection was "cut in", was saddle or dutchman used? (Circle, if yes)
5. Length, size and material of new connection 25' 6" CAST IRON
6. Depth of connection at curb line is 6 1/2 feet.
7. All work was exposed and inspected.



DATE: July 21, 1978 SIGNED _____
INSPECTOR-DIVISION OF SEWER CONSTRUCTION