

Test Report

Report Number: 150331004SHF-BP-1

Test Items, Method and Results:

Test item: Seal Around Nail

Test method: ASTM D1970/D1970M-15 Clause 7.9

Test result:

Observation	Specimen 1	Specimen 2
Water was found in the bottom can	No	No
Water was found on the underside of the substrate	No	No
Water was found on the shank of the fastener	No	No
Water was found between the material and substrate	No	No
Conclusion	Pass	