

Radiator Cap Gasket

If your Model T has a tendency to boil over (what Model T doesn't?) and the antifreeze or rusty water seeps out of the radiator cap and stains the paint, take heart. There is an easy way to solve the problem. Go to your nearest hardware store and find the "BASIN DRAIN GASKET" which fits all 1¼" tubes. This gasket is manufactured by the "Plumb Shop" and carries part number "PS 342". Put this neoprene gasket into the filler neck of your radiator, put your radiator cap on, and you will NEVER have to worry about any antifreeze or rusty water soiling your beautiful paint again!!!