



MANITOU

Yale
67210



S11

MANITOU



S11

S9

S8

MANITOU

M60-2
TURBO





**IMPORTANT !
OPERATOR PLEASE READ**

Non-Recovery Maintenance - Failure to perform these maintenance procedures will cause failure of the A/C system. These service procedures are not covered under the warranty. Contact a service technician and perform these jobs according to procedures.

1. Fresh air ducts must be clean and free of debris.
2. Wash the evaporator coil and blower motor with a special coil cleaner.
3. Check the oil level for the condenser fan motor.
4. Inspect and clean the condenser coil if needed.
5. Check the refrigerant level and add if needed.

Call us for more information. We are
at your service. Call today.
1-800-844-6464

Refrills - Sales
Service - Parts

TRAC, INC.