

Caterpillar 3406B Mechanical


\$30



Caterpillar C7/C9 HPOP

\$100

\$75 if plug is damaged. Pump must turn.



Caterpillar Perkins C6.4L & C6.6L

\$100

Must have good solenoids.




Cummins 4 Cylinder "P"

\$100


0-402-034-XXX

0-402-734-XXX



Ambac Model 100


\$25



Bosch P7100 Cummins Commercial

\$70


Part Numbers: 0-402-736-XXX; 0-402-746-XXX



Bosch P7100 Dodge 5.9L

\$100

All Dodge Numbers: 0-402-736-838/841/854/885/887/911/912/913




Bosch VE


\$30

Not Accepting Automotive Applications

Fuel Injection Pumps

- No burned units.
- No units that have been dismantled or are missing parts.
- Units must be able to turn (when appropriate).
- Plastic electronic connectors must be in good condition.
- No excessive rust. Units that have been stored outdoors are likely to be scrap.





Bosch VE Dodge 5.9L


\$100

Dodge part numbers: 0-460-426-
103/114/184/205



Cat/Perkins 9.3L Motor

\$100




Caterpillar 3116

\$3



**Caterpillar 3116/3126 Old Style
HPOP (Round Top)**

\$70



**Caterpillar 3126 New Style HPOP
(Flat Top)**

\$75



Caterpillar 3208 Turbo

\$15



**Caterpillar 3304 / 3306 New
Scroll**


\$30



Caterpillar 3304 4N145


\$30





Cummins AFC R/H

\$5




Cummins CAPS 1

\$250




Cummins CAPS 2

\$125



Cummins Celect N14

\$50



Cummins ISX12 (without ribs)

\$100



Cummins ISX15

\$100


Part # 2872662 / 4307527 / 4307700



Cummins VP30

300


\$200.00 If plastic electronic plug is damaged.



Cummins VP44

\$100

\$75.00 If plastic electronic plug is damaged. Pump must turn.



Delphi DP200/210/300

\$30

Accepting All Part Numbers 8520 (and above)



Denso Common Rail

\$15




Detroit Gear Pump

\$7



Ford 6.0L Aluminum HPOP

\$125




Ford 6.0L V8 Cast Iron HPOP

\$35

Ford 6.0L V8 Cast Iron 2004.5 - 2010

* Not Buying Navistar V6 Type



Ford 6.9L

\$40



Ford 7.3 Aluminum HPOP

\$100



Ford 7.3 Stanadyne DB2

\$30



GM 6.2 Stanadyne

\$30


All Part #'s \$50.00 each



GM 6.5 Stanadyne Mechanical

\$30

Part #'s DB2831-4911; 4970; 5079; 5088;
5119; 5149; 5157; 5209; 5434; 5436; 5437;
5438; 5485; 5827; 5942




GM 6.5L DS

\$50

Part # 5067, 5068, 5288, 5459, 5521,
5942DS-5288, 5459, 5521, 5942, DS-
5067, 5068 & more...

No broken plastic components **Shaft
must turn**



John Deere Bosch

\$30



Navistar Maxxforce 0-445-020-126


\$70

0-445-020-126
Plugs must be good.



Navistar Maxxforce HPOP


\$30



Simms/Minimec 4 Cylinder

\$50

Pump must turn.



**Stanadyne & Roosa Master -
John Deere / Case / Caterpillar /
Perkins (Agricultural &
Industrial) DBG; DM; JDB; JDM**


\$50



**Stanadyne - Caterpillar /
Perkins / Case (Agricultural &
Industrial) DB2 & DB4**

\$30

**These do not include GM5.7, 6.2, and 6.5 and Ford 6.9/7.3.
All units must turn and be complete.**



**Stanadyne - John Deere
(Agricultural & Industrial) DB2
& DB4**

\$30

**These do not include GM5.7, 6.2, and 6.5 and Ford 6.9/7.3.
All units must turn and be complete.**

RECTORE
We Buy Used Auto Parts
RECYCLING THE WORLD ONE PART AT A TIME

Fuel Injector Cores

- No burned units
- No units that have been dismantled or are missing parts
- No broken tips (except Detroit Series 60 Part 5000. & up)
- No cut wire harnesses
- Plastic electronic connectors must be in good condition
- No excessive rust.
- Units that have been stored outdoors are likely to be scrap
- No damaged or bent electrical studs (Bosch solenoids)
- Part #'s must be legible
- No plier marks on shafts

Examples of Damaged Fuel Injectors



Damaged Ford 6.0
Injector Plug



Damaged Dodge
CR Injector



Damaged CAT C7/C9
Injector



Caterpillar 3116 Mechanical

10



Caterpillar 3126 HEUI Side Mount

NOT CURRENTLY BUYING



Caterpillar 3126 HEUI Top Mount


\$35

Top Solenoid Style Only.
Must have good solenoid;
No burned or damaged units.



Caterpillar 3176/C10/C12 - Must have a Ceramic Solenoid and legible Part #

\$10



Caterpillar 3406E/C15

\$65



Caterpillar 3408 / 3412

\$20



**ONE PIECE
BODY
ONLY**

**Caterpillar 3500 (One Piece Body
Only)**

\$60



Caterpillar 7000 Series Pencil

\$1.50

* One Piece Body Only, \$25.00 deduction
for damaged solenoid.



Caterpillar C13

\$40

Must have black band and plunger with hole on top.



Caterpillar C7

\$35

These part numbers only: 10R4761, 10R4762, 10R4763, 10R4764, 222-5961, 222-5962, 226-7681, 233-3534, 223-3535, 233-3536, 235-5518, 236-0953, 236-0973, 236-0974, 238-8091, 238-9808, continued...



Caterpillar C9

\$80

These part numbers only: 10R7222, 10R7224, 10R7225, 188-8739, 217-2570, 235-2888, 236-0962, 254-4339, 263-8218, 267-3360, 293-4072, 328-2574.



Caterpillar E3

\$75

4 Pins



Chevrolet Duramax 6.6L (LBZ)
2006-2007 #0-445-120-042

\$2



Chevrolet Duramax 6.6L (LGH)
2011+ #0-445-117-008

\$7



Chevrolet Duramax 6.6L (LLY)
2004.5-2005 #0-445-120-027

\$3.00



Chevrolet Duramax 6.6L (LMM)
2007-2010 #0-445-120-082

\$3.00





Chevrolet Duramax L5P
#12696966; 12678992

\$10.00



Cummins 24 Valve Mechanical

\$1.50



Cummins 5.9L 12 Valve

\$5.00

KDAL59-P5,6,7,9,12,16

Must have edge filter as shown in photo.



Cummins Celect M11 with Allen Bolt

\$30

No plier marks on body.



Cummins Celect M11 with Flat Bolt

\$30



Cummins Celect N14 with Cup Spacer

\$35

No plier marks on body.



Cummins HPI ISX

\$20

Must have LINK on top. **No fake tips accepted.** Pressure plugs on tip must be intact.



Cummins STC

\$20

Should have metal link. No plier marks on body.



Cummins Top Stop

\$2.50

Must have ridge



Cummins XPI (Pegasus)

NOT CURRENTLY BUYING



Cummins XPI ISX15

\$50



Delphi Paccar EUP

\$15

Part Numbers: 1871117, 1934322, 2034927,
2102391



Detroit 92 Electronic

NOT CURRENTLY BUYING



Detroit Diesel DD13/15

\$15



Detroit Diesel E3 (4 pin)

\$65

Part # PE4E00001; RFE4E00001;
FE4E0001



Detroit Diesel N3

\$50

0-414-703-002; 0-414-703-003
0-414-703-005; 0-414-703-007
0-986-441-028; 0-986-441-029
0-986-441-030; 0-986-441-031
Not buying if damaged plug;
Must be able to read the Part #



**Detroit N, C & 92 Series
Mechanical**

\$10

NC92 has 2 notches on hex \$10
HV & S Type have 1 notch or no notches on
hex = No Value!



**Detroit Series 60 (5000 and
above)**


\$70

Part #'s 5000 & UP only.



**Dodge Cummins 6.7L Common
Rail 2007.5-2015**

\$7



**Ford 6.0L Powerstroke 2003-
2007**

\$8

We are buying only these Part #'s: 0-445-
120-050 or 185 or 193 0-445-120-071 or
184 or 204 0-986-435-518 or 519



Ford 6.4L Powerstroke 2008-2010

\$3



Ford 6.7 with Blue Arm 2011-2014 (0-445-117-023/024)

\$7



Ford 6.7L Powerstroke

Part # 0-445-118-028
With "Pink Arm"

NOT CURRENTLY BUYING



← GREY ARM

Ford 6.7L Powerstroke with grey arm 2015-2019

\$7

Part # 0-445-117-040



Ford 6.9/7.3 IDI Mechanical

\$1



Ford 7.3L Powerstroke AA

\$7




Ford 7.3L Powerstroke AB

\$7



Ford 7.3L Powerstroke AD

\$10





Ford 7.3L Powerstroke AE

\$10



GM 6.2 & 6.5 Mechanical

\$1.00



International DT466

NOT CURRENTLY BUYING



John Deere Denso

095000-6310; 095000-6320
RE546784; RE531209; RE530362
RE546783; RE531210; RE530361

NOT CURRENTLY BUYING



John Deere Denso CR

Must have good solenoid.
No Isuzu, Fuso or Hino.

NOT CURRENTLY BUYING



L'Orange

\$40

Part # 5940-750-0020

Part # 5240-750-0053



Mack EUP

\$3.00



Mercedes MBE4000

\$40.00

Part numbers: A4600170312; A0030179112



Mercedes Sprinter 2001-2006

04451062 0986435129

04451063 0986435109

0445110162 0445110181

\$3



Navistar DT466 BA BB BC BD BE

BF

\$30

Navistar DT466 BI BJ BN BP

\$30



**Navistar G2.9
DT466/DT570/Maxxforce**

NOT CURRENTLY BUYING



**Paccar M13
\$20**



**Volvo 2 Pin
\$7**



**Volvo 4 Pin
\$7
All Part #'s**





Volvo with Ceramic Solenoid

\$65


NOTE: Must have "W" or "Y" letter on body



VW 1.9L TDI

038-130-073, 0-414-720-215, and 0-414-720-265. \$25.00 each

NOT CURRENTLY BUYING





**2015+ Ford 6.7L F250
Powerstroke**

\$40

Part Numbers Starting FC + HC Only.



Automotive


NOT CURRENTLY BUYING



Caterpillar 3406E

\$50

No value for damaged units.



**Caterpillar ACERT C13/C15 High
Pressure**

\$50

No value for damaged housing



Caterpillar ACERT C13/C15 Low Pressure

\$35



Caterpillar C7/C9

NOT CURRENTLY BUYING



Chevrolet 6.5L GM8 Only

NOT CURRENTLY BUYING



**Chevrolet Duramax 6.6L (LB7)
2001-2004.5**

IHI Turbo.

NOT CURRENTLY BUYING



Chevrolet Duramax 6.6L (LB7)
2001-2004.5 California
Emissions

Part # 8972541603

NOT CURRENTLY BUYING



Chevrolet Duramax 6.6L (LBZ)
2006-2007

\$35



Chevrolet Duramax 6.6L (LLY)
2004.5-2005

\$35



Chevrolet Duramax 6.6L
(LML/LGH) 2011+

\$35



Chevrolet Duramax 6.6L (LMM)

2008-2011

\$35



Chevrolet Duramax L5P

\$200




Cummins Dodge Ram HE300VG

+ HE351VE

\$200

Good units \$250.00. Damaged units
\$125.00



**Cummins Electronic VGT
Turbocharger Actuator Core**

\$40

HE300VG + HE351VE Actuator.
No value for damaged.



**Cummins Holset HE300VG /
HE351VE Industrial**

\$200



Cummins Holset HE341VE


\$150



Cummins Holset HT60

\$50

Good units only!



Cummins Holset HX55W

\$70



Cummins Holset HX60W

\$70



Cummins Holset HX80 / HX82 / HX83

\$50



Cummins Holset Wastegated HX30 / HX30W

\$45



Cummins Holset Wastegated HX35W, HX40W, WH1E, WH1C

NOT CURRENTLY BUYING



**Cummins ISX Holset HE431VE /
HE451VE / HE400VG**

\$200


\$100.00 each if damaged. Must have the electronic actuator.



**Cummins ISX Holset HE500VG /
HE551VE / HE561VE**

\$200.00


\$150.00 each if damaged. Must have the electronic actuator.



Cummins ISX Holset HE551V

\$100.00

\$25.00 each if damaged. Must have a mechanical actuator.



Cummins M11 Holset HX55

NOT CURRENTLY BUYING



**Daimler Detroit Diesel
DD13/DD15**

\$70

Part # A4720901480



Detroit 14L

\$35

\$15 If damaged or missing actuator.



**Detroit Series 60 12.7L
Wastegated**

\$45

No value on damaged units. Garrett only.



**Detroit Series 60 Non-
Wastegated**

\$30

No value on damaged units. Garrett only.



Dodge 5.9L Cummins HE341CW

NOT CURRENTLY BUYING



**Dodge Cummins 5.9L Holset
HE351CW 2004.5-2007**

NOT CURRENTLY BUYING




Ford 6.0L

\$25



Ford 6.4L Dual

NOT CURRENTLY BUYING





Ford 6.4L Turbo Actuator


\$20



Ford 6.9/7.3 IDI

\$25

Part #'s 466533-1, 2, 3, 4, 5, 6,
1819744C92, 1821328C91, 1821329C91.



Ford 7.3L Powerstroke GTP38

Large compressor housing only. Exhaust side 7 Bolt pattern only - shown on image. Years 1995.5 and higher only. No value on damaged units. With proper vertical Actuator Nipple - not horizontal.

NOT CURRENTLY BUYING



Ford 7.3L Powerstroke GTP38 Mid Year 1998 - 1999

Part Numbers 1825878C91 / C92

NOT CURRENTLY BUYING



Ford Powerstroke 6.7L Scorpion

NOT CURRENTLY BUYING



Ford Powerstroke 6.7L Single Outlet


NOT CURRENTLY BUYING



Holset Cummins ISX HX55

\$70

Part # 3595090, 4036892,
4089754...others



Holset Detroit Diesel DD15 HX55

\$60

Part # 3768075...plus others



Holset HE400/451 Volvo Mack


\$200



Holset HE531VE Detroit Diesel

\$200

Part # 2836825, 4043261, 4045291,
23539570, 23539062...



**Holset Non-Wastegated H1C /
H1E**

No value for damaged units.
NOT CURRENTLY BUYING



**Holset Non-Wastegated H2C /
H2D / H2E**

\$20

No value for damaged units.



Holset Non-Wastegated HT3B

No value for damaged units.


NOT CURRENTLY BUYING



**Holset Non-Wastegated H2C /
H2D / H2E**

\$20

No value for damaged units.



**Holset Paccar HE500VG /
HE531VE**

\$300

Part # 2842125, 3767294, 1831156.



**International 6.0L VT 365
Industrial/Commercial App**

Six Blade Compressor Wheel

NOT CURRENTLY BUYING



International DT466E Borg Warner B2V

\$100

NOTE: V-Band Turbine Housing



International DT466E Borg Warner S300V

\$100

NOTE: Bolted Turbine Housing.



International MaxxForce Twin Turbos 9 / 10 / 11 / 13 / 15

\$125



Mack BWTS E7

(Upturn Compressor Cover Only)


NOT CURRENTLY BUYING



Mack S430V

\$150

NOTE: Must Have Good Electronics.



Marine

\$50-100 Good units. \$25 Damaged units.



Mercedes Sprinter w/actuator

NOTE: Must Have Good Electronic Actuator.

NOT CURRENTLY BUYING



Nissan Titan Cummins Twin Turbo

\$100



Cummins EGR Valve

\$15



Cummins ISX Solenoid

\$15



Cummins ISX15 EGR Valve

\$45

Part Numbers: 2881762, 4352302,
5406049, 5411635



Detroit Accessory Drive

NOT CURRENTLY BUYING



Detroit EGR Valve

\$15



Detroit Series 60 Gear Pump

\$5



Detroit VPOD Cores

\$30

No value for broken plug.




Ford 7.3 Throttle Shaft

\$10

Part # 23588

Program: DDE6 Group: S50/60 VPOD
C23530299 R23530299/CR
C23530736 R23530736/CR
C23536813 E - R 23536813/CR
C23536814 E - R 23536814/CR



**International Maxxforce
Navistar 11, 13 EGR Valve 2014-
2015**

\$25

Part # 5010918R92 at
Part # 5010696R94 at



Holset Actuator Control Valve


\$25



**Tappet for Stanadyne IFS
Injector**

\$7

Tappet for Stanadyne IFS Injector



Caterpillar 120 Pin

\$50

Cat #s MXS, SDP, LEE, NXS



Caterpillar 40 Pin

\$50


Cat #s 1LW, 5EK, 6TS



Caterpillar 70 Pin

\$50

Cat #s 157-3705, 162-7584, 259-1159,
240-5303, 206-2700, 179-4899



Cummins Celect & Celect Plus

\$80



Cummins ISX

\$55

Cummins # 3684009 (CM870), 3684275 (CM871)



Cummins ISX15

\$55

Cummins # 4358814



Detroit DDEC III and IV ECM

\$75

No water or fire damage.
Plugs can not be damaged.
No disassembled units.



Detroit Diesel DDEC III

\$75

Detroit #s 23513553, 23518645, 23518743



Detroit Diesel DDEC IV

\$150

Detroit #s 23519307, 23519308



Detroit Diesel DDEC V

\$150


Detroit #s 23530802, 23535798, 23535990



Duramax LLY FICM

\$55

Part Numbers # 0-281-011-134 , 97303751



Ford 6.0L FICM

\$40

Navistar # 1845117C1/2/3/4/ , 4307224R1, 4307211R93



Ford 7.3L IDM

\$80


Part Numbers # IDM100, IDM110, IDM120



Freightliner CPC4 Module

\$75


A 003 446 10 02 / 005



International Maxxforce

Part Numbers # 3007009C2, 5010979R1, 5010980R1, 0-281-020-159


NOT CURRENTLY BUYING



International Maxxforce DT

International # 1881708C91, 1883086C93

NOT CURRENTLY BUYING



Paccar MX13

\$125



V-Mac & II

\$75

Part #s 0-281-001-095, 12MS51M,
12MS59M


* Note: If the ECM is not the numbers
listed, price reduced to \$35



V-Mac E7

\$75

Part #s 0-281-001-095, 12MS45M2
* Note: If the ECM is not the numbers
listed, price reduced to \$25



Volvo Mack MP7, MP8, D12, D13

\$35

Part #s 20412511, 20561256, 20583789,
20814620, 20814642, 20977021,
21042371, 21107008, 21300060, 21358126,
21900553, 22581042