
ARTISAN 1.3.1 UPDATE FOR PHOENIX & SEDONA ROASTERS WITH FUJI PXF

STARTING IN MAY OF 2018 FUJI DISCONTINUED THE USE OF THE PXR SERIES PID CONTROLS AND REPLACED THEM WITH THE FUJI PXF CONTROLS. THIS WILL EFFECT THE SETUP OF THE NEW 2018 PHOENIX ORO LINE THAT USES THE FUJI PXF AND SOME OF THE SEDONA ELITE THAT US THE PXF MODELS.

WHILE THE DRIVER TO CONNECT TO EACH WILL DEPEND ON THE USB CONNECTOR USED FOR EACH MACHINE THE PXF USES DIFFERENT COMMANDS TO OPERATE ON ARTISAN. THEREFORE MARKO AT ARTISAN GRACIOUSLY ADDED THE CODE SO ARTISAN 1.3.1 AND ABOVE WILL NOW WORK WITH THE FUJI PXF PIDS. HERE IS A BRIEF DESCRIPTION OF HOW TO SET THIS UP. BASICALLY YOU CAN FOLLOW THE ORIGINAL SETUP UP GUIDE AND VIDEO PROVIDED ON OUR TECH PAGE OF WEBSITE BUT NEED TO NOW CLICK ON THE PXF TAB IN ARTISAN MACHINES:


FOR PHOENIX ORO WITH PXF:



CLICK ON CONFIG. THEN ON MACHINES AND THEN PHOENIX AND LASTLY THE ROASTER PXF

FOR SEDONA ELITE MODELS WITH WITH FUJI PXF:

(SANTOKER/SEDONA LINE)



IF YOU HAVE MORE QUESTIONS FIRST SEE ALL OUR FREE VIDEOS AND PDF'S ON THE TECH PAGE OF <u>BUCKEYECOFFEE.COM</u> WEBSITE AND IF YOU NEED MORE HELP EMAIL THE TECH DEPARTMENT:

TECH@BUCKEYECOFFEE.COM

(BE SURE TO EMAIL YOUR ACCOUNT NUMBER TOO)