


C515 REPLACEMENT CONTROLLER FOR McQuay Mark IV HEAT PUMP CONTROL BOARD P/N 056792401K, 60638801 and 056792402K.

One Board replacement for both AC and DC RV Solenoids

FEATURES

MARK IV controllers were used in McQuay Heat Pumps since the early 80's thru to present. McQuay produced 3 versions over this time period and the versions are not universal. The product shown is the latest version Generic replacement Heat Pump Controller that replaces all OEM PN's.

With a more robust power supply and microprocessor, the logic is identical to the 3 OEM offerings and re-wires identically to the existing McQuay heat pumps wiring diagram. 24 VAC or 24 VDC selectable by a jumper. The control board is a 45 minute change out and no wiring modifications; ships securely packaged with instructions and all new hardware. The Original Manufacturer only sells a replacement specific to the exact version board being replaced, increasing truck stock 3 to 1.



BENIFITS

The C515 is a generic replacement for the McQuay Mark IV controllers P/N 056792401K, 60638801 and 056792402K. The C515 has three significant advantages; (1) Lower price than the OEM replacement. (2) The versatility that 1(one) board can activate both a 24 VDC reversing solenoid and a 24 VAC reversing solenoid selectable by a jumper.

(3) C515 wires exactly the same and is dimensionally identical to the original board.



WARRANTY

The C515- replacement control board is brand new, not rebuilt or refurbished and all boards include a 1 year unconditional parts warranty.