

MITRE HOUSE MANAGEMENT LIMITED

(REPRESENTING THE NINE LEASEHOLD OWNERS OF MITTE HOUSE)

124 Kings Road • Chelsea • London SW3 4TP
Email: enquiry@mitrehouse.org • www.mitrehouse.org
Temporary Contact Phone 020 7589 7502







Invitation To Tender

SPECIFICATION OF WORKS

to be carried out and materials to be used for THE INTERNAL REPAIRS & REDECORATION PROGRAMME TO THE COMMON PARTS AT MITRE HOUSE, 124 KINGS ROAD, SW3 4TP

Under the direction, supervision and satisfaction of the Directors of Head Lessee MITRE HOUSE MANAGEMENT LIMITED

Mitre House, 124 Kings Road, London SW3 4TP Telephone 0798 33 33 543 email: mitrehouse@graffiti.biz

January 2012 Job Ref: 2nd Draft/February 2012

| | WADE DESIGN Including 20% VAT | | Commer | t & Management/Wade Differences indicated in GREEN |
|--|--|---|--|--|
| | | | | |
| TERRAZZO FLOORING_ALL | | | | TERRAZZO FLOORING QUOTES INCL. VAT |
| External Marble Step & Threshold | 529 | 378 | | larble Master + £300 To Do Test area |
| Wall Lining To Inner Stairwell | 4,716 | 3,622 | • | Natural Stone Renovation |
| Windowsills to 3rd, 2nd & 1st Floors | 1,133 | 831 | £11970 | Posh Floors (no grouting) £21,900 Incl. grouting |
| Treads, Risers & Stringer Course | 5,264 | 3,861 | | |
| Landings & Entrance Hallways | 5,849 | - | _ | ment recommends a wash & clean for £888 incl. VAT |
| FLOORING TOTAL incl. 20% VAT | 17,491 | 12,982 | | ote: ALL QUOTES LISTED make No guarantee |
| | | | of remov | val of all scratches and stains_all Quotes |
| GENERAL ITEMS | 1 000 | 2.075 | | |
| Electricity Meter Cupboards & Fit (3) | 1,896 | 2,075 | Mngt: In | cludes BASEMENT ELECTRICS BOXED AS REQUIRED |
| Clean & Varnish All Communal Brass | 1,176 | 324 | | |
| Replace All Tenant's Door Furniture | 2,376 | | | /Knob/Letterbox (+spyhole on Management's Cost) |
| Replace Handrail With New Brass One | 3,223 | 475 | _ | emove & Re-brass Only |
| Lift Car Interior Makeover | 2,232 | <i>3,573</i> | Managei | nent's Incl. Painting Lift Doors/Architraves |
| GENERAL TOTAL incl. 20% VAT | 10,903 | 8,309 | | |
| ELECTRICS & LIGHTING | | | | |
| PIR 5 yearly Test | 648 | 475 | | |
| Install TWO additional Hall Lights | 474 | 747 | | ment incl. FOUR fittings & re-positioning & auto-sensors |
| Replace all 9 Timer Light Switches | 9 <i>7</i> 9 | | | Only - No Longer required With Auto Sensor Lighting |
| Install 2 more on 1st & 2nd Floor | 501 | <i>572</i> | | ment incl. SIX fittings & re-positioning & auto-sensors |
| Replace Lift Bell Push Unit In Brass | | | To main | tain quote Totals the same - approx cost £280 |
| Replace Front Door Bell Unit In Brass | 250 | 208 | | |
| ELECTRICS TOTAL incl. 20% VAT | 2,852 | 2,227 | | |
| HARDWOOD WOODWORK | | | | |
| Strip, Repair & Polish ALL Woodwork | 9,048 | 1,075 | ff Mngt: Qu | uote ONLY Front Door & Surround, both sides |
| including Main Entrance Front Door | | | | |
| WOODWORK TOTAL incl. 20% VAT | 9,048 | 1,075 | | |
| PAINTWORK | | | | |
| Paint Throughout in THREE Colours | 11,976 | - | ff Managei | nent's Budget was always for TWO Colours only |
| Gloss White On Painted Woodwork | inclusive | inclusive | C M | |
| Clean & Roller Paint Lift Doors (4) | inclusive | in LIFT quote | | agement's LIFT quote in GENERAL ITEMS ABOVE |
| Clean & Steam Lift Mesh Cage | inclusive | in LIFT quote | | agement's LIFT quote in GENERAL ITEMS ABOVE |
| Strip, Repair & Paint Crittall Windows (5) PAINTWORK TOTAL incl. 20% VAT | inclusive 11,976 | 1,230 | Mngt: In | cl. new brass fitments and full stripping down pt/work |
| PAINTWORK TOTAL INC. 20% VAT | 11,970 | 6,980 | SO AS T | O MAKE A FAIR COMPARISON, LIKE FOR LIKE (approx) |
| TOTAL THIS PAGE INCL. 20% VAT | 52,270 | 31,573 | | LY THE ORANGE VALUES TO SEE A FINAL TOTAL BUDGET |
| OPTIONAL EXTRAS | 32,270 | 31,373 | ADD ON | IT THE ORANGE VALUES TO SEE ATTIMAL TOTAL BODGET |
| LetterBox Pigeon Hole (Painted) | 720 | 208 | | |
| - , | 1,440 | 455 | | |
| LetterBox Pigeon Hole (Oak Veneer) | | | All Ours | as Taskeda Emarganae Light fitmonts |
| Emergency Lighting Throughout | 4,800 | 2,833 | All Quot | es Include Emergency Light fitments |
| Fire Detection System Cable TV Installation | 4,560 2,588 | 3,850 | | |
| Cable 14 Installation | 2,300 | | | |
| | | 1,049 | | |
| OPTIONS TOTAL incl. VAT. (LOW) | 12 668 | - | Only Inc | I WADE Painted Pigeon Roy |
| OPTIONS TOTAL incl. VAT (LOW) | 12,668 13 388 | 7,940 | = | l. WADE Painted Pigeon Box DE Oak Veneer Pigeon Box |
| OPTIONS TOTAL incl. VAT (LOW) OPTIONS TOTAL incl. VAT (HIGH) | 12,668 13,388 | - | = | l. WADE Painted Pigeon Box DE Oak Veneer Pigeon Box |
| | 13,388 | 7,940 8,395 | = | - |
| OPTIONS TOTAL incl. VAT (HIGH) | • | 7,940 | Incl. WA | - |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL | 13,388 | 7,940 8,395 | Incl. WA | DE Oak Veneer Pigeon Box |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) | 13,388 64,938 | 7,940 8,395 39,513 | Incl. WA | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) | 13,388 64,938 | 7,940 8,395 39,513 | Incl. WA | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) | 13,388 64,938 | 7,940 8,395 39,513 | Incl. WA | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required | 13,388 64,938 | 7,940 8,395 39,513 | Incl. WA Incl. WA Incl. WA | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT | 13,388 64,938 65,658 | 7,940 8,395 39,513 39,968 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box | 13,388 64,938 65,658 not quoted | 7,940 8,395 39,513 39,968 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor | 13,388 64,938 65,658 not quoted not quoted | 7,940 8,395 39,513 39,968 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Require Mngt.(4 | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat | 13,388 64,938 65,658 not quoted not quoted not quoted not quoted not quoted | 7,940 8,395 39,513 39,968 75 744 1,275 | Incl. WA Incl. WA Necessa Mngt Inc Require Mngt.(4 Mngt Inc | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting d to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned | 13,388 64,938 65,658 not quoted not quoted not quoted not quoted not quoted not quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Require Mngt.(4 Mngt Inc Mngt Po | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting it to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat | 13,388 64,938 65,658 not quoted not quoted not quoted not quoted not quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Require Mngt.(4 Mngt Inc Mngt Po | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting d to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc | 13,388 64,938 65,658 not quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Require Mngt.(4 Mngt Inc Mngt Po | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting it to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc | 13,388 64,938 65,658 not quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Require Mngt.(4 Mngt Inc Mngt Po | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting it to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT | not quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Required Mngt.(4 Mngt Inc Mngt Co. | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting spible brassing/Gold etc |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door MAI MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS | not quoted soft quoted not quoted soft quoted not quoted not quoted not quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Requirec Mngt.(4 Mngt Inc Mngt Co. Mngt Co. | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc ntingency for expenditure items |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY | not quoted soft quoted not quoted not quoted not quoted not quoted not quoted not quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 31,573 3,239 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Required Mngt.(4 Mngt Inc Mngt Co. Manager THIS IS | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting sisible brassing/Gold etc intingency for expenditure items |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY | not quoted 52,270 1,440 53,710 | 7,940 8,395 39,513 39,968 75 744 1,275 135 450 2,784 31,573 3,239 34,812 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Required Mngt.(4 Mngt Inc Mngt Co. Manager THIS IS | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc intingency for expenditure items |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY FINAL TOTAL incl. VAT + ORANGE | not quoted 52,270 1,440 53,710 incl. VAT | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 31,573 3,239 34,812 incl. VAT | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Requirec Mngt.(4 Mngt Inc Mngt Co. Manager THIS IS ADVISER | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc Intingency for expenditure items ments Final Total EXACTLY THE £35,000 INCL. VAT AS OUTLINED AND D IN ALL RECENT (SINCE JUNE 2012) CORRESPONDENCE |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY FINAL TOTAL incl. VAT + ORANGE | not quoted 52,270 1,440 53,710 | 7,940 8,395 39,513 39,968 75 744 1,275 135 450 2,784 31,573 3,239 34,812 | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Require Mngt.(4 Mngt Inc Mngt Co. Manager THIS IS ADVISEI A DIFF | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting it to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc intingency for expenditure items ments Final Total EXACTLY THE £35,000 INCL. VAT AS OUTLINED AND D IN ALL RECENT (SINCE JUNE 2012) CORRESPONDENCE ERENCE OF £21,682 (62%) rising more if further |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY FINAL TOTAL incl. VAT + ORANGE ADD WADE missing quotes, possibly the SAME £2784 as Management? | not quoted social quoted not quoted not quoted not quoted not quoted not quoted to quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 31,573 3,239 34,812 incl. VAT | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Require Mngt.(4 Mngt Inc Mngt Co. Manager THIS IS ADVISEI A DIFF | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc intingency for expenditure items ments Final Total EXACTLY THE £35,000 INCL. VAT AS OUTLINED AND D IN ALL RECENT (SINCE JUNE 2012) CORRESPONDENCE |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY FINAL TOTAL incl. VAT + ORANGE ADD WADE missing quotes, possibly the SAME £2784 as Management? | not quoted social quoted not quoted not quoted not quoted not quoted not quoted to quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 31,573 3,239 34,812 incl. VAT | Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Requirec Mngt.(4 Mngt Inc Mngt Co. Manager THIS IS ADVISER Manager | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc intingency for expenditure items ments Final Total EXACTLY THE £35,000 INCL. VAT AS OUTLINED AND D IN ALL RECENT (SINCE JUNE 2012) CORRESPONDENCE ERENCE OF £21,682 (62%) rising more if further ement savings are made (eg Terrazzo Cleaning!) |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY FINAL TOTAL incl. VAT + ORANGE ADD WADE missing quotes, possibly the SAME £2784 as Management? MANAGEMENT CONTINGENCY CDM Co-Ordinator @ 1% Budget? | not quoted social quoted not quoted not quoted not quoted not quoted not quoted to quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 31,573 3,239 34,812 incl. VAT 34,812 | Incl. WA Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Require Mngt.(4 Mngt Inc Mngt Po Mngt Co Manage THIS IS ADVISEI A DIFFI Manage Mngt Co | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost Pry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc Intingency for expenditure items ments Final Total EXACTLY THE £35,000 INCL. VAT AS OUTLINED AND D IN ALL RECENT (SINCE JUNE 2012) CORRESPONDENCE ERENCE OF £21,682 (62%) rising more if further ement savings are made (eg Terrazzo Cleaning!) Intingency for H&S Legal Requirement |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY FINAL TOTAL incl. VAT + ORANGE ADD WADE missing quotes, possibly the SAME £2784 as Management? MANAGEMENT CONTINGENCY CDM Co-Ordinator @ 1% Budget? Misc Contingency Funds Set Aside | not quoted solution quoted for quoted for quoted for quoted 52,270 1,440 53,710 incl. VAT 56,494 | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 31,573 3,239 34,812 incl. VAT 34,812 | Incl. WA Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Requiret Mngt. (4 Mngt Inc Mngt Po Mngt Co Managet THIS IS ADVISED A DIFF Manage Mngt Co Mngt Co | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc Intingency for expenditure items MENTALY THE £35,000 INCL. VAT AS OUTLINED AND D IN ALL RECENT (SINCE JUNE 2012) CORRESPONDENCE ERENCE OF £21,682 (62%) rising more if further ement savings are made (eg Terrazzo Cleaning!) Intingency for H&S Legal Requirement Intingency for Oversights/extras/additional costs etc |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY FINAL TOTAL incl. VAT + ORANGE ADD WADE missing quotes, possibly the SAME £2784 as Management? MANAGEMENT CONTINGENCY CDM Co-Ordinator @ 1% Budget? Misc Contingency Funds Set Aside MANAGEMENT OPTIONAL EXTRAS | not quoted social quoted not quoted not quoted not quoted not quoted not quoted to quoted | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 31,573 3,239 34,812 incl. VAT 34,812 | Incl. WA Incl. WA Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Requiret Mngt.(4 Mngt Inc Mngt Po Mngt Co Managet THIS IS ADVISEL A DIFF Manage Mngt Co not requ | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting ssible brassing/Gold etc intingency for expenditure items ments Final Total EXACTLY THE £35,000 INCL. VAT AS OUTLINED AND O IN ALL RECENT (SINCE JUNE 2012) CORRESPONDENCE ERENCE OF £21,682 (62%) rising more if further ement savings are made (eg Terrazzo Cleaning!) intingency for H&S Legal Requirement intingency for Oversights/extras/additional costs etc ired for information only |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door MAI MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY FINAL TOTAL incl. VAT + ORANGE ADD WADE missing quotes, possibly the SAME £2784 as Management? MANAGEMENT CONTINGENCY CDM Co-Ordinator @ 1% Budget? Misc Contingency Funds Set Aside MANAGEMENT OPTIONAL EXTRAS Runners & Carpetting All Surfaces | not quoted solution quoted for quoted for quoted for quoted 52,270 1,440 53,710 incl. VAT 56,494 | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 31,573 3,239 34,812 incl. VAT 34,812 incl. vAT | Incl. WA Incl. WA Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Required Mngt.(4 Mngt Inc Mngt Co. Managei THIS IS ADVISEI A DIFFI Manage Mngt Co. not required Fully car | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting sible brassing/Gold etc intingency for expenditure items ments Final Total EXACTLY THE £35,000 INCL. VAT AS OUTLINED AND D IN ALL RECENT (SINCE JUNE 2012) CORRESPONDENCE ERENCE OF £21,682 (62%) rising more if further ement savings are made (eg Terrazzo Cleaning!) intingency for H&S Legal Requirement intingency for Oversights/extras/additional costs etc ired for information only uppeted (runners) from Ground to 3rd Floor stairs |
| OPTIONS TOTAL incl. VAT (HIGH) IF BOTH QUOTES WERE USED IN FULL THEY WOULD TOTAL incl. VAT (LOW) THEY WOULD TOTAL incl. VAT (HIGH) PLUS items originally required and specified from MANAGEMENT Front Entrance Brass Mail Box Install Double Elec Plugs on Each Floor NEW Light Fitments Budget NEW Main Entrance Door Mat MITRE HOUSE SIGNAGE - Cleaned Misc Plants/Mail Table/Mirror etc ADDITIONS TOTAL incl. VAT carried forward from PAGE 1 TOTALS ADD ORANGE ITEMS ONLY FINAL TOTAL incl. VAT + ORANGE ADD WADE missing quotes, possibly the SAME £2784 as Management? MANAGEMENT CONTINGENCY CDM Co-Ordinator @ 1% Budget? Misc Contingency Funds Set Aside MANAGEMENT OPTIONAL EXTRAS | not quoted solution quoted for quoted for quoted for quoted 52,270 1,440 53,710 incl. VAT 56,494 | 7,940 8,395 39,513 39,968 75 744 1,275 135 105 450 2,784 31,573 3,239 34,812 incl. VAT 34,812 | Incl. WA Incl. WA Incl. WA Incl. WA Incl. WA Necessa Mngt Inc Requirec Mngt.(4 Mngt Inc Mngt Co. Manager THIS IS ADVISE A DIFF Manage Mngt Co. Mngt Co. Mngt Co. Mngt Co. Mrgt | DE Oak Veneer Pigeon Box DE Painted Pigeon Box but not Front Door Bell Cost DE Oak Veneer Pigeon Box but not Front Door Bell Cost ry but seemingly neglected in WADE quote cl. fitting It to facilitate electrical cleaning equipment each floor Hallway); (6 Landings); (6 Exterior); all +autosensors cl. fitting sible brassing/Gold etc Intingency for expenditure items ments Final Total EXACTLY THE £35,000 INCL. VAT AS OUTLINED AND D IN ALL RECENT (SINCE JUNE 2012) CORRESPONDENCE ERENCE OF £21,682 (62%) rising more if further ement savings are made (eg Terrazzo Cleaning!) Intingency for H&S Legal Requirement Intingency for Oversights/extras/additional costs etc ired for information only |

Brief analysis of ALL works

- a) Clean & Polish Mitre House Signage
- b) New Brass Bell Push
- c) Street Front Door attention
 - 1 Strip both sides + varnish
 - 2 Renovate/new door furniture 3 Marbling/granite/steps/clea
- 4 Affix door hold backs d) Install Internal mail box
- e) New Door Mat
- f)_ Renovate inside double doors
- 1 Brassware attention
- 2 Affix door hold backs
- g) Hall Table & Mail Pigeon boxes
- h) Install (4) New Lights in Hallway
- i) Mirrors on panels TBA j)_Terrazzo Flooring attention
 - 1 Major attention & Repair
 - 2 Clean only throughout
 - 3 Carpeting k) Communal Walls & Ceilings Painting
 - 1 Two colours
 - 2_Wallpapering
 - 3 Mirrors
 - I) Handrail attention & brassware i)_Lift Interior Car and External Doors
 - 1 Internal car decor
 - 2 External doors, frames, grill/cage
 - 3 All TBA
 - k)_Lighting incl. plug points & Emergency
 - 1_Internal + auto sensors
 - 2_External + auto sensors
 - 3_New plud points each floor 3 NICEIC tests & reports
 - I) Communal Crittall Windows attention
 - 1_Strip to bare & prime/gloss
 - 2_Renew furniture (brass)
 - m)_Communal Brass Door Furniture
 - n)_Leaseholder's Door Brass Furniture & mats

 - o)_Various joinery & re-wriring
 - p)_Attention to rear yard, basement etc
 - 1 Attention to drains
 - 2 Emergency Lighting
 - 3_Clean & renovate
 - 4_Stair lighting
 - q)_Gloss to all wood surfaces 1_All 4 Fire Exit doors
 - - 2 Cleaners Cupboard area
 - 3_New joinery throughout
 - r) Clean all double door windows
 - 1 Back to bronze frames
 - 2_Repair as required
 - s)_Attention to ALL Fire Assessments 1_Signs & Notices
 - 2_Remove obstacles
 - 3 Extinguishers or not?
 - 4_Check all door self closers
 - 5_Check Fire Escape Route
 - t) Misc Communal Additions 1_SKY & TV install
 - 2 Solar Panels
 - 3_Piped music in lift...!!
 - t)_Misc as required (£2500 contingency)