


AZ ONE CUP PLUS INSPECTION & REPAIR

IN THE EVENT YOU HAVE ISSUES WITH YOUR HEAT PLATE CLOSING AND NOT REOPENING (LIFTING OFF PLATE) IT IS BEST TO TURN OFF POWER SO AS NOT TO OVERHEAT UNIT.
NEXT OPEN TOP PANEL AND TAKE SEVERAL PICTURES AND EMAIL TO TECH@BUCKEYECOFFEE.COM AND WE WILL HELP DIAGNOSE ISSUE AND GET A FIX.

1. LOOK FOR ANY LOOSE WIRES OR PARTS THAT MAY HAVE COME LOOSE. CHECK THESE RELAYS TO ENSURE THEY ARE SNAPPED INTO PLACE

2. THE BLACK RECTANGLE PLASTIC PART SEEN HERE IS THE CAPACITOR. CHECK THAT WIRING IS NOT LOOSE AND THAT NOTHING IS TOUCHING CONNECTIONS. WIRES MAY BE SOLDERED ONTO ELECTRIC BOARD





3. WHEN MOTOR PUSHES THE HEAT PLATE UNTO CUPS TO SEAL THE CUPS TO BEGIN TIMER. IF LATCH SEEN HERE PRESSES DOWN ON A MICRO-SWITCH TO BEGIN TIMER. IF LATCH IS NOT POSITIONED PROPERLY IT MAY NOT PRESS



AZ ONE CUP PLUS INSPECTION & REPAIR

4. ALSO CHECK WIRING TO MICRO-SWITCH TO ENSURE IT IS NOT LOOSE

YOU MAY NEED GET TO MICRO-SWITCH FROM BACK SIDE OF UNIT



5. TAKE PICTURES OF THESE PARTS AS WELL AS AN OVERVIEW OF ENTIRE INSIDES OF UNIT AND EMAIL TO: TECH@BUCKEYECOFFEE.COM

