



Dimensions



Glass dimension

Glass thickness	6+1.52+6	8+1.52+8	10+1.52+10	12+1.52+12
Glass dimension				
PA max for 4 points	1000	1300	1600	1900
PA max for 6 points	800	1000	1100	1300
PB max for 4 or 6 points	650	1050	1250	1450
PF max	200	250	300	400

Glass drilling



For further technical information, please infer to technical catalogue.

Fittings


① YP11

② YP21

③ Q01A-16

④ YP31


Dimensions



Glass dimension

Glass thickness	6+1.52+6	8+1.52+8	10+1.52+10	12+1.52+12
Glass dimension				
PA max for 6 points	800	1000	1100	1300
PB max for 6 points	650	1050	1250	1450
PF max	200	250	300	400

Glass drilling



For further technical information, please infer to technical catalogue.

Fittings



① YP11

② YP21

③ Q01A-16

④ YP31

Dimensions




Glass dimension

Glass thickness Glass dimension	6+1.52+6	8+1.52+8	10+1.52+10	12+1.52+12
PA max for 4 points	1000	1300	1600	1900
PB max for 4 points	650	1050	1250	1450
PF max	200	250	300	400


For further technical information, please refer to technical catalogue.

Glass drilling




Fittings


① YP12




② YP21






③ Q01A-16



④ YP31



Dimensions




Glass dimension

Glass thickness Glass dimension	6+1.52+6	8+1.52+8	10+1.52+10	12+1.52+12
PA max for 4 points	1000	1300	1600	1900
PB max for 4 points	650	1050	1250	1450
PF max	200	250	300	400

For further technical information, please refer to technical catalogue.

Glass drilling



Fittings


① YP11




② YP21




③Q01A-16



④ YP31



⑤ YP22



⑥ YP32

