


OHIO HISTORIC INVENTORY

1. No. ERI-1522		4. Present Name(s) Edward Curilla Property		1. No. ERI-1522	2. County Erie
2. County ERIE		5. Other Name(s) Patrick Leyden Residence			
3. Location of Negatives C.H.S.					
6. Specific Location West side of Huntington Ln third from last house		16. Thematic Category ethnic - manufacturing		28. No. of Stories 1 1/2	
7. City or Town If Rural, Township & Vicinity Kelleys Island, Ohio		17. Date(s) or Period c. 1905		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
8. Site Plan with North Arrow 		18. Style or Design Vernacular Queen Anne		30. Foundation Material Ashler stone	
9. U.T.M. Reference Zone Easting Northing 17 356800 4606200		19. Architect or Engineer		31. Wall Construction WOOD FRAME	
10. Site <input type="checkbox"/> Structure <input type="checkbox"/> Building <input checked="" type="checkbox"/> Object <input type="checkbox"/>		20. Contractor or Builder		32. Roof Type & Material Gable/Asph shingle	
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		21. Original Use, if apparent Residence		33. No. of Bays Front 2 Side 2	
12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use Residence		34. Wall Treatment bevelled siding with end boards	
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		35. Plan Shape Square	
14. District Potent'/? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		24. Owner's Name & Address, if known Edward Curilla 624 W. St. Clair Ave. Cleveland, Ohio 44113		36. Changes (Explain in #42) Addition <input checked="" type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/>	
15. Name of Established District N/A		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		37. Condition Interior Exterior Poor	
16. Further Description of Important Features (Continue on reverse if necessary) A narrow eave board follows beneath the roofline. Hipped gables on the north and south and a gable-ended front pavilion feature notched siding under the gables, while the gable-ended pavilion additionally displays barge-board with molded design and trimboards. A belt course separates the two floors of the residence and a gabled wall dormer protrudes above the roofline in back. Windows		26. Local Contact Person or Organization Kevin Pape, K.I. Hist		38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
43. History and Significance This house was built by Patrick Leyden, a laborer in the Kelley Lime & Transport Co. south quarry. Patrick was the son of John and Ann Leyden who immigrated to the island from Ireland in 1879 with their seven children. John Leyden labored in the Norman Kelley and Co. quarry and his family lived in company housing near the quarry. They resided in the vicinity		27. Other Surveys in Which Included N/A		39. Endangered? By What? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
44. Description of Environment and Outbuildings Located on a street that now dead-ends into the south quarry. When the KIL&T Co. was operating, it owned the houses and property north of this lot, anticipating further expansion. Beginning with this lot, all property		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		41. Distance from and Frontage on Road 35' / 66'	
45. Sources of Information Census Records of Erie Co. 1914 Directory of Erie Co. 1909 Platt Map 1896 Atlas of Erie Co.		46. Prepared by Kevin Pape & Kyle Johannsen		47. Organization K.I. Planning Comm.	
		48. Date 9/85		49. Revision Date(s)	

1. No. ERI-1522
 2. County Erie
 4. Present Name(s) Edward Curilla Property
 5. Other Name(s) Patrick Leyden Residence



<p>50. House Type No.</p> <p>Code No. Name</p> <p>_____</p>	<p>53. Farmstead Plan</p> <p><input type="checkbox"/> <input type="checkbox"/></p>
<p>51. Historic Outbuildings and Dependencies</p> <p>Barn Type(s)</p> <p>Code No. Type</p> <p>_____</p> <p>_____</p> <p>Corn Crib or Shed <input type="checkbox"/> Smoke House, <input type="checkbox"/> Privy <input type="checkbox"/> Silo <input type="checkbox"/> Spring House Carriage House <input type="checkbox"/> Summer Kitchen <input type="checkbox"/> or Ice House</p> <p>Other _____</p>	<p>.</p> <p>.</p> <p>.</p> <p>.</p>
<p>52. Archaeological Site on Property?</p> <p>Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>Basis for Information</p> <p>Owner Collection <input type="checkbox"/> Above Ground Earthworks or Mound <input type="checkbox"/> Cultural Materials Noted <input type="checkbox"/> OAI No. _____</p>	<p>.</p> <p>.</p> <p>54. Photo Roll No. <u>33</u> Picture No(s). <u>20</u></p>

42. (Cont'd) are predominantly double-hung 1/1. Open front porch features turned columns and pilasters with pediment over entry. A wood water table runs above the high foundation. A one story frame addition in back includes a porch/entry set on concrete blocks. Some windows have been replaced.

43. (Cont'd.) of other Irish immigrants such as Patrick Murphy (ERI-1521), Patrick Barry (ERI-1698), and Michael Keeley families who later lived in their own island homes. Patrick Leyden married his wife, Bridget, in 1884 but she did not emigrate to the island until 1888. After she arrived they established their own residence, also in company housing, along with Patrick's brother, John. Both brothers labored in the KIL&T Co. south quarry. By 1910, the Leydens had two children, Margaret and Theodore, and owned their own home; Patrick still worked for the quarry. This home was later owned by John and Mary Betzenheimer. John Betzenheimer, born in 1879, was the son of John and Elizabeth Betzenheimer. John, senior, was an engineer for the wine company. His son was a teamster for the quarry in 1900 and a locomotive engineer by 1910. (There is some suggestion that this house belonged to Hugh Brennen, superintendent of the quarry.)

44. (Cont'd.) to the south was privately owned. Outbuildings include a gable-roofed garage/shed in back.