

March 13, 2014 - Tennis Committee Report

CBTB tennis court #1, closest to the gate has the same asphalt that was put on the court in 1970 when it was constructed. The old asphalt is now thin, has large and long cracks, the cracks go down to the ground so it can't be patched. Stick a knife down the cracks and you will see. The patching that was done didn't work and now the tennis court has uneven bumps and cracks on the court. When water from the pool is drained out in the fields, the water flows under the tennis court and causes cracks to appear on the surface. This court is now closed as it is too dangerous to play on. The tennis net was taken down. A sign was posted on the tennis fence. This tennis court has to be reconstructed and raised so it is higher than the surrounding area.

Tennis court #2, away from the gate. It was resurfaced in 2008. Underground water and surface water draining in from the surrounding land after rain and storms have caused cracks to appear on the tennis court surface. The asphalt is also bubbling up in areas which is dangerous to the tennis players. This tennis court also has to be raised and resurfaced.

C. Jean Ehlman
CBTB Tennis Court Chair

