

## Water Coordinator' s Report

Water System Report

Respectfully submitted by Judi Shellenbarger

a) a description of any notable repairs and maintenance activities-

Saturday, July 27, Doug Smith was in the well house and discovered the Potassium Permanganate vat was overflowing. He called me to report this and I contacted Nathan from NWNWS. Nathan and Jeremy came out to clean up the mess. No cause of this overflowing could be determined at this time.

Monday, July 29, I met with Jeremy to discuss the issues. I asked him to talk to Dylan from Jerry Beck Electric to explain what was going on and to see if Dylan could come and help determine the problem. In addition, I have requested that Dylan finish up the upgrade on the electrical work, add a switch in the well house that will allow well #2 to be turned on from the well house, reconnect the alarm and any additional work that Jeremy sees as necessary. Jeremy will also repair the gauge on the outside of the reservoir so it will work more smoothly. Jeremy will also set up a system flush and check to see when our next reservoir cleaning will be. I asked Jeremy for a local referral for fire hydrant repair and replacement technicians.

b) notice of upcoming system activities and/or maintenance -this next quarter will bring the usual generator maintenance, system flushing and perhaps reservoir cleaning if we are due for a cleaning .