

SUPPORT NOTE

15 SEPTEMBER 2015

MAPPING & GIS: CURRENT SOFTWARE AND FIRMWARE VERSIONS

This document gives the current software and firmware versions of Trimble® Mapping & GIS products. For details on upgrades and downloads, refer to the support area for each product on the Trimble website (www.trimble.com/support) or click the name of the product from the list below.

Field software	Platform	Current version
ASPEN® software*	Windows®	2.11
Asset Surveyor® software*	TDC1™ / TDC2™	3.40
	TSC1™	5.27
GeoBeacon™ Controller software	Windows, Windows Mobile®	1.0.32
GeoExplorer® I and II handhelds*		2.20
GeoExplorer 3 and 3c handhelds*		1.20
GPS Controller software	Windows, Windows Mobile 6, 6.1, 6.5, Windows Embedded Handheld 6.5	2.70
GPS Pathfinder® Controller software*	Palm OS	1.20
	Windows, Windows CE	1.31
GPS Pathfinder Field toolkit run-time	Windows, Windows Mobile	1.60
TDL 3G Connector software	Windows, Windows Mobile	1.40.27
TerraSync™ software	Windows Mobile, Windows Embedded Handheld 6.5	5.80
	Windows	5.61
Trimble GPSCorrect™ extension for Esri ArcPad software	Windows, Windows Mobile, Windows Embedded Handheld 6.5	3.40
Trimble Positions™ ArcPad extension	Windows	10.2.2.1
Trimble Positions Mobile extension	Windows Mobile 6, 6.1, Windows Embedded Handheld 6.5	10.2.1.1
Trimble Positions run-time	Windows Mobile 6, 6.1, Windows Embedded Handheld 6.5	10.2.1.1
TrimPix™ Pro software	Windows Mobile 6, 6.1	2.00
TrimPix technology*	Windows Mobile 5.0, 6	1.10
Trimble Municipal Reporter™ field software	Windows Mobile 6, 6.1, Windows Embedded Handheld 6.5	1.50
Trimble TerraFlex™ Mobile	Windows 7, Windows Embedded Handheld 6.5, iOS, Android	3.2

This document is for informational purposes only and is not a legally binding agreement or offer. Trimble makes no warranties and assumes no obligations or liabilities hereunder.

Geospatial Division, 10368 Westmoor Drive, Westminster, CO 80021, USA

© 2006–2015, Trimble Navigation Limited. All rights reserved. Trimble, the Globe & Triangle logo, ASPEN, GeoExplorer, GPS Pathfinder, Juno, Nomad, Recon, and Yuma are trademarks of Trimble Navigation Limited registered in the United States and other countries. BoB, GeoBeacon, GeoXH, GeoXM, GeoXT, GPS Analyst, GPSCorrect, Municipal Reporter, Positions, ProXH, ProXT, Ranger, TDC1, TDC2, TerraFlex, TerraSync, TrimPix, TRS, TSC1, and TSCe are trademarks of Trimble Navigation Limited. Microsoft, Windows, and Windows Mobile are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries. All other trademarks are the property of their respective owners.



Office software	Platform	Current version
Data Transfer Utility	Windows	1.51
GPS Pathfinder Office software	Windows	5.80
MediaMapper software*	Windows	3.1–20
Trimble GPS Analyst™ extension for Esri ArcGIS for Desktop software	ArcGIS 9.2, 9.3	2.20
	ArcGIS 10	2.40
Trimble Positions Desktop add-in	Windows	10.3.0.2
Trimble Reference Station (TRS™)*	Windows	1.05
Trimble SSF and DDF data format extensions for FME	Windows	2.10
Trimble TerraFlex Cloud	Browsers: Internet Explorer 9 and 10, FireFox, Chrome	Current

Development software	Platform	Current version
GPS Pathfinder Field Toolkit	Windows	1.60
GPS Pathfinder Tools Software Development Kit (SDK)*	Windows	2.42
Trimble Positions toolkit	Windows	10.2.1.1

Notes:

- For versions of the Windows operating system that the software listed is above is compatible with, see the [Product Compatibility List](#).
- * Indicates discontinued product.

Hardware	Embedded software	Current version
BoB™ (Beacon-on-a-Belt) receiver*		1.00
GeoBeacon Receiver		1.351
Juno® 5B and 5D handhelds	Operating system	Windows Embedded Handheld 6.5 Pro
	GPS firmware	7.03
Juno 3B and 3D handhelds	Operating system	Windows Embedded Handheld 6.5 Pro
	GPS firmware	3.2.5.1.0
Juno SA handheld	Operating system	Windows Mobile version 6.1 Classic; rev 1.00.12
	GPS firmware	3.2.5.0.3
Juno SB and SC handhelds	Operating system	Windows Mobile version 6.1 Classic; rev 1.03.04
	GPS firmware	3.2.5.0.3
Juno SD handheld	Operating system	Windows Mobile version 6.1 Pro; rev 1.01.00
	GPS firmware	3.2.5.0.3
Juno ST handheld*	Operating system	Windows Mobile version 5.0 software
	GPS firmware	3.10

Geo 7X handheld	Operating system	Windows Embedded Handheld 6.5 Pro
	GPS firmware	4.11.1
Geo 5T handheld	Operating system	Windows Embedded Handheld 6.5 Pro
	GNSS firmware	v1.00.3 (Hm25, 1.05)
GeoExplorer 6000 series handhelds (GeoXH™, GeoXT™)	Operating system	Windows Mobile 6.5 Professional software
	GNSS firmware	4.01.1
GeoExplorer 2008/3000 series handhelds (GeoXH, GeoXT, GeoXM™)	Operating system	Windows Mobile 6.1 software
	GPS firmware	2.11
GeoExplorer 2005 series handhelds* (GeoXH, GeoXT, GeoXM)	Operating system	Windows Mobile 5.0 software; rev 5.1.16
	GPS firmware	1.82
GeoExplorer 2003 series handhelds* (GeoXT, GeoXM)	Operating system	Windows Embedded Handheld 6.5 Pro
	GPS firmware	1.05A
GeoExplorer CE series handhelds* (GeoXT, GeoXM)	Operating system	Windows CE .NET; rev 2.00.02 Windows CE version 3.0; rev 1.10.02
	GPS firmware	1.05A
GPS Pathfinder Pocket receiver*		1.00
GPS Pathfinder XB receiver*		2.30
GPS Pathfinder XC receiver		3.10
GPS Pathfinder Power receiver*		1.70
GPS Pathfinder ProXH™ receiver		2.04
GPS Pathfinder Pro XL receiver*		3.15
GPS Pathfinder Pro XR receiver*		1.96, 1.31
GPS Pathfinder Pro XRS receiver*		1.96, 1.52A
GPS Pathfinder ProXT™ receiver		2.04
GPS Pathfinder ProXRT receiver*		4.44
GPS Pathfinder ProXRT Model 2 receiver*		4.44
GPS Pathfinder ProXRT Model 2 Rev C receiver		4.71
Pro 6H receiver	GPS firmware	1.04.3
Pro 6T receiver	GPS firmware	1.04.3
GIS TSCe™ field device*	Operating system	Windows CE .NET version 4.0.11 Windows CE version 3.0 (Build 126); rev 2.3.7
Trimble Nomad® series handhelds*	Operating system	Windows Mobile version 6 operating system; rev 5.2 (version 1.0.4 -800LE, 800LD, 800LC, 800L, and 800B) (version 1.0.3 - 800X,800XC, or 800XE)
	GPS firmware	3.10

Trimble Nomad 800G series handhelds	Operating system	Windows Mobile version 6 operating system; rev.2 <i>Optional upgrade to:</i> Windows Mobile version 6.1 operating system; rev 1.1
	GPS firmware	3.30
Trimble Nomad 900G series handhelds	Operating system	Windows Mobile version 6.1 operating system; revision 1.1
	GPS firmware	3.30
Trimble Nomad 1050 series	Operating system	Windows Embedded Handheld 6.5 Pro
	GPS firmware	GSD4e_4.1.2-P1
Trimble Ranger™ handheld	Operating system	Windows Mobile 5.0 software; revision 5.0.3 Windows Mobile 2003 Software for Pocket PCs version 4.2.2C*
Trimble Recon® handheld	Operating system	Windows Mobile 6 operating system; rev 6.0.1 Windows Mobile 5.0 software; rev 5.0.2* Windows Mobile 2003 Software for Pocket PCs version 4.2.5* Windows CE .NET version 4.1.9*
Trimble Yuma® rugged tablet computer	Operating system	Windows 7, revision HDI R1.15
	GPS firmware	3.30
Trimble Yuma 2 rugged tablet computer	Operating system	Windows 7, SP1
Trimble Recon® handheld	Operating system	Windows Mobile 6 operating system; rev 6.0.1 Windows Mobile 5.0 software; rev5.0.2* Windows Mobile 2003 Software for Pocket PCs version 4.2.5* Windows CE .NET version 4.1.9*

For more information

For more information contact your local [Trimble Distribution Partner](#).