

OASIS POOL SERVICES, LLC 2161 Baltimore Pike Oxford PA 19363 610-869-7870 FAX 610-869-7871

2025 Pool Opening Services

SPRING OPENING: Includes re-assembling filter, system, pumps, and accessories from winterization. Light heater pilot and test fire (the heater will be turned back to the off position after we test the pilot). Removing all plugs, installing handrails and ladders <u>if left available</u>. Water chemistry will be tested and adjusted unless otherwise specified by pool owner. <u>Chemicals for adjustment are billed additionally</u>. Water level must be 1/2 way across the mouth of the skimmer and the parts must be made available. There is a return visit charge of \$45.00 if this has not been completed and we need to return to start up system. If you have signed for a clean-up service, the pool will not be vacuumed on the opening day, we will return to complete clean-up. Additional charges will occur for systems with multiple filter systems, or extensive water features.

It is the customers responsibility to bring the water level to operational level prior to the scheduled opening date.

\$275.00

COVER REMOVAL: As described below. <u>Please note, there is an additional \$35.00 charge if this is the only service we are providing</u>.

Mesh Safety Cover. Cover removed, folded, and left on deck. Pop-ups lowered. \$100.00

Custom Solid Cover, Small Debris brushed off, cover folded and left on deck. Pop-ups lowered. \$125.00

Solid Vinyl Cover, Small Debris brushed off, folded, and left on deck. Empty water bags. \$150.00

It is the customers responsibility to remove all excess water and debris from the top of the cover prior to the scheduled opening date. If cover needs to be pumped and heavy debris removed, there is a minimum \$75.00 additional charge and \$25.00 per each 15 minutes of pump time. Covers are left folded on the deck for the customer to store away.

POOL CLEAN UP SERVICE: Pool will be cleaned and adjusted throughout the course of several visits until it is clean and clear and chemically balanced. Service is provided and billed out hourly and <u>chemicals are not included and will be billed additionally</u>. Please know, this service requires several hours and varies year to year. Please plan for a minimum of \$300.00 or higher. Staining is not part of the clean-up process.

This service is only offered if oasis pool service is spring assembling the pool as well.

NO beginning clean up services will be scheduled for the week of May 20th due to the upcoming holiday

\$140.00 per hour

HEATER INSPECTION & CLEANING: We will clean burner tray, ignition assembly, and components of heater. We will inspect the controls and operation of the heater to ensure it meets safety requirements. Heater will be test fired and left to run no longer than 10 minutes, heater will be left with pilot lit but not running. Any parts needed and labor to install will be billed in addition to the cleaning service. IF PROPANE HEATER, PROPANE MUST BE FILLED TO COMPLETE INSPECTION. A fee will be charged to return to fire heater if propane tanks are not filled. Please note that no repairs or parts are offered for this service, this is for the inspection only.

This service is only offered if oasis pool service is spring assembling the pool as well.

\$ 105.00

SALT CELL INSPECTION & CLEANING: Salt system will be inspected, cell will be cleaned to remove build up from prior season, anode will be cleaned and replaced if necessary. Salt system will be left operational unless specified on paper. Salt cell will not be left on until pool is clean and clear and free of debris. All parts and labor to install include Anode will be billed additionally. Please note that no repairs or parts are offered for this service, this is for the inspection only.

This service is only offered if oasis pool service is spring assembling the pool as well.

\$ 90.00