

Home Office - 1717 East Erwin Street Tyler, Texas 75702-6398

Jason Wheeler

Office: (903) 595-4421 Lab: (903) 595-6402 Fax: (903) 595-6113

Area Offices

 210 Beech Street
 Texarkana, AR 71854
 (870) 772-0013

 707 West Cotton St.
 Longview, TX 75604
 (903) 758-0402

 2000E Randol Mill Rd. Ste 613
 Arlington, TX 76011
 (817) 962-0048

 8403 Cross Park Dr. Ste D-3
 Austin, TX 78754
 (512)-519-9312

By Order Of:

Order Number:

Acct ID: WESTHENLY Report Date: 06/13/2017

Project: West Henly Materials

Location:

Client: West Henly Materials

Contractor:

REPORT: Earthwork Observation

LAB NO: 1562

Test Method: See Below

1562

Date Sampled: 06/13/2017

Sampled By: Paz, John

**TEST RESULTS** 

Report No:

Page 1 of 2

See attached report for details.

Proj. No.: C7229169

Respectfully Submitted,

ETTL Engineers & Consultants, Inc.

Chris Taylor, SET

Project NO: C7229-169

Client: West Henly Materials

Date: 6/13/2017

Report NO: 1562

Project Name: West Henly Materials Stockpile Testing

Description: Manufactured 1" Pipe Bedding

Source: West Henly Materials

Test Method as

applicable ASTM C117, C136, D1140

Location: 1" Pipe Bedding Stockpile

## **Aggregate Gradation**

Sieve Size	Individual Weight Retained	Percent Retained	Percent Passing
1 1/2"	0	0.0%	100.0%
1"	9190.7	41.8%	58.2%
1/2"	12320.2	97.7%	2.3%
#4	109.7	98.2%	1.8%
#8	19.6	98.3%	1.7%

Chris Taylor S.E.T

THIS REPORT APPLIES ONLY TO THE STANDARDS OR PROCEDURES INDICATED AND TO THE SAMPLE(S) TESTED AND/OR OBSERVED AND ARE NOT NECESSARILY INDICATIVE OF THE QUALITIES OF APPARENTLY IDENTICAL OR SIMILAR PRODUCTS OR PROCEDURES, NOR DO THEY REPRESENT AN ONGOING QUALITY ASSURANCE PROGRAM UNLESS SO NOTED. THESE REPORTS ARE FOR THE EXCLUSIVE USE OF THE ADDRESSED CLIENT AND ARE NOT TO BE REPRODUCED WITHOUT WRITTEN PERMISSION.