

100 Vehicle Count			Speed	Total	Average	85%
1	28	51	29	25		
2	27	52	28	26		
3	24	53	30	27		
4	47	54	38	28		
5	26	55	28	29		
6	27	56	34	30		
7	28	57	20	31		31
8	22	58	22	32		
9	20	59	28	33		
10	28	60	29	34		
11	27	61	24	35		
12	22	62	30	36		
13	27	63	26	37		
14	32	64	38	38		
15	29	65	22	39		
16	36	66	25	40		
17	26	67	26	41		
18	23	68	27	42		
19	28	69	27	43		
20	32	70	22	44		
21	24	71	22	45		
22	25	72	27	46		
23	31	73	26	47		
24	22	74	30	48		
25	27	75	31	49		
26	28	76	26	50		
27	24	77	25	51		
28	17	78	27	52		
29	26	79	29	53		
30	35	80	27	54		
31	27	81	26	55		
32	33	82	25	56		
33	30	83	24	57		
34	33	84	27	58		
35	25	85	32	59		
36	26	86	26	60		
37	27	87	28	61		
38	30	88	27	62		
39	24	89	26	63		
40	31	90	27	64		
41	27	91	24	65		
42	26	92	22	66		
43	25	93	27	67		
44	25	94	25	68		
45	26	95	26	69		
46	24	96	26	70		
47	34	97	27	71		
48	20	98	23	72		
49	28	99	29	73		
50	27	100	36	74		
				75		

Date: 5/7/13 Location: E. D Ave Speed Detection Device: Czoo
 Time: 1500 Direction of Travel: West Model Number: Malleson
 Weather: Clear / Sunny Off: For road
 Road Surface: Paved

30 mph

100 Vehicle Count				Speed	Total	Average	85%
1	25	51	24	25			
2	26	52	24	26			
3	23	53	24	27			
4	38	54	37	28			
5	23	55	29	29			
6	26	56	30	30			
7	27	57	27	31			
8	28	58	43	32			32
9	31	59	26	33			
10	33	60	29	34			
11	39	61	25	35			
12	32	62	28	36			
13	32	63	27	37			
14	24	64	28	38			
15	26	65	32	39			
16	38	66	32	40			
17	29	67	29	41			
18	37	68	29	42			
19	28	69	28	43			
20	22	70	26	44			
21	26	71	24	45			
22	29	72	37	46			
23	28	73	28	47			
24	25	74	36	48			
25	30	75	32	49			
26	28	76	22	50			
27	25	77	27	51			
28	36	78	28	52			
29	23	79	28	53			
30	25	80	28	54			
31	27	81	29	55			
32	28	82	24	56			
33	25	83	30	57			
34	25	84	30	58			
35	31	85	31	59			
36	26	86	23	60			
37	26	87	34	61			
38	27	88	26	62			
39	31	89	40	63			
40	29	90	28	64			
41	29	91	28	65			
42	26	92	29	66			
43	30	93	24	67			
44	32	94	23	68			
45	26	95	24	69			
46	25	96	28	70			
47	45	97	23	71			
48	28	98	32	72			
49	46	99	22	73			
50	31	100	28	74			
				75			

Date: 5/8/13
 Time: 13:50
 Weather: Sunny clear
 Road Surface: Pavement

Location: N. 32nd
 Direction of Travel: N & S
 Off: M-89

Speed Detection Device: Laser
 Model Number: LTI 2020
 7799 N. 32nd St.

30 mph

20 -
21 - ||
22 - |||
23 - |||

100 Vehicle Count		Speed		Total	Average	85%
1	22	51	29	25		
2	21	52	25	26		
3	30	53	27	27		
4	29	54	28	28		
5	31	55	33	29		
6	27	56	30	30		
7	47	57	28	31		
8	27	58	26	32		32
9	31	59	28	33		
10	27	60	37	34		
11	26	61	25	35		
12	28	62	33	36		
13	24	63	26	37		
14	31	64	24	38		
15	31	65	31	39		
16	36	66	28	40		
17	31	67	35	41		
18	31	68	25	42		
19	30	69	23	43		
20	34	70	36	44		
21	31	71	28	45		
22	27	72	26	46		
23	27	73	30	47		
24	28	74	27	48		
25	30	75	31	49		
26	27	76	27	50		
27	25	77	26	51		
28	32	78	22	52		
29	32	79	24	53		
30	28	80	31	54		
31	29	81	27	55		
32	34	82	25	56		
33	29	83	35	57		
34	31	84	27	58		
35	23	85	21	59		
36	28	86	33	60		
37	36	87	41	61		
38	27	88	25	62		
39	31	89	27	63		
40	26	90	22	64		
41	27	91	28	65		
42	23	92	25	66		
43	24	93	28	67		
44	32	94	31	68		
45	36	95	26	69		
46	28	96	28	70		
47	26	97	24	71		
48	28	98	31	72		
49	26	99	27	73		
50	25	100		74		
				75		

Date: 5/8/13
 Time: 14:54
 Weather: Sunny Clear
 Road Surface: Pavement
 Location: E. D. E. Av
 Direction of Travel: W + E
 Speed Detection Device: Laser Marksmen
 Model Number: LTI 8000
 9315 E. D. E. Ave.

30mph