

PHASE IV REPORT

9 March 2017

Phase IV REPORT: Districts of Vatomandry-Mahanoro-Andovoranto

MWP23

Location: SONDRARA: 3rd village in South after Kalomalala along Pangalana Channel

Date: March 17th, 2017

Global View:

250houses with 950people

Fonkontany Sondrara

Commune Andovoranto

District Brickaville

Has 02 bucket wells, 01 broken 01 still working

1h30 on boat from Andovoranto

Beneficiary: 300 People

Well Assessment:

Water table 3.5m

Total depth underground 5.7m

Total depth from the Table to the bottom 6.5m

Completion: steel screen 1m + Galva 2m + Galva 2m + 0.5m + 1m + valve

Formation: Sand (white clean coarse grain sand found starting at 4m down hole)

Flow: 30 liters per min

Work duration: 5hours (under the rain)

Issues: Impact coupling unscrewed on hammering, due to the thickness of the Galva

Additional Information:

Well committee settled

Paperwork Demand of pump done

Paperwork Land granted done

02spares of cup and 01 wrench have been given to well committee

Maintenance Training not done

Contact:

034 81 425 44 Mr. Doudou, President of the Well Committee

034 37 631 18 Chief of the Fonkontany

MWP24

Location: ANDOVONA (village near the ferry cross in Andavakimena)

Date: March 18th, 2017

Global View:

45houses with 400people

Fonkontany Andavakimena

Commune Andovoranto

District Brickaville

Did not have any potable water

7km on road from Andovoranto at its north

Beneficiary: 400 People

Well Assessment:

Water table 2m

Total depth underground 4.2m

Total depth from the Table to the bottom 5m

Completion: PVC screen 1m + Galva 2m + Galva 2m + valve

Formation: Sand

Flow: 30 liters per min Work duration: 4hours

Additional Information:

Well committee settled

Paperwork Demand of pump done

Settled on Public Land

01spare of cup have been given to well committee

Formation of maintenance not done

Contact: TBD

MWP25

Location: AMBODITAFARA (2nd village in South after Kalomalala Pangalana Channel)

Date: March 19th, 2017

Global View:

130 houses with 450 people

Fonkontany Sondrara

Commune Andovoranto

District Brickaville

Has 01 broken bucket well

1h on boat from Andovoranto

Beneficiary: 300 People

Well Assessment:

Water table 3.5m

Total depth underground 5.m

Total depth from the Table to the bottom 6m

Completion: steel screen 1m + Galva 3m + 2m + valve

Formation: Sand

Flow: 30 liters per min Work duration: 5hours

Additional Information:

Well committee settled

Paperwork Demand of pump done

Paperwork Land granted done

02spares of cup and 01 wrench have been given to well committee

Maintenance Training not done

Contact:

034 79 992 05 Mr. Jean, Secretary of the Well Committee

034 36 085 25 Mr. Gaston, Deputy Chief of the Fonkontany

MWP26

Location: SCHOOL in ANDOVORANTO

Date: March 20th, 2017

Global View:

230 Children

Fonkontany Andovoranto

Commune Andovoranto

District Brickaville

Beneficiary: 230 People

Well Assessment:

Water table 3.5m

Total depth underground 5.1m

Total depth from the Table to the bottom 6m

Completion: PVC screen 1m + Galva 3m + valve + 2m

Formation: Sand

Flow: 30 liters per min Work duration: 5hours

Issues: hammer broken due to a hard hit against something on first drilling at 4m depth

Additional Information:

Well committee not settled

Paperwork Demand of pump done

02spares of cup have been given to Director

Contact:

034 36 082 47 Director of school

MWP27

Location: AMPASIMBE (village near Vatomandry)

Date: March 21st, 2017

Global View:

840 people

Fonkontany Ampasimbe

Commune Tsivangiana

District Vatomandry

Located on north of Tsivangiana

Pump has been installed on the main road up on the village

Beneficiary: 400people

Well assessment:

Water table 5m

Total depth underground 6m

Total depth from the Table to the bottom 7m

Completion: plastic screen 1m + Galva 2m + 2m + 2m

Formation: white Sand on top, black sand mixed with clay at 5m depth

Flow: 30 liters per min Work duration: 01day

No valve

Issues: hammer penetration stopped at 5.5m depth

Additional information:

Used same Well Committee as first well

Paperwork Demand of pump done

Paperwork Land granted not yet done

Any spare of cup haven't been given to well committee

Contact:

034 51 932 77 Deputy Mayor Mr. Alex

MAINTENANCE DONE ON MARCH 2017

I MWP05 ANDAVAKIMENA

Valve and steel pipe changed because was leaking Table need to be replaced

II MWP10 MAHATSARA

Cup has been changed

WELL SUMMARY

PHASE	NAME OF WELL		STATUS	PEOPLE BENEFICIARY IN VILLAGE		FLOW RATE	DEPTH TO TOP OF WATER (m)	TOTAL DEPTH OF WELL (m)
1	MWP01	ADVO	PRODUCING	ANDOVORANTO	300	30L/min	2.5	7
1	MWP02	ADVO	PRODUCING	ANDOVORANTO	300	30L/min	2	5
1	MWP03	ADVO	PRODUCING	ANDOVORANTO	300	30L/min	2	4
1	MWP04	ADVO	PRODUCING	ANDOVORANTO	300	30L/min	2	3.5
1	MWP05	ADVK	PRODUCING	ANDAVAKIMENA	300	30L/min	2	7
П	MWP06	ADVO	PRODUCING	ANDOVORANTO	300	30L/min	2.7	5.2
П	MWP07	ADVO	UNSUCCESS	ANDOVORANTO	0	Temp plug	2.3	4.8
П	MWP08	ADVO	PRODUCING	ANDOVORANTO	300	30L/min	2.7	5.2
П	MWP09	ADVO	PRODUCING	ANDOVORANTO	300	30L/min	2.7	5.2
П	MWP10	MTSR	PRODUCING	MAHATSARA	400	30L/min	2.7	5.2
П	MWP11	ABLB	PRODUCING	AMBILABE	400	30L/min	3	5.2
П	MWP12	TSVG	PRODUCING	TSIVANGIANA	400	20L/min	3.1	7.1
П	MWP13	APSB	PRODUCING	AMPASIMBE	400	25L/min	3	7.5
Ш	MWP14	ABDK	UNSUCCESS	AMBANDRIKA	0	Temp plug	0	9.1
Ш	MWP15	ABRM	UNSUCCESS	AMBODIARAMY	0	Temp plug	0	8.0
III	MWP16	ABDV	PRODUCING	AMBODIVARO	250	25L/min	2.1	7.1
Ш	MWP17	TSVG	PRODUCING	TSIVANGIANA	100	15L/min	3	8.2
Ш	MWP18	KLML	PRODUCING	KALOMALALA	200	30L/min	2.4	6.4
Ш	MWP19	KLML	PRODUCING	KALOMALALA	200	30L/min	2.4	6.4
Ш	MWP20	ADVK	PRODUCING	ANDAVAKIMENA	100	30L/min	2.5	5
Ш	MWP21	ABLB	PRODUCING	AMBILABE	150	30L/min	1.7	5.2
Pilot	MWP22	TTVE	PRODUCING	AMPANDROANTSIRIRY	200	30L/min	5	9.0
IV	MWP23	SNDR	PRODUCING	SONDRARA	300	30L/min	2.2	5.7
IV	MWP24	ADVN	PRODUCING	ANDOVONA	400	30L/min	2.2	4.2
IV	MWP25	ABDT	PRODUCING	AMBODITAFARA	300	30L/min	1.5	5.0
IV	MWP26	ADVO	PRODUCING	ANDOVORANTO	230	30L/min	1.6	5.1
IV	MWP27	APSB	PRODUCING	AMPASIMBE	300	30L/min	1	6
IV	MWP28	TSVG	UNSUCCESS	TSIVANGIANA	0	Temp plug	0	9
	6,730							