


TILE RECORD MAP



NAME Harold Winston Lawyer
Stevens Charitable Trust

Section 33 Township Falls County _____
NW 1/4


Contractor _____ Date installed Oct 98

Amount of tile installed 5" 5115 6" _____ 8" _____
 10" _____ 12" _____ Larger 4" 68115

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
 Jim Blood — Telephone 515-892-4330

TILE RECORD MAP



NAME Jerry Fritz - Bertha Stebbens.

Section 33 Township Falls County
N 1/2 SW 1/4

Contractor Date installed 1997

Amount of tile installed 5" 2665' 6" 8"

10" 12" Larger 4" 28595

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
Jim Blood — Telephone 515-892-4330