



ENCO ENGINEERING INC

1621 N. Whiting Circle
PO Box 31918
(480) 844 9525

Mesa, Arizona 85213
Mesa, Arizona 85275
FAX (480) 844 9545

December 9, 2009

Inspection report
BESD Warehouse

I visited this site on November 23, 2009 for a substantial completion inspection. Also present was Dan Ramirez of M&P Solutions.

The electrical portion of the project was substantially complete. The quality of the electrical installation was among the best I have seen. I discussed several minor issues with the Contractor, who was aware of each issue and had materials on site to address each issue. The only substantive issue was that the electrical systems at the receiving desk in the warehouse had not yet been terminated. I consider this more of a timing issue than anything else. I see no reason for further inspection from my office.

I recommend acceptance of the electrical installations at this site.

