

**West Virginia Department of Health &
Human Resources
Berkeley County Health Department**

No image found with name:
Berkeley.png. Image files
needed to be generated.

GENERAL SANITATION INSPECTION REPORT

Establishment Information		
Facility Name Super 8	Facility Type Motel/Hotel	
Licensee Name Super 8(Jay Ganesh LLC)	Facility Telephone # 304	
Facility Address 2048 Edwin Miller Blvd Martinsburg , WV	Licensee Address 2048 Edwin Miller Blvd Martinsburg , WV 25404	
Inspection Information		
Inspection Type Routine	Inspection Date 02/28/2019	Total Time Spent 1.25

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 11 Repeated # 0</p> <p>Room: 101 64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose. OBSERVATION: Duct tape covering hole in bathroom. Hole needs repaired and sealed</p> <p>Room: 103 64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose. OBSERVATION: Floor under beds needs cleaned</p> <p>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose. OBSERVATION: Floor under drawers needs cleaned (dust/debris)</p> <p>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose. OBSERVATION: Wall around shower needs repaired (cracking)</p> <p>Room: 109 64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose. OBSERVATION: Drawers need cleaned</p> <p>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose. OBSERVATION: Vent in bathroom needs cleaned</p>

Room: 207

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Vent in bathroom needs cleaned

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Floor under beds need cleaned

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Wall around shower/Tub needs repaired and painted

Room: 302

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Floor under couch needs cleaned (food)

64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.

OBSERVATION: Vent cover in bathroom needs cleaned

Inspection Outcome

Comments

Disclaimer

Person in Charge



Dale Chudasama

Sanitarian



Keith Allison