

Scope of Work

This project consist of completing renovations on on the reference house that was started in 2019 under Building Permit number # BU19-0963. This permit has since expired and a new permit to finish

Basic items included under a New Permit are; 1. Remedy of inspection problems 3. All Interior Finishes, Doors, Cabinetry and Fixtures 4. Correction of drainage at rear of house 5. Removal of existing rear wood patio and

6. Obtain Certificate of Occupancy

Current Status: Under the previous permit the House was gutted to the studs, structural modifications were made, exterior was reclad, and a front exterior stairway was added. The house was insulated with foam insulation. The Plumbing, Electrical, and HVAC Roughin was completed and passed inspections on 4/8/20 and

Based upon the last recorded COK inspection, listed below are items on the inspection report that need addressed to pass the framing inspection and proceed

1. INSULATION HAS BEEN DONE WITH NO FRAMING INSPECTION

2.NO DRAFT STOPPING COMPLETED

3. OVER SPAN 2X6 CEILING JOIST BEAM

4.CEILING JOIST MUST SPAN FROM BEARING TO BEARING AND CAN NOT BE BUTTED IN MID SPAN

5.CLIPS AND JOIST HANGERS MUST HAVE CORRECT NAILS AND NAIL PATTERN

6 NEED PROPER HEADERS OVER DOORS AND WINDOWS

7.NO AIR BARRIER BEHIND SHOWER

8.CROWN VENT ON WASHER BOX

9.0PEN RISERS, NO HANDRAILS OR GUARDRAILS ON FRONT

10.NON COMPLIANT GUARDRAILS ON FRONT PORCH

11 EXPOSED NON WEATHER RESISTANT WOOD ON EXTERIOR

Plans prepared : Jan 29 2021

2 of 3